

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

AXA Ref:

Date : 12/2/2018

ATTN:THE MOTOR CLAIMS DEPT

AXA INSURANCE PTE LTD

78 SHENTON WAY #B1-01

AXA TOWER SINGAPORE 068811

ESTIMATE COST OF REPAIR

Vehicle Reg No.	SFZ5025M	Model / Year	TOYOTA ALTIS /2005
Date of Accident	09-Feb-18	Policy No.	GA162626
Type of Claim	Own Damage	Prepared By	SAMANTHA
Chassis	MR053ZEC107101138		

S/NO	Description	Qty	Unit Price	Amount
1	FRT BUMPER	1	\$ 120.00	\$ 120.00 <i>de</i>
2	FRT BUMPER SIDE RETAINER	2	\$ 12.00	\$ 24.00 <i>rec</i>
3	FRT BUMPER LOWER SKIRT	1	\$ 165.00	\$ 165.00 <i>de</i>
4	FRT BUMPER FOGLAMP LH	1	\$ 50.00	\$ 50.00 <i>?</i>
5	FRT BUMPER REINFORCEMENT	1	\$ 120.00	\$ 120.00 <i>?</i>
6	FRT BUMPER CLIP	10	\$ 2.50	\$ 25.00 <i>rec</i>
7	FRT GRILLE ASSY	1	\$ 100.00	\$ 100.00 <i>ara</i>
8	FRT GRILLE CLIP	2	\$ 2.50	\$ 5.00 <i>rec</i>
9	FRT GRILLE BUSH	2	\$ 9.00	\$ 18.00 <i>?</i>
10	FRT HEADLAMP LH	1	\$ 95.00	\$ 95.00 <i>ara</i>
11	FRT FENDER LH	1	\$ 90.00	\$ 90.00 <i>bt</i>
12	FRT FENDER INNER SHEILD LH	1	\$ 14.00	\$ 14.00 <i>de</i>
13	FRT FENDER INNER SHIELD CLIP	8	\$ 2.50	\$ 20.00 <i>rec</i>
14	FRT FENDER QUARTER GARNISH LH	1	\$ 15.00	\$ 15.00 <i>?</i>
15	FRT DOOR LH	1	\$ 460.00	\$ 460.00 <i>Rx</i>
16	FRT DOOR PROTECTOR WITH CHROME LH	1	\$ 30.00	\$ 30.00 <i>x</i>
17	FRT SUPPORT PANEL COMPLETE	1	\$ 520.00	\$ 520.00 <i>bt</i>
18	FRT BATTERY TOP BRACKET	1	\$ 16.00	\$ 16.00 <i>bt</i>
19	FRT BATTERY TRAY	1	\$ 25.00	\$ 25.00 <i>ara</i>
20	AIR INTAKE DUCT	1	\$ 40.00	\$ 40.00 <i>de</i>
21	FRT BONNET	1	\$ 320.00	\$ 320.00 <i>bt</i>
22	FRT BONNET LOCK	1	\$ 25.00	\$ 25.00 <i>Rx</i>
23	FRT BONNET HINGES	2	\$ 12.00	\$ 24.00 <i>Rx</i>
24	FRT SIDE SKIRT LH	1	\$ 200.00	\$ 200.00 <i>Rx</i>
25	AIRCON CONDENSER	1	\$ 380.00	\$ 380.00 <i>?</i>
26	RADIATOR	1	\$ 350.00	\$ 350.00 <i>?</i>
27	RADIATOR FAN COWLING	1	\$ 65.00	\$ 65.00 <i>?</i>
28	RADIATOR FAN MOTOR	1	\$ 85.00	\$ 85.00 <i>?</i>
29	RADIATOR FAN BLADE	1	\$ 40.00	\$ 40.00 <i>?</i>
30	COOLANT	1	\$ 40.00	\$ 40.00 <i>rec</i>
				\$ 3,481.00

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

31	TO CHECK WIRING	1	\$	30.00	\$	30.00	✓
32	TO REFILL AIRCON GAS	1	\$	100.00	\$	100.00	✓
33	TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS	1	\$	800.00	\$	900.00	700
34	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	1	\$	750.00	\$	1,100.00	800
		TOTAL			\$	5,611.00	

This is a computer printout no signature is required.

Tarfin 97495749

Ex \$400

Relevant.

13/2/18 @ 1700

6 days

Resurvey before paint

sur @ 1khantowm

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: