

AIG
13/02 Tues

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

*Not Authenkd
U/Sig B7
Resony After Paint
4 days*

02/02/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR BMW 523I - SKS8384J

1pc	rear bumper	\$ 1,270.00	?
1pc	rear bumper RH side retainer	<i>na</i> \$ 55.00	—
1pc	rear RH top arm	\$ 330.00	?
1pc	rear RH lower arm	\$ 280.00	?
1pc	rear RH lower front arm	\$ 155.00	?
1pc	rear RH lower rear arm	\$ 160.00	?
1pc	rear RH absorber	\$ 295.00	?
1pc	rear RH knuckle arm	\$ 1,080.00	?
1pc	rear RH knuckle bearing	\$ 170.00	?
1pc	rear RH sport rim	<i>na</i> \$ 1,065.00	✓
		<hr/>	
		\$ 4,860.00	
	less 5%	\$ 243.00	
		<hr/>	
		\$ 4,617.00	
1pc	rear RH sport rim	<i>na</i> s.nett \$ 850.00	✓
	remove & refit undercarriage	\$ 380.00	?
	remove & refit tyre	\$ 40.00	200
	alignment	\$ 80.00	600
	spray painting	\$ 500.00	4500
	labour charges	\$ 550.00	3000
	Total	<hr/>	
		\$ 7,017.00	