

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax: 62870590

Company Reg No: 200704370C GST Reg No: 200704370C

Your ref : SKU3997M

Date: 19.04.2018

M/S EQ INSURANCE COMPANY LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SKU3997M(TOYOTA HIACE)

DATE OF ACCIDENT : 08.02.2018

TO SUPPLY :

| | <u>Labour Cost</u> | | |
|-----|--|-----------|---------------|
| 01) | TO REPAIR & RESPRAY REAR LH FENDER PANEL | \$ | 600.00 400 |
| 02) | COMPANY ARTWORK | \$ | 380.00 300 |
| | TOTAL LABOUR COST | \$ | 980.00 |
| | TOTAL | \$ | 980.00 |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Ref: CC6/EQ118002814/Y63.