Our Ref:



320 UBI ROAD 3 SINGAPORE 408649 ACCIDENT REPAIR ESTIMATES

Type of Claim: TP Ins Company: SOMPO vs AIG Excess: Date of Accident: 30/01/2018 Suggested Days of Repair Repair Estimates	Vehicle No. : SKH2123T MÈRCEDES BENZ C 180 Make & Model : BLUEEFFICIENCY Year of Manufacture : 2012 Chassis No. : WDD2040312A776581 Engine No. : 27491030019086 Policy No. : Time of Accident : In-house Vehicle Assessor Case Owner : ANIKKA
Parts (a) Cost / List Price Items \$8,944.00 Plus/Less20% \$(1,788.80) Total of Cost / List \$7,155.20 (b) Nett Price Items \$45.00 Less Total of Nett Item (c) Special Nett Items \$- Total Parts Cost (Appendix A) \$7,155.20 Labour (Appendix B) \$2,650.00 Total Repair Cost \$9,805.20 The above total will be subjected to 7% G.S.T.	Contact No 68485725 – ANIKKA 68485726 – JASMINE CHNG
Name of Surveyor Company Survey conducted on Remarks By Surveyor (a) The repair of this vehicle is authorized / is not authorized (b) Recommended Days of Repair: (b) Resurvey (c) Resurvey Required / Not Resurvey (d) Excess (e) Signature of surveyor ACCOUNT REPAIR ESTIMATES TO SURVEYOR	zed until further notice. day(s)

Spark Car Care
ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	:	SKH2123T	Case Owner	:	ANIKKA	
Make & Model	:	MERCEDES BENZ C 180 BLUEEFFICIENCY	Year Manufacture	:	2012	
Chassis No	:	WDD2040312A776581	Engine No	:	27491030019086	
Sales Order	:		Supplier	:		
Order By	:		Type of Claim	:	<u>TP</u>	

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposi Surveyo
1	FRONT NUMBER PLATE	1			\$45.00	-	
2	FRONT NUMBER PLATE GARNISH	10		\$115.00	4.		
3	FRONT BUMPER Del-	1		\$1,315.00			
4	FRONT BUMPER INNER BRACKET LH 7,	2		\$48.00	~		
5	FRONT BUMPER INNER BRACKET RH	1		\$48.00			
6	FRONT BUMPER SPONGE	1		\$115.00			
7	FRONT BUMPER REINFORCEMENT 3	1		\$295.00	?		
8	FRONT BUMPER SIDE BRACKET LH ?	1		\$82.00	3		
9	FRONT BUMPER SIDE BRACKET RH 7	1		\$82.00	7		
10	FRONT BUMPER CLIPS &	10		\$80.00			
11	FRONT SUPPORT PANEL 7,	1		\$125.00	+		
12	FRONT SUPPORT PANEL LH	1		\$117.00	+		
13	FRONT SUPPORT PANEL RH	1		\$117.00	V		
14	SUPPORT PANEL TOP GARNISH	1		\$65.00	R.		
15	HEAD LAMP ASSY LH Men	1		\$1,050.00	2		
16	HEAD LAMP ASSY RH Mr.	1		\$1,050.00	4.		
17	HEAD LAMP BRACKET LH 440	1		\$240.00	S		
18	HEAD LAMP BRACKET RH	1		\$240.00	9.		
19	FRONT BUMPER LOWER GRILLE (CTR) 7	1		\$150.00	x		
20	FRONT BUMPER LOWER GRILLE (LH)	1		\$62.00	£		
21	FRONT BUMPER LOWER GRILLE (RH)	1		\$62.00	8.		
22	FOG LAMP - CHROME (LH)	1		\$118.00	x		
23	FOG LAMP - CHROME (RH)	1		\$118.00	*		
24	CONDENSOR 714	1		\$1,250.00	+		
25	RADIATOR	1		\$1,280.00	+		
26	RADIATOR GRILLE combid	1		\$720.00			
27							
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

-	n	~		34
а	1.7	• .	ы	п

Vehicle No. : SKH2123T Case Owner : ANIKKA

MERCEDES BENZ C 180

Make & Model : BLUEEFFICIENCY Year of Manufacture : 2012

S/No	Labour Description	Esimated Price	Adjusted Price	
1	TO KNOCK, STRAIGHTEN, REMOVE & REFIX DAMAGE PARTS	\$1,200.00	300	
2	TO PUTTY & SPRAY PAINTING ON THE BONNET, FRONT BUMPER FRONT SUPPORT PANEL & AFFECTED AREA	\$1,200.00	250	
3	TO CHECK WIRING	\$100.00	30	
4	TO REMOVE & REFIX CONDENSOR TO ASSIST WORKLOAD	\$150.00	٧.	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.