



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : GBA5240L
ACCIDENT DATE : 12-02-2018 10:00
THIRD PARTY REF. : SGT4310R

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE GBA5240L RENAULT KANGOO

LKF to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT HEADLAMP RH / CRA	450.00
2	1	FRONT FENDER RH / BUC	395.00
3	1	FRONT FENDER SHIELD RH / TN	153.00
4	10	FRONT FENDER SHIELD CLIP@\$5.00 / MC	50.00
5	1	FRONT APRON PANEL / CRA	560.00
6	1	FRONT BUMPER / CA	540.00
7	1	FRONT BUMPER SIDE RETAINER RH / MC	33.00
8	1	FRONT BUMPER PAD RH / CA	190.00
9	10	FRONT BUMPER CLIP@\$3.00 / MC	30.00
			2,401.00
			LESS 20 %
			480.20
			TOTAL (A)
			1,920.80

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	550.00
3	1	SPRAYPAINTING CHARGES	680.00

4 Days.

Lumpsum Repair.

Eno Qiao - 82880282

22/2/18

After repair photos

TOTAL (D)	1,260.00
ESTIMATE TOTAL	3,180.80