

振明摩哆

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST047/18/TP

Your Ref: TP claim against GBG1459T

12-Feb-18

AXA Insurance Singapore Pte Ltd

#01-01 GB Building

Singapore 069542

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Kia K2500 no: GBE7593J

Date of accident: 09-02-2018

Parts supply:

1 pc Front R/h door	S\$ 985.50
2 pcs Front R/h door hinges @\$65.70	131.40
1 pc Front R/h door mirror	389.50
1 pc Front R/h door signal lamp	45.05
1 pc Front R/h door top moulding	89.50
1 pc Front R/h door regulator	268.50
1 pc Front R/h door motor	265.50
1 pc Front R/h door board	333.50
1 pc Front R/h door pillar	785.90
1 pc Front windscreen moulding	65.60
1 pc Front R/h corner panel	155.60
1 pc Front R/h corner panel bracket	45.90
1 pc Headlamp R/h	420.50
1 pc Headlamp clip R/h	10.00
1 pc Wiper panel	255.60
1 pc Bonnet	402.80
2 pcs Bonnet hinges @\$75.80	151.60
1 pc Bonnet grille	166.50
1 pc Bonnet emblem	45.80
1 pc Bonnet weatherstrip	66.50
1 pc Front support panel	334.50
1 pc Front bumper	395.50
2 pcs Front bumper retainers @\$45.90	91.80
2 pcs Front bumper brackets @\$75.80	151.60
8 pcs Front bumper clips @\$3.50	28.00
1 pc Front bumper reinforcement	221.30
1 pc Front bumper R/h cover	29.50
1 pc Front bumper lower grille	78.80

6,411.75

Less 10%: (641.18)

5,770.58

ESTIMATE

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Kia K2500 no: GBE7593J

Date of accident: 09-02-2018

Parts supply:

Balance b/f:	S\$	5,770.58
1 pc Front R/h door sticker - Company logo (S/Nett)		150.00
1 pc Front R/h door sticker - Address (S/Nett)		12.00
1 pc Front windscreen gum (S/Nett)		40.00
1 pc Front no. plate with cover (S/Nett)		45.00

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.		1,400.00
To respray affected part.		1,200.00
To remove & refit front windscreen.		100.00
To remove & refit front R/h door glass		40.00
To apply underseal.		60.00
To check wirings.		30.00
	S\$	<u><u>8,847.58</u></u>