

INS. CASE OWNER:

Stacey Ng | CC4 / ASM1800 2828 / U ua3s2 IDAC: 30407

ASSIGNMENT

Surveyor:

NAME

DOI:

14/2/18

Date / Time:

12/10/18

Registered in Merimen:

Pre-assign / CCU / FTE

SLR 484SR



Insured Vehicle No.:

Name of Insured:

Sim Wai Meng Leonard

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

09/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Sfm 008QA

6A265907

Subaru Forester

New Pangloss Plaza

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFC9173m

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
Eurokars
PteINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

21/2
TGR

SFC9173m X; SLR484SR X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN By Email
12/3

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 30 OCT 2018

PRELIMINARY ADVICE Date/Time:

14/2

Sent By:

LSP.

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

9/10/18

Confirm with:

Jessica

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

8655.74

Loss of Rental (LOR):

S\$

642.00

(

6 days) x 100 + 617

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

9299.74

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

9299.74

Name 1:

TRANS EUROKARS PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

SRV 117
Suzuki

REF:

Asm (AXA)

Ua3

ASSIGNMENT

From: _____ Date: 14.02.2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFC 9173M

at Workshop mis Trans Eurokars

of 5 Ubi Close

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

3.30pm
owner waiting



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFC 9173M Yr Regn: 9.17

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 9/

Make: merzda 5 cc 1998

Colour: S. /uer A/C Insured / Std / NI / NA

Sp. Reading: 13495 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6 C W107 / H / U / 12 6540

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 55 R 16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/2/18 D.O.I. 14/2/18

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 8089.48 (Red: \$ 9148.23 / 53%).

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos: _____

Others: _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002828/Uua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLR 4845R	Veh. Inspected	SFC 9173M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/02/2018	Inspection Date	14/02/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



P/P \$8089.48

62.

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		NAME : Mr Kang William ADDRESS : 171c Edgedale Plains #12-432 Singapore 823171 TEL : 97592564		WIP : 62344 EXCESS : DATE: 10-Feb-18	
ATTN : MOTOR CLAIMS		FAX :			
VEH NO :	SFC9173M	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071H0126540	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	29-Sep-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MC513-50-221EBB	22/Dec ✓	\$ 915.40	✓
2	1	MC513-50-2J1C	re ✓	\$ 45.30	✓
3	1	MC513-50-2H1B	re ✓	\$ 45.30	✓
4	1	MC513-51-077A	re ✓	\$ 5.40	✓
5	1	MC513-51-067A	re ✓	\$ 5.40	✓
6	1	MC513-50-371	17 X	\$ 20.50	X
7	1	MD350-51-5L0E	17 X	\$ 50.40	X
8	1	MC513-50-361	17 X	\$ 20.50	X
9	1	MD350-51-5M0E	17 X	\$ 50.40	X
10	1	MC235-56-B9XC	17 X	\$ 148.00	X
11	2	MG07A-50-EA1	re ✓	\$ 6.00	✓
12	4	MBN8F-50-355	re ✓	\$ 21.60	✓
13	1	M9991-00-501	re ✓	\$ 2.80	✓
14	4	MBHN1-50-021A	re ✓	\$ 10.00	✓
15	2	MC235-50-ES1	re ✓	\$ 8.80	✓
16	1	MCG15-70-750B	17 X	\$ 491.10	X
17	1	MCGY3-62-02XF	22/Dec ✓	\$ 1,559.00	✓
18	2	MGHP9-58-867	re ✓	\$ 22.80	✓
19	1	MC513-68-960B	17 X	\$ 411.40	X
20	1	MC513-62-761C	17 X	\$ 169.00	X
21	2	MBR55-56-994	re ✓	\$ 14.40	✓
22	2	MTK48-62-864	re ✓	\$ 14.00	✓
23	1	MC513-62-310A	17 X	\$ 244.00	X
24	1	MC513-50-810F50	17 X	\$ 459.40	X
25	1	MCGY0-51-711	re ✓	\$ 43.10	✓
26	1	MCGY0-51-721	re ✓	\$ 34.50	✓
27	1	MTD11-51-731	re ✓	\$ 42.00	✓
28	1	MC597-51-771	re ✓	\$ 76.10	✓
29	1	MC513-50-611	re ✓	\$ 57.60	✓
30	2	MD204-50-896A	re ✓	\$ 5.20	✓

31	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	nr ✓	\$	6.80	✓
32	FASTENER, REAR WINDSCREEN	2	MC273-50-896	nr ✓	\$	15.60	✓
33	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	nr ✓	\$	48.40	✓
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B	nr ✓	\$	10.40	✓
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B	nr ✓	\$	22.80	✓
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B	nr ✓	\$	26.80	✓
37	CLIP, REAR SPOILER	3	MC514-51-958A	nr ✓	\$	21.90	✓
38	CLIP, REAR SPOILER	1	MC525-51-958A	nr ✓	\$	8.20	✓
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	nr ✓	\$	90.80	✓
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	nr ✓	\$	90.80	✓
			TOTAL PARTS		\$	5,341.90	
			LESS 10%		\$	534.19	
			TOTAL PARTS COST		\$	4,807.71	

Labour Description							
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	660	1320	\$	4,620.00	✓
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE	630	1890	\$	3,780.00	✓
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		11X	\$	350.00	
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION		150	\$	250.00	
5	MZ-BR-TRIM52	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION		330	\$	660.00	
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS		NETT ✓	\$	560.00	
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS	nr	NETT ✓	\$	120.00	
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA		200	\$	660.00	
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS		200	\$	660.00	
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE	50	NETT ✓	\$	70.00	
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		120	\$	250.00	
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS		150	\$	350.00	
13	MZ-BR-SUNDRI	SUNDRIES	nr 30	NETT	\$	100.00	
			TOTAL LABOUR	\$	-	\$ 12,430.00	

TOTAL PARTS	\$ -	\$ 4,807.71
TOTAL	\$ -	\$ 17,237.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Not Authorized
LH
14/2/18
Take photo before painting
tel. 62563561
6 days confirmed.

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Kang William ADDRESS : 171c Edgedale Plains #12-432 Singapore 823171 TEL : 97592564		WIP : 62344 EXCESS : DATE: 10-Feb-18	
VEH NO :	SFC9173M	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6CW1071H0126540	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	29-Sep-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	\$ 915.40	\$ 915.40
2	RETAINER(LHS), REAR BUMPER	1	MC513-50-2J1C	\$ 45.30	\$ 45.30
3	RETAINER(RHS), REAR BUMPER	1	MC513-50-2H1B	\$ 45.30	\$ 45.30
4	BRACKET(LHS), REAR BUMPER	1	MC513-51-077A	\$ 5.40	\$ 5.40
5	BRACKET(RHS), REAR BUMPER	1	MC513-51-067A	\$ 5.40	\$ 5.40
6	GUARD(LHS), REFLECTOR	1	MC513-50-371		\$ 20.50
7	REFLECTOR LHS	1	MD350-51-5L0E		\$ 50.40
8	GUARD(RHS), REFLECTOR	1	MC513-50-361		\$ 20.50
9	REFLECTOR RHS	1	MD350-51-5M0E		\$ 50.40
10	REAR REINFORCEMENT	1	MC235-56-B9XC		\$ 148.00
11	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.00	\$ 6.00
12	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 21.60	\$ 21.60
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
14	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
15	GROMMET, REAR BUMPER	2	MC235-50-E51	\$ 8.80	\$ 8.80
16	PANEL, REAR END	1	MCG15-70-750B		\$ 491.10
17	TAILGATE	1	MCGY3-62-02XF	\$ 1,559.00	\$ 1,559.00
18	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	\$ 22.80	\$ 22.80
19	TRIM LOWER, TAILGATE	1	MC513-68-960B		\$ 411.40
20	WEATHERSTRIP, TAILGATE	1	MC513-62-761C		\$ 169.00
21	TAPE PROTECTOR, TAILGATE	2	MBR5S-56-994	\$ 14.40	\$ 14.40
22	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864	\$ 14.00	\$ 14.00
23	LOCK, TAILGATE	1	MC513-62-310A		\$ 244.00
24	GARNISH, TAILGATE	1	MC513-50-810F50		\$ 459.40
25	MAZDA, EMBLEM	1	MCGY0-51-711	\$ 43.10	\$ 43.10
26	S, EMBLEM	1	MCGY0-51-721	\$ 34.50	\$ 34.50
27	MASCOT, REAR	1	MTD11-51-731	\$ 42.00	\$ 42.00
28	SKYACTIV, EMBLEM	1	MC597-51-771	\$ 76.10	\$ 76.10
29	MOULD, REAR WINDSCREEN	1	MC513-50-611	\$ 57.60	\$ 57.60
30	FASTENER, REAR WINDSCREEN	2	MD204-50-896A	\$ 5.20	\$ 5.20
31	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	\$ 6.80	\$ 6.80

32	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 15.60	\$ 15.60
33	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	\$ 48.40	\$ 48.40
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B	\$ 10.40	\$ 10.40
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B	\$ 22.80	\$ 22.80
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B	\$ 26.80	\$ 26.80
37	CLIP, REAR SPOILER	3	MC514-51-958A	\$ 21.90	\$ 21.90
38	CLIP, REAR SPOILER	1	MC525-51-958A	\$ 8.20	\$ 8.20
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	\$ 90.80	\$ 90.80
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	\$ 90.80	\$ 90.80
			TOTAL PARTS	\$ 3,277.20	\$ 5,341.90
			LESS 10%	\$ 327.72	\$ 534.19
			TOTAL PARTS COST	\$ 2,949.48	\$ 4,807.71

Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 1,320.00	\$ 4,620.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.		\$ 1,890.00	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 150.00	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 330.00	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.		\$ 560.00	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		\$ 120.00	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 200.00	\$ 660.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		\$ 200.00	\$ 660.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00	\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 120.00	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 150.00	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES.		\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 5,140.00	\$ 12,430.00
			TOTAL PARTS	\$ 2,949.48	\$ 4,807.71
			TOTAL	\$ 8,089.48	\$ 17,237.71
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 8,089.48	
			GST 7%	\$ 566.26	\$ -
			GRAND TOTAL	\$ 8,655.74	\$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD		NAME : Mr Kang William	WIP : 62344
8 SHENTON WAY		ADDRESS : 171c Edgedale Plains	EXCESS :
#24-01 AXA TOWER		#12-432	DATE: 10-Feb-18
SINGAPORE 068811		Singapore 823171	
ATTN. :	MOTOR CLAIMS	TEL : 97592564	
FAX :			
VEH NO :	SFC9173M	DATE IN :	CONTACT PERSON : JESS 6395 7874
CHASSIS NO :	JM6CW1071H0126540	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.: 29-Sep-17	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MC513-50-221EBB	DS/De ✓	\$ 915.40
2	1	MC513-50-2J1C	re ✓	\$ 45.30
3	1	MC513-50-2H1B	re ✓	\$ 45.30
4	1	MC513-51-077A	re ✓	\$ 5.40
5	1	MC513-51-067A	re ✓	\$ 5.40
6	1	MC513-50-371	re X	\$ 20.50
7	1	MD350-51-5L0E	re X	\$ 50.40
8	1	MC513-50-361	re X	\$ 20.50
9	1	MD350-51-5M0E	re X	\$ 50.40
10	1	MC235-56-B9XC	?	\$ 148.00
11	2	MGD7A-50-EA1	re ✓	\$ 6.00
12	4	MBN8F-50-355	re ✓	\$ 21.60
13	1	M9991-00-501	re ✓	\$ 2.80
14	4	MBHN1-50-0Z1A	re ✓	\$ 10.00
15	2	MC235-50-ES1	re ✓	\$ 8.80
16	1	MCG15-70-750B	re X	\$ 491.10
17	1	MCGY3-62-02XF	DS/De ✓	\$ 1,559.00
18	2	MGHP9-58-867	re ✓	\$ 22.80
19	1	MC513-68-960B	re X	\$ 411.40
20	1	MC513-62-761C	?	\$ 169.00
21	2	MBR55-56-994	re ✓	\$ 14.40
22	2	MTK48-62-864	re ✓	\$ 14.00
23	1	MC513-62-310A	?	\$ 244.00
24	1	MC513-50-810F50	re X	\$ 459.40
25	1	MCGY0-51-711	re ✓	\$ 43.10
26	1	MCGY0-51-721	re ✓	\$ 34.50
27	1	MTD11-51-731	re ✓	\$ 42.00
28	1	MC597-51-771	re ✓	\$ 76.10
29	1	MC513-50-611	re ✓	\$ 57.60
30	2	MD204-50-896A	re ✓	\$ 5.20

31	SPACER, REAR WINDSCREEN	1	MDJ01-50-897	ner ✓	\$ 6.80
32	FASTENER, REAR WINDSCREEN	2	MC273-50-896	ner ✓	\$ 15.60
33	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897	ner ✓	\$ 48.40
34	PROTECTOR, REAR SPOILER	2	MC514-51-979B	ner ✓	\$ 10.40
35	PROTECTOR, REAR SPOILER	2	MC514-51-982B	ner ✓	\$ 22.80
36	PROTECTOR, REAR SPOILER	2	MC514-51-972B	ner ✓	\$ 26.80
37	CLIP, REAR SPOILER	3	MC514-51-958A	ner ✓	\$ 21.90
38	CLIP, REAR SPOILER	1	MC525-51-958A	ner ✓	\$ 8.20
39	GASKET(LHS), TAILGATE LAMP	1	MC513-51-3J8	ner ✓	\$ 90.80
40	GASKET(RHS), TAILGATE LAMP	1	MC513-51-3H8	ner ✓	\$ 90.80
TOTAL PARTS					\$ 5,341.90
LESS 10%					\$ 534.19
TOTAL PARTS COST					\$ 4,807.71

Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	1320	\$ 4,620.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	630	1890	\$ 3,780.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		11X	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		330	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.		NETT ✓	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	ner	NETT ✓	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		200	\$ 660.00
9	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		200	\$ 660.00
10	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	ner	NETT ✓	\$ 70.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		150	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES.	ner 30	NETT	\$ 100.00
TOTAL LABOUR				\$ -	\$ 12,430.00

TOTAL PARTS	\$ -	\$ 4,807.71
TOTAL	\$ -	\$ 17,237.71
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

 Authorised Signature

Not Authorized
 LKK
 14/2/18
 Take photo before painting
 Tel. 62563561
 6 days confirmed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M008QA
Our ref: CC4/ASM18002828/Uua3

Date: 14.02.2018

The Motor Claims Department
M/s AXA INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SFC9173M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.02.2018 at the premises of M/s Trans Eurokars Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	17,237.71
Revised Estimate Amount	: S\$	8,089.48
"Check" Items Amount	: S\$	504.90
Total (Including Check Items)	: S\$	8,594.38
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



SERVICE REQUESTS

MESSAGES

CLAIMS

<< RE: Request for Mandate approval S8M008QA

Type

Question

Message

Dear Sir / Madam, OI rear-ended to TP. We have informed TP claim and he agree to settle. Liability(TP)
100% Proposed repair cost \$ 8,655.74 Loss of rental \$ 642.00 no. of 6 days x \$ 100 w/gst LTA search
fees \$ 2.00 Proposed Total \$ 9,299.74 Best Regards, Thin Thin Hlaing | Case Handler LKK Auto
Consultants Pte Ltd

[Reply](#)

<< Re:RE: Request for Mandate approval S8M008QA

Type	Question
Message	pls proceed


Reply



DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned repairers my/our vehicle No: PEC 9173 M which has been repaired to my satisfaction and I/we admit that the payment for such repairs by Trans Eurokars Pte Ltd is in full and final discharge of my claim under policy number: _____ in respect of damage

caused to the said vehicle as a result of an accident that occurred on 09 FEB 2018 at CAR PARK ENTRANCE TO PRUIT BUK
17th FLOOR


Witnessed by Repairs

MAY 23, '18
Date


Signature by Insured

MAY 23, '18
Date



Corporate Head Office

: Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sungei Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

Showroom & Service Centre :

23 Leng Kee Road Singapore 159095
Sales Hotline : 6803 8118 Service Hotline : 6603 8128
Sales Fax : 6476 7073 Service Fax : 6476 7417
5 Ubi Close Singapore 408605
Sales Hotline : 6395 8888 Service Hotline : 6395 8899
Sales Fax : 6846 1700 Service Fax : 6744 9402

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR 4845R (Insd veh)	Model:	MAZDA 5 (A)
	SFC 9173M (TP veh)		
Date of Accident:	09/02/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	18,444.35
Final Repair Cost	:	\$	8,655.74
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	642.00 6 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	9,299.74

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	TRANS EUROKARS PTE LTD	:	\$ 9,299.74

NUR SHAQILAH BTE ABDOL
WAHAB

09/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18002828/Uua3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG			Date : 09-11-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 4845R	Veh. Inspected	SFC 9173M	
Policy No.	GA265907	Coverage (\$)	0.00	
Claim No.	S8M008QA	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0126540	Colour	SILVER	
Odometer	13495	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	TOYO	6 mm	
L/H Front Tyre	205/55R16	TOYO	6 mm	
R/H Rear Tyre	205/55R16	TOYO	6 mm	
L/H Rear Tyre	205/55R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2018	Inspection Date	14/02/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFC 9173M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	915.40	915.40
1	RETAINER (LHS), REAR BUMPER (CONSISTENT)	NECESSARY	45.30	45.30
1	RETAINER (RHS), REAR BUMPER (CONSISTENT)	NECESSARY	45.30	45.30
1	BRACKET (LHS), REAR BUMPER (CONSISTENT)	NECESSARY	5.40	5.40
1	BRACKET (RHS), REAR BUMPER (CONSISTENT)	NECESSARY	5.40	5.40
1	GUARD (LHS), REFLECTOR (CONSISTENT)	NOT NECESSARY	20.50	-
1	REFLECTOR LHS (CONSISTENT)	NOT NECESSARY	50.40	-
1	GUARD (RHS), REFLECTOR (CONSISTENT)	NOT NECESSARY	20.50	-
1	REFLECTOR RHS (CONSISTENT)	NOT NECESSARY	50.40	-
1	REAR REINFORCEMENT (CONSISTENT)	NOT NECESSARY	148.00	-
2	FASTENER, REAR BUMPER (CONSISTENT)	NECESSARY	6.00	6.00
4	RIVET, REAR BUMPER (CONSISTENT)	NECESSARY	21.60	21.60
1	GROMMET, REAR BUMPER (CONSISTENT)	NECESSARY	2.80	2.80
4	GROMMET, REAR BUMPER (CONSISTENT)	NECESSARY	10.00	10.00
2	GROMMET, REAR BUMPER (CONSISTENT)	NECESSARY	8.80	8.80
1	PANEL, REAR END (CONSISTENT)	TO REPAIR SEE LABOUR	491.10	-
1	TAILGATE (CONSISTENT)	DENTED / BENT	1,559.00	1,559.00
2	VAVLE ONEWAY, TAILGATE (CONSISTENT)	NECESSARY	22.80	22.80
1	TRIM LOWER, TAILGATE (CONSISTENT)	NOT NECESSARY	411.40	-
1	WEATHERSTRIP, TAILGATE (CONSISTENT)	NOT NECESSARY	169.00	-
2	TAPE PROTECTOR, TAILGATE (CONSISTENT)	NECESSARY	14.40	14.40
2	TAPE PROTECTOR, TAILGATE (CONSISTENT)	NECESSARY	14.00	14.00
1	LOCK, TAILGATE (CONSISTENT)	NOT NECESSARY	244.00	-
1	GARNISH, TAILGATE (CONSISTENT)	NOT NECESSARY	459.40	-
1	MAZDA, EMBLEM (CONSISTENT)	NECESSARY	43.10	43.10
1	5, EMBLEM (CONSISTENT)	NECESSARY	34.50	34.50
1	MASCOT, EMBLEM (CONSISTENT)	NECESSARY	42.00	42.00
1	SKYACTIV, EMBLEM (CONSISTENT)	NECESSARY	76.10	76.10
1	MOULD, REAR WINDSCREEN (CONSISTENT)	NECESSARY	57.60	57.60

Report Ref No. CC4/ASM18002828/Uua3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FASTENER, REAR WINDSCREEN (CONSISTENT)	NECESSARY	5.20	5.20
1	SPACER, REAR WINDSCREEN (CONSISTENT)	NECESSARY	6.80	6.80
2	FASTENER, REAR WINDSCREEN (CONSISTENT)	NECESSARY	15.60	15.60
4	SPACER, REAR WINDSCREEN (CONSISTENT)	NECESSARY	48.40	48.40
2	PROTECTOR, REAR SPOILER (CONSISTENT)	NECESSARY	10.40	10.40
2	PROTECTOR, REAR SPOILER (CONSISTENT)	NECESSARY	22.80	22.80
2	PROTECTOR, REAR SPOILER (CONSISTENT)	NECESSARY	26.80	26.80
3	CLIP, REAR SPOILER (CONSISTENT)	NECESSARY	21.90	21.90
1	CLIP, REAR SPOILER (CONSISTENT)	NECESSARY	8.20	8.20
1	GASKET (LHS), TAILGATE LAMP (CONSISTENT)	NECESSARY	90.80	90.80
1	GASKET (RHS), TAILGATE LAMP (CONSISTENT)	NECESSARY	90.80	90.80
	LESS 10% DISCOUNT		-534.19	-327.72
			4,807.71	2,949.48
	SPECIAL NETT ITEMS			
1	SEALER ON THE WINDSCREEN GLASS (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	NUMBER PLATE (SN) (CONSISTENT)	BENT	70.00	70.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
			290.00	220.00
	LABOUR			
	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF PANEL, REAR END.		4,620.00	1,320.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.		3,780.00	1,890.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		660.00	330.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS.		560.00	560.00
	TO TRANSFER REVERSE CAMERA.		660.00	200.00
	TO TRANSFER REVERSE SENSORS.		660.00	200.00

Report Ref No. CC4/ASM18002828/Uua3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELETRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			12,140.00	4,920.00
GRAND TOTAL			17,237.71	8,089.48
RECOMMENDED COST OF REPAIRS				8,089.48

Report Ref No. CC4/ASM18002828/Uua3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.