

25/03/2018

ASS. REC. BY:

REF: CS/FWD18002829/K/d3st

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Merimen

From (Person):

Belliana

of

FWD

Date/Time: 12/2/18 @ 11:21am

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFE 2231P

Insured:

at Workshop m/s

Ah Lim Motor

Tel: 6483 1244

of 10, AMK Ind. Prk 2A # 01-09

Policy No: PNPV2017-00007809

Claim No:

1201800001865

Sum Insured:

Excess:

\$ 500.00

Make of Veh:

(Client's Record)

D.O.A.

30/01/2018

13/02/2018

H.O.D. Endorsement:

CA / ☒ REV / REP. / REV 24 HRS

Date/Time: 3:59pm @ 12/2/18

Person Contacted:

Zila

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFE 2231P - CC4/ASM18002095 / Tie 93 D.O.A: 30/01/18
13/2/18	Revert via merimen
14/2/18	12:03pm authorize repair by Belliana
14/2/18	12:15 inform email to ah lim authorize excess 500
	mandate up to 12k, more need re seek.

REF: FWD cs/FWD18002829/Ktd3

ASSIGNMENT

SFE 2231P

11 16

Date: 13/2/18

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFE 2231P

at Workshop mis: Ah Lim Motor

of 10, AMK Ind. Prk 2A # 01-09

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$ 500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S
☒	☒

Bal. or Market Value: \$ 100k

(DAO Accident Report) Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 11 days Res: Yes or No

Lump Sum: 1. B. 1 % 3 Val: Yes or No

CA / (REV) / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

Date / Time Action / Instruction

14/2 File parts to Cathman

Part by part \$14887 (Red: 6544; 3070)

RECEIVED 02 AUG 2018

Date/Time File Pass to?

> 18 Typist

Date/Time File Return to?

1

Report Format: OD

Lump Sum (E) \$ 14887

Days Of Repair: 11

Resurvey No. of Trip: 7

Add Fee:

☐	Site Insp	\$
☐	Inter. Insp	\$
☐	Tech. File	\$
☐	Weekend	\$

Survey Fee:

Transportation:

1-40

Photo:

Sketch:

300
50
50
10

Veh No: SFE 2231P

Type: M/Car/M/Cycle/Bus/Van/Lorry/Taxi/Prime Mover

Truck/Trailer:

Make: Subaru (A) Forster Wagon 1998

Colour: M. Brown

Sp. Reading: 21808

Eng. No:

Ch. No: JF15JGK 85G 079871

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RUM or

Tyre Size: 225/55R18

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front: 2 mm

R. Bal: 2 mm

L. Bal: 2 mm

D.O.A: 30 / 118

D.O.L: 13 / 12 / 118

Survey held at: ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rm

The U/C / Chassis frame & Body Structure affected due to collision ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FWD SINGAPORE PTE LTD		Ref : CS/FWD18002829/Ktd3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986		Date : 13-02-2018	
		Code : FWD	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SFE 2231P
Policy No.	PNPV2017-00007809	Coverage (\$)	0.00
Claim No.	1201800001865	Excess (\$)	500.00
Assign From	MERIMEN (BELLIANA)	Assign Date	13/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/01/2018	Inspection Date	13/02/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	12 Feb 2018 10:53	12 Feb 2018 11:00 S\$20,100.00	12 Feb 2018 11:24 Assign			New Assignment

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LIM CHWEE HWA , ID: S6813564H, Tel: +6596573320		
Vehicle Reg. No.:	SFE2231P	Date of Loss:	30/01/2018 00:00 - :59
Claim Type:	OD / 1201800001865	Policy/Cover Note No.:	PNPV2017-00007809 (Comprehensive) Coverage: 07/11/2017 - 06/11/2018
		Excess:	S\$500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Belliana - 67275741]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561		
Driver/Custodian:	LIM CHWEE HWA (49 / Female), NRIC: S6813564H, Tel: +6596573320		
Adj Asg. Remarks:	Auto-assignment adjuster same as linked case		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 14 February 2018 1:31 PM
To: 'ahlimmc@singnet.com.sg'
Subject: SFE 2231P / OD / FWD

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SFE 2231P (Excess \$500/-)**. Up to \$12,000/- on part by part base on marking sheet, if there is any supplementary/revised will need to seek approval.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SFE2231P (1201800001865)

OD

Jan 30 2018 12:00AM

[LIM CHWEE HWA]

Ah Lim Motor Company

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 14/02/2018 12:08 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12000.00) - SFE2231P - Claim Handler: Belliana

Approved:12000.00:Approved mandate up to \$12,000/- Please re-seek mandate if there is any supplementary and revised COR above \$12,000/-

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 14 February 2018 12:15 PM
To: 'ahlimmc@singnet.com.sg'
Cc: SUR
Subject: SFE 2231P / OD / FWD

Dear Eileen,

As instructed by our client, please proceed to repair the insured vehicle **SFE 2231P (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Current mandate up to \$12,000/- on part by part, we will need to re-seek mandate if there is any supplementary and revised COR above \$12,000/-

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<u>PARTS</u>	<u>S.NETT</u>	<u>LABOUR</u>
--------------	---------------	---------------

520	30	20
50	30	100
90	15	80
180	15	320
20	15	150
10	105	1100
20		1100
10		2870

	<u>TOTAL</u>
--	--------------

	8929
--	------

120
12
2500
20
50
35
300
20
30
6
70
140
30
10
280
60
16
250
15
16
15
35
4
110
140
250
140
100
280

5954

<u>CHECK</u>

<u>PARTS</u>	<u>LABOUR</u>
--------------	---------------

35	120
45	380
140	80
380	580

300
420
150

30
55

20

8

8

23

22

30

30

25

50

95

125

125

110

140

250

70

500

90

100

100

70

900

1350

140

144

250

220

100

160

240

135

40

7225

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Belliana

Date: 13 Feb 2018

Preliminary Advice

Vehicle No	: SFE2231P	Accident Date	: 30/01/2018
Make	: SUBARU FORESTER	Policy No.	: PNPV2017-00007809
Assignment Date	: 12/02/2018	Excess	: S\$500.00
Date of Inspection	: 12/02/2018	Est. Duration of Repair	: 11.00
Inspection At	: AH LIM MOTOR COMPANY (AMK) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and undercarriage claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,100.00
Revised Amount	:S\$	8,929.00
Check Items (Estimated)	:S\$	7,805.00
Total	:S\$	16,734.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	106,000.00
COE / PARF Rebate	:S\$	60,258.00
Salvage Value	:S\$	
Margin for Repair	:S\$	45,742.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/01/2018 13:49
Date Of Accident	30/01/2018 08:35
Exact Location Of Accident	OUTSIDE THE EXIT GANTRY OF YISHUN SAPPHIRE CONDO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFE2231P
Insured/Policyholder	
Name Of Registered Owner	LIM CHWEE HWA
NRIC No	S6813564H
Email Address	SL@3PA.SG
Mobile Phone No	(LOCAL) +65-96573320
Alternative Phone No	OFFICE-63252158

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER 2.0XT CVT AWD SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00007809
Cover Note Number	N.A.

Driver

Name of Driver	LIM CHWEE HWA
NRIC No	S6813564H
Date Of Birth	07/04/1968
Occupation	INDOOR
Date Of Driving Pass	09/04/2007
Driving Experience	10 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96573320
Fax Number	
Contact Number	OFFICE-63252158
Email Address	SL@3PA.SG

NRIC/Passport Number	S1766457C
Contact Number	NA
Address	NA
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM CHWEE HWA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SFE2231P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

AS PER ATTACHED POLICE REPORT LODGED AT TRAFFIC POLICE DIV HQ.
VIDE REPORT T/20181030/7006.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

31 January 2018 at 10:45 AM

Date/Time:

31 January 2018 at 10:45 AM

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180130/7006

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180130/7006

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM CHWEE HWA	ID No.	S6813564H
Related Vehicle	SFE2231P (Car)	Contact No.	96573320
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	30/01/2018	Date Discharge	30/01/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Passenger			
Name	Teo Hui Xi Serina	ID No.	S9514966I
Related Vehicle	SFE2231P (Car)	Contact No.	94562879
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

I was driving slowly after the condo, Yishun Sapphire exit gantry and saw a lorry far away moving down the new road. I slowly turned out after ascertaining the safe distance when all of sudden the lorry knocked onto the right of my car and sped past me.

There were pedestrians just outside the condo (on my left) and stationery vehicles along the road.

In order not to knock onto people or other vehicles, I swerved to my vehicle to the right after the sudden impact, and mounted the kerb and hit the construction barricade on the opposite side. I had made sure there was nobody and vehicle on the opposite road. The referred lorry driver, Mr Low Kian Huat (Licence No. S1766457C) driving lorry no GBB8927P) carrying foreign workers only stopped his lorry after a substantial distance- outside 8courtyard.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3564H

Vehicle Details

Vehicle No.:	SFE2231P
Vehicle to be Exported:	Yes
Intended De-registration Date:	09 Feb 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	FA20B857723
Chassis No.:	JF15JGK85GG079871
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$20,817.00
Original Registration Date:	08 Nov 2016
First Registration Date:	08 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$21,144.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2026
PARF Rebate Amount:	\$15,858.00

Intended COE Rebate Details

COE Expiry Date:	07 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$44,400.00
Total Rebate Amount:	\$60,258.00

The information contained herein is correct as at 09 Feb 2018

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6813564H



LIM CHWEE HWA

林翠华

CHINESE

Date of Birth

07-04-1968

Country of Birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Number S6813564H

LIM CHWEE HWA



Valid Until 07 Apr 2007

Valid From 08 Apr 2007



2221961



NRIC No. S6813564H



Valid Until 29-07-1994

A+

APT BLK 54 CANBERRA DRIVE #01-28

SINGAPORE 769440

NRIC No. S6813564H

Date of Birth 15/07/2010


No. 8534387

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

09 Apr 2007

Class 3A Motor cars without clutch pedals (Auto) <= 3000kg
with <= 7 passengers, exclusive of the driver, and
other motor vehicles without clutch pedals <= 2500kg



Licence No. S6813564H

NP 428A



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00007809 (Comprehensive - Executive Plan)

Car plate number: SFE2231P

Your name (As the policyholder): Lim Chwee Hwa

Coverage start date: 07/11/2017

Coverage end date: 06/11/2018

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 11/10/2017

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimme@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00007809	Date of Loss:	30/01/2018
Vehicle Reg. No.:	SFE2231P	Driveable?	
Driver Age/Info:	49 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM CHWEE HWA	Contact No:	+6596573320
Driver:	LIM CHWEE HWA		
Make/Model:	SUBARU FORESTER, 2.0 XT AWD CVT (A)	Vehicle Reg. Date:	08/11/2016
Vehicle Colour:	BROWN	Chassis No:	JF1SJGK85GG079871
Engine No:	FA20B857723		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	28 / 1 day		
Description of Accident/Loss	REFER TO THE GIA REPORT.		
Remarks:	CAR IS IN OUR WORKSHOP (TOW IN) ON 9/2/18		

Present Location: AH LIM MOTOR COMPANY (AMK)

COST OF CLAIMS	Amount
Parts	14,690.00
Miscellaneous Items	0.00
Labour	5,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	20,100.00
+ GST 7.00% (S\$)	1,407.00
Nett Amount (S\$)	21,507.00

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Estimate Report

Page 2 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Feb 2018)

Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SFE2231P/12/02/2018 11:00

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET ✓	0.00	0.00	*520.00 F	✓
2	2		*FRONT BONNET HINGE LH & RH ✓	0.00	0.00	*50.00 F	✓
3	1		*FRONT BONNET CHROME MOULDING TOP ✓	0.00	0.00	*90.00 F	✓
4	1		*FRONT BONNET CHROME MOULDING LOWER ✓	0.00	0.00	*180.00 F	✓
5	1		*FRONT BONNET CENTER GARNISH - CHECK PRICE	0.00	0.00	*F	✗
6	1		*FRONT BONNET INSULATOR CENTER - CHECK PRICE	0.00	0.00	*F	✗
7	7		*FRONT BONNET INSULATOR CLIPS X 7 - CHECK PRICE	0.00	0.00	*F	✗
8	1		*FRONT BONNET INSULATOR LH ✓	0.00	0.00	*20.00 F	✓
9	5		*FRONT BONNET INSULATOR CLIPS X 5	0.00	0.00	*10.00 F	✓
10	1		*FRONT BONNET INSULATOR RH ✓	0.00	0.00	*20.00 F	✓
11	5		*FRONT BONNET INSULATOR CLIPS X 5	0.00	0.00	*10.00 F	✓
12	1		*FRONT BONNET INNER LOCK (BOTTOM)	0.00	0.00	*35.00 F	✗
13	1		*FRONT GRILLE	0.00	0.00	*120.00 F	✓
14	6		*FRONT GRILLE CLIPS X 6 ✓	0.00	0.00	*12.00 F	✓
15	2		*HEADLAMP LH & RH ✓	0.00	0.00	*2,500.00 F	✓
16	2		*HEADLAMP LOWER BEAM LH & RH	0.00	0.00	*40.00 F	✗
17	1		*HEADLAMP WASHER NOZZLE RH ✓	0.00	0.00	*50.00 F	✓
18	1		*HEADLAMP WASHER NOZZLE COVER RH ✓	0.00	0.00	*35.00 F	✓
19	1		*HEADLAMP WASHER NOZZLE HOSE RH	0.00	0.00	*45.00 F	✗
20	1		*FRONT BUMPER ✓	0.00	0.00	*300.00 F	✓
21	2		*FRONT BUMPER SIDE RETAINER LH & RH ✓	0.00	0.00	*20.00 F	✓
22	15		*FRONT BUMPER CLIPS X 15 ✓	0.00	0.00	*30.00 F	✓
23	1		*FRONT BUMPER TOW COVER RH ✓	0.00	0.00	*6.00 F	✓
24	1		*FRONT BUMPER REINFORCEMENT OUTER	0.00	0.00	*70.00 F	✓
25	1		*FRONT BUMPER REINFORCEMENT INNER ✓	0.00	0.00	*140.00 F	✓
26	2		*FOGLAMP LH & RH ✓	0.00	0.00	*280.00 F	✓
27	2		*FOGLAMP COVER WITH CHROME MOULDING LH & RH ✓	0.00	0.00	*60.00 F	✓
28	2		*FOGLAMP SIDE GRILLE LH & RH ✓	0.00	0.00	*20.00 F	✓
29	2		*FRONT FENDER LH & RH ✓	0.00	0.00	*280.00 F	✓
30	2		*FRONT FENDER COWLING LH & RH ✓	0.00	0.00	*120.00 F	✓
31	16		*FRONT FENDER COWLING CLIPS X 16 ✓	0.00	0.00	*32.00 F	✓
32	1		*RADIATOR SUPPORT PANEL ✓	0.00	0.00	*250.00 F	✓
33	1		*RADIATOR SUPPORT PANEL TOP GARNISH	0.00	0.00	*15.00 F	✓
34	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS X 8	0.00	0.00	*16.00 F	✓
35	2		*RADIATOR SUPPORT PANEL SIDE AIR GUIDE LH & RH	0.00	0.00	*30.00 F	✓
36	1		*AIR CON CONDENSER ✓	0.00	0.00	*380.00 F	✓
37	1		*AIR CON CONDENSER FAN MOTOR ASSY	0.00	0.00	*300.00 F	✗
38	1		*RADIATOR ASSY ✓	0.00	0.00	*420.00 F	✓
39	1		*RADIATOR FAN MOTOR	0.00	0.00	*150.00 F	✗
40	1		*RADIATOR FAN BLADE	0.00	0.00	*30.00 F	✗
41	1		*RADIATOR FAN COWLING	0.00	0.00	*55.00 F	✗

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00, Not valid without Reference section.
Generated using Merimen o-Claims IEAS

Estimate Report

Page 3 of 4

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	2		*RADIATOR TOP BRACKET LH & RH	0.00	0.00	*20.00 F
43	2		*RADIATOR TOP BUSH LH & RH	0.00	0.00	*8.00 F
44	2		*RADIATOR BOTTOM BUSH LH & RH	0.00	0.00	*8.00 F
45	1		*RADIATOR TOP HOSE	0.00	0.00	*23.00 F
46	1		*RADIATOR BOTTOM HOSE	0.00	0.00	*22.00 F
47	1		*RADIATOR SPARE TANK	0.00	0.00	*45.00 F
48	1		*AIR FILTER BOX TOP	0.00	0.00	*30.00 F
49	1		*AIR FILTER BOX BRACKET - CHECK PRICE	0.00	0.00	*.F
50	1		*AIR FILTER BOX LOWER	0.00	0.00	*30.00 F
51	1		*AIR FILTER	0.00	0.00	*30.00 F
52	1		*AIR DUCT (OUTER)	0.00	0.00	*35.00 F
53	2		*AIR DUCT CLIPS X 2	0.00	0.00	*4.00 F
54	1		*AIR DUCT NO.1 (FROM FILTER BOX TO TURBO) - CHECK PRICE	0.00	0.00	*.F
55	1		*AIR DUCT NO.2 (FROM FILTER BOX TO TURBO) - CHECK PRICE	0.00	0.00	*.F
56	1		*AIR DUCT NO.2 BRACKET - CHECK PRICE	0.00	0.00	*.F
57	1		*HORN RH	0.00	0.00	*25.00 F
58	1		*WIPER WASHER TANK	0.00	0.00	*50.00 F
59	1		*WIPER WASHER TANK MOTOR	0.00	0.00	*45.00 F
60	1		*FRONT AIRBAG SENSOR RH	0.00	0.00	*95.00 F
61	1		*FRONT WHEELHOUSE PANEL RH	0.00	0.00	*100.00 F
62	1		*FRONT CHASSIS RH	0.00	0.00	*300.00 F
63	1		*FRONT WHEELHOUSE PANEL TO CHASSIS PANEL RH - CHECK PRICE	0.00	0.00	*.F
64	1		*ENGINE MOUNTING LH	0.00	0.00	*125.00 F
65	1		*ENGINE MOUNTING RH	0.00	0.00	*125.00 F
66	1		*ENGINE UNDER COVER	0.00	0.00	*180.00 F
67	10		*ENGINE UNDER COVER CLIPS X 10	0.00	0.00	*20.00 F
68	1		*GEARBOX MOUNTING REAR	0.00	0.00	*70.00 F
69	2		*FRONT WHEEL BEARING LH & RH	0.00	0.00	*220.00 F
70	2		*FRONT KNUCKLE ARM LH & RH	0.00	0.00	*280.00 F
71	2		*FRONT LOWER ARM LH & RH	0.00	0.00	*500.00 F
72	2		*FRONT LOWER ARM BALL JOINT LH & RH	0.00	0.00	*500.00 F
73	2		*FRONT TIE ROD END LH & RH	0.00	0.00	*90.00 F
74	2		*FRONT TIE ROD END BALL JOINT LH & RH RACK END	0.00	0.00	*100.00 F
75	1		*FRONT STABILISER BAR	0.00	0.00	*100.00 F
76	2		*FRONT STABILISER LINKAGE LH & RH	0.00	0.00	*70.00 F
77	2		*FRONT DRIVE SHAFT LH & RH	0.00	0.00	*900.00 F
78	1		*FRONT STEERING RACK	0.00	0.00	*1,350.00 F
79	2		*FRONT ABS SENSOR LH & RH	0.00	0.00	*270.00 F
80	2		*FRONT SHOCK ABSORBER LH & RH	0.00	0.00	*280.00 F
81	2		*FRONT SHOCK ABSORBER TOP MOUNTING LH & RH	0.00	0.00	*144.00 F
82	1		*FRONT CROSSMEMBER	0.00	0.00	*250.00 F
83	2		*REAR WHEEL BEARING RH	0.00	0.00	*220.00 F
84	1		*REAR LOWER ARM RH	0.00	0.00	*100.00 F
85	1		*REAR SIDE ARM RH	0.00	0.00	*100.00 F
86	1		*REAR CONTROL ARM RH	0.00	0.00	*160.00 F
87	2		*REAR KNUCKLE ARM RH	0.00	0.00	*280.00 F
88	1		*REAR UPPER ARM RH	0.00	0.00	*240.00 F
89	1		*REAR SHOCK ABSORBER RH	0.00	0.00	*135.00 F
90	1		*REAR ABS SENSOR RH	0.00	0.00	*125.00 F
91	1		*REAR STABILISER LINKAGE RH	0.00	0.00	*40.00 F
92	2		*SPORT RIM LHF; RHF; RHR - CHECK PRICE	0.00	0.00	*450.00 FS
93	2		*TYRE LHF; RHF; RHR - CHECK PRICE	0.00	0.00	*390.00 FS
94	1		*COOLANT	0.00	0.00	*30.00 FS

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
95	1		*BRAKE OIL	0	0.00	*30.00 FS
96	1		*HEADLAMP SIGNAL BULB	0	0.00	*15.00 FS
97	1		*HEADLAMP HIGH BEAM BLUB	0	0.00	*15.00 FS
98	1		*HEADLAMP LOW BEAM BULB	0	0.00	*15.00 FS
Total Parts (S\$)						14,690.00

F=Franchise part S=SpcNott

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 201
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00 ✓
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00 ✓
4	TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	New 280 nn	380.00 X
5	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (FRONT)	New	450.00 320
6	TO DISMANTLE AND REPLACE UNDERCARRIAGE (REAR)	New	380.00 150
7	TO REMOVE AND REPLACE ENGINE MOUNTING & GEARBOX MOUNTING	New	120.00 X
8	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	380.00 200
9	TO REMOVE AND REPLACE AIR BAG SENSOR	New nn	80.00 X
10	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL;FRONT WHEELHOUSE PANEL RH;FRONT CHASSIS RH. TO KNOCK & REPAIR FRONT WHEELHOUSE LH; FRONT CHASSIS LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New 1400.	2,000.00 1100
11	TO SPRAY FRONT BONNET;FRONT BUMPER;FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL;FRONT WHEELHOUSE PANEL LH & RH; FRONT CHASSIS LH & RH	New 1300	1,400.00 1100
Gross Labour Cost (S\$)			5,410.00

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

00 / 8WD

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2017-00007809	Date of Loss:	30/01/2018
Vehicle Reg. No.:	SFE2231P	Driveable?	
Driver Age/Info:	49 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM CHWEE HWA	Contact No:	+6596573320
Driver:	LIM CHWEE HWA		
Make/Model:	SUBARU FORESTER, 2.0 XT AWD CVT (A)	Vehicle Reg. Date:	08/11/2016
Vehicle Colour:	BROWN	Chassis No:	JF1SJGK85GG079871
Engine No:	FA20B857723		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	20 / 1 day		
Description of Accident/Loss	REFER TO THE GIA REPORT.		
Remarks:	CAR IS IN OUR WORKSHOP (TOW IN) ON 9/2/18		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

Not Authorised
1. B. I
Resurvey B4 paint
Ex 8500
Fix: 62564315

COST OF CLAIMS

	Amount
Parts	14,690.00
Miscellaneous Items	0.00
Labour	5,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	20,100.00
+ GST 7.00% (S\$)	1,407.00
Nett Amount (S\$)	21,507.00

This claim is handled by: EILEEN CHUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Feb 2018)
Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ah Lim Motor Company/SFE2231P/12/02/2018 11:00
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET	R1	0.00	0.00	*520.00 F	✓
2	2		*FRONT BONNET HINGE LH & RH	D11	0.00	0.00	*50.00 F	✓
3	1		*FRONT BONNET CHROME MOULDING TOP	m31RA	0.00	0.00	*90.00 F	✓
4	1		*FRONT BONNET CHROME MOULDING LOWER	nu	0.00	0.00	*180.00 F	✓
5	1		*FRONT BONNET CENTER GARNISH - CHECK PRICE		0.00	0.00	*-F	?
6	1		*FRONT BONNET INSULATOR CENTER - CHECK PRICE		0.00	0.00	*-F	?
7	7		*FRONT BONNET INSULATOR CLIPS X 7 - CHECK PRICE		0.00	0.00	*-F	?
8	1		*FRONT BONNET INSULATOR LH	CM	0.00	0.00	*20.00 F	✓
9	5		*FRONT BONNET INSULATOR CLIPS X 5	nu	0.00	0.00	*10.00 F	✓
10	1		*FRONT BONNET INSULATOR RH	CM	0.00	0.00	*20.00 F	✓
11	5		*FRONT BONNET INSULATOR CLIPS X 5	nu	0.00	0.00	*10.00 F	✓
12	1		*FRONT BONNET INNER LOCK (BOTTOM)		0.00	0.00	*35.00 F	?
13	1		*FRONT GRILLE	CM	0.00	0.00	*120.00 F	✓
14	6		*FRONT GRILLE CLIPS X 6	nu	0.00	0.00	*12.00 F	✓
15	2		*HEADLAMP LH & RH	c/s nu	0.00	0.00	*2,500.00 F	✓
16	2		*HEADLAMP LOWER BEAM LH & RH	c/s R1	0.00	0.00	*40.00 F	✓
17	1		*HEADLAMP WASHER NOZZLE RH	m11	0.00	0.00	*50.00 F	✓
18	1		*HEADLAMP WASHER NOZZLE COVER RH	m11	0.00	0.00	*35.00 F	✓
19	1		*HEADLAMP WASHER NOZZLE HOSE RH		0.00	0.00	*45.00 F	?
20	1		*FRONT BUMPER	T1	0.00	0.00	*300.00 F	✓
21	2		*FRONT BUMPER SIDE RETAINER LH & RH	m11	0.00	0.00	*20.00 F	✓
22	15		*FRONT BUMPER CLIPS X 15	nu	0.00	0.00	*30.00 F	✓
23	1		*FRONT BUMPER TOW COVER RH	nu	0.00	0.00	*6.00 F	✓
24	1		*FRONT BUMPER REINFORCEMENT OUTER	R1	0.00	0.00	*70.00 F	✓
25	1		*FRONT BUMPER REINFORCEMENT INNER		0.00	0.00	*140.00 F	?
26	2		*FOGLAMP LH & RH	c/s nu	0.00	0.00	*280.00 F	✓
27	2		*FOGLAMP COVER WITH CHROME MOULDING LH & RH	c/s m11	0.00	0.00	*60.00 F	✓
28	2		*FOGLAMP SIDE GRILLE LH & RH	c/s m11	0.00	0.00	*20.00 F	✓
29	2		*FRONT FENDER LH & RH	c/s R1	0.00	0.00	*280.00 F	✓
30	2		*FRONT FENDER COWLING LH & RH	c/s nu	0.00	0.00	*120.00 F	✓
31	16		*FRONT FENDER COWLING CLIPS X 16	nu	0.00	0.00	*32.00 F	✓
32	1		*RADIATOR SUPPORT PANEL	R1	0.00	0.00	*250.00 F	✓
33	1		*RADIATOR SUPPORT PANEL TOP GARNISH	CM	0.00	0.00	*15.00 F	✓
34	8		*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS X 8	nu	0.00	0.00	*16.00 F	✓
35	2		*RADIATOR SUPPORT PANEL SIDE AIR GUIDE LH & RH	c/s m11	0.00	0.00	*30.00 F	✓
36	1		*AIR CON CONDENSER		0.00	0.00	*380.00 F	?
37	1		*AIR CON CONDENSER FAN MOTOR ASSY		0.00	0.00	*300.00 F	?
38	1		*RADIATOR ASSY		0.00	0.00	*420.00 F	?
39	1		*RADIATOR FAN MOTOR		0.00	0.00	*150.00 F	?
40	1		*RADIATOR FAN BLADE		0.00	0.00	*30.00 F	?
41	1		*RADIATOR FAN COWLING		0.00	0.00	*55.00 F	?

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
42	2		*RADIATOR TOP BRACKET LH & RH	0.00	0.00	*20.00 F	?
43	2		*RADIATOR TOP BUSH LH & RH	0.00	0.00	*8.00 F	?
44	2		*RADIATOR BOTTOM BUSH LH & RH	0.00	0.00	*8.00 F	?
45	1		*RADIATOR TOP HOSE	0.00	0.00	*23.00 F	?
46	1		*RADIATOR BOTTOM HOSE	0.00	0.00	*22.00 F	?
47	1		*RADIATOR SPARE TANK	Sm 0.00	0.00	*45.00 F	X
48	1		*AIR FILTER BOX TOP	0.00	0.00	*30.00 F	?
49	1		*AIR FILTER BOX BRACKET - CHECK PRICE	0.00	0.00	*-F	
50	1		*AIR FILTER BOX LOWER	0.00	0.00	*30.00 F	?
51	1		*AIR FILTER	Sm 0.00	0.00	*30.00 F	X
52	1		*AIR DUCT (OUTER)	Pod 0.00	0.00	*35.00 F	✓
53	2		*AIR DUCT CLIPS X 2	Me 0.00	0.00	*4.00 F	✓
54	1		*AIR DUCT NO.1 (FROM FILTER BOX TO TURBO) - CHECK PRICE	0.00	0.00	*-F	
55	1		*AIR DUCT NO.2 (FROM FILTER BOX TO TURBO) - CHECK PRICE	0.00	0.00	*-F	
56	1		*AIR DUCT NO.2 BRACKET - CHECK PRICE	0.00	0.00	*-F	
57	1		*HORN RH	0.00	0.00	*25.00 F	?
58	1		*WIPER WASHER TANK	0.00	0.00	*50.00 F	?
59	1		*WIPER WASHER TANK MOTOR	Sm 0.00	0.00	*45.00 F	X
60	1		*FRONT AIRBAG SENSOR RH	0.00	0.00	*95.00 F	?
61	1		*FRONT WHEELHOUSE PANEL RH	R 0.00	0.00	*100.00 F	X
62	1		*FRONT CHASSIS RH	R 0.00	0.00	*300.00 F	X
63	1		*FRONT WHEELHOUSE PANEL TO CHASSIS PANEL RH - CHECK PRICE	0.00	0.00	*-F	
64	1		*ENGINE MOUNTING LH	0.00	0.00	*125.00 F	?
65	1		*ENGINE MOUNTING RH	0.00	0.00	*125.00 F	?
66	1		*ENGINE UNDER COVER	Sm 0.00	0.00	*180.00 F	X
67	10		*ENGINE UNDER COVER CLIPS X 10	nn 0.00	0.00	*20.00 F	X
68	1		*GEARBOX MOUNTING REAR	0.00	0.00	*70.00 F	?
69	2		*FRONT WHEEL BEARING LH & RH	o/s R1 N/S ? 0.00	0.00	*220.00 F	✓
70	2		*FRONT KNUCKLE ARM LH & RH	o/s R1 N/S ? 0.00	0.00	*280.00 F	✓
71	2		*FRONT LOWER ARM LH & RH	N/S ? o/s R1 0.00	0.00	*500.00 F	✓
72	2		*FRONT LOWER ARM BALL JOINT LH & RH	0.00	0.00	*500.00 F	?
73	2		*FRONT TIE ROD END LH & RH	0.00	0.00	*90.00 F	?
74	2		*FRONT TIE ROD END BALL JOINT LH & RH RACK END	0.00	0.00	*100.00 F	?
75	1		*FRONT STABILISER BAR	0.00	0.00	*100.00 F	?
76	2		*FRONT STABILISER LINKAGE LH & RH	0.00	0.00	*70.00 F	?
77	2		*FRONT DRIVE SHAFT LH & RH	0.00	0.00	*900.00 F	?
78	1		*FRONT STEERING RACK	0.00	0.00	*1,350.00 F	?
79	2		*FRONT ABS SENSOR LH & RH	Sm 0.00	0.00	*270.00 F	X
80	2		*FRONT SHOCK ABSORBER LH & RH	o/s R1 N/S ? 0.00	0.00	*280.00 F	✓
81	2		*FRONT SHOCK ABSORBER TOP MOUNTING LH & RH	0.00	0.00	*144.00 F	?
82	1		*FRONT CROSSMEMBER	0.00	0.00	*250.00 F	?
83	2		*REAR WHEEL BEARING RH	0.00	0.00	*220.00 F	?
84	1		*REAR LOWER ARM RH	R1 0.00	0.00	*100.00 F	✓
85	1		*REAR SIDE ARM RH	0.00	0.00	*100.00 F	?
86	1		*REAR CONTROL ARM RH	0.00	0.00	*160.00 F	?
87	2		*REAR KNUCKLE ARM RH	R1 0.00	0.00	*280.00 F	✓
88	1		*REAR UPPER ARM RH	0.00	0.00	*240.00 F	?
89	1		*REAR SHOCK ABSORBER RH	0.00	0.00	*135.00 F	?
90	1		*REAR ABS SENSOR RH	Sm 0.00	0.00	*125.00 F	X
91	1		*REAR STABILISER LINKAGE RH	0.00	0.00	*40.00 F	?
92	2		*SPORT RIM LHF; RHF; RHR - CHECK PRICE	Pod 0	0.00	*-FS	✓
93	2		*TYRE LHF; RHF; RHR - CHECK PRICE	At o/s puc 70? 0	0.00	*-FS	?
94	1		*COOLANT	Me 0	0.00	*30.00 FS	✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
95	1		*BRAKE OIL	<i>nr</i> 0	0.00	*30.00 FS	<i>—</i>
96	1		*HEADLAMP SIGNAL BULB	<i>nr</i> 0	0.00	*15.00 FS	<i>—</i>
97	1		*HEADLAMP HIGH BEAM BLUB	<i>nr</i> 0	0.00	*15.00 FS	<i>—</i>
98	1		*HEADLAMP LOW BEAM BULB	<i>nr</i> 0	0.00	*15.00 FS	<i>—</i>
F=Franchise part. S=SpcNett.						Total Parts (S\$)	14,690.00

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount	
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	<i>200</i>
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00	<i>✓</i>
3	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00	<i>✓</i>
4	TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	New	<i>nr</i> 380.00	<i>x</i>
5	TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. (FRONT)	New	450.00	<i>320</i>
6	TO DISMANTLE AND REPLACE UNDERCARRIAGE (REAR)	New	380.00	<i>1500</i>
7	TO REMOVE AND REPLACE ENGINE MOUNTING & GEARBOX MOUNTING	New	120.00	<i>?</i>
8	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	380.00	<i>?</i>
9	TO REMOVE AND REPLACE AIR BAG SENSOR	New	80.00	<i>?</i>
10	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL; FRONT WHEELHOUSE PANEL RH; FRONT CHASSIS RH. TO KNOCK & REPAIR FRONT WHEELHOUSE LH; FRONT CHASSIS LH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2,000.00	<i>11000</i>
11	TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL; FRONT WHEELHOUSE PANEL LH & RH; FRONT CHASSIS LH & RH	New	1,400.00	<i>11000</i>
Gross Labour Cost (S\$)			5,410.00	

Ah Lim Motor Company/SFE2231P/12/02/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3564H

Vehicle Details

Vehicle No.: SFE2231P

Vehicle to be Exported: Yes

Intended De-registration
Date: 09 Feb 2018

Vehicle Make: SUBARU

Vehicle Model: FORESTER 2.0XT CVT
AWD SR

\$ 106 K

Primary Colour: Brown

Manufacturing Year: 2016

Engine No.: FA20B857723

Chassis No.: JF15JGK85GG079871

Maximum Power Output: 177.0 kW (237 bhp)

Open Market Value: \$20,817.00

Original Registration Date: 08 Nov 2016

First Registration Date: 08 Nov 2016

Transfer Count: 0

Actual ARF Paid: \$21,144.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 07 Nov 2026

PARF Rebate Amount: \$15,858.00

Intended COE Rebate Details

COE Expiry Date: 07 Nov 2026

COE Category: B - Car above 1600cc or
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$55,501.00

COE Rebate Amount: \$44,400.00

Total Rebate Amount: \$60,258.00

The information contained herein is correct as at 09 Feb 2018

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Mar 2018)

Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ah Lim Motor Company/SFE2231P/07/03/2018 10:45

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*ENGINE VALVE OIL CONTROL RH	CM	0.00	+0.00	*118.00 F
2	1		*FRONT GRILLE TOP SIDE STOPPER RH	nif	0.00	+0.00	*5.00 F
3	1		*FRONT JOINT STEERING COUPLING	B1	0.00	+0.00	*250.00 F
4	1		*INTAKE AIR DUCT	Del	0.00	0.00	*140.00 F
5	1		*WHEEL HOSE SIDE PANEL RH	B1	0.00	+0.00	*110.00 F
6	1		*SUPPORT LOWER INNER PANEL	B1	0.00	+0.00	*60.00 F
7	1		*CHASSIS FRAME BRACKET RH	B1	0.00	+0.00	*15.00 F
8	1		*BATTERY TRAY	Del	0.00	+0.00	*8.00 F
9	1		*BUMPER AIR DUCT	CM	0.00	+0.00	*10.00 F
10	1		*BUMPER SIDE GRILLE RH	nif	0.00	+0.00	*10.00 F
11	1		*HEADLAMP NOZZLE LH	CP1	0.00	+0.00	*50.00 F
12	1		*TURBO AIR DUCT HOSE RH	Del/Let	0.00	+0.00	*140.00 F
13	1		*ENGINE UNDER COVER	B1	0.00	+0.00	*180.00 F

F=Franchise part.

Total Parts (S\$) 1,096.00

Ah Lim Motor Company/SFE2231P/07/03/2018 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Ah Lim Motor Company/SFE2231P/07/03/2018 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >