

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Han

Date: 23 Feb 2018

**Preliminary Advice**

Vehicle No	: SKA799T	Accident Date	: 02/02/2018
Make	: MERCEDES-BENZ C200	Policy No.	: DMPCSN3102791600
Assignment Date	: 12/02/2018	Excess	: S\$50.00
Date of Inspection	: 22/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: CHENG AUTO BODYWORKS (HQ) 5 SOON LEE STREET #01-62 PIONEER POINT SINGAPORE 627607		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,324.54
Revised Amount	:S\$	10,007.62
Check Items (Estimated)	:S\$	1,611.75
Total	:S\$	11,619.37
 Lump Sum Repair	 :S\$	 9,300.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	39,140.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,860.00

**Remarks**

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :