

15/02/18

INS. CASE OWNER:

Lynn

CC6 / EQ118002841 10y535V

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

13/02/18

Date / Time:

12/02/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGY 4996K

Name of Insured:

WONG KIN WAH

Insured Tel No.:

HP: 9711 0026

Excess Sec II :SS

D.O.A.: 11/02/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

DMPPHQ18-000489

Make / Model:

HONDA CIVIC

Place of Accident:

JUNCTION OF BEDDOE NORTH & AVE 1

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGY 6995A



INSRS:

WSP: Hup Motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
20/02/18 (JSS)	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	21/02/18 - M
	After call ltr to OI:	
20/02/18 @ 10:25	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☐
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE Date/Time: 14/02/18 Sent By: Shirley Hwee

FINALIZATION Date/Time: Confirm with: Confirm by: Email ☐ Call ☐

Repair Cost: SS 1,800 (4 days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 10/3/18 Confirm with: Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:

Repair Cost: SS 1,800.00

Loss of Rental (LOR): 120 SS 480.00 (4 days)

Loss of Use (LOU): SS (5 x days)

Loss of Income (LOI): SS (5 x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: SS 2.00

Medical: SS

Disbursement: SS (e.g. Tow/ Independent)

Legal Cost: SS

Total: SS 2,282.00 Global Sum SS: Email ☐ Call ☐

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: SS 2,282.00 Name 1: Hup Motor Trading & Service

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ18002841/Uus3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 13-02-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGY 4996K	Veh. Inspected	SGY 6995A	
Policy No.	DMPPHQ18-000489	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/02/2018	Inspection Date	13/02/2018	
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2887/02/18 Your Ref: _____ Date: 12th February 2018

MR CHOO CHIN KIAT
BLK 896, #13-876
TAMPINES STREET 81
SINGAPORE 520896

Estimate cost of repair to HONDA ACCORD 2.4 (A) Saloon - SGY 6995 A

1 pc rear bumper	<i>DO/A</i>		\$ 769.10	✓
8 pcs rear bumper clips	<i>me</i>	@ \$ 3.90	31.20	✓
2 pcs rear bumper o/s & n/s side retainer	<i>set</i>	@ \$ 28.60	57.20	✓
2 pcs rear bumper o/s & n/s top retainer	<i>set</i>	@ \$ 19.70	39.40	✓
1 pc rear bumper sponge damper	<i>NT</i>		65.00	✓
1 pc rear bumper reinforcement	<i>set</i>		135.40	✓
2 pcs rear bumper centre reverse sensor		@ \$ 203.50	407.00	✓
2 pcs rear bumper o/s & n/s reverse sensor		@ \$ 203.50	407.00	X
1 pc boot lid 'Accord' emblem			28.20	X
1 pc boot lid '2.4-Vtec' emblem			59.90	X
			\$ 1,999.40	1439.3
Less 20%			\$ 399.88	1139.42
			\$ 1,599.52	

To wiring check up for reverse sensor.

40.00 ✓

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre & tool set, for enable repair boot lid, rear end panel & necessary parts.

120.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out boot lid, rear end panel & necessary parts, to weld, renew & align above parts.

500.00 400

To putty & respray painting on all affected accident parts.

750.00 500

\$ 3,009.52
===== 1000
2139.42

Dollars : Three Thousand Nine Dollars And Cents Fifty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
2/15/18
4 days
13/2/18
Wright to other agent



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQI18002841/Uus3

Date: 14.02.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SGY 6995A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.02.2018 at the premises of M/s Hup Motor Trading & Service (Tampines) and have the following to report:-

Workshop Estimate Amount	: S\$	3,009.52
Revised Estimate Amount	: S\$	2,043.12
"Check" Items Amount	: S\$	160.32
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Remarks :

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Shirley Hiew (LKK Auto)

From: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>
Sent: Wednesday, 14 February 2018 4:02 PM
To: Shirley Hiew (LKK Auto); Thin Thin (LKKAuto)
Cc: Jas Khine (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SGY4996K (OI : EQI - TBA) AND SGY6995A (TP : LKK REF - CC6/EQI18002841/us3) on 11/02/2018
Attachments: SGY4996K 11.02.2018.pdf

Dear Shirley

Please find attached our insured GIA report

Thank You.

Regards,
Lynn Ahmad
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, February 13, 2018 10:44 AM
To: Bazlin Ahmad; Thin Thin (LKKAuto)
Cc: Jas Khine (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SGY4996K (OI : EQI - TBA) AND SGY6995A (TP : LKK REF - CC6/EQI18002841/us3) on 11/02/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Hup Motor Trading & Service - Tampines.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair

We have not authorized repairs.

We will revert preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 15/03/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SGY 4996K (Insd Veh)	Your Ref. No. : DMPPHQ18-000489
	SGY 6995A (TP Veh)	Our Ref. No. : CC6/EQ118002841/Uys3s2
Date of Accident	11/2/2018	

Liability	100%	
Final Repair Cost	: \$ 1,800.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 480.00	4 days
Others:	: \$ 2.00	
	: \$	
	2,282.00	
Final Settlement Sum	: \$ 2,282.00	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	HUP MOTOR TRADING & SERVICE	: \$ 2,282.00
		: \$

NUR SHAQILAH
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI18002841/Uys3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 15-03-2018



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGY 4996K	Veh. Inspected	SGY 6995A
Policy No.	DMPPHQ18-000489	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ACCORD (A)	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MRHCP26308P020446	Colour	GREY
Odometer	270667	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R17	GOODYEAR	6 mm
L/H Front Tyre	225/50R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PROTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2018	Inspection Date	13/02/2018
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 6995A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	769.10	769.10
8	REAR BUMPER CLIPS @ \$3.90	NECESSARY	31.20	31.20
2	REAR BUMPER O/S & N/S SIDE RETAINER @ \$28.60	BENT	57.20	57.20
2	REAR BUMPER O/S & N/S TOP RETAINER @ \$19.70	BENT	39.40	39.40
1	REAR BUMPER SPONGE DAMPER	NOT FITTED	65.00	-
1	REAR BUMPER REINFORCEMENT	BENT	135.40	135.40
2	REAR BUMPER CENTRE REVERSE SENSOR @ \$203.50	SHORTED	407.00	407.00
2	REAR BUMPER O/S & N/S REVERSE SENSOR @ \$203.50	NOT NECESSARY	407.00	-
1	BOOT LID 'ACCORD' EMBLEM	NOT NECESSARY	28.20	-
1	BOOT LID '2.4-VTEC' EMBLEM	NOT NECESSARY	59.90	-
	LESS 20% DISCOUNT		-399.88	-287.86
			1,599.52	1,151.44
LABOUR				
	TO WIRING CHECK UP FOR REVERSE SENSOR.		40.00	40.00
	TO REMOVE & REFIX CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, SPARE TYRE & TOOL SET, FOR ENABLE REPAIR BOOT LID, REAR END PANEL & NECESSARY PARTS.		120.00	60.00
	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT BOOT LID, REAR END PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.		500.00	400.00
	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.		750.00	500.00
			1,410.00	1,000.00
GRAND TOTAL			3,009.52	2,151.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,800.00

Report Ref No. CC6/EQ18002841/Uys3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.