

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2887/02/18 Your Ref: _____ Date: 12th February 2018

MR CHOO CHIN KIAT
BLK 896, #13-876
TAMPINES STREET 81
SINGAPORE 520896

Estimate cost of repair to HONDA ACCORD 2.4 (A) Saloon - SGY 6995 A

1 pc rear bumper	20/22		\$ 769.10	✓
8 pcs rear bumper clips	mc	@ \$ 3.90	31.20	✓
2 pcs rear bumper o/s & n/s side retainer	4/4	@ \$ 28.60	57.20	✓
2 pcs rear bumper o/s & n/s top retainer	4/4	@ \$ 19.70	39.40	✓
1 pc rear bumper sponge damper			65.00	>
1 pc rear bumper reinforcement			135.40	7
2 pcs rear bumper centre reverse sensor		@ \$ 203.50	407.00	✓
2 pcs rear bumper o/s & n/s reverse sensor		@ \$ 203.50	407.00	X
1 pc boot lid 'Accord' emblem			28.20	X
1 pc boot lid '2.4-Vtec' emblem			59.90	X
			\$ 1,999.40	
		Less 20%	\$ 399.88	
			\$ 1,599.52	

To wiring check up for reverse sensor.

40.00 ✓

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre & tool set, for enable repair boot lid, rear end panel & necessary parts.

120.00 60

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out boot lid, rear end panel & necessary parts, to weld, renew & align above parts.

500.00 400

To putty & respray painting on all affected accident parts.

750.00 500

\$ 3,009.52

=====

Dollars : Three Thousand Nine Dollars And Cents Fifty Two Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
2/15/18
4 days
13/2/18
Weight to Attorney