

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2887/02/18 Your Ref: \_\_\_\_\_ Date: 12th February 2018

MR CHOO CHIN KIAT  
BLK 896, #13-876  
TAMPINES STREET 81  
SINGAPORE 520896

### Estimate cost of repair to HONDA ACCORD 2.4 (A) Saloon - SGY 6995 A

|                                            |             |           |
|--------------------------------------------|-------------|-----------|
| 1 pc rear bumper                           |             | \$ 769.10 |
| 8 pcs rear bumper clips                    | @ \$ 3.90   | 31.20     |
| 2 pcs rear bumper o/s & n/s side retainer  | @ \$ 28.60  | 57.20     |
| 2 pcs rear bumper o/s & n/s top retainer   | @ \$ 19.70  | 39.40     |
| 1 pc rear bumper sponge damper             |             | 65.00     |
| 1 pc rear bumper reinforcement             |             | 135.40    |
| 2 pcs rear bumper centre reverse sensor    | @ \$ 203.50 | 407.00    |
| 2 pcs rear bumper o/s & n/s reverse sensor | @ \$ 203.50 | 407.00    |
| 1 pc boot lid 'Accord' emblem              |             | 28.20     |
| 1 pc boot lid '2.4-Vtec' emblem            |             | 59.90     |

Less 20% \$ 1,999.40  
\$ 399.88

\$ 1,599.52

To wiring check up for reverse sensor. 40.00

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre & tool set, for enable repair boot lid, rear end panel & necessary parts. 120.00

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out boot lid, rear end panel & necessary parts, to weld, renew & align above parts. 500.00

To putty & respray painting on all affected accident parts. 750.00

\$ 3,009.52

=====

Dollars : Three Thousand Nine Dollars And Cents Fifty Two Only.

HUP MOTOR TRADING & SERVICE

