

ASS. REC. BY:

REF: CS/MSG18002853/K/d30

Special Instruction:

Surveyor: Kenneth
Merimen

ASSIGNMENT (Office)

From (Person): Katherine Wong

of MSG

Date/Time: 13/2/18 @ 10:35am

Estimated Cost:

Bill to:

OD / ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 3290S

Insured:

GBD 1013L

at Workshop n/s

Motor Image

Tel:

of 19 Lorong 8 Toa Payoh

Policy No. 2895 2568 MKC

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 9/2/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 12:11pm @ 13/2/18

Person Contacted:

Sayed

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 3290S - X
	GBD 1013L - X
14/2-	Report via merimen preli
2/7	\$5288.32 Confirm by email (Red: 7493, 59%)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/2 File party to Catherine

RECEIVED 02 JUL 2018

Date/Time, File Pass to?

11/7 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Phone

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

5288.32

Veh No:

SL532905

Yr Regn:

09, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Impreza

c.c.

1600

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading:

2890

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF16K3K05146.009684

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

205/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

9/2/18

D.O.I.

13/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		13 Feb 2018 10:35 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	Kian Hong Aluminium Works Pte Ltd, Co. Reg. No.: 200808814K		
Main Claimant:	Tan Hou Hock, ID: S8513763H		
Vehicle Reg. No.:	SLS3290S	Date of Loss:	09/02/2018 17:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28952568MKC Coverage: 16/06/2017 - 15/06/2018
Vehicle Reg. No. (Insured):	GBD1013L	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Image Enterprises Pte Ltd (HQ) 19 LORONG B TOA PAYOH, 319255 Toa Payoh - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/02/2018]		
Adj Asg. Remarks:	Survey - Car In. Thank You.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002853/Ktd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1013L	Veh. Inspected	SLS 3290S
Policy No.	28952568MKC	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (KATHERINE WONG)	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/02/2018	Inspection Date	13/02/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2018 10:15
Date Of Accident	09/02/2018 17:40
Exact Location Of Accident	PIE ABOUT 100M BEFORE WOODSVILLE FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS3290S
Insured/Policyholder	
Name Of Registered Owner	TAN HOU HOCK
NRIC No	S8513763H
Email Address	TANHOUHOCK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94761466
Alternative Phone No	HOME-67464193

Vehicle Particulars

Manufacturer	SUBARU
Model	IMPREZA-1.6I SEDAN (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700054366
Cover Note Number	

Driver

Name of Driver	TAN HOU HOCK
NRIC No	S8513763H
Date Of Birth	29/04/1985
Occupation	INDOOR
Date Of Driving Pass	09/04/2009
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94761466
Fax Number	
Contact Number	HOME-67464193
Email Address	TANHOUHOCK@GMAIL.COM

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 16/12/2018
0850

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre's Signature
Name: _____
NRIC/IN No.: _____

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


It was heavy traffic on PIE, and I was moving slowly with other vehicles. Suddenly, the lorry hit me from my right rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: 
 Date & Time: 10/12/2018
 0850

Driver's Signature:
 (If driver is not the policyholder)
 Date & Time:

Reported by Personnel's Signature: 
 Name:
 NRIC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 9, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0627/2018
DATE : 10-FEB-2018

MEIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6627 7880
FAX : 66431349/6627 7809
7313 DAVID

OWNER'S NAME : TAN HOU HOCK
ADDRESS : APT BLK 61 CIRCUIT ROAD #03-221
S(378061)
TELEPHONE NO : 94761466

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700054366
VEHICLE NO : SLB32908
MODEL CODE : GK3AK2C
MODEL/YEAR : IMPREZA 4D 1.6I-S AND CVT
ENGINE NO : FB16YA95190
CHASSIS NO : JF1GK3KC5HG004684
MILEAGE : 1 KM
DATE IN : 10/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 09/02/2018

Print Date : 10/02/2018
Print Time : 15:44:21

MCORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TDA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SL832908

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDU
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	22/001	CONDUCT TP CLAIM MSIG LOCATION:PIK ABOUT 100M BEFORE WOODSVILLE FLYOVER DATE09/02/2018 TIME:1740		
3	22/002	REMOVE/REFIX REAR BUMPER,PANEL,BOOTLID,REAR LH RH FENDER	2800.00	16801
4	22/003	RESPRAY REAR BUMPER,PANEL,BOOTLID,REAR LH RH FENDER	2100.00	16801
5	22/004	DISMANTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	nn 300.00	X
6	22/005	REMOVE AND REFIX EXHAUST	nn 150.00	X
7	22/006	TO CONDUCT WATER SEEPAGE TEST	100.00	501
8	22/007	TRANSFER(BOOTLID)MECHANISM	150.00	1001
9	22/008	TO CONDUCT(REAR)LIGHTING TEST	50.00	✓
10	22/009	SUNDRIES	100.00	301
TOTAL LABOUR CHARGES			5750.00	

27
t

624*+
57*6+
202*9+
378*+
201*6+
72*+
79*2+
36*+
=
1,651*3+
1,651*3+
453*6+
18*+
=
2,172*9+
2,172*9+
80*+
1,698*32+
0*0
1,680*+
1,680*+
50*+
110*+
50*+
30*+
=
3,590*+
3,590*+
1,698*32+
=
5,278*32+
378*+
201*6+
72*+
79*2+
36*+
1,448*+
1,448*+
80*+
1,158*+
0*0
3,590*+
1,158*+
4,748*+
4,748*0

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL532905

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1	GASKET	44011EG000	Sm 14.00	X			
2	EKH PIPE ASSY R SIS	44200FL130	R 493.20	✓			
3	MUFFLER ASSY RH	44300FL080	R 504.00	X			
4	TAIL PIPE CUTTER	44370FL000	Sm 72.00	X			
5	PNL SD OUT QTR RHH	51439FL1409P	R 946.80	X			
6	PNL SD OUT QTR RPSLN	51439FL1509P	R 946.80	X			
7	R FLOOR PANEL 4D	52129FL0319P	R 432.00	X			
8	SKIRT COMPL R 4D	52401FL0309P	Sm 263.30	X			
9	TRUNK LID COMPL	57509FL0109P	Sm 624.00	✓			
10	LOCK AY TRUNK	57530AJ050	R 158.40	X			
11	WSTR TRUNK	57532FL010	O/R 57.60	✓			
12	BRKT SD R 4D FHI RH	57707FL380	R 30.60	X			
13	BRKT SD R 4D FHI LH	57707FL390	R 30.60	X			
14	BEAM COMPL R EU	USE FL0409P 57711FL0419P	R 202.90	✓			
15	COVER HOOK R 4D FHI	57731FL560NH	Sm 9.00	X			
16	LENS & BODY COMPLRH	84912FL100	COY 378.00	✓			
17	LENS & BODY COMPL LH	84912FL110	Sm 378.00	X			
18	LENS & BODY COMPL LH	84912FL13A	Sm 201.60	X			
19	LENS & BODY COMPLRH (SUPP)	84912FL140	Sm 201.60	✓			
20	RADAR ASSY R & E	87611FL000	Sm 2160.00	X			
21	RADAR BRACKET 4D RH	87613FL020	R 11.90	X			
22	RADAR BRACKET 4D LH	87613FL030	R 11.90	X			
23	ORNAMENT ASSY F SIX	911748A170	Sm 72.00	✓			
24	LETTER MK R	93079FL020	Sm 79.20	✓			
25	LETTER MK R IMP	93079FL050	Sm 36.00	✓			

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK12908

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
SUB TOTAL			8317.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1461.48	0.00	0.00	0.00
GRAND TOTAL			6653.92	0.00	0.00	0.00
OVERALL TOTAL			6653.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLS32908

TOTAL LABOUR CHARGES	5750.00
TOTAL SPARE PARTS CHARGES	6653.92

GRAND TOTAL	12403.92 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLEASE NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Authorized
1.B.1
Resurvey B4 paint
6 days

12381.20

LIG Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be recognized and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0627/2018
DATE : 10-FEB-2018

MSIG INSURANCE (SINGAPORE) PTE LTD
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
S(048581)
TEL : 66431335/6827 7880
FAX : 66431349/6827 7809
7313 DAVID

OWNER'S NAME : TAN HOU HOCK
ADDRESS : APT BLK 61 CIRCUIT ROAD #05-221

S(370061)
TELEPHONE NO : 94761466

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700054366
VEHICLE NO : SLS32908
MODEL CODE : GE3AK2C
MODEL/YEAR : IMPREZA 4D 1.6I-S AWD CVT
ENGINE NO : FB16YA95190
CHASSIS NO : JF1GK3HC5HG004684
MILEAGE : 2891 KM
DATE IN : 10/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 09/02/2018

Print Date : 28/06/2018
Print Time : 10:27:07

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8; TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLS3290S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM MSIG LOCATION:PIE ABOUT 100M BEFORE WOODSVILLE FLYOVER DATE09/02/2018 TIME:1740		
3	ZZ/002	REMOVE/REFIX REAR BUMPER, PANEL, BOOTLID, REAR LH RH FENDER	2800.00	1680.00
4	ZZ/003	RESPRAY REAR BUMPER, PANEL, BOOTLID, REAR LH RH FENDER	2100.00	1680.00
5	ZZ/004	DISMANTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	300.00	.00
6	ZZ/005	REMOVE AND REFIX EXHAUST	150.00	.00
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50.00
8	ZZ/007	TRANSFER(BOOTLID)MECHANISM	150.00	100.00
9	ZZ/008	TO CONDUCT(REAR)LIGHTING TEST	50.00	50.00
10	ZZ/009	SUNDRIES	100.00	30.00
TOTAL LABOUR CHARGES			5750.00	3590.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLS3290S

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	GASKET	44011SG000	14.00			X
2	EXH PIPE ASSY R SIS	44200FL130	493.20			X
3	MUFFLER ASSY RH	44300FL080	504.00			X
4	TAIL PIPE CUTTER	44370FL000	72.00			X
5	PHL SD OUT QTR RHH	51439FL1409P	946.80			X
6	PHL SD OUT QTR RPSLH	51439FL1509P	946.80			X
7	R FLOOR PANEL 4D	52129FL0319P	432.00			X
8	SKIRT COMPL R 4D	52401FL0309P	265.30			X
9	TRUNK LID COMPL	57509FL0109P	624.00			OK
10	LOCK AY TRUNK	57530AJ050	158.40			X
11	WSTR TRUNK	57532FL010	57.60			OK
12	BUMPER FACE R 4D FHI	57704FL240	453.60			OK ✓
13	BRKT SD R 4D FHI RH	57707FL380	30.60			X
14	BRKT SD R 4D FHI LH	57707FL390	30.60			X
15	BEAM COMPL R EU	USE FL0409P 57711FL0419P	202.90			OK
16	COVER HOOK R 4D FHI	57731FL560NN	9.00			X
17	LENS & BODY COMPLEH	84912FL100	378.00			OK
18	LENS & BODY COMPLLH	84912FL110	378.00			X
19	LENS & BODY COMPLLH	84912FL13A	201.60			X
20	LENS & BODY COMPLEH (SUPP)	84912FL140	201.60			OK
21	PACKING RH	84940FL06A	18.00			OK ✓
22	RADAR ASSY B & S	87611FL000	2160.00			X
23	RADAR BRACKET 4D RH	87613FL020	11.90			X
24	RADAR BRACKET 4D LH	87613FL030	11.90			X
25	ORNAMENT ASSY F SIX	91174SA170	72.00			OK

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLS3290S

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	LETTER MK R	93079FL020	79.20			OK
27	LETTER MK R IMP	93079FL050	36.00			OK
SUB TOTAL			2122.90	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			424.58	0.00	0.00	0.00
GRAND TOTAL			1698.32	0.00	0.00	0.00
OVERALL TOTAL			1698.32			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SL532905

NETT ITEM	2122.90
LESS 20 %	-424.58
NETT AMOUNT	1698.32

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	3590.00
TOTAL SPARE PARTS CHARGES	1698.32

TOTAL CHARGES	5288.32
ADD 7 % GST	370.18

GRAND TOTAL	5658.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		13 Feb 2018 10:35 Edit Adj Rpt	S\$5,288.32 Edit Estimates	S\$5,288.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Kian Hong Aluminium Works Pte Ltd , Co. Reg. No.: 200808814K								
Main Claimant:	Tan Hou Hock , ID: S8513763H								
Vehicle Reg. No.:	SL532905	Date of Loss:	09/02/2018 17:00 - :59 [4 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 549617	Policy/Cover Note No.:	28952568MKC (Comprehensive) Coverage: 16/06/2017 - 15/06/2018						
Vehicle Reg. No. (Insured):	GBD1013L	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Image Enterprises Pte Ltd (HQ) 19 LORONG 8 TOA PAYOH, 319255 Toa Payoh - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/03/2018]								
Adj Asp. Remarks:	Survey - Car in. Thank You.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS3290S (549617)**
[GBD1013L]
TP
Tan Hou Hock
Feb 9 2018 5:00PM
[Kian Hong Aluminium Works Pte Ltd]
Motor Image Enterprises Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/02/18 11:43	Video - Accident - TP Cam From-SC - Reg. No: GBD1013L, Claimant: KIAN HONG ALUMINIUM WORKS PTE LTD	Load MP4	
2	14/02/18 11:43	Video - Accident - TP Cam From-SC - Reg. No: GBD1013L, Claimant: KIAN HONG ALUMINIUM WORKS PTE LTD	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 17:14	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/07/18 14:56	General View	Load JPG	☒
2	02/07/18 14:56	General View	Load JPG	☒
3	02/07/18 14:56	General View	Load JPG	☒
4	02/07/18 14:56	General View	Load JPG	☒
5	02/07/18 14:56	General View	Load JPG	☒
6	02/07/18 14:56	General View	Load JPG	☒
7	02/07/18 14:56	General View	Load JPG	☒
8	02/07/18 14:56	General View	Load JPG	☒
9	02/07/18 14:56	General View	Load JPG	☒
10	02/07/18 14:56	General View	Load JPG	☒
11	02/07/18 14:56	General View	Load JPG	☒
12	02/07/18 14:56	General View	Load JPG	☒
13	02/07/18 14:56	General View	Load JPG	☒
14	02/07/18 14:56	General View	Load JPG	☒
15	02/07/18 14:56	General View	Load JPG	☒
16	02/07/18 14:56	General View	Load JPG	☒
17	02/07/18 14:56	General View	Load JPG	☒
18	02/07/18 14:56	General View	Load JPG	☒
19	02/07/18 14:56	General View	Load JPG	☒
20	02/07/18 14:56	General View	Load JPG	☒
21	02/07/18 14:57	Reinspection Photo	Load JPG	☒
22	02/07/18 14:57	Reinspection Photo	Load JPG	☒
23	02/07/18 14:57	Reinspection Photo	Load JPG	☒
24	02/07/18 14:57	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/02/18 09:53	SLS3290S E REPORT	Load PDF	
2	13/02/18 09:53	ESTIMATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer.			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002853/KTD3E2

Date: 05/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28952568MKC

Claimant Vehicle No : SLS3290S

Insured Vehicle No : GBD1013L

Date of Loss: 09/02/2018

Nature of Claim: TP

Claim No: 549617

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS3290S

Make & Model: SUBARU IMPREZA, 1.6I SEDAN

Engine No: FB16YA95190

Reg. Date: 20/09/2017 (Man. Year: 2017)

Chassis No: JF1GK3KC5HG004684

Colour: Metallic Pearl White

Odometer: 2890 km

Engine Capacity: 1600 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size: 205/50 R17

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,131.20	1,728.32	5,402.88	75.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	3,560.00	2,090.00	36.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,781.20	5,288.32	7,492.88	58.62
+ GST 7.00/7.00% (S\$)	894.68	370.18	524.50	58.62
Nett Amount (S\$)	13,675.88	5,658.50	8,017.38	58.62

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 13/02/2018 Inspected At:

Motor Image Enterprises Pte Ltd (HQ)
19 LORONG 8 TOA PAYOH
Singapore 319255

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

**NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2018)
Parts:	143	SUBARU IMPREZA 1.6I SEDAN (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS3290S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*GASKET	Serviceable	14.00 FN	*- FN
3	1		*EXH PIPE ASSY R SIS	Repair	493.20 FN	*- FN
4	1		*MUFFLER ASSY RH	Repair	504.00 FN	*- FN
5	1		*TAIL PIPE CUTTER	Serviceable	72.00 FN	*- FN
6	1		*PNL SD OUT QTR RRH	Repair	946.80 FN	*- FN
7	1		*PNL SD OUT QTR RPSLH	Repair	946.80 FN	*- FN
8	1		*R FLOOR PANEL 4D	Repair	432.00 FN	*- FN
9	1		*SKIRT COMPL R 4D	Serviceable	265.30 FN	*- FN
10	1		*TRUNK LID COMPL	Buckled	624.00 FN	*624.00 FN
11	1		*WSTR TRUNK	Distorted	57.60 FN	*57.60 FN
12	1		*BRKT SD R 4D FHI RH	Repair	30.60 FN	*- FN
13	1		*BRKT SD R 4D FHI LH	Repair	30.60 FN	*- FN
14	1		*BEAM COMPL R EU	Bent	202.90 FN	*202.90 FN
15	1		*COVER HOOK R 4D FHI	Serviceable	9.00 FN	*- FN
16	1		*LENS & BODY COMPLRH	Cracked	378.00 FN	*378.00 FN
17	1		*LENS & BODY COMPL LH	Serviceable	378.00 FN	*- FN
18	1		*LENS & BODY COMPL LH	Serviceable	201.60 FN	*- FN
19	1		*LENS & BODY COMPLRH	Dented	201.60 FN	*201.60 FN
20	1		*RADAR ASSY B & S	Serviceable	2,160.00 FN	*- FN
21	1		*RADAR BRACKET 4D RH	Repair	11.90 FN	*- FN
22	1		*RADAR BRACKET 4D LH	Repair	11.90 FN	*- FN
23	1		*ORNAMENT ASSY F SIX	Necessary	72.00 FN	*72.00 FN
24	1		*LETTER MK R	Necessary	79.20 FN	*79.20 FN
25	1		*LETTER MK R IMP	Necessary	36.00 FN	*36.00 FN
26	1		*BUMPER FACE R 4D FHI	Bent	453.60 FN	*453.60 FN
27	1		*PACKING RH	Necessary	18.00 FN	*18.00 FN
28	1		*LOCK AY TRUNK	Repair	158.40 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	8,889.00	2,152.90
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,757.80	424.58
Total Parts (S\$)	7,131.20	1,728.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / REFIX REAR BUMPER, PANEL, BOOTLID, REAR LH RH FENDER	New	2,800.00	1,680.00
2	RESPRAY REAR BUMPER, PANEL, BOOTLID, REAR LH RH FENDER	New	2,100.00	1,680.00
3	DISMENTLE & REFIX UNDERCARRIAGE (REAR) TO FACILITATE REPAIR	New	300.00	0.00
4	REMOVE AND REFIX EXHAUST	New	150.00	0.00
5	TO CONDUCT WATER SEEPAGE TEST	New	100.00	50.00
6	TRANSFER (BOOTLID) MECHANISM	New	150.00	100.00
7	TO CONDUCT (REAR) LIGHTING TEST	New	50.00	50.00
Gross Labour Cost (S\$)			5,650.00	3,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >