


Signature: *Faruq*

REF: NS/INC18002875 / R19bn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: **PA 9223 U**
 Policy No: **5098 514877** **260317**
 Claims No: **NT/0981684-003**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seed: _____ Consistent? : Yes or No
 Est. Repairs: **13** days Res.: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SHO 6453 X** Vc Regn: **2017 MK**
 Type: M/Car / M/Cycle / Bus / Van / Lorry ☒ Prime Mover
 Truck / Trailer or _____
 Make: **TOYOTA PRIUS 4** Yr: **1798**
 Colour: **Maroon** A/C: Insured / Std / NI / NA
 Sp. Reading: **776** T. Radio: Insured / Std / NI / NA
 Eng No: _____
 O No: **JTOKB3Fu403876431**
 Gen. Cond: Good ☒ / Fair / Poor / Burnt
 Steering: ☒ Order / Jammed / Leaked / Burnt or
 Brake: ☒ Order / Jammed / Leaked / Burnt or
 Mod: ☒ NI / S/Rim / STD A/Rim or
 Tyre Size: F: **195/65R15**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / ☒ YOKE or
 Front: _____ Rear: _____
 R/Bal: **5** mm R/Bal: **5** mm
 L/Bal: **5** mm L/Bal: **5** mm
 D.O.A: **08/02/18** D.O.I: **12/02/18**
 Survey held at: **smet**
 Des. of Damages: Fnt / ☒ Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction: _____
SHO 6453 X - X
PA 9223 U - NA / INC11016103 / S2 DUA: 10.08.2011
02/18/2018
NTUC
PA 9223 U
 From try to 10/60.33, 13 days, finalised by Repul.
 (Red & 12687.07, 56%)

RECEIVED 25 APR 2018

Date/Time: File Passes? ☐ Preli. Report
25/4 *Faruq* ☐ Final Report
 Date/Time: File Return to? _____
 Report Format: **TP**
 Lump Sum / I.B.I: **10160.33**

Days Of Repair: **13**
 Resurvey No. of Trip: **1**
 Add Fee: ☐ Site Insp: \$
☐ Interview: \$
☐ Tech Insp: \$
☐ Washing: \$

Survey Fee	160
Tax	35
Stamp	
Other	
Total	195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002879/R1qb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 13-02-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PA 9223U	Veh. Inspected	SHD 6453X	
Policy No.	5088514877	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date	12/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5088514877	YANG YUN XIN BUS SERVICE	44258900W	GFT	Third Party, Fire & Theft	PA9223U	PA9223U	26/03/2017	

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0989232-002	SMRT TAXIS PTE LTD	SHB 606Y	PC 659U	03/04/2018
2	MT/0988033-002	SMRT TAXIS PTE LTD	SHC 4622T	SKK 5387M	26/03/2018
3	MT/0990162-002	COMFORT TRANSPORTATION PTE LTD	SHC 3053S	GY 2779J	12/04/2018
4	MT/0990253-002	COMFORT TRANSPORTATION PTE LTD	SHA 7586E	SJE 7264P	12/04/2018
5	MT/0981684-003	SMRT TAXIS PTE LTD	SHD 6453X	PA 9223U	08/02/2018
6	MT/0990655-002	COMFORT TRANSPORTATION PTE LTD	SHC 8854P	SKG 3498K	16/4/2018
7	MT/0990517-002	CITYCAB	SHC 7760H	SJM 9186B	15/4/2018
8	MT/0990876-002	COMFORT TRANSPORTATION PTE LTD	SH 6210D	SLB 9287C	17/4/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 17:03
Date Of Accident	08/02/2018 19:50
Exact Location Of Accident	SLIP ROAD FROM AYE TOWARDS CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6453X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	TOH KHAI BIN
NRIC No	S1206345H
Date Of Birth	12/05/1956
Occupation	OUTDOOR
Date Of Driving Pass	25/10/1977
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	119 BUKIT MERAH VIEW 13-79
Postcode	152119
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM AYE TOWARDS CLEMENTI AVE 6 WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE PA9223U HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9223U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Clementi Ave G

Fly over

A SHD6453X
B- PA 9223U

AYE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

✓ 9/2/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

9/2/08

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHD6453X
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS HYBRID 1.8 CVT
Chassis No. :	JTDKB3FU403576431
Propellant :	Petrol-Electric
Engine No. :	2ZR8257714
Motor No. :	1NM8257714
Engine Capacity :	1798 cc
Power Rating :	53.0 kW
Maximum Power Output :	90.0 kW (120 bhp)
Maximum Laden Weight :	1790 kg
Unladen Weight :	1375 kg
Year Of Manufacture :	2017
Original Registration Date :	14 Dec 2017
Lifespan Expiry Date :	13 Dec 2025
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$34,159.00
COE Expiry Date :	13 Dec 2025
Road Tax Expiry Date :	13 Jun 2018
PARF Eligibility Expiry Date :	13 Dec 2025
Inspection Due Date :	13 Dec 2018
Intended Transfer Date :	25 Apr 2018
CO2 Emission :	87.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$27,610.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 13 Jun 2018. You may renew the road tax from 14 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 13 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 14 Jun 2018 to 13 Dec 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			535.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6453X
Ref. No : TAX/02/18/2061
Reg. Date : 14/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : TOH KHAI BIN
Type of Accident : HEAD TO REAR
Date / Time of Accident : 08/02/2018 07:52:00 PM
Accident Reported Date / Time : 09/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094556
Special Instruction to ARC, if any :
TOWED \$40/ PA9223U / note / Rem by post
Prepared Date : 09/02/2018 01:02:48 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403576431

Mileage

0

Work Shop :

Repair Completed Date / Time :


Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 2,952.00	0.00
Total Material Charges	: 14,023.08	14,023.08
Other Charges	: 1,245.00	0.00
TOTAL	: 19,910.08	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 10.00	0.00 10 days - 9/10
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 10/02/2018 09:19:05 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 10/02/2018 09:19:05 AM


12/02/18 @ 1530
27/2/18**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00	0.00 <i>1200 900</i>
Total Labour	1,690.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 <i>200 /</i>
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 <i>X</i>
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 <i>X</i>
TO RESPRAY TAIL GATE	378.00	0.00 <i>200 /</i>
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 <i>100 /</i>
TO RESPRAY SPOILER	180.00	0.00 <i>100 /</i>
TO RESPRAY REAR PANEL	180.00	0.00 <i>100 /</i>
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 <i>X</i>
TO RESPRAY PANEL ROOF	378.00	0.00 <i>X</i>
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00 <i>X</i>
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 <i>X</i>
TO RESPRAY REAR FENDER LH	378.00	0.00 <i>200 /</i>
Total Spray Painting & Panel Beating	2,952.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 <i>X 40</i>
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 <i>40 /</i>
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 <i>60 /</i>
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 <i>60 /</i>
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 <i>60 /</i>
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 <i>120 /</i>
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 <i>125 /</i>
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 <i>30 /</i>
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 <i>60 /</i>
TO REPLACE SUNDRY PARTS	100.00	0.00 <i>20 /</i>
TO WASH AND VACUUM	60.00	0.00 <i>40 /</i>
Total Other Costs	1,245.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>DE</i>	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace <i>TH</i>	No
5246247030			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	2.85	Replace	Replace <i>me</i>	No
5246247020			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	2.85	Replace	Replace <i>me</i>	No
5246247010			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	2.85	Replace	Replace <i>me</i>	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	8.25	Replace	Replace <i>me</i>	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace <i>me</i>	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace <i>X SVC</i>	No
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace <i>me</i>	No
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Replace <i>X SVC</i>	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>DE</i>	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>?</i>	No
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace <i>X SVC</i>	No
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace <i>Fix SVC</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>me</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>me</i>	No
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.72	Replace	Replace <i>?</i>	No
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.12	Replace	Replace <i>?</i>	No
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace <i>?</i>	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace <i>TH</i>	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace <i>CRA</i>	No
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace <i>me</i>	No
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace <i>me</i>	No
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace <i>me</i>	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>me</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>me</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
68810470-61			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	25.00	88.65	Replace	Replace X SUC	No
689600W-860			TAIL GATE STAY ASSY, BACK DOOR, LH	1	235.00	25.00	176.25	Replace	Replace X SUC	No
689500W-860			TAIL GATE STAY ASSY, BACK DOOR, RH	1	235.00	25.00	176.25	Replace	Replace X SUC	No
69350470-50			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace X ? SUC	No
69321470-10			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.97	Replace	Replace SUC	No
69430520-50			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace X SUC	No
64801470-31			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace BR	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace RE	No
75571470-10			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace RE	No
56117501-40			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.92	Replace	Replace RE	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace RE	No
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace X	No
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace X	No
81270331-10			LAMP ASSY, LICENSE PLATE	2	63.70	10.00	114.66	Replace	Replace X	No
67750470-80C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.62	Replace	Replace X ?	No
67938470-60C0			TAILGATE TRIM, LH	1	92.10	25.00	69.07	Replace	Replace X ?	No
67751471-10C0			TAILGATE TRIM, LOWER	1	218.50	25.00	163.87	Replace	Replace X ?	No
67937470-60C0			TAILGATE TRIM, RH	1	92.10	25.00	69.07	Replace	Replace X ?	No
64790470-60C0			TAILGATE TRIM, UPPER	1	50.50	25.00	37.87	Replace	Replace X ?	No
74811470-20C0			TAILGATE BOARD, HANDLE PULL	1	19.50	25.00	14.62	Replace	Replace X	No
76085479-16			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace CRA	No
81006470-30			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	Replace	Replace X ?	No
67881470-50			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace na	No
64718470-80C0			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Replace X ?	No
64716471-30C0			END PANEL, COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace X ?	No
64740471-90C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace X ?	No
64730472-40C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.52	Replace	Replace X ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58415471 10C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace ?	No <i>gvc</i>
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace <i>Repair</i>	No ✓
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No <i>gvc</i>
58311471 30			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace <i>X</i>	No <i>gvc</i>
75607470 10			MOULDING SUB-ASSY, ROOF TOP	1	637.40	25.00	478.05	Replace	Replace ?	No ✓
75056470 10			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	52.70	25.00	39.52	Replace	Replace <i>CRA</i>	No
75055470 10			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	1	52.70	25.00	39.52	Replace	Replace <i>CRA</i>	No
63111470 60			PANEL, ROOF	1	1,245.20	25.00	933.90	Replace	Replace <i>X</i>	No <i>gvc</i>
61622470 60			TROUGH, BACK DOOR, LH	1	99.80	25.00	74.85	Replace	Replace ?	No <i>X gvc</i>
61621470 50			TROUGH, BACK DOOR, RH	1	99.80	25.00	74.85	Replace	Replace ?	No <i>X gvc</i>
81591470 10			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace <i>CRA</i>	No
81561471 51			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace <i>CRA</i>	No
81581470 10			LENS & BODY ASSY, RR BUMPER, RH	1	486.80	10.00	438.12	Replace	Replace <i>X</i>	No <i>gvc</i>
81551472 81			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Replace <i>X</i>	No <i>gvc</i>
61602471 60			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace <i>Repair</i>	No
TOTAL MATERIALS							13,404.62	13,404.48		
TOTAL MATERIALS(Discounted)							14,023.08	14,023.08		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

26-2-18/16:41



27-2-18/11:41

13-2-18/11:41


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6453X
 Ref. No : TAX/02/18/2061
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TOH KHAI BIN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 08/02/2018 07:52:00 PM
 Accident Reported Date / Time : 09/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Rasul
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094556
 Special Instruction to ARC, if any :
 TOWED \$40/ PA9223U - NTUC IDAC
 SURVEY ON 12-2-2018 / 16:55
 Resurvey before paint, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com
 Prepared Date : 09/02/2018 01:02:48 PM



Recording Camera



Radio Antenna



1st witness

Date 13-2-18

2nd witness

Date

Supplementary
 & Refer to the Supplementary part list

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 28-2-2018

Vehicle Return Time: 16:20

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU403576431


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,690.00	1,200.00
Total Spray Painting Charges :	2,952.00	900.00
Total Material Charges :	9,735.48	7,445.33
Other Charges :	1,165.00	615.00
TOTAL :	15,542.48	10,160.33
Lum Sum Total :	0.00	0.00
No. of Repair Days :	14.00	13.00
Prepared / Adjusted By :		RASUL (LKK)
Arc / Surveyor Sign Off Date :	10/02/2018 09:19:05 AM	12/02/2018 05:13:09 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/02/2018 09:19:05 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0188

Invoice No :

Quotation Date : 9/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,690.00	1,200.00
Total Labour	1,690.00	1,200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	378.00	200.00
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 <i>xnn</i>
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 <i>xnn</i>
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00
TO RESPRAY SPOILER	180.00	100.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 <i>xnn</i>
TO RESPRAY PANEL ROOF	378.00	0.00 <i>xnn</i>
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00 <i>xnn</i>
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 <i>xnn</i>
TO RESPRAY REAR FENDER LH	378.00	200.00
Total Spray Painting & Panel Beating	2,952.00	900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	120.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 <i>nel</i>
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
Total Other Costs	1,165.00	615.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>ne</i>	No <i>/</i>
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace <i>ne</i>	No <i>/</i>
5246247030			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	2.85	Replace	Replace <i>ne</i>	No <i>/</i>
5246247020			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	2.85	Replace	Replace <i>ne</i>	No <i>/</i>
5246247010			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	2.85	Replace	Replace <i>ne</i>	No <i>/</i>
5219147030			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	8.25	Replace	Replace <i>ne</i>	No <i>/</i>
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace <i>ne</i>	No <i>/</i>
5257547040			RETAINER, RR BUMPER, RH	0	112.70	25.00	0.00	Replace	Not given <i>ne</i>	No <i>X</i>
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace <i>ne</i>	No <i>/</i>
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Check <i>ne</i>	No <i>X</i>
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>S</i>	No <i>cat</i>
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace <i>S</i>	No <i>CRD</i>
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace <i>S</i>	No <i>CRD</i>
5256547900			FILLER, RR BUMPER, RH	0	119.90	25.00	0.00	Replace	Not given <i>ne</i>	No <i>X</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>ne</i>	No <i>/</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>ne</i>	No <i>/</i>
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.73	Replace	Check <i>ne</i>	No <i>X</i>
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.13	Replace	Check <i>ne</i>	No <i>X</i>
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace <i>S</i>	No <i>BC</i>
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace <i>ne</i>	No <i>/</i>
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace <i>ne</i>	No <i>/</i>
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace <i>ne</i>	No <i>/</i>
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace <i>ne</i>	No <i>/</i>
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace <i>ne</i>	No <i>/</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>ne</i>	No <i>/</i>
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>ne</i>	No <i>/</i>

3216.19

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
68810470 61			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	0	59.10	25.00	0.00	X Replace	Not given	No <i>see</i> X
689600W 860			TAIL GATE STAY ASSY, BACK DOOR, LH	0	235.00	25.00	0.00	X Replace	Not given	No <i>see</i> X
689500W 860			TAIL GATE STAY ASSY, BACK DOOR, RH	0	235.00	25.00	0.00	X Replace	Not given	No <i>see</i> X
69350470 50			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	X Replace	Check	No <i>see</i> X
69321470 10			TAIL GATE LOCK COVER, BACK DOOR	1	25.30	25.00	18.97	Replace	Replace	No <i>see</i> X
69430520 50			TAIL GATE STRIKER ASSY, BACK DOOR	0	24.90	25.00	0.00	X Replace	Not given	No <i>see</i> X
64801470 31			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	725.90	25.00	544.42	Replace	Replace	No <i>see</i> X
	COMMO N		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No <i>see</i> X
75571470 10			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace	No <i>see</i> X
56117501 40			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	25.00	20.92	Replace	Replace	No <i>see</i> X
	COMMO N		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No <i>see</i> X
			NUMBER PLATE	0	35.00	0.00	0.00	X Replace	Not given	No X
			NUMBER PLATE FRAME	0	25.00	0.00	0.00	X Replace	Not given	No X
81270331 10			LAMP ASSY, LICENSE PLATE	0	63.70	10.00	0.00	X Replace	Not given	No X
67750470 80C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.63	X Replace	Check	No X
67938470 60C0			TAILGATE TRIM, LH	1	92.10	25.00	69.08	X Replace	Check	No X <i>see</i>
67751471 10C0			TAILGATE TRIM, LOWER	1	218.50	25.00	163.88	X Replace	Check	No X
67937470 60C0			TAILGATE TRIM, RH	1	92.10	25.00	69.08	X Replace	Check	No X
64790470 60C0			TAILGATE TRIM, UPPER	1	50.50	25.00	37.88	X Replace	Check	No X
74811470 20C0			TAILGATE BOARD, HANDLE PULL	0	19.50	25.00	0.00	X Replace	Not given	No X
76085479 16			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace	No <i>see</i> X
81006470 30			LAMP SET, STOP CENTER	1	186.50	10.00	167.85	X Replace	Check	No <i>see</i> X
67881470 50			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace	No <i>see</i> X
64718470 80C0			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	X Replace	Check	No <i>see</i> X
64716471 30C0			END PANEL, COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace	No <i>see</i> X
64740471 90C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.53	Replace	Replace	No <i>see</i> X
64730472 40C2			PANEL ASSY, DECK TRIM SIDE, RH	1	344.70	25.00	258.53	X Replace	Check	No <i>see</i> X

2367.29

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58415471 10C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Check	No
58307470 90			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No
58311471 30			SPARE TYRE PANEL, PAN, REAR FLOOR	0	564.80	25.00	0.00	Replace	Not given	No
75607470 10			MOULDING SUB-ASSY, ROOF TOP	1	637.40	25.00	478.05	Replace	Replace	No
75056470 10			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	1	52.70	25.00	39.52	Replace	Replace	No
75055470 10			MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	1	52.70	25.00	39.52	Replace	Replace	No
63111470 60			PANEL, ROOF	0	1,245.20	25.00	0.00	Replace	Not given	No
61622470 60			TROUGH, BACK DOOR, LH	1	99.80	25.00	74.85	Replace	Check	No
61621470 50			TROUGH, BACK DOOR, RH	1	99.80	25.00	74.85	Replace	Check	No
81591470 10			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No
81561471 51			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No
81581470 10			LENS & BODY ASSY, RR BUMPER, RH	0	486.80	10.00	0.00	Replace	Not given	No
81551472 81			LENS & BODY, REAR COMBINATION LAMP, RH	0	438.10	10.00	0.00	Replace	Not given	No
61602471 60			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	100.00	0.00	Replace	Repair	No
TOTAL MATERIALS							9,735.55	7,445.33		
TOTAL MATERIALS(Discounted)							9,735.48	7,445.33		

Added Spare Parts / Material Usage After Surveyor Signed off

1861.85

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

7445.33
+ 1200.00
+ 1515.00
10,160.33

22842.40



Thatcham describe


National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002879/R1qbn2			
73 BRAS BASAH ROAD		Date: 04-05-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE		Code: INC4	
189556			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PA 9223U	Veh. Inspected	SHD 6453X
Policy No.	5088514877	Coverage (\$)	0.00
Claim No.	MT/0981684-003	Excess (\$)	0.00
Assign From		Assign Date	12/02/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU403576431	Colour	MAROON
Odometer	776	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2018	Inspection Date	12/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6453X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER,RR BUMPER ASSY (DISC 25%)	DEFORMED	423.90	317.92
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	PAD,RR BUMPER,RH & LH,1 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD,RR BUMPER,RH & LH,2 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD,RR BUMPER,RH & LH,3 (DISC 25%)	NECESSARY	3.80	2.85
1	SEAL,RR BUMPER ARM RH & LH (DISC 25%)	NECESSARY	11.00	8.25
1	RETAINER,RR BUMPER,LH (DISC 25%)	NECESSARY	111.50	83.62
1	SEAL RR BUMPER LH (DISC 25%)	NECESSARY	85.20	63.90
1	GUARD,RR BUMPER LOWER (DISC 25%)	CRACKED	558.30	418.72
1	COVER,GUARD RR BUMPER LOWER (DISC 25%)	CRACKED	14.80	11.10
1	FILLER,RR BUMPER LH (DISC 25%)	CRACKED	119.90	89.92
1	COVER,REAR FLOOR UNDER CENTER (DISC 25%)	DEFORMED	222.60	166.95
1	TAIL GATE PANEL SUB-ASSY,BACK DOOR (DISC 25%)	BENT	929.60	697.20
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	DEFORMED	891.20	668.40
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	TAIL GATE LOCK COVER,BACK DOOR (DISC 25%)	DEFORMED	25.30	18.97
1	TAIL GATE LOWER GLASS SUB-ASSY,BACK DOOR (DISC 25%)	BROKEN	725.90	544.42
1	TAIL GATE MOULDING GLASS,BACK DOOR (DISC 25%)	NECESSARY	29.70	22.27
1	TAIL GATE DAM,BACK DOOR GLASS UPPER ADHESIVE (DISC 25%)	NECESSARY	27.90	20.92
1	SPOILER SUB-ASSY REAR (DISC 25%)	CRACKED	1,322.10	991.57
1	TAIL GATE WEATHERSTRIP,BACK DOOR (DISC 25%)	NECESSARY	360.70	270.52
1	END PANE,COVER,DECK TRIM,REAR (DISC 25%)	DEFORMED	122.80	92.10
1	PANEL ASSY,DECK TRIM SIDE,LH (DISC 25%)	DEFORMED	344.70	258.52
1	END PANEL SUB-ASSY,BODY LOWER BACK (DISC 25%)	DEFORMED	629.80	472.35
1	MOULDNG SUB-ASSY,ROOF TOP (DISC 25%)	NECESSARY	637.40	478.05

Report Ref No. NS/INC18002879/R1qbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MOULDING SUB-ASSY,ROOF DRIP SIDE FINISH,REAR LH (DISC 25%)	CRACKED	52.70	39.52
1	MOULDING SUB-ASSY,ROOF DRIP SIDE FINISH,REAR RH (DISC 25%)	CRACKED	52.70	39.52
1	LENS & BODY ASSY,RR BUMPER LH (DISC 10%)	CRACKED	486.80	438.12
1	LENS & BODY REAR COMBINATION LAMP,LH (DISC 10%)	CRACKED	438.10	394.29
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	SOLAR FILM (SN)	NECESSARY	125.00	125.00
1	RETAINER,RR BUMPER,RH	SERVICEABLE	112.70	-
1	FILLER,RR BUMPER,RH	SERVICEABLE	119.90	-
1	COVER,REAR FLOOR UNDER,LH	SERVICEABLE	234.30	-
1	COVER,REAR FLOOR UNDER,RH	SERVICEABLE	169.50	-
1	TAIL GATE BACK,DOOR HINGE ASYS,RH & LH	SERVICEABLE	59.10	-
1	TAIL GATE STAY ASSY,BACK DOOR,LH	SERVICEABLE	235.00	-
1	TAIL GATE STAY ASSY,BACK DOOR,RH	SERVICEABLE	235.00	-
1	TAIL GATE LOCK ASSY,BACK DOOR	SERVICEABLE	452.10	-
1	TAIL GATE STRIKER ASSY,BACK DOOR	SERVICEABLE	24.90	-
1	NUMBER PLATE	SERVICEABLE	35.00	-
1	NUMBER PLATE FRAME	SERVICEABLE	25.00	-
1	LAMP ASSY,LICENSE PLATE	SERVICEABLE	63.70	-
1	TAILGATE BOARD ASSY	SERVICEABLE	251.50	-
1	TAILGATE TRIM,LH	SERVICEABLE	92.10	-
1	TAILGATE TRIM,LOWER	SERVICEABLE	218.50	-
1	TAILGATE TRIM,RH	SERVICEABLE	92.10	-
1	TAILGATE TRIM,UPPER	SERVICEABLE	50.50	-
1	TAILGATE BOARD,HANDLE PULL	SERVICEABLE	19.50	-
1	LAMP SET,STOP CENTER	SERVICEABLE	186.50	-
1	END PANEL,COVER DECK TRIM SERVICE HOLE	SERVICEABLE	47.00	-

Report Ref No. NS/INC18002879/R1qbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL ASSY,DECK TRIM SIDE,RH	SERVICEABLE	344.70	-
1	BOARD,REAR FLOOR NO.1	SERVICEABLE	502.20	-
1	SPARE TYRE PANEL,PANEL REAR FLOOR	SERVICEABLE	564.80	-
1	PANEL,ROOF	SERVICEABLE	1,245.20	-
1	TROUGH,BACK DOOR,LH	SERVICEABLE	99.80	-
1	TROUGH,BACK DOOR,RH	SERVICEABLE	99.80	-
1	SEL RR BUMPER RH	NOT NECESSARY	85.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	LENS & BODY ASSY RR BUMPER,RH	NOT NECESSARY	486.80	-
1	LENS & BODY,REAR COMBINATION LAMP,RH	NOT NECESSARY	438.10	-
1	PANEL SUB-ASSY,FENDER REAR LH	TO REPAIR	824.80	-
			17,160.40	7,570.33
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,370.00	1,570.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,152.00	960.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
			5,682.00	2,590.00
	GRAND TOTAL		22,842.40	10,160.33
RECOMMENDED COST OF REPAIRS (CONFIRMED)				10,160.33

Report Ref No. NS/INC18002879/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.