

FABU

REF:

NS/TNC18002880 / R19bnz

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop/mis: _____
of: _____
Insured: **GBA 6665M**
Policy No: **506304699-04** **25-10-17 - 08-10-18**
Claims No: **W/0981796-002**
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: **7** days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: **SHC 4663A** Yr: **2014** **8CP**
Type: M/Car / M/Cycle / Bus / Van / Lorry / **Truck** / Prime Mover /
Truck / Trailer or

Make: **TOYOTA PRINS** No: **1798**
Colour: **Maroon** A/C: Insured / Std / NI / NA
Sp. Reading: **479833** T. Radio: Insured / Std / NI / NA

Eng No: _____
C No: **3T0KN 36U X05 75 0305**

Gen. Cond: Good / **Fair** / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: **NI** / S/Rim / STD A/Rim or

Tyre Size: F: **195/65R15**
R: **-**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Falken**

Front	Rear
R.Bal: 5 mm	R.Bal: 5 mm
L.Bal: 5 mm	L.Bal: 5 mm
D.O.A: 09/02/18	D.O.A: 12/02/18

Survey held at: **SMRT**
Des. of Damages: Frt: **3** / Rr: **3** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

SHC 4663A - NS / TNC16013155 / K14h3d1
GBA 6665M - NA / TNC17021502 / 24

OUT: **11/11/16**
OUT: **01/11/17**

02/18/2068

NMC

GBA 6665M

US \$2850, 7 days (red \$6982.40, 71%)
26/2/18 @ 1.30pm re-finished car US \$2750 by email.
(red \$2082.40, 72%).

RECEIVED 01 MAR 2018

Date/Time File Pass No? ☐ : Prel. Report

01/3/18 ☐ : Final Report

Date/Time File Return No?

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Accident

Other

Total

Add Fee:

☐

Site Insp

☐

Inter. Insp

☐

Test Insp

☐

Rep. Insp

Report Format:

Lump Sum / **2750**

160

35

195

Survey Department Check List (Case Handler)

Reference No.: N2/INC18002880/R19/b
 Policy Type: OD / TP / TP RES / TL / EVA

SAC 4663A

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	<input checked="" type="checkbox"/>			
C Customer Code	<input checked="" type="checkbox"/>			
N Assign From				
C Assign Date	<input checked="" type="checkbox"/>			
C Veh No (Inspected)	<input checked="" type="checkbox"/>			
C Veh No (Insured)	<input checked="" type="checkbox"/>			
C D.O.A	<input checked="" type="checkbox"/>			
C Policy No	<input checked="" type="checkbox"/>			
C Claim No	<input checked="" type="checkbox"/>			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	<input checked="" type="checkbox"/>			
C Weekend Charges				
N Survey held at/Repairer	<input checked="" type="checkbox"/>			
C Excess				

Surveyor (Phom): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form	Y-Date	N-Date	Y-Date	N-Date
C Vehicle No	<input checked="" type="checkbox"/>			
C Regn Month/Year	<input checked="" type="checkbox"/>			
N Vehicle Type	<input checked="" type="checkbox"/>			
N Make & Model	<input checked="" type="checkbox"/>			
C Engine Capacity. (C.C)	<input checked="" type="checkbox"/>			
N Colour	<input checked="" type="checkbox"/>			
C Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>			
C Chassis No	<input checked="" type="checkbox"/>			
N General Condition	<input checked="" type="checkbox"/>			
N Steering	<input checked="" type="checkbox"/>			
N Brake	<input checked="" type="checkbox"/>			
N Modification (Modi)	<input checked="" type="checkbox"/>			
C Tyre Size	<input checked="" type="checkbox"/>			
N Tyre Make	<input checked="" type="checkbox"/>			
C Tyre Balance	<input checked="" type="checkbox"/>			
C Date of Inspection	<input checked="" type="checkbox"/>			
N Survey held	<input checked="" type="checkbox"/>			
N Des.of Damages	<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>			
--	-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

N ALL Parts condition	<input checked="" type="checkbox"/>			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	<input checked="" type="checkbox"/>			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C Resurvey photo Uploaded	<input checked="" type="checkbox"/>			
---------------------------	-------------------------------------	--	--	--

Check By: [Signature] 28/2/18
 Case Handler Date

*C: Critical *N: Non-Critical

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/0983795-001	SMRT TAXIS PTE LTD	SHF 463X	SJN 9459J
2	MT/0981796-002	SMRT TAXIS PTE LTD	SHC 4663A	GBA 6665M
3	MT/0975626-001	COMFORT TRANSPORTATION PTE LTD	SHD 7056C	GBB 1942R
4	MT/0981648-002	COMFORT TRANSPORTATION PTE LTD	SHC 1712L	SGH 1324J
5	MT/0983803-001	COMFORT TRANSPORTATION PTE LTD	SHD 7132R	SJF 7099U
6	MT/0982121-002	CITYCAB PTE LTD	SHC 813K	FY 9030B
7	MT/0983229-002	COMFORT TRANSPORTATION PTE LTD	SHB 6683J	FBL 894A
8	MT/0981814-002	COMFORT TRANSPORTATION PTE LTD	SHA 7150D	SGK1749B
9	MT/0974867-002	COMFORT TRANSPORTATION PTE LTD	SHC 8221R	SJR 8271T
10	MT/0983812-001	CITYCAB PTE LTD	SHC 600H	SKH 1597R
11	MT/0981491-002	COMFORT TRANSPORTATION PTE LTD	SHC 8248P	SJL 8210B
12	MT/0982113-002	COMFORT TRANSPORTATION PTE LTD	SHC 2469H	SJE 4769U
13	MT/0976388-001	COMFORT TRANSPORTATION PTE LTD	SHD 3298Y	SKP 4054D
14	MT/0977790-003	SMRT TAXIS PTE LTD	SHC 4018M	SKK 7897U
15	MT/0983818-001	CITYCAB PTE LTD	SHB 3377M	SJN 6180G
16	MT/0974783-002	COMFORT TRANSPORTATION PTE LTD	SHC 8897R	SJB 8136K
17	MT/0974882-002	COMFORT TRANSPORTATION PTE LTD	SHD 3364P	GBF 2607G

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5063043699-04	YAPPY GLOBAL PETS PTE. LTD.	199403949G	GCV	Comprehensive	GBA6665M	GBA6665M	25/10/2017	08/10/2018

Shiau Chan (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 28 February 2018 1:30 PM
To: Rasul (LKKAUTO)
Cc: Shiau Chan (LKKAUTO); Gan Kwai Leng (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Subject: RE: SHC4663A

Hi Rasul,

Noted and I will credit the old invoice and create a new invoice under repair cost \$2750.00.

Aside Joey,

Please take note that I will credit off the invoice that I had just sent to you.

Regards
Poh Suan

-----Original Message-----

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Wednesday, 28 February 2018 11:04 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: Shiau Chan (LKKAUTO)
Subject: RE: SHC4663A

Hi Poh Suan,

Called you several time not available just to inform you about this case, On part 2 section spray painting and panel beating related works in the estimate, the rear spoiler actually written there replace no spray.
As for that, I have to remove the \$100 for the spray.
Re-finalise again at \$ 2,750.00 / 7 days lump sum Kindly confirm

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 24 February, 2018 10:00 AM
To: Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHC4663A

Hi

Amount confirmed as per your recommendation, thanks.

Regards

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2018 09:11
Date Of Accident	09/02/2018 18:00
Exact Location Of Accident	BOON LAY WAY TOWARDS JURONG EAST ST 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4663A
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	KASSIM BIN MADNOOR
NRIC No	S0141271Z
Date Of Birth	13/07/1950
Occupation	OUTDOOR
Date Of Driving Pass	28/02/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	424 JURONG WEST AVENUE 1 02-352
Postcode	640424
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HONG KAH SOUTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 510 JURONG WEST STREET 52 , POSTCODE: 640510 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5648999 - FAX NO: 66655797
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180209/2183 ON 9 FEB 2018 FEB AT ABOUT 1800HRS, I WAS TRAVELLING ALONG BOON LAY WAY IN MY TAXI, SHC4663A. I APPROACHED A TRAFFIC JUNCTION ALONG BOON LAY WAY AND ATOPPED AT THE RIGHT TURN LANE WHICH IS TURNING INTO JURONG EAST ST 31. WHILST I WAS WAITING TO MAKE A TURN, A LORRY GBA6665M HIT THE REAR OF MY TAXI. AS A RESULT, IT CAUSED SERIOUS DAMAGE TO THE MY REAR BUMPER. THE SAID LORRY DRIVER WHOM IS A CHINESE WAS NOT INJURED DURING THE ACCIDENT AND HIS LORRY SUSTAINED SLIGHT DAMAGES. AFTER EXCHANGING PARTICULARS, I WENT TO CENTRAL HEALTH CLINIC TO SEE A DOCTOR AS I FELT PAIN ON MY NECK DUE TO THE ACCIDENT AND THE DOCTOR GAVE ME 4 DAYS MC. THERE WERE NO PASSENGERS IN MY TAXI AND THE SAID LORRY WHEN THE ACCIDENT HAPPENED. NO PEDESTRIAN WAS INJURED AND NO GOVERNMENT PROPERTY WERE DAMAGED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	GBA6665M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	YANG FEI

NRIC/Passport Number G2590112L
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name KASSIM BIN MADNOOR
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHC4663A
Were seat belts worn?
Was this injured conveyed to hospital by
ambulance? NO
Address
Postcode

④ 若 $\lim_{x \rightarrow \infty} f(x) = A$, 则 $\lim_{x \rightarrow -\infty} f(x) = A$ 不一定成立.

[illegible]

I/We declare the foregoing particulars are true in every respect.

declare the fore

January 23

10/2/2018

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 10/2/2018 0920h.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180209/2183

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999

1 of 3

Report No. T/20180209/2183

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/02/2018 20:51		Vide Report No.:	Station Diary No.: 33
Informant's Particulars			
Name of Informant: KASSIM BIN MADNOOR		Address: APT BLK 424 JURONG WEST AVENUE 1 #02-352 SINGAPORE 640424	
ID Type / ID No.: NRIC NO / S0141271Z		Contact No.: Home/Office: Mobile: 96469168	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 67	Date of Birth: 13/07/1950	Type of Informant: Driver
Race: Malay		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/02/2018 18:00	Type of Location: Straight Road
Location: Along Road 1 BOON LAY WAY Turning right into Jurong East St 31				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBA6665M	Lorry				Slightly Damaged	0
SHC4663A	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180209/2183

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999

2 of 3

Report No. T/20180209/2183

CONTINUATION OF REPORT

Driver			
Name	Yang Fel		ID No. G2590112L
Related Vehicle	GBA6665M (Lorry)		Contact No. 91090775
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	KASSIM BIN MADNOOR		ID No. S0141271Z
Related Vehicle	SHC4663A (Car)		Contact No. 96469166
Hospital/Clinic	Central Health Clinic		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	09/02/2018	Date Discharge	09/02/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 9 Feb 2018 at about 1800hrs, I was travelling along Boon Lay Way in my taxi, SHC4663A. I approached a traffic junction along Boon Lay Way and stopped at the right turn lane which is turning into Jurong East St 31. While I was waiting to make a turn, a lorry GBA6665M hit the rear of my taxi. As a result, it caused serious damage to my rear bumper. The said lorry driver whom is a Chinese was not injured during the accident and his lorry sustained slight damages. After exchanging particulars, I went to Central Health Clinic to see a doctor as I felt pain on my neck due to the accident and the doctor gave me 4 days MC. There were no passengers in my taxi and the said lorry when the accident happened. No pedestrian was injured and no government property were damaged.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hong Kah South NPP
510 Jurong West Street 52 #01-90
SINGAPORE 640510
Tel No: 1800-5648999



T/20180209/2183

3 of 3

* Report No. T/20180209/2183

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474865 stating the report number as reference.

Signature Of Officer Recording The Report:

J/
Sr Staff Sgt MOHAMED FHAIZAL BIN AB
HAMID

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / AEIT /
Staff Sgt WONG SIEU LUI
* Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
09/02/2018 20:51

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4663A
Vehicle to be Exported:	No
Intended De-registration Date:	28 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR1418997
Chassis No.:	JTDKN36UX05750305
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	19 Sep 2014
First Registration Date:	19 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$28,837.00
Total Rebate Amount:	\$34,903.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Feb 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4663A
Ref. No : TAX/02/18/2068
Reg. Date : 19/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KASSIM BIN MADNOOR
Type of Accident : HEAD TO REAR
Date / Time of Accident : 09/02/2018 06:00:00 PM
Accident Reported Date / Time : 10/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094566
Special Instruction to ARC, if any :
DROVE IN / GBA6665M / NINE / Resurvey after repair
Prepared Date : 10/02/2018 09:56:22 AM



Chassis No : JTDKN36UX05750305

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,296.00	0.00
Total Material Charges	: 4,068.61	4,151.64
Other Charges	: 940.00	0.00
TOTAL	: 7,318.61	0.00
Lum Sum Total	: 7,300.00	0.00
No. of Repair Days	: 6.00	0.00 <i>6 days - Lumpsum</i>
Prepared / Adjusted By		
Arc / Surveyor Sign Off Date	: 10/02/2018 11:09:50 AM	01/01/1900 12:00:00 AM

*12/02/18 @ 15:00*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/02/2018 11:09:50 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X
TO RESPRAY SPOILER	180.00	0.00 100
Total Spray Painting & Panel Beating	1,296.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	940.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>CRA</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>?</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace <i>?</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>X</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>X</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>See</i>	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace <i>X</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace <i>X</i>	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>?</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>See</i>	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>Repair</i>	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace <i>Repair</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>See</i>	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace <i>X</i>	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace <i>X</i>	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace <i>X</i>	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace <i>X</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace <i>X</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>X</i>	No
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace <i>X</i>	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace <i>X</i>	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>X</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>X</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>X</i>	No
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace <i>CRA</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
81006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace	No
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No
TOTAL MATERIALS							4,856.55	4,856.48		
TOTAL MATERIALS(Discounted)							4,068.61	4,151.64		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

12-2-18/16:50

Section A To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHC4663A
Ref. No : TAX/02/18/2068
Reg. Date : 19/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KASSIM BIN MADNOOR
Type of Accident : HEAD TO REAR
Date / Time of Accident : 09/02/2018 06:00:00 PM
Accident Reported Date / Time : 10/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Rasul
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094566
Special Instruction to ARC, if any :



DROVE IN / GBA6665M
Resurvey after repair, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001
0068, email: rasul@lkkauto.com
SURVEYOR APPROVE ON 12-2-18 / 16:50

Prepared Date : 10/02/2018 09:56:22 AM

479833



Recording Camera

Radio Antenna

ness

ness

Date

Date

Supplementary

Refer to the Supplementary part list

17:30 19-2-18 reject receiver sensor 479899

8:20 20-2-18 pass

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 19-2-2018

Vehicle Return Time: 16:15

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX05750305

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	600.00
Total Spray Painting Charges	: 1,296.00	600.00
Total Material Charges	: 1,310.44	2,047.56
Other Charges	: 940.00	-397.56
TOTAL	: 4,560.44	2,850.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 8.00	7.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sign Off Date	: 10/02/2018 11:09:50 AM	12/02/2018 05:09:05 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/02/2018 11:09:50 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

QN-1802-0499

Invoice No :

Quotation Date :

22/2

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION ✓	1,014.00	600.00
Total Labour	1,014.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER ✓	378.00	200.00
TO RESPRAY REAR PANEL ✓	180.00	100.00
TO RESPRAY TAIL GATE ✓	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH X	180.00	0.00 X n n
TO RESPRAY SPOILER replace no spray X	180.00	100.00 X
Total Spray Painting & Panel Beating	1,296.00	600.00 500

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X n n
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X n n
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
Total Other Costs	940.00	310.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>RC</i>	No <input checked="" type="checkbox"/>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace <i>SR</i>	No <input checked="" type="checkbox"/>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>SR</i>	No <input checked="" type="checkbox"/>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Check	No <input checked="" type="checkbox"/>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	0	94.80	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <input checked="" type="checkbox"/>
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.68	Replace	Check	No <input checked="" type="checkbox"/>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <input checked="" type="checkbox"/>
58307-47060		6505522	END PANEL	1	802.10	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
	COMMON	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
67005-47241			TAILGATE ASY	1	1,007.90	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <input checked="" type="checkbox"/>
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
76801-47070-80			TAILGATE OUTSIDE GARNISH	0	504.90	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
75442-47030			NAME PLATE (PRIUS)	0	60.80	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
75443-47030			NAME PLATE (TOYOTA)	0	51.90	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
75310-47020		6505639	EMBLEM REAR	0	60.30	25.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No <input checked="" type="checkbox"/>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
81006-47011		6505464	3RD BRAKE LAMP	0	231.30	10.00	0.00	Replace	Not given	No <i>X8u</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace <i>S</i>	No <i>re</i>
64718-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Replace <i>S</i>	No <i>re</i>
69350-47030			TAILGATE DOOR LOCK	0	444.10	25.00	0.00	Replace	Not given	No <i>X8u</i>
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace <i>S</i>	No <i>re</i>
TOTAL MATERIALS							2,047.58	2,047.57		
TOTAL MATERIALS(Discounted)							1,310.44	2,047.56		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
67881-47022		TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						265.05			

2047.55
+ 600.00
+ 810 910.00

~~3457.55~~ ~~3557.55~~
- 202

~~2766.04~~ ~~2846.04~~
2750

4S \$2850/-
7 days

983240



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002880/R1qbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 05-03-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 6665M	Veh. Inspected	SHC 4663A
Policy No.	5063043699-04	Coverage (\$)	0.00
Claim No.	MT/0981796-002	Excess (\$)	0.00
Assign From		Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36UX05750305	Colour	MAROON
Odometer	479833	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/02/2018	Inspection Date	12/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4663A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY,RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	SPOILER REAR (DISC 25%)	CRACKED	953.70	715.27
1	END PANEL COVER,DECK TRIM HOLE (DISC 25%)	DEFORMED	46.10	34.58
1	END PANEL COVER,DECK TRIM,RR (DISC 25%)	DEFORMED	121.10	90.83
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	CUT	353.40	265.05
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	ARM SUB-ASSY,RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	TAIL GATE DOOR GLASS MOULDING,LH	SERVICEABLE	29.40	-
1	TAIL GATE DOOR GLASS MOULDING,RH	SERVICEABLE	29.40	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	MOULDING BACK WINDOW,LOWER NO 1	SERVICEABLE	29.40	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	TAILGATE OUTSIDE GARNISH	SERVICEABLE	504.90	-
1	NAME PLATE (PRIUS)	SERVICEABLE	60.80	-
1	NAME PLATE (TOYOTA)	SERVICEABLE	51.90	-
1	EMBLEM REAR	SERVICEABLE	60.30	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	NAME PLATE FRAME	SERVICEABLE	12.00	-
1	3RD BRAKE LAMP	SERVICEABLE	231.30	-
1	TAILGATE DOOR LOCK	SERVICEABLE	444.10	-

Report Ref No. NS/INC18002880/R1qbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	END PANEL	TO REPAIR	602.10	-
1	TAILGATE ASY	TO REPAIR	1,007.90	-
			6,582.40	2,047.58
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,694.00	790.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,396.00	560.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
			3,250.00	1,410.00
	GRAND TOTAL		9,832.40	3,457.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,750.00

Report Ref No. NS/INC18002880/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.