

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190388 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

13 FEB 2018

Estimate No. : b1 45915  
Date Estimated : 12/02/2018  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

### - ESTIMATE REPAIR FOR -

DLM PTE.LTD  
183 Kaki Bukit Avenue 1  
Shun Li Industrial Park

Singapore 416026

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------|------------|---------|---------|
| SKP1194C  | NS37867     | 15/08/2014 | 316iA/4 | 0       |

### DESCRIPTION

### VALUE

To replace rear bumper & attachments including to knock out dented area caused by the accident

1,275.00

To respray rear bumper

1,038.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

661.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

177.00

To check electrical wiring systems and lightings at the rear section for proper function.

177.00

Sundries.

80.00

Total Labour 1: 3,408.00

### DESCRIPTION

### QTY

### PRICE

### VALUE

RR BUMPER BOTTOM REINFORCEMENT

1

66.10

66.10

REAR BUMPER CENTRE GUIDE

1

32.10

32.10

REAR BUMPER CARRIER (ECE)

1

432.90

432.90

REAR BUMPER PANEL PRIMED BASIS

1

1,100.25

1,100.25

RR BUMPER FLAP TOWING EYE PRIMED

1

42.20

42.20

REAR PDC HOLDER SET

1

23.10

23.10

PLUG BLACK D=5MM

10

0.90

9.00

SENSOR WIRE FOR SMART OPENER TOP

1

42.10

42.10

SENSOR WIRE FOR SMART OPENER BOTTOM

1

40.50

40.50

EXPANDING NUT

10

0.55

5.50

RR BUMPER LH REFLECTOR

1

35.20

35.20

RR BUMPER RH REFLECTOR

1

35.20

35.20



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45915  
Date Estimated : 12/02/2018  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------|------------|---------|---------|
| SKP1194C  | NS37867     | 15/08/2014 | 316ia/4 | 0       |

Total Parts : 2,401.00

|                |   |          |
|----------------|---|----------|
| Labour 1       | : | 3,408.00 |
| Parts          | : | 2,401.00 |
| Labour 2       | : | 0.00     |
| Excess         | : | 0.00     |
| Total GST @ 7% | : | 406.63   |
| Grand Total    | : | 6,215.63 |