

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7847Y - AIG**AAD1802-113***Not Authorised**1/10/18*

Vehicle No.:	SHB7847Y - CANDY
Chassis No.:	KL1LA69RJB097013
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	09.02.2018
Third Party Insurer :	AIG

PART		LIST	
1	1	Rear Bumper	\$ 1,202.00
2	1	Rear Bumper Beam	\$ 239.94
3	1	Rear Bumper Centre Absorber	\$ 260.00
4	1	Rear Bumper Side Retainer RH	\$ 68.76
5	1	Rear Bumper Side Retainer LH	\$ 68.76
6	1	Rear Bumper Reflectors RH	\$ 119.74
7	1	Rear Bumper Reflectors LH	\$ 119.74
8	1	Rear Bumper Tow Hook Cover	\$ 93.00
9	1	Rear End Panel Outer	\$ 623.76
10	1	Rear End Panel Inner Trim	\$ 263.84
11	1	Bootlid	\$ 973.00
12	1	Bootlid Weatherstrip	\$ 344.28
13	1	Bootlid Lock - Top	\$ 466.56
14	1	Bootlid 'CHEVROLET' Badge	\$ 120.62
15	1	Bootlid Logo	\$ 138.84
16	1	Bootlid 'EPICA LT' Badge	\$ 119.84
17	1	Bootlid Reflector Centre	\$ 217.97
18	1	Bootlid Reflector RH	\$ 128.40
19	1	Bootlid Reflector LH	\$ 128.40
20	1	Rear Tail Lamp RH	\$ 479.30
21	1	Rear Tail Lamp Panel RH	\$ 359.00
22	1	Rear Tail Lamp LH	\$ 479.30
23	1	Rear Tail Lamp Panel LH	\$ 359.00
24	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ 1,110.00
25	1	Rear Fender RH	\$ 1,145.00
26	1	Rear Fender LH	\$ 1,145.00

TOTAL	\$	10,774.05
10%	\$	1,077.41
	\$	9,696.65

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-113

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7847Y - AIG

Specical Nett

1	1Set	Licence Plate With Holder	\$	Sm	60.00	}
2	1Set	Bootlid inner trim board Clip	\$	vn	40.00	
3	1Set	Rear Bumper Parking Sensor	\$	Sm	300.00	
4	1Set	Rear Bumper Fastener Clip	\$	vn	44.00	
5	1Set	Rear Bumper End Dust Cover Clip	\$	vn	30.00	
6	1	Rear Boot Sticker 'Trans-cab'	\$	vn	30.00	
7	1	Rear Boot Sticker '6555-3333'	\$	vn	30.00	
8	1	Rear Exhaust Mounting	\$	Sm	10.00	
9	2	Rear Windscreen Sealant	\$	vn	80.00	
10	1	Rear Windscreen Inner Sponge Seal	\$	vn	100.00	
11	1	Spare Tyre	\$	Sm	180.00	
12	1	Spare Wheel Rim	\$	Sm	126.74	

TOTAL	\$	1,030.74
--------------	-----------	-----------------

TOTAL PARTS	\$	10,727.39
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	2,700.00	100%
----	----------	------

To Check Electrical Lighting Concerned.

\$	vn	170.00	X
----	----	--------	---

To Rust-Proofing Of The Affected Areas.

\$	vn	170.00	X
----	----	--------	---

Putty And Spray Painting Of The Affected
Portion.

\$	2,800.00	200%
----	----------	------

To reinstall rear bumper parking sensor.

\$	vn	170.00	X
----	----	--------	---

To transfer of end panel fittings and conduct
water seepage test.

\$	vn	170.00	X
----	----	--------	---

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$	vn	170.00	X
----	----	--------	---

To transfer of boot fittings and conduct water
seepage test.

\$	vn	170.00	X
----	----	--------	---

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-113

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7847Y - AIG

Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
	\$	<u>7,410.00</u>
TOTAL	\$	<u>18,137.39</u>

Repair Days*10 Days*
1 day