

ASS. REC. BY:

REF:

CS/EG118002885/Mvd3m Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGJ

Date/Time: 13/2/18 @ 9:25am

Estimated Cost:

Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 81584

Insured:

SKZ 588D

at Workshop m/s

Pegasus Engineering

Tel:

6858 1846

of

51 Defu Lane 10

Policy No:

Claim No:

SKZ 588D / SE / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 09/02/2018

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time: 9:41am @ 13/2/18

Person Contacted:

Caymen

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 81584-X
	SKZ 588D-X
14/2/18	Email preli revised to Pei Li

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ER1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 81584

at Workshop m/s

regus 17m.

of

Insured:

SL & Sffp

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1345N

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 81584

Yr Regn:

7, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

C.C.

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

46364

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0152592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

9/1/18

D.O.I.

13/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & LS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/1/18 confirmed fine f.y # 2430.40 with Sharon.
(Red 226.80, 99)

RECEIVED 22 FEB 2018

19/1/2018

Date/Time. File Pass to?

☐

Preli. Report

Days Of Repair:

3

1)

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time. File Return to?

Transportation:

2) 226- typst

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

TP

Lump Sum / I.B.I. (\$) 2430.40

TOTAL

250

Survey Department Check List (Case Handler)

Reference No. : CS/ EGI/ 18002885 / Uvcl3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Veron 14/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18002885/Uvd3		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 13-02-2018		
Code : EGI				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 588D	Veh. Inspected	SLQ 8158U	
Policy No.		Coverage (\$)	0.00	
Claim No.	SKZ 588D/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/02/2018	Inspection Date	13/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SKZ588D/SE/pl
Our Ref: CS/EG118002885/Uvd3

Date: 14/2/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLQ 8158U


We thank you for your instruction on 13/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/2/2018 at the premises of M/s PEGASUS ENGINEERING & TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,657.20
Revised Estimate Amount	: S\$2,430.40
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 14 February 2018 4:00 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SKZ588D / TP : SLQ8158U/LKK / DOA : 09/02/2018
Attachments: SLQ 8158U PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLQ 8158U
Date of survey: 13/2/2018
Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 13 February 2018 9:45 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKZ588D / TP : SLQ8158U/LKK / DOA : 09/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Tuesday, 13 February 2018 9:25 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SKZ588D / TP : SLQ8158U/LKK / DOA : 09/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PEGASUS ENGINEERING & TRADING PTE LTD**,

ADDRESS : NO 51 DEFU LANE 10
SINGAPORE 539216

PERSON TO CONTACT : CAYMEN @ 6858 1846

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS. (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 13 February 2018 9:25 AM
To: 'admin-d@lkkauto.com'
Subject: OI : SKZ588D / TP : SLQ8158U/LKK / DOA : 09/02/2018
Attachments: SKZ588D - SAS.pdf; SLQ8158U - SAS.pdf; SLQ8158U - ESTIMATE.pdf; SLQ8158U - PRS FORM.pdf; Re: Third Party Survey - SLQ8158U Your Insured - SKZ588D D.O.A - 09.02.2018 (10.4 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **PEGASUS ENGINEERING & TRADING PTE LTD,**

ADDRESS : NO 51 DEFU LANE 10
SINGAPORE 539216

PERSON TO CONTACT : CAYMEN @ 6858 1846

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS. (note: reports not to be released to any Third Party).

Kindly acknowledged receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 13.02.2018
Our Reference: SKZ 588D/SE/pl
Your Reference: SLQ 8158U

To: TAN LIM MOTOR PTE LTD

Sent via Fax
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLQ 8158U
Insured's Vehicle: SKZ 588D
Date Of Accident: 09.02.2018

We acknowledge receipt of your request for PRS on: 13.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

***LKK - MARCUS CHUA**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's complete cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1345N

Vehicle Details

Vehicle No.:	SLQ8158U
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520445368
Chassis No.:	JM6BN22A8H0153592
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2027
PARF Rebate Amount:	\$7,320.00

Intended COE Rebate Details

COE Expiry Date:	23 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$34,240.00
Total Rebate Amount:	\$41,560.00

The information contained herein is correct as at 10 Feb 2018

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 28, SIN MING LANE, #07-71 MIDVIEW CITY SINGAPORE 573969 Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1080	Quotation Date : 12/02/2018	Terms : 30 DAYS
Vehicle No : SLQ8158U	Chassis No : JM6BN22A8H0153592	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: NTUC ; TP VEHICLE: SKZ588D ; DOA: 09/02/2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>DIS</i>	1	1,066.0000	1,066.00
2	REAR BUMPER REFLECTOR O/S <i>11</i>	1	51.0000	51.00
3	REAR BUMPER SIDE RETAINER <i>24</i>	1	36.0000	36.00
4	REAR BUMPER CLIPS <i>30</i>	6	5.0000	30.00
5	REAR BUMPER REINFORCEMENT <i>10/100</i>	1	538.0000	538.00
6	REAR BUMPER SIDE HOLDER O/S <i>20</i>	1	46.0000	46.00
7	REAR BUMPER SIDE HOLDER RIVETS <i>11</i>	4	5.0000	20.00
8	REAR BUMPER TOW COVER O/S <i>70</i>	1	17.0000	17.00
9	LESS 20% ITEMS 1-8	1	-360.8000	-360.80
10	REAR BUMPER PARKING SENSOR <i>check</i>	1	194.0000	194.00
11	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	40.0000	40.00
13	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	380.0000	380.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	480.0000	480.00

1733
1386.40
2430.40
2 day

Not Alvin
13/02/18
Take photo before repair.
13/2/18

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 639216

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party insurance is subject to confirmation
- No illegal work is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub Total 2,657.20
GST(7.00%) 186.00
Total (SGD) 2,843.20

Acknowledged by Repairer
 Signature:
 Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18002885/Uvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 22-02-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 588D	Veh. Inspected	SLQ 8158U	
Policy No.		Coverage (\$)	0.00	
Claim No.	SKZ 588D/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0153592	Colour	BLUE	
Odometer	46364	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2018	Inspection Date	13/02/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8158U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	1,066.00	1,066.00
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	51.00	-
1	REAR BUMPER SIDE RETAINER	BENT	36.00	36.00
6	REAR BUMPER CLIPS @\$5.00	NECESSARY	30.00	30.00
1	REAR BUMPER REINFORCEMENT	DENTED / BENT	538.00	538.00
1	REAR BUMPER SIDE HOLDER O/S	BENT	46.00	46.00
4	REAR BUMPER SIDE HOLDER RIVETS @\$5.00	NOT NECESSARY	20.00	-
1	REAR BUMPER TOW COVER O/S	TORN	17.00	17.00
	LESS 20% DISCOUNT		-360.80	-346.60
			1,443.20	1,386.40
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	194.00	194.00
			194.00	194.00
LABOUR				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		40.00	20.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		380.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		480.00	480.00
			1,020.00	850.00
GRAND TOTAL			2,657.20	2,430.40
RECOMMENDED COST OF REPAIRS				2,430.40

Report Ref No. CS/EG18002885/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.