

INS CASE OWNER:

Notalie.

CC 4 / III1800

2888

A^w ka3s2LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

14/5/2018

Date / Time:

12/02/18

Registered in Merimen:

13/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 7494L

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

09/02/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Kusmalyaori bin KANARUSANAW

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MUT18020304

Policy No.:

M10M0015

Make / Model:

H-140

Place of Accident:

TPE > SUE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHA 9743X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah Motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
21/2	SHA 9743X - X;	Non-Reporting ltr (1st):	
21/2	SHA 7494L - CUE/Asm (870159/1043, 007, 12/1/18)	Non-Reporting ltr (2nd):	
	- CC4/III 17016840/KPA3A2; 007, 13/1/18	Non-Reporting ltr (Final):	
23/2/2018	FILES REVIEWED. CASE OF 4 veh C-C and OTO is 2nd vehicle. seek liability mandate via merimen.	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐ ☐
		After call ltr to OI:	☐ ☐
		Authorisation To Act:	☒ ☐
		Release Voucher:	☒ ☐
		Final Repair Bill:	☒ ☐
		Car Rental Invoice:	☒ ☐
		Towing Invoice:	☐ ☐
		LTA / GIA:	☐ ☐
		Medical Bill:	☐ ☐
		PIR:	☐ ☐
		Mandate/Reject Instruction:	☒ ☐
		LOD	☒ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☐ ☐
		Others:	☐ ☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days)	Reduction: %
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.: 28
Repair Cost:	SS 5486.94		
Loss of Rental (LOR):	SS 535.00	(5 days)	x 100 + 631
Loss of Use (LOU):	SS -	(\$ x days)	
Loss of Income (LOI):	SS -	(\$ x days)	
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search:	SS -		
Medical:	SS -		
Disbursement:	SS -		(e.g. Tow/ Independent)
Legal Cost:	SS -		
Total:	SS 6021.94		Global Sum SS:
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 6021.94	Name 1:	Kah Motor Co. Soln. Bhd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18002888/Aka3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 13-02-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7494L	Veh. Inspected	SLH 9743X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/02/2018	Inspection Date	14/02/2018	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SLH9743X
 Chassis No : JHMRU1810GX201168
 Model : HRV DX-SIN CVT YM 2016
 Owner's Name : NAGAPPAN CHANDRASEKARAN
 Ins Policy No :
 Date of Accident : 9/2/2018

Document No. : SQT18000636 Page 1
 Date : 10. Feb 2018
 Customer No. : WZI007
 Svc Advisor : LIEW THYE WEI
 Engine No : L15B4531168
 Date | Time : 10. Feb 2018 8:30:48 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NAGAPPAN CHANDRASEKARAN OWNER INSURER: DIRECT ASIA INSURANCE (S) PTE LTD ACC DATE: 9/2/18 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHA7494L						
66100-T7A-300ZZ	PANEL COMPR. <i>Repair</i>	1	365.70	25	274.27	19.20	293.47 X
68100-T7A-J20ZZ	TAILGATE COMP <i>Dented</i>	1	838.90	25	629.17	44.04	✓ 673.21
74440-T7A-003	WEATHERSTRIPTAILGATE <i>new</i>	1	96.80	25	72.60	5.08	+ 77.68
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>new</i>	1	103.20	25	77.40	5.42	+ 82.82
74800-T7A-J02	LOCK ASSYTAILGATE <i>new</i>	1	76.60	25	57.45	4.02	+ 61.47
73215-T7A-003	RUBBER CR.WINDSHIELD DAM <i>new</i>	1	19.30	25	14.47	1.01	✓ 15.48
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	1	8.30	25	6.22	0.44	✓ 6.66
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.30	25	14.47	1.01	✓ 15.48
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	✓ 10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	✓ 7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	✓ 5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	✓ 64.20
84640-T7A-J01ZA	LINING ASSYRR.PANEL <i>new</i>	1	43.00	25	32.25	2.26	✓ 34.51 X
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING <i>new</i>	1	144.20	25	108.15	7.57	+ 115.72
75722-T7W-A01	EMBLEMRR. <i>new</i>	1	12.90	25	9.67	0.68	✓ 10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	✓ 11.31
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH <i>new</i>	1	172.10	25	129.07	9.03	+ 138.10
74450-T7B-003	PROTECTOR,L,RR.WHEEL ARCH <i>new</i>	1	172.10	25	129.07	9.03	+ 138.10
71501-T7B-000	FACE RR.BUMPER <i>new</i>	1	762.60	25	571.95	40.04	✓ 611.99
					347.87		372.11



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLH9743X
Chassis No : JHMRU1810GX201168
Model : HRV DX-SIN CVT YM 2016
Owner's Name : NAGAPPAN CHANDRASEKARAN
Ins Policy No :
Date of Accident : 9/2/2018

Document No. : SQT18000636 Page 2
Date : 10. Feb 2018
Customer No. : WZI007
Svc Advisor : LIEW THYE WEI
Engine No : L15B4531168
Date | Time : 10. Feb 2018 8:30:48 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER <i>3 new</i>	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
71593-T7A-000	SPACERR.RR.BUMPER SIDE <i>3 new</i>	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>3 new</i>	1	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	151.80	25	113.85	7.97	121.82
33502-T7A-J01	LAMP UNITR. <i>3 new</i>	1	428.70	25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL.	1	428.70	25	321.52	22.51	344.03
34150-T7A-J01	LIGHT ASSY.R.LID <i>3 new</i>	1	264.60	25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSYL.LID	1	264.60	25	198.45	13.89	212.34
38387-TZ5-A01	ANTENNA ASSYL.F. <i>Not New</i>	1	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART <i>Not New</i>	1	59.30	25	44.47	3.11	47.58
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>Not New</i>	1	320.00		320.00	22.40	342.40
Sum Item					4050.34	283.52	4,333.86
BOSUN	SUNDRIES	1	30.00	<i>Not New</i>	30.00	2.10	32.10
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN (N)	1	280.00		280.00	19.60	299.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00		320.00	22.40	342.40
BOMISC1	REMOVE, REPLACE & INSTALL SMART ENTRY SENSOR.1	1	450.00		450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2400.00		2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00		2500.00	175.00	2675.00
Sum Labor					7080.00	495.60	7,575.60

Printed on 10/2/2018 2:16:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH9743X

Chassis No : JHMRU1810GX201168

Model : HRV DX-SIN CVT YM 2016

Owner's Name : NAGAPPAN CHANDRASEKARAN

Ins Policy No. :

Date of Accident : 9/2/2018

Document No. : SQT18000636 **Page** 3

Date : 10. Feb 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4531168

Date | Time : 10. Feb 2018 8:30:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<u>Adrian L</u>						
Date & Time	<u>14/02/18.</u>						
Excess							
Status							
Signature	<u>[Signature]</u>						
					Total Amount	11,130.34	11,909.46
					Total (Inclusive of GST)		11,909.46

05 Days.
08 Days

11133.24

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 10/2/2018 2:16:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

QUOTATION


KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE	Document No.	: SQT18001033	Page	1
	64 CECIL STREET	Date	: 11. Mar 2018		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLH9743X	Engine No	: L15B4531168		
Chassis No	: JHMRU1810GX201168	Date Time	: 11. Mar 2018 10:52:48 AM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: NAGAPPAN CHANDRASEKARAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 9/2/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 70083)						
	OWNER: NAGAPPAN CHANDRASEKARAN						
	OWNER INSURER: DIRECT ASIA INSURANCE (S) PTE LTD						
	ACC DATE: 9/2/18						
	SURVEYED BY: ADRIAN LING						
	DATE: 14/02/18						
	REF NO: CC4/III18002888/ka3						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHA7494L						
	SUPPLEMENTARY LABOUR & PARTS						
90676-SA7-003	GROMMET SCREW 5 <i>NU</i>	2	2.30	25	3.45	0.24	3.69
				Sum Item	3.45	0.24	3.69

Survey By	_____				
Date & Time	_____	Total Amount	3.45	0.24	3.69
Excess	_____	Total (Inclusive of GST)			3.69
Status	_____				
Signature	_____				

Printed on 11/3/2018 10:57:30 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).



18/03/2018

Page 1/3

SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380GAttn: Adrian Ling (L.k.l.c.)
5 daysCustomer: WZ1007 / INDIA INTERNATIONAL
Chassis No: JHMRU1810GX201168
License No: SLH9743X
Mileage: 33597
Engine No: L15B4531168Document No: SVO18012680
Printed By: TWLIEW
Order Date: 5. March 2018
Order Time: 12:47:01 PM
Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70063)							
	OWNER: NAGAPPAN CHANDRASEKARAN							
	OWNER INSURER: DIRECT ASIA INSURANCE (S) PTE LTD							
	ACC DATE: 9/2/18							
	SURVEYED BY: ADRIAN LING							
	DATE: 14/02/18							
	REF NO: CC4/III18002888/ka3							
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD							
	TP VEH: SHA7494L							
68100-T8P-U10ZZ	TAILGATE COMP	1	838.90	25	629.17	44.04	673.21	
73215-T7A-003	RUBBER CR.WINDSHIELD DAM	1	19.30	25	14.47	1.01	15.48	
73226-SZW-000	DAMPERSTD 5X5	1	8.30	25	6.22	0.44	6.66	
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.30	25	14.47	1.01	15.48	
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27	
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86	
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62	
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20	
75722-T7W-A01	EMBLEMRR.	1	12.90	25	9.67	0.68	10.35	
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	11.31	
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11	
90676-SA7-003	GROMMET.SCREW.5	2	2.30	25	3.45	0.24	3.69	
	SUM PARTS:				1,117.99	78.25	1,196.24	
BOSUN	0672	1	10.00		10.00	0.70	10.70	
	SUNDRIES							
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60	
	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)							
BG02D	EXT-YJ	1	280.00		280.00	19.60	299.60	
	REMOVE & INSTALL RR. WINDSCREEN. (N)							
BMI02D	EXT-YJ	1	320.00		320.00	22.40	342.40	
	REMOVE & INSTALL SPEAKER BOARD. RR SEATS TRUNK LININGS GARNISHES & ETC.(N)							
BOMISC1	EXT-YJ	1	280.00		280.00	19.60	299.60	
	REMOVE, REPLACE & INSTALL SMART ENTRY SENSOR. RESET MEMORY. (N)							
BA02R	EXT-YJ	1	120.00		120.00	8.40	128.40	
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)							
BKTG02R	EXT-YJ	1	450.00		450.00	31.50	481.50	
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE (N)							
BKRP02S	EXT-YJ	1	1,120.00		1,120.00	78.40	1,198.40	
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.							
BP05R	EXT-YBH	1	1,350.00		1,350.00	94.50	1,444.50	



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No: M200050223

Company Ref. No.: S60FC1380G

Customer: WZI007 / INDIA INTERNATIONAL
Chassis No: JHMRU1810GX201168
License No: SLH9743X
Mileage: 33597
Engine No: L15B4531168

Document No: SVO18012680
Printed By: TWLIEW
Order Date: 5. March 2018
Order Time: 12:47:01 PM
Service Advisor: LIEW THYE WEI

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(5P)

SUM LABOUR:	4,010.00	280.70	4,290.70
TOTAL SGD	5,127.99	358.95	5,486.94

Total Payable (SGD) 5,486.94

GST Amount is calculated from individual line(s)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 12 February 2018 1:48 PM
To: Liew Thye Wui; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Natalie Lee
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLH9743X AGAINST SHA7494L. Accident date on 9/2/18
Attachments: 4081_001.pdf

2.45pm @ 12/2/2018

vehicle Not In

Mr. Hew

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLH9743X and let us have your report urgently.

This claim will be handled by Ms Natalie.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Liew Thye Wui [mailto:twliew@honda.com.sg]

Sent: 12 February, 2018 9:35 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLH9743X AGAINST SHA7494L. Accident date on 9/2/18

Dear Gabriel,

Kindly help to arrange LKK for the survey.

Thank you and have a Nice Day.

Best Regards

TW LIEW

Kah Motor Co. Sdn. Bhd.

15 Ubi Road 4

Singapore 408610

DID: 6514 5687

Fax: 6748 0770

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: Monday, 12 February, 2018 9:12 AM

To: Liew Thye Wui <twliew@honda.com.sg>

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLH9743X AGAINST SHA7494L. Accident date on 9/2/18

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Liew Thye Wui [<mailto:twliew@honda.com.sg>]

Sent: 10 February, 2018 2:31 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: DIRECT SETTLEMENT OF VEHICLE NO: SLH9743X AGAINST SHA7494L. Accident date on 9/2/18

Dear Officer-in-charge,

Kindly refer to the attachments for third party direct settlement.

Vehicle is not in our workshop. Please call for the arrangement.

Meanwhile, kindly get back to me once liability has establish.

Thank you very much.

Best Regards

TW LIEW

Kah Motor Co. Sdn. Bhd.

15 Ubi Road 4

Singapore 408610

DID: 6514 5687

Fax: 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this

communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.


If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018 Edit Reg		12 Feb 2018 00:00 Edit Adj Rpt	S\$5,127.99 Edit Estimates	S\$5,127.99 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	NAGAPAN CHANDRASEKARAN , ID: S2666185D		
Vehicle Reg. No.:	SLH9743X	Date of Loss:	09/02/2018 06:00 - :59 [14 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18020304	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA7494L	Policy No. (Claimant):	MT/00418342
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/02/2018]		
Driver/Custodian (Insured):	KUSMAYADI BIN KAMARUSANAWI (), NRIC: S8421387Z		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (03/05/2018): Alert - Adj Mandate Approved (S\$6021.95) - SLH9743X - Claim Handler: NATALIE LEE
- III_SG (14/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SLH9743X - Claim Handler: NATALIE LEE

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLH9743X (MCT18020304)**
[SHA7494L]
TP
NAGAPAN CHANDRASEKARAN
Feb 9 2018 6:00AM
[COMFORT TRANSPORTATION PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/04/18 09:24	General View	Load JPG	☒
2	13/04/18 09:24	General View	Load JPG	☒
3	13/04/18 09:24	General View	Load JPG	☒
4	13/04/18 09:24	General View	Load JPG	☒
5	13/04/18 09:24	General View	Load JPG	☒
6	13/04/18 09:24	General View	Load JPG	☒
7	13/04/18 09:24	General View	Load JPG	☒
8	13/04/18 09:24	General View	Load JPG	☒
9	13/04/18 09:24	General View	Load JPG	☒
10	13/04/18 09:24	General View	Load JPG	☒
11	13/04/18 09:24	General View	Load JPG	☒
12	13/04/18 09:24	General View	Load JPG	☒
13	13/04/18 09:24	General View	Load JPG	☒
14	13/04/18 09:24	General View	Load JPG	☒
15	13/04/18 09:24	General View	Load JPG	☒
16	13/04/18 09:24	General View	Load JPG	☒
17	13/04/18 09:24	General View	Load JPG	☒
18	13/04/18 09:24	General View	Load JPG	☒
19	13/04/18 09:24	General View	Load JPG	☒
20	13/04/18 09:24	General View	Load JPG	☒
21	13/04/18 09:24	General View	Load JPG	☒
22	13/04/18 09:24	General View	Load JPG	☒
23	13/04/18 09:24	General View	Load JPG	☒

Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 14:51	ACKNOWLEDGEMENT EMAIL TO III DD 13.02.2018	Load PDF	
2	13/02/18 14:51	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT	Load PDF	
3	14/02/18 10:24	SAS Alert - Accident involving SHA7494L (OI) and SLH9743X (TP) ON 09.02.2018	Load PDF	
4	20/02/18 19:27	TP ESTIMATE - MARKED	Load PDF	
5	27/04/18 13:03	LOD	Load PDF	
6	27/04/18 13:03	WORKSHOP INVOICE	Load PDF	
7	27/04/18 13:03	RENTAL RECEIPT	Load PDF	
8	11/05/18 10:25	AUTHORISATION TO ACT	Load PDF	
9	11/05/18 10:25	DISCHARGE VOUCHER	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 08:44	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002888/AWA3S2
Date: 11/05/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No: SLH9743X Insured Vehicle No: SHA7494L
Date of Loss: 09/02/2018 Nature of Claim: TP Claim No: MCT18020304

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH9743X Engine No: L15B4531168
Make & Model: HONDA HR-V, 1.5 (A) Chassis No: JHMRU1810GX201168
Reg. Date: 24/11/2016 (Man. Year: 2016) Odometer: 32280 km
Colour: Brown
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,083.79	1,127.99	2,955.80	72.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	4,000.00	3,050.00	43.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,133.79	5,127.99	6,005.80	53.94
+ GST 7.00/7.00% (S\$)	779.37	358.96	420.41	53.94
Nett Amount (S\$)	11,913.16	5,486.95	6,426.21	53.94
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
Nett Liability (S\$)		6,021.95		

INSPECTION

Date of Assignment: 12/02/2018
Date Inspected: 14/02/2018 Inspected At: Kah Motor Co. Sdn. Bhd. (Ubi)
Estimated Period of Repair: 5.0 days 15 Ubi Road 4
Singapore 408610

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but
https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=683963&extid=264527&CFID=33611192&CFTOKEN=6

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 May 2018)

Parts: M1-SUV HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH9743X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPRR.	Repair	274.27 FS	*- FS
2	1		*TAILGATE COMP	Dented	629.17 FS	*629.17 FS
3	1		*WEATHERSTRIP TAILGATE	Not Necessary	72.60 FS	*- FS
4	1		*SWITCH ASSYTAILGATE OPENER	Not Necessary	77.40 FS	*- FS
5	1		*LOCK ASSYTAILGATE	Not Necessary	57.45 FS	*- FS
6	1		*RUBBER CR.WINDSHIELD DAM	Necessary	14.47 FS	*14.47 FS
7	1		*DAMPERSTD 5X5	Necessary	6.22 FS	*6.22 FS
8	1		*RUBBER,L.WINDSHIELD DAM	Necessary	14.47 FS	*14.47 FS
9	4		*FASTENER BW/SHIELD	Necessary	9.60 FS	*9.60 FS
10	1		*FASTENER B	Necessary	7.35 FS	*7.35 FS
			2pcs			
11	1		*FASTENER AW/SHIELD	Necessary	5.25 FS	*5.25 FS
			2pcs			
12	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
13	1		*LINING ASSYRR.PANEL	Not Necessary	32.25 FS	*- FS
14	1		*BASE COMPL.TRUNK SIDE LINING	Not Necessary	108.15 FS	*- FS
15	1		*EMBLEMRR.	Necessary	9.67 FS	*9.67 FS
16	1		*EMBLEM,RR. I-VTEC	Necessary	10.57 FS	*10.57 FS
17	1		*PROTECTOR,R,RR.WHEEL ARCH	Not Necessary	129.07 FS	*- FS
18	1		*PROTECTOR,L,RR.WHEEL ARCH	Not Necessary	129.07 FS	*- FS
19	1		*FACE RR.BUMPER	Deformed	571.95 FS	*347.77 FS
20	1		*FACE.RR.BUMPER CORNER	Not Necessary	69.22 FS	*- FS
21	1		*FACEL.RR.BUMPER CORNER	Not Necessary	69.22 FS	*- FS
22	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
23	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
24	1		*REFLECTOR ASSYR.RR.	Not Necessary	113.85 FS	*- FS
25	1		*REFLECTOR ASSYL.RR.	Not Necessary	113.85 FS	*- FS
26	1		*LAMP UNITR.	Not Necessary	321.52 FS	*- FS
27	1		*LAMP UNITL.	Not Necessary	321.52 FS	*- FS
28	1		*LIGHT ASSY,R.LID	Not Necessary	198.45 FS	*- FS
29	1		*LIGHT ASSYL.LID	Not Necessary	198.45 FS	*- FS
30	1		*ANTENNA ASSYL.F.	Not Necessary	43.57 FS	*- FS
31	1		*BUZZER ASSYSMART	Not Necessary	44.47 FS	*- FS
32	4		*ACT RR.SENSOR	Not Necessary	320.00 FS	*- FS
33	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
34	1		*GROMMET.SCREW.5	Necessary	3.45 FS	*3.45 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$) 4,083.79 1,127.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY JOINT SEALANT.	New	100.00	0.00
2	BODY UNDERSIDE COATING.	New	100.00	0.00
3	APPLY BODY UNDERSIDE COATING.	New	250.00	0.00
4	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.	New	80.00	80.00
5	REMOVE & INSTALL RR. WINDSCREEN.	New	280.00	280.00
6	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.	New	320.00	320.00
7	REMOVE, REPLACE & INSTALL SMART ENTRY SENSOR.	New	450.00	280.00
8	REMOVE & RENEW REVERSE SENSOR.	New	120.00	120.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	450.00	450.00
10	CUT OFF & RENEW RR PANEL. STRAIGHTEN.	New	2,400.00	1,120.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	2,500.00	1,350.00
Gross Labour Cost (S\$)			7,050.00	4,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >