

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH9743X

Chassis No : JHMRU1810GX201168

Model : HRV DX-SIN CVT YM 2016

Owner's Name : NAGAPPAN CHANDRASEKARAN

Ins Policy No. :

Date of Accident : 9/2/2018

Document No. : SQT18000636

Date : 10. Feb 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4531168

Date | Time : 10. Feb 2018 8:30:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: NAGAPPAN CHANDRASEKARAN OWNER INSURER: DIRECT ASIA INSURANCE (S) PTE LTD ACC DATE: 9/2/18 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHA7494L						
66100-T7A-300ZZ	PANEL COMPR. ?	1	365.70	25	274.27	19.20	293.47
68100-T7A-J20ZZ	TAILGATE COMP <i>Painted</i>	1	838.90	25	629.17	44.04	✓ 673.21
74440-T7A-003	WEATHERSTRIPTAILGATE <i>new</i>	1	96.80	25	72.60	5.08	✓ 77.68
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER <i>new</i>	1	103.20	25	77.40	5.42	✓ 82.82
74800-T7A-J02	LOCK ASSYTAILGATE <i>new</i>	1	76.60	25	57.45	4.02	✓ 61.47
73215-T7A-003	RUBBER CR.WINDSHIELD DAM <i>new</i>	1	19.30	25	14.47	1.01	✓ 15.48
73226-SZW-000	DAMPERSTD 5X5 <i>new</i>	1	8.30	25	6.22	0.44	✓ 6.66
73265-T7A-003	RUBBER,L.WINDSHIELD DAM	1	19.30	25	14.47	1.01	✓ 15.48
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	✓ 10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	✓ 7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	✓ 5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ?	1	60.00		60.00	4.20	✓ 64.20
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	43.00	25	32.25	2.26	✓ 34.51
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING <i>new</i>	1	144.20	25	108.15	7.57	✓ 115.72
75722-T7W-A01	EMBLEMRR. <i>3mm</i>	1	12.90	25	9.67	0.68	✓ 10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.10	25	10.57	0.74	✓ 11.31
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH <i>3mm</i>	1	172.10	25	129.07	9.03	✓ 138.10
74450-T7B-003	PROTECTOR,L,RR.WHEEL ARCH	1	172.10	25	129.07	9.03	✓ 138.10
71501-T7B-000	FACE RR.BUMPER <i>Dehd</i>	1	762.60	25	571.95	40.04	✓ 611.99

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH9743X

Chassis No : JHMRU1810GX201168

Model : HRV DX-SIN CVT YM 2016

Owner's Name : NAGAPPAN CHANDRASEKARAN

Ins Policy No. :

Date of Accident : 9/2/2018

Document No. : SQT18000636 Page 2

Date : 10. Feb 2018

Customer No. : WZI007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4531168

Date | Time : 10. Feb 2018 8:30:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER <i>3 new</i>	1	92.30	25	69.22	4.85	74.07
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
71593-T7A-000	SPACERR.RR.BUMPER SIDE <i>3 new</i>	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>3 new</i>	1	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	151.80	25	113.85	7.97	121.82
33502-T7A-J01	LAMP UNITR. <i>3 new</i>	1	428.70	25	321.52	22.51	344.03
33552-T7A-J01	LAMP UNITL.	1	428.70	25	321.52	22.51	344.03
34150-T7A-J01	LIGHT ASSY,R.LID <i>3 new</i>	1	264.60	25	198.45	13.89	212.34
34155-T7A-J01	LIGHT ASSYL.LID	1	264.60	25	198.45	13.89	212.34
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	58.10	25	43.57	3.05	46.62
74940-TZ5-A01	BUZZER ASSYSMART ?	1	59.30	25	44.47	3.11	47.58
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
Sum Item					4050.34	283.52	4,333.86
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00		280.00	19.60	299.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00		320.00	22.40	342.40
BOMISC1	REMOVE, REPLACE & INSTALL SMART ENTRY SENSOR.1	1	450.00		450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2400.00		2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00		2500.00	175.00	2675.00
Sum Labor					7080.00	495.60	7,575.60

Printed on 10/2/2018 2:16:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLH9743X

Chassis No : JHMRU1810GX201168

Model : HRV DX-SIN CVT YM 2016

Owner's Name : NAGAPPAN CHANDRASEKARAN

Ins Policy No. :

Date of Accident : 9/2/2018

Document No. : SQT18000636 **Page** 3

Date : 10. Feb 2018

Customer No. : WZ1007

Svc Advisor : LIEW THYE WEI

Engine No : L15B4531168

Date | Time : 10. Feb 2018 8:30:48 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<i>Adrian L</i>						
Date & Time	<i>14/02/18.</i>						
Excess							
Status							
Signature	<i>[Signature]</i>						
					Total Amount	11,130.34	779.12
					Total (Inclusive of GST)		11,909.46

05 Days.
08 Days.

Printed on 10/2/2018 2:16:44 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)