

PDI TUAS

PDI TUAS

TAN ROBIN
613B PUNGGOL DRIVE
#07-847
Singapore, 822613
Singapore

5 Days .
before paint photos .
Guo Qiang - 8880282
13/2/18 .

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV030758
Quote No. SER/QUO/1800242
QuoteDate 10/02/18
Salesperson REX LEOW
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE	78,733	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKX8699A	WVWZZZ16ZFM029989	27/08/15	REX LEOW
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F54281	1634G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR 840	7	UNIT	1680	5,880.00
P B&P MACP LABOUR	R&R REAR LUGGAGE TRIM	1	UNIT	?	840.00
P B&P MACP PAINT	SPRAY PAINT 800	7	UNIT	2000	5,600.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE ?	1	Pieces		400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				13,480.00
P 1K0253144AT	REAR SILENCER BRACKET ?	1	Pieces		106.43
P 5C6253609J	REAR SILENCER ?	1	Pieces		1,721.12
P 5C6807305	REINFORCEMENT / BT	1	Pieces		514.20
P 5C6807375	LHR BUMPER BRACKET ?	1	Pieces		96.14
P 5C6807376	RHR BUMPER BRACKET ?	1	Pieces		96.14
P 5C6807421H GRU	REAR BUMPER / TN	1	Pieces		1,452.29
	Predecessor 5C6807417J GRU				
P 5C6807433J	SPOILER / BL	1	Pieces		476.26
P 5C6807863B	REAR CENTRE BRACKET ?	1	Pieces		111.92
P 5C6827025E	BOOT LID X Repair	1	Pieces		1,411.01
	Predecessor 5C6827025D				
P 5C6827301E	LHR HINGE X NN	1	Pieces		94.92
	Use Predecessor 5C6827301D				
P 5C6827302D	RHR HINGE X NN	1	Pieces		94.92
	Use Predecessor 5C6827302B				
P 5C6827705A 5AP	BOOT LID SEAL ?	1	Pieces		252.81
	Sum carried forward				19,908.13

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN ROBIN
613B PUNGGOL DRIVE
#07-847
Singapore, 822613
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV030758
Quote No. SER/QUO/1800242
QuoteDate 10/02/18
Salesperson REX LEOW
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE	78,733	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKX8699A	WVWZZZ16ZFM029989	27/08/15	REX LEOW
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F54281	1634G5
Continued			19,908.13
P 5C6853630F ULM	VW SIGN	1 Pieces	125.10
P 5C6853675APGQF	TSI EMBLEM	1 Pieces	57.33
P 5C6853687 739	JETTA EMBLEM	1 Pieces	76.11
P 5C6945093D	LHR INNER TAILLIGHT	1 Pieces	182.58
P 5C6945094E	RHR INNER TAILLIGHT	1 Pieces	182.58
P 5C6945095H	LHR OUTER TAILLIGHT	1 Pieces	401.20
P 5C6945096H	RHR OUTER TAILLIGHT	1 Pieces	412.98
P 5C6945105B	LHR REFLECTOR	1 Pieces	62.30
Sum Item			7,928.30
Sum Labor			13,480.00
Sum Item			7,928.30

Explanations

P = Proportionately Charged

Payment Terms

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and No Credit to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total SGD 21,408.30
7% GST 1,498.62
Total SGD Incl. GST 22,906.92

Payments to:

- BBN: - Acc.-No..: