

ASS. REC. BY:

REF:

CS / MSC18002901 / Tlvbn2

Special Instruction:

Surveyor:

Tavfilch.

ASSIGNMENT (Office)

From (Person):

Dng Shu Xiang

of

NSLH

Date/Time: 13.02.2018 1037Gm

Estimated Cost:

Bill to:

OD / ~~TP~~ AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGM 6325Y

Insured:

Public Liability

at Workshop m/s

Cycle & Carriage

Tel:

of

188 Pandan Loop.

Policy No:

Claim No:

28813274 PLY

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11.02.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

13.02.2018 11am

Person Contacted:

Alan

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGM 6325Y - NA / ALH / 80027114 / r3
	Public Liability - x
14/2/18	Email preli revised to Shu Xiang
8/3/18	@ 238pm Alan will check
23/4/18	@ 434pm Alan will check



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002901/T1vb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-02-2018

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SGM 6325Y
Policy No.		Coverage (\$)	0.00
Claim No.	28813274 PLY	Excess (\$)	0.00
Assign From	ONG SHU XIANG	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/02/2018	Inspection Date	13/02/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 28813274PLY
Our ref: CS/MSG18002901/T1vb 1/4/2016

DATE: 14/2/2018

The Motor Claims Department
M/s: MSIG INSURANCE (SINGAPORE) I

WITHOUT PREJUDICE

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SGM 6325Y


We thank you for your instruction on 13/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13/2/2018 at the premises of M/s CYCLE & CARRIAGE INDUSTRIES (1986) PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$9,671.28
Revised Estimate Amount	: S\$8,114.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No.: CS/MSG 18002901/Tivb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

VERON

Case Handler

28/5/18

Date

*C: Critical *N: Non-Critical

21/05/20

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 14 February 2018 2:40 PM
To: 'Ong Shu Xiang'
Cc: SUR
Subject: RE: URGENT - New Matter: Survey on SGM6325Y - MSIG Ref: 28813274 PLY
Attachments: SGM 6325Y PRELI REVISED.pdf

Dear Shu Xiang,

Enclosed preliminary revised of vehicle SGM 6325Y
Date of survey: 13/2/2018
Number of days: 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 13 February 2018 12:13 PM
To: 'Ong Shu Xiang' <shuxiang_ong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: URGENT - New Matter: Survey on SGM6325Y - MSIG Ref: 28813274 PLY

Dear Shu Xiang,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shu Xiang [mailto:shuxiang_ong@sg.msig-asia.com]
Sent: Tuesday, 13 February, 2018 10:37 AM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: URGENT - New Matter: Survey on SGM6325Y - MSIG Ref: 28813274 PLY
Importance: High

Dear Sirs

This is a new matter.

We will like LKK to arrange for a survey on SGM6325Y on a Without Prejudice basis.

Circumstances of accident

Our Insured is GN Valet Pte Ltd. On 11 Feb 2018, our Insured's driver drove the customer's vehicle too close to the side of the wall when turning left while driving up from the basement car park at Clarke Quay Capitaland. This has resulted in some scratches on the left-hand side of the back door.

Enclosed is the driver's sketch plan of the incident, photograph of the damages sustained and the repair quotation from Cycle & Carriage (will be sent in two emails due to file size constraint).

Please let us have your advice regarding repair costs, number of days of repair and if the damages sustained by sGM6325Y is consistent with the circumstances of accident.

We hope to hear from you soon.

Ong Shu Xiang

Executive, Claims Services

D: +65 6643 1337 | F: +65 6643 1349 | shuxiang_ong@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Catherine Chong (LKK Auto)

From: Ong Shu Xiang <shuxiang_ong@sg.msig-asia.com>
Sent: Tuesday, 13 February, 2018 10:37 AM
To: assignments; SUR
Subject: URGENT - New Matter: Survey on SGM6325Y - MSIG Ref: 28813274 PLY
Attachments: 20180211_131034.jpg; img-212223445-0001.pdf

Importance: High

Dear Sirs

This is a new matter.

We will like LKK to arrange for a survey on SGM6325Y on a Without Prejudice basis.

Circumstances of accident

Our Insured is GN Valet Pte Ltd. On 11 Feb 2018, our Insured's driver drove the customer's vehicle too close to the side of the wall when turning left while driving up from the basement car park at Clarke Quay Capitaland. This has resulted in some scratches on the left-hand side of the back door.

Enclosed is the driver's sketch plan of the incident, photograph of the damages sustained and the repair quotation from Cycle & Carriage (will be sent in two emails due to file size constraint).

Please let us have your advice regarding repair costs, number of days of repair and if the damages sustained by SGM6325Y is consistent with the circumstances of accident.

We hope to hear from you soon.

Ong Shu Xiang
Executive, Claims Services
D: +65 6643 1337 | F: +65 6643 1349 | shuxiang_ong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGM6325Y

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No **21291**
Reg No/Reg Date **SGM6325Y / 15/11/2016**
Date In/Mileage **/ 0**
Chassis No **WDD2221622A291970**
Engine No **27682430464370**
Make/Model **MB/MB S 320 L SEDAN (V222)**
Colour/Trim **027 799 Diamond Whi/ 048 805 Orient Beig**

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000558	Credit	12/02/2018/ 22:33	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPNSUN ACC DATE :10-02-2018 DRIVE IN:12-02-2018 / GN VALET (MSIG INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT								✓ ✓ 480.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT								✓ ✓ 600.00
A BPILAB REMOVE & REPLACE REAR LEFT DOOR & REPAIR FRONT LEFT DOOR								✓ 1440 1920.00
A BPIRES RESPRAY FRONT LEFT DOOR & REAR LEFT DOOR								✓ 1600 2000.40
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								n ⁿ x 540.00
M	LH/R DOOR SHELL	1.00	3597.70	00.00				dd ✓ 3597.70
M	LH/R DOOR SIDE SEAL	1.00	28.10	00.00				nee ✓ 28.10
M	LH/R DOOR INNER SEAL	1.00	28.10	00.00				nee ✓ 28.10
M	LH/R DOOR WEATHERSTRIP	1.00	280.72	00.00				nee ✓ 280.72
M	LH/R DOOR BOTTOM SEAL	1.00	59.38	00.00				nee ✓ 59.38
M	LH/R DOOR TOP HINGE	1.00	136.88	00.00				fee ✓ 136.88

Alan Quek
Cycle & Carriage Industries Pte Ltd
16 Raffles Quay #24-01
Hong Leong Building
Singapore 048581
Tel: 6779 5377 / 6779 5388 Fax: 6779 5383
Email: alan.quek@cyclecarriage.com.sg

Tayfik 97495749
13/2/18 @ 1455
WP
* Resurvey before paint
sure @ lkkauto.com.
7 days.

9853.89

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting

Confirmed & accepted by part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company
Authorized signatory and company stamp

Nett 9,671.28
7% GST on 9671.28 676.99
Total Payable 10,348.27

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-5500111-X

ESTIMATE FOR SGM6325Y

Finalization

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Taufikh

Vehicle & Document Information
WIP No 21291
Reg No/Reg Date SGM6325Y / 15/11/2016
Date In/Mileage 13/02/2018 / 14716
Chassis No S WDD2221622A291970
Engine No 27682430464370
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 027 799 Diamond Whi/ 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	29/04/2018/ 20:51	AQ	305 / Alan Quek At Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
NOT AN OFFICIAL TAX INVOICE M_BPNSUN ACC DATE: 10-02-2018 DRIVE IN: 12-02-2018 / GN VALET (MSIG INSURANCE) DATE IN/DATE SURVEY: 13-02-2018 // LKK TAUFIKH BY/AUTHORIZED ON: LONG SHU XIANG // 13-02-2018 A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT A BPILAB REMOVE & REPLACE REAR LEFT DOOR & REPAIR FRONT LEFT DOOR A BPIRES RESPRAY FRONT LEFT DOOR & REAR LEFT DOOR X LH/R DOOR SHELL X LH/R DOOR SIDE SEAL X LH/R DOOR INNER SEAL X LH/R DOOR WEATHERSTRIP X LH/R DOOR BOTTOM SEAL X PLUG X LH/R DOOR SELF-ADHESIVE TRIM X LOCKING CAP X LOCKING CAP X LH/R DOOR MOULDING				
				480.00
				600.00
				1440.00
		0.05		1600.00
	1.00	3597.70	00.00	3597.70
	1.00	28.10	00.00	28.10
	1.00	28.10	00.00	28.10
	1.00	280.72	00.00	280.72
	1.00	59.38	00.00	59.38
	1.00	6.33	00.00	6.33
	1.00	16.05	00.00	16.05
	1.00	4.16	00.00	4.16
	1.00	4.16	00.00	4.16
	1.00	151.91	00.00	151.91

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 8,296.61
7% GST on 8296.61 580.76
Total Payable 8,877.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

SUPPLEMENTARY

ESTIMATE FOR SGM6325Y

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 21291
Reg No/Reg Date SGM6325Y / 15/11/2016
Date in/Mileage 13/02/2018 / 14716
Chassis No S WDD2221622A291970
Engine No 27682430464370
Make/Model MB/MB S 320 L SEDAN (V222)
Colour/Trim 027 799 Diamond Whl / 048 805 Orient Beig

Account No	Terms	Date/Time Printed	CSE	Operator
W1000558	Credit	29/04/2018/ 20:51	AQ	305 / Alan Quek A1 Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M. BRNSUN

ACC. DATE: 10-02-2018
DRIVE IN: 12-02-2018 / GN VALET (MSIG INSURANCE)
DATE IN/DATE SURVEY: 13-02-2018 // LKK TAUFIKH
BY/AUTHORIZED ON : ONG SHU XIANG // 13-02-2018

NOT AN OFFICIAL TAX INVOICE

X PLUG	1.00	6.33	00.00	6.33
X LH/R DOOR SELF-ADHESIVE TRIM	1.00	16.05	00.00	16.05
X LOCKING CAP	1.00	4.16	00.00	4.16
X LOCKING CAP	1.00	4.16	00.00	4.16
X LH/R DOOR MOULDING	1.00	151.91	00.00	151.91

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 FAX: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	182.61
7% GST on	182.61	12.78
Total Payable		195.39

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 120378
Tel: 6777 8380
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18002901/T1vbn2

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 30-05-2018

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SGM 6325Y
Policy No.		Coverage (\$)	0.00
Claim No.	28813274 PLY	Excess (\$)	0.00
Assign From	ONG SHU XIANG	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ S320	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2221622A291970	Colour	DIAMOND WHITE
Odometer	14716	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/30 R21	MICHELIN	6 mm
L/H Front Tyre	295/30 R21	MICHELIN	6 mm
R/H Rear Tyre	295/30 R21	MICHELIN	6 mm
L/H Rear Tyre	295/30 R21	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/02/2018	Inspection Date	13/02/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 6325Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH/R DOOR SHELL (SN)	DENTED	3,597.70	3,597.70
1	LH/R DOOR SIDE SEAL (SN)	NECESSARY	28.10	28.10
1	LH/R DOOR INNER SEAL (SN)	NECESSARY	28.10	28.10
1	LH/R DOOR WEATHERSTRIP (SN)	NECESSARY	280.72	280.72
1	LH/R DOOR BOTTOM SEAL (SN)	NECESSARY	59.38	59.38
1	LH/R DOOR TOP HINGE (SN)	TO REPAIR SEE LABOUR	136.88	-
1	PLUG (ADDITIONAL)(SN)	NECESSARY	6.33	6.33
1	LH/R DOOR SELF-ADHESIVE TRIM (ADDITIONAL)(SN)	NECESSARY	16.05	16.05
1	LOCKING CAP (ADDITIONAL)(SN)	NECESSARY	4.16	4.16
1	LOCKING CAP (ADDITIONAL)(SN)	NECESSARY	4.16	4.16
1	LH/R DOOR MOULDING (ADDITIONAL)(SN)	NECESSARY	151.91	151.91
			4,313.49	4,176.61
	<u>LABOUR</u>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		480.00	480.00
	TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.		600.00	600.00
	REMOVE & REPLACE REAR LEFT DOOR & REPAIR FRONT LEFT DOOR.INCLUSIVE OF THE REPAIR OF LH/R DOOR TOP HINGE.		1,920.00	1,440.00
	RESPRAY FRONT LEFT DOOR & REAR LEFT DOOR.		2,000.40	1,600.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	540.00	-
			5,540.40	4,120.00
	GRAND TOTAL		9,853.89	8,296.61
	RECOMMENDED COST OF REPAIRS			8,296.61

Report Ref No. CS/MSG18002901/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.