



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : POH FAIR LI
20A AH SOO GARDEN

SINGAPORE 539981

ATTN:

Your Ref No: SDV618E
Claim Type: Third Party
Accident Date: 05/02/2018
TP Veh Reg No: SHD9516D

Estimate No: MC0912837
Date: 07 Feb 2018
Policy No: GA310761
Veh Reg No: SDV618E
Make/Model: MERCEDES BENZ
SLK200

Estimate Repair Cost to Vehicle No :SDV618E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT FENDER LH	1 PC	790.00 X	
2 FRONT FENDER KOMPRESSOR BADGE LH	1 PC	138.00 ✓	
		928.00	
	Less 20%	185.60	742.40
LABOUR			
3 TO REPAIR SPORTS RIM LHF	1 PC	180.00 X	
4 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00 60	
5 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR FRONT DOOR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00 150	
6 TO SPRAY FRONT FENDER LH, FRONT DOOR LH	1 PC	500.00 400	
		1,160.00	1,160.00
Total			S\$ 1,902.40
Add GST @ 7%			133.17
Total Amount Payable			S\$ 2,035.57

TOTAL: SINGAPORE DOLLAR TWO THOUSAND THIRTY FIVE AND CENTS FIFTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Not Authorized
12/2/18

For AH LIM MOTOR COMPANY

20/2/18



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: