CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO.: SHA 8679P

MAKE

DATE 12/2/2018 16:37

AVOY

: HYUNDAI i40 MODEL Parts Description/ Labour Type **Unit Price** Amount Qty \$ 562.30 Front Bumper Cover X Mp.2 Front Bumper Bracket Top (LH) ? \$ 22.40 Front Bumper Retainer Mounting ? \$ 9.20 SUB TOTAL \$ 593.90 Front Fee La (L4) X My are **LESS 20%** \$ 118.78 DISCOUNTED TOTAL \$ 475.12 Frt Fender Advertisement Logo (LH) 100.00 \$ Nett 100.00 Labour Charge 200 350.00 Panel Beating \$ 400.00 Spray Painting Charge Tuff Kote TOTAL LABOUR 800.00 ESTIMATE TOTAL 1,375.12 Kalia (Cky)

13/2/8 1005h

2 Pags.

P(p)

After Report place KK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged partis) damagresurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementa vitem(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.