

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lentor Plain
Singapore 786548

Not Authorized
11/12/18
Presuming After Painting
4 days

Date: 12/02/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : TOYOTA COROLLA AXIO 1.5 G A / SKZ8576K		
1 pc	front head lamp L.E.D Assy <i>Car</i>	
1 pc	front head lamp lower bracket <i>Sw X</i>	
1 pc	front bumper <i>?</i>	
1 pc	front bumper lower gear <i>Sw X</i>	
1 pc	front bumper reinforcement <i>R X</i>	
1 pc	front bumper sponge <i>Sw X</i>	
1 pc	front bumper side retainer <i>Sw X</i>	
1 pc	front shock adsorber <i>?</i>	
1 pc	front lower arm	
1 pc	front lower arm ball joint <i>Sw X</i>	
1 pc	front steering road <i>?</i>	
1 pc	front steering road end ball joint <i>Sw X</i>	
1 pc	front knuckle arm <i>?</i>	
1 pc	front wheel hub <i>?</i>	
1 pc	front wheel bearing <i>?</i>	
1 pc	hub cap <i>Not Seen</i>	
1 pc	rod rim <i>Sw X</i>	
Sub total		0.00
To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.		500.00 <i>3001</i>
To check wiring system		50.00 <i>201</i>
To apply putty and spray painting on affected areas.		600.00 <i>4001</i>
To remove and install front undercarriage parts to eable to repair.		150.00 <i>?</i>
To replace alloy rim and perform wheel balancing.		40.00 <i>an X</i>
To machine press wheels bearing.		40.00 <i>?</i>
To perform 4 wheels computerised alignment.		85.00 <i>601</i>
Total		1,465.00