

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SFY4005H

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 11/02/2018

TP Veh Reg No: SGP37C

Estimate No: ES1890152

Date: 13 Feb 2018

Policy No: 509104148-12

Veh Reg No: SFY4005H

Make/Model: NISSAN SUNNY 1.6EXM

Chassis No: JN1CFAN16Z0092582

Engine No: QG16384087

Reg. Date: 14/09/2005

Estimate Repair Cost to Vehicle No :SFY4005H

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR PANEL	394.90	1 PC	394.90	✓
2 REAR PANEL INNER TOP GARNISH	85.00	1 PC	85.00	✓
3 REAR PANEL INNER SIDE GARNISH	144.10	1 PC	144.10	✓
4 REAR PANEL INNER SIDE GARNISH CLIPS	12.10	3 PC	36.30	✓
5 REAR SPARE TYRE TOP BOARD	203.40	1 PCS	203.40	✓
6 TAIL LAMP	385.70	2 PCS	771.40	✓
7 REAR FENDER	776.30	2 PC	1,552.60	✓
8 REAR FENDER INNER GARNISH	233.30	2 PC	466.60	✓
9 REAR FENDER INNER GARNISH CLIPS	5.50	6 PC	33.00	✓
10 REAR WINDSCREEN GLASS MOULDING	157.30	1 PC	157.30	✓
11 REAR SPARE TYRE PANEL	832.70	1 PC	832.70	✓
12 REAR FENDER INNER SHIELD	51.20	2 PC	102.40	✓
13 REAR BUMPER	452.50	1 PC	452.50	✓
14 REAR BUMPER SPONGE	133.80	1 PC	133.80	✓
15 REAR BUMPER RH BRACKET	91.70	1 PC	91.70	✓
16 REAR BUMPER SIDE RETAINER	35.20	2 PC	70.40	✓
17 REAR BUMPER CLIPS	2.60	6 PC	15.60	✓
18 REAR BOOT	674.60	1 PC	674.60	✓
19 REAR BOOT LOGO	64.60	1 PC	64.60	✓
20 REAR BOOT EMBLEM 'SUNNY'	82.60	1 PC	82.60	✓
21 REAR BOOT EMBLEM 'EX SALOON'	68.70	1 PC	68.70	✓
22 REAR BOOT EMBLEM 'CVTC'	68.70	1 PC	68.70	✓
23 REAR BOOT EMBLEM 'E-THROTTLE'	67.10	1 PC	67.10	✓
24 REAR BOOT TOP MOULDING	369.10	1 PC	369.10	✓
25 REAR BOOT LOWER MOULDING	208.90	1 PC	208.90	✓
26 REAR BOOT INNER LOCK	69.00	1 PC	69.00	✓
27 REAR BOOT INNER RUBBER	80.30	1 PC	80.30	✓
28 REAR BOOT HINGES	87.60	2 PCS	175.20	✓
			7,472.50	
		Less 10%	747.25	6,725.25
Special Net				
29 REAR BUMPER MOULDING	174.00	1 PC	174.00	✓
30 REAR BUMPER LOWER SKIRT	578.00	1 PC	578.00	✓
31 REAR EXHAUST PIPE	504.00	1 PC	504.00	✓
32 REAR MUD FLAP	87.80	2 PCS	175.60	✓
33 REAR WINDSCREEN GUM	40.00	1 PCS	40.00	✓
34 REVERSE SENSOR	200.00	1 PC	200.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP-AIG
 Claim Type: Third Party
 Accident Date: 11/02/2018
 TP Veh Reg No: SGP37C

Estimate No: ES1890152 ES1890152/WS
 Date: 13 Feb 2018
 Policy No: 509104148-12
 Veh Reg No: SFY4005H
 Make/Model: NISSAN SUNNY 1.6EXM
 Chassis No: JN1CFAN16Z0092582
 Engine No: QG16384087
 Reg. Date: 14/09/2005

Estimate Repair Cost to Vehicle No :SFY4005H

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
35 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00	80.00
36 REAR BUMPER REFLECTOR	120.00	1 PC	120.00	120.00
37 REAR NUMBER PLATE	35.00	1 PC	35.00	35.00
			1,906.60	1,906.60
Labour				
38 TOWING (BILL ATTACHED)	60.00	1 LA	60.00	60.00
39 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	120.00
40 REMOVE AND REFIX REAR SEAT, CARPET, GARNISH SAFETY BELT, TOP ROOF LINING ETC	120.00	1 LA	120.00	120.00
41 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, REAR BOOT AND ATTACHMENT. TO STRIAGHTEN, KNOCK OUT, CUTTING, WELDING, RENEW REAR SPARE TYRE PANEL, REAR PANEL, BOOT, REAR BOTH FENDERS. KNOCK AND REPAIR REAR RH WHEEL HOUSING, STRIAGHTEN REAR RH CHASSISS AND REALIGN THE SAME	2,300.00	1 LA	2,300.00	2,300.00
42 REMOVE AND REFIX REAR EXHAUST PIPE, REAR UNDER CARRIAGE ETC	100.00	1 LA	100.00	100.00
43 TO PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, BOOT, HINGES, REAR PANEL, BUMPER AND REAR AFFECTED AREA	1,400.00	1 LA	1,400.00	1,400.00
44 RUSTPROOFING	90.00	1 LA	90.00	90.00
			4,190.00	4,190.00
			Total	SS 12,821.85
			Add GST @ 7%	897.53
			Total Amount Payable	SS 13,719.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/001

CASH SALE / WORK ORDER

No. 18250

Date: 11/2/18

寶號

Messrs:

車號

Vehicle No:

由

From:

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$:

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.