

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4027G

DATE 13/2/2018 12:01

MAKE :

MODEL : HYUNDAI SONATA

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✓			\$ - 1,349.50	
	Boot Lid Rubber ✕			\$ 110.90	
	Boot Lid Lock Upper ✕			\$ 132.10	
	Boot Lid Lock Lower ✕			\$ 30.30	
	Boot Lid Sonata Plate ✓			\$ - 43.60	
	Boot Lid Hyundai Plate ✓			\$ 24.20	
	Boot Lid 'H' Emblem ✓			\$ - 26.10	
	Boot Lid CRDI Plate ✓			\$ - 22.70	
	Boot Lid Lamp (RH) ✕			\$ 230.20	
	Boot Lid Trimboard ✕			\$ 165.40	
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00	
	Rear Bumper ✓			\$ - 578.40	
	Rear Bumper Reinforcement ✓			\$ - 483.30	
	Rear Bumper Clip ✓			\$ - 22.00	
	Rear Bumper Sponge ✓			\$ - 137.40	
	Rear Bumper Under Cover ✕ reg			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕ reg		\$ 38.00	\$ 76.00	
	Tail Lamp (LH/RH) ✕		\$ 344.00	\$ 688.00	
	Rear Panel ✕			\$ 391.80	
	Rear Panel Garnish ✕			\$ 95.80	
	SUB TOTAL			\$ 4,803.50	
	LESS 20%			\$ 960.70	
	DISCOUNTED TOTAL			\$ 3,842.80	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Rear No. Plate ✕			\$ 25.00	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 105.00	
	Labour Charge				
	Panel Beating			\$ 850.00	360
	Spray Painting Charge			\$ 600.00	
	Wiring Charge			\$ 50.00	✕
	Tuff Kote			\$ 50.00	20
	TOTAL LABOUR			\$ 1,550.00	
	ESTIMATE TOTAL			\$ 5,497.80	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Kalvin (LKK)
 13/2/18 1500hrs.
 3 Days
 4/5
 After Repair p.l.h.