

REPAIR DETAILS
REFERENCE

Vehicle Reg No. : GBB7969A
 Make & Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
 Chassis No. : JN1SC2F24Z0801383
 Engine No. : ZD30245595K
 Year of Manufacture : 2010
 Labour : REPAIRER'S
 TP Vehicle Reg No. : PC3388G PH2992S
 DOA & Location : 09/02/2018 ALONG BKT BATOK ROAD (NEAR FLYOVER)
 Our Ref : GBB7969A / PAREXGROUP (S) PTE LTD

Repair ✓
 f7p/axj
 4/5

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	REAR TAILGATE		\$ 1,399.70
2	1	REAR TAILGATE LOCK		\$ 33.30
3	1	REAR TAILGATE LOCKCATCH		\$ 163.40
4	1	HEADLAMP RH		\$ 473.40
5	1	SIDE RH MIRROR ASSY		\$ 171.80
6	1	FRONT CABIN FRONT RH GARNISH COVER		\$ 111.30
7	1	SIDE RH MIRROR ROUND COVER		\$ 22.90
8	1	SIDE RIGHT MIRROR BASE COVER		\$ 22.90
9	1	R/H DOOR		\$ 1,480.50

Sub-Total (S\$) \$ 3,879.20

SAAA List Item Discount 30% (S\$) \$ 1,163.76

Sub-Total (S\$) \$ 2,715.44

LABOUR

No.	Description	Price
1	LABOUR	\$ 1,400.00
2	SPRAYPAINTING	\$ 1,400.00
3	ANTI-RUST COATING	\$ 100.00
4	REMOVE AND REFIT REAR END PANEL AND GARNISH TO FACILITATE REPAIR	\$ 100.00
5	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE	\$ 120.00
6	REALIGN EXHAUST PIPE	\$ 60.00

Total Labour (S\$) \$ 3,180.00

Total Parts (S\$) \$ 2,715.44

Total Labour (S\$) \$ 3,180.00

Total (S\$) \$ 5,895.44

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
 HP 90010068
 6 days
 22/02/18 @ 1310
 Resy after repair