

ASS. REC. BY:

REF:

CS/FCI18002925/Srd3n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

13/2/18 @ 2:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 587Y

Insured:

SHB 3288L

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Rd

Policy No:

Claim No:

D18001261MESH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 08/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

4:01pm @ 13/2/18

Person Contacted:

caroline

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SKD 587Y - X

SHB 3288L - X

Sent preli thru email.

Confirm

\$5532.65 @ 5 days

Red: \$3606.95, 39%

REF: Hay

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time | Action / Instruction

Veh No: SKD 5874 Yr Regn: 20/4/2012Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 520i c.c. 1997Colour: Black A/C: Insured / Std / NI / NASp. Reading: 7149g T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAHG12050DW35783Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 245/40ZR19R: 275/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/2/18 D.O.I. 5/5/18Survey held at Performance MotorDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist
Date/Time, File Return to?☒ : Final Report

2) _____

Report Format :

Lump Sum / I.B.I. (\$) 5532.657pDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

) \$ + RS. \$ _____

) Photos

) Others

TOTAL

170
50
50
40
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002925/Srd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3288L	Veh. Inspected	SKD 587Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001261MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Your Ref: D18001261MFSH

Our Ref: CS/FCI18002925/Srd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKD 587Y .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05/03/2018 at the premises of M/s PERFORMANCE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 9,139.60 .
Revised Estimate Amount	: S\$ 5,684.30 .
"Check" Items Amount	: S\$ 2,243.30 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at rear portion.



Yours faithfully
SEBASTIAN
Automotive Assessor

Janice Lee (LKKAuto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Wednesday, April 18, 2018 3:20 PM
To: Sebastian Yeang (LKK Auto); SUR
Subject: FINAL REPORT / SKD587Y
Attachments: Final Report SKD587Y_2.pdf; Final Report SKD587Y.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 3,948.00
Total Parts : 1,584.65
Total Labour & Parts : 5,532.65

Repair days: 5

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

MOTOR SURVEY ASSIGNMENT

Date	09-02-2018	Our Ref No. D18001261MFSH
Accident Date	08-02-2018	Claim Type. Third Party
Insured Vehicle	SHB3288L	Third Party Vehicle. SKD587Y
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 63190174	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234896)



PRI Documents



Close



PRI Header Details

Claim No	D18001261MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 63190174 , Phone: 63190174 , Fax: 6479460 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB3288L	TP Vehicle No	SKD587Y
PRI Recieved Date	13-02-2018 02:14:22 PM	Surveyor Appointed Date	13-02-2018 02:54:18 PM	Surveyor Accept Date	13-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, March 08, 2018 5:42 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: RE: SURVEY ASSESSMENT - D18001261MFSH/1
Attachments: SKD 587Y.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SKD 587Y**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, February 13, 2018 4:59 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001261MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 13 February 2018 2:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001261MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Mon 05/03 @ 10AM

SKD587Y

SJR

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

18 FEB 2018

Estimate No. : b1 45896
Date Estimated : 12/02/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Mok Boon Rui (Mo Wenrui)
10 Seletar Green Walk

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 805246

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD587Y	DW35783	20/04/2012	520ia	0

DESCRIPTION

To replace rear bumper & attachments including to knock out boot lid and dented area caused by the accident 850/day

VALUE
2,550.00
100

To respray rear bumper and boot lid bumper 1038 Boot lid 1038

1868 2,076.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

561 661.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 5,721.00

DESCRIPTION

BODY NUT ✓ NEC
RR BUMPER GUIDE BOTTOM CENTRE ✓ TN Bottom Centre Guide
RR BUMPER CTR GUIDE ?
RR BUMPER CARRIER ?
RR BUMPER PANEL PRIMED (PDC) ✓ Deform
RR BUMPER ADAPTER ✓ NEC
EMBLEM GROMMET ✓ NEC
MODEL LETTERING 520i ✓ NEC
BMW EMBLEM ✓ NEC
PLUG ✓ NEC
PLUG BLACK D=5MM ✓ NEC
SENSOR WIRE FOR SMART OPENER TOP ?
SENSOR WIRE FOR SMART OPENER BOTTOM ?
REAR LH REFLECTOR ?
REAR RH REFLECTOR ?

QTY	PRIC
10	0.90
1	58.95
1	67.35
1	714.25
1	1,467.20
1	48.00
2	0.80
1	62.55
1	69.50
10	1.05
10	0.90
1	42.10
1	40.50
1	35.20
1	35.20

VALUE
9.00
58.95
67.35
714.25
1,467.20
48.00
1.60
62.55
69.50
10.50
9.00
42.10
40.50
35.20
35.20



302, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45896
Date Estimated : 12/02/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKD587Y	DW35783	20/04/2012	520iA	0

DESCRIPTION

DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (A90 SOPHISTOGRAU

QTY	PRIC	VALUE
2	5.05	10.10
2	368.80	737.60
Total Parts :		3,418.60

5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 5/3/18 Excess \$5

Surveyor's Name Sebastian Sign [Signature]

Surveyor's Tel 90036121 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No FML Yes / No

Surveyor's E-mail sebastianseang@lkkauto.com

No. of Working Days Recommended _____

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

[Signature]
12/3/18

Labour 1	: 91396	5,721.00
Parts	:	3,418.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	639.77
Grand Total	:	9,779.37

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45896
Date Estimated : 12/02/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mok Boon Rui (Mo Wenrui)
10 Seletar Green Walk

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 805246

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SKD587Y	DW35783	20/04/2012	520iA	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident				1700.00		1,700.00
To respray rear bumper and boot lid				1838.00		1,868.00
To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function				150.00		150.00
To check electrical wiring systems and lightings at the rear section for proper function				150.00		150.00
Sundries.				80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER BOTTOM CENTRE GUIDE *	58.95	1.00		58.95
RR BUMPER PANEL PRIMED (PDC)	1,467.20	1.00		1,467.20
RR BUMPER ADAPTER	48.00	1.00		48.00
PLUG	1.05	10.00		10.50

SUPPLEMENTARY ITEMS

Total Labour :	3,948.00
Total Parts :	1,584.65
Total Labour & Parts :	5,532.65
Deduction for Excess :	
Total Repair Costs less Excess:	5,532.65
GST @7%:	387.29
Grand Total :	5,919.94

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45896
Date Estimated : 12/02/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mok Boon Rui (Mo Wenrui)
10 Seletar Green Walk

- ACCOUNT - 303
First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 805246

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKD587Y	DW35783	20/04/2012	520iA	0		
DESCRIPTION					ORIGINAL PRICE	DISC. % NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER BOTTOM CENTRE GUIDE *	58.95	1.00		58.95

Total Labour :	
Total Parts :	58.95
Total Labour & Parts :	58.95



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002925/Srd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3288L	Veh. Inspected	SKD 587Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001261MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W 520i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBAXG12050DW35783	Colour	BLACK	
Odometer	91498	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 ZR19	YOKOHAMA	6 mm	
L/H Front Tyre	245/40 ZR19	YOKOHAMA	6 mm	
R/H Rear Tyre	275/35 ZR19	YOKOHAMA	6 mm	
L/H Rear Tyre	275/35 ZR19	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2018	Inspection Date	05/03/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 587Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BODY NUT (SN)	NOT NECESSARY	9.00	-
1	RR BUMPER GUIDE BOTTOM CENTRE (SN)	TORN	58.95	58.95
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	67.35	-
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	714.25	-
1	RR BUMPER PANEL PRIMED (PDC)(SN)	DEFORMED	1,467.20	1,467.20
1	RR BUMPER ADAPTER (SN)	NECESSARY	48.00	48.00
2	EMBLEM GROMMET (SN)	NOT NECESSARY	1.60	-
1	BMW EMBLEM (SN)	NOT NECESSARY	69.50	-
1	MODEL LETTERING 520i (SN)	NOT NECESSARY	62.55	-
10	PLUG (SN)	NECESSARY	10.50	10.50
10	PLUG BLACK D=5MM (SN)	NOT NECESSARY	9.00	-
1	SENSOR WIRE FOR SMART OPENER TOP (SN)	NOT NECESSARY	42.10	-
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN)	NOT NECESSARY	40.50	-
1	REAR LH REFLECTOR (SN)	NOT NECESSARY	35.20	-
1	REAR RH REFLECTOR (SN)	NOT NECESSARY	35.20	-
2	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	10.10	-
2	BUMPER PDC SENSOR (A90 SOPISTOGRAU)(SN)	NOT NECESSARY	737.60	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			3,498.60	1,664.65
LABOUR				
TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT BOOT LID AND DENTED AREA CAUSED BY THE ACCIDENT.			2,550.00	1,700.00
TO RESPRAY REAR BUMPER AND BOOT LID.			2,076.00	1,868.00
TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		NOT NECESSARY	661.00	-
TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.			177.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			5,641.00	3,868.00
GRAND TOTAL			9,139.60	5,532.65
RECOMMENDED COST OF REPAIRS				5,532.65

Report Ref No. CS/FC118002925/Srd3n2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.