

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJP6159J

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Estimate by workshop
	1	front bumper ✓ CRK	693.00
	2	front bumper side retainer ✓ NEC	56.00
	1	front bumper reinforcement ✓ CRK	579.00
	2	front bumper fog lamp ✓ CRK	258.00
	1 set	front bumper fasteners ✓ NEC	28.00
	2	head lamp @ \$757 each ✓ CRK	1594.00
	2 set	headlamp fasteners ✓ NEC	56.00
	1	front support panel R	99.00
	1	front support panel top garnish ✓ CRK	95.00
	1 set	front support panel top garnish fasteners ✓ NTC	28.00
	2	front fender @ \$650 each R LH RH ✓ DT	1300.00
	2 set	front fender fasteners @ \$20.00 ✓ NTC	40.00
	1	radiator assy ✓ ✓ DT	694.00
	2	radiator mounting w/bracket @ \$28.00 ✓ NTC	56.00
	1	A/C condensor ✓ DT 796 ←	825.00
	2	A/C condensor mounting w/bracket @ \$35.00 ✓ NTC	70.00
	2	front fender inner shield @ \$75.60 X	151.20
	2 set	front fender inner shield fasteners @ \$25.00 ✓ NTC	50.00 30
	1	bonnet inner lock X	45.00
	1	front bonnet ✓ DT 843.70 ←	1496.00
	1	air con fan cowlng ✓ CRK	438.00
	1	radiator fan cowlng ✓ CRK	448.00
			9099.20
		Less 10%	909.92
			8189.28

check price

Special nett item

1	1	front bumper lower skirt ✓ CRK	350.00
3	1	front bumper lower skirt fasteners / clips ✓ NTC	38.00 30
11	2	number plate w casing ✓ DT	60.00 45
		Total parts	448.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and front expandable items.

1490.00
/000

To remove and replaced damaged parts including straightening and

repositioning replacement parts & panel beat

700
1600.00 (400) -

Check wiring and rewire

50.00 30 } 30 Δ
35.00 ✓

to realign headlamp focus

to remove and reinstall radiator and A/C condensor

120.00 80

to vacuum and refill a/c refrigerant R134A

60.00 50

to anti-rust

120.00 80

to top up coolant

50.00 40

Total labour

3435.00

Sub Total

12072.28

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJP6159J

Adjustment of Spare Parts Costs for Repairs			Estimate by
Item	Qty	Vehicle parts description	
			workshop
	1	front bumper upper grille ✓ <i>Cek</i>	703.00
	1	front bumper lower grille ✓ <i>Cek</i>	98.00
	1	front bumper logo ✓ <i>NEC</i>	95.00
	2	front bumper fog lamp cover @ \$59 each ✕	118.00
	1 set	front bumper fasteners <i>Repaired</i>	28.00
	2	head lamp panel @ \$256 each <i>R</i>	512.00
	1	radiator member ✕	279.00
			1833.00
		Less 10%	183.30
			1649.70
Labour			
Towing for dismantle/ fixing of carplate seal			
			208.00
			130