



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 PEUGEOT 508 1.6 TURBO (SKZ8617B)

Date of Loss

6 February 2018

Time of Loss

7.20

Loss Description

SKZ8617B (INSD) C/W GBB588L (TP)

Comment

Workshop Details

Total Rebate Amount

48874

Nett Loss Amount

\$33,126.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

28/05/2018



Days of work completion *

104



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKZ8617B

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

05/02/2016



Mileage

30198

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LEO HEE HENG

POST SURVEY INF...

CATEGORY	Make	
POLICY INFORMAT...	PEUGEOT	
ASSESSMENT INFO...	PEUGEOT	

CATEGORY	Model	
POLICY INFORMAT...	508 1.6 TURBO	
ASSESSMENT INFO...	508 ALLURE 1.6 BLUEHDI EAT6	

CATEGORY	Type	
POLICY INFORMAT...		
ASSESSMENT INFO...		

CATEGORY	Type of Paint	
POLICY INFORMAT...		
ASSESSMENT INFO...		

CATEGORY	Chassis No	
POLICY INFORMAT...	VF38DBHZTFL044008	

CATEGORY	Date of Birth	
FNOL INFORMATI...	7 June 1955	
POST SURVEY INF...	dd/mm/yyyy	

CATEGORY	Age	
FNOL INFORMATI...	62	
POST SURVEY INF...		

CATEGORY	Occupation	
FNOL INFORMATI...	Unknown	
POST SURVEY INF...		

CATEGORY	Education Qualification	
FNOL INFORMATI...	Other	
POST SURVEY INF...		

CATEGORY	Driving Experience	
----------	--------------------	--

ASSESSMENT INFO... VF38DBHZTFL044008

CATEGORY Engine No

POLICY INFORMAT... 10JBHC3022252

ASSESSMENT INFO... 10JBHC3022252

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1560

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 82000

FNOL INFORMATI... 38

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 1 January 1980

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... 5 JALAN GIRANG, 359177, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1108965H

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

14/02/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

900

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

Front left side

MICHELIN8mm

Front right side

MICHELIN8mm

Rear left side

MICHELIN8mm

Rear right side

MICHELIN8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Parts

Add		Approve		Deny											
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			REAR BUMPER			Damaged	1150		10		1035	Reviewing
		2	1			LEFT REAR TAIL LAMP			Damaged	525		10		472.5	Reviewing
		3	1			LEFT REAR BUMPER RETAINER			Damaged	85		10		76.5	Reviewing

Labour

Add	Approve	Deny								
EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		DISMANTLE & REFIT BUMPER, REVERSE SENSORS, ETC	250	0	0	Reviewing		
		2		SPRAY PAINT ON REAR BUMPER, AND REAR FENDERS	200	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 3 DAYS	Reviewing			
		2	LEFT REAR TAIL LAMP CLIP - 2PCS ONLY	Reviewing	20	NECESSARY	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$1,154.00			Claim Amount	\$1,154.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$450.00	\$450.00
Miscellaneous	\$20.00	\$20.00
Excess	-\$900.00	-\$900.00
Spare Parts	\$1,584.00	\$1,584.00

Submit for Review