

REF:

CCB/ms619002940/Apbn2

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: **PA 2675 U**
 Policy No: **A28699581 TMV**
 Claims No: **549812**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **7** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLB8126R** - Yr Regn: **2016 April**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mazda 2** cc **1496**
 Colour: **Red** A/C: Insured / Std / NI / NA
 Sp. Reading: **13853** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MM6DL2SAA 6W18/42**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **185/65 R15**
 R: **185/65 R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. **13/02**
 Survey held at: **Paya ubi (New Hock Teck)**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MS16.

SLB 8126R - X

PA 2675U - X

13/2/18 @ 8.49m Email GIA report to Irene Tan & Hasrianaah.
 06/6/18 @ 2.33pm revised to Chhira Nyuk Pui via WhatsApp.
 LG 186500, 7 days cred \$10906.20, 63%

RECEIVED 14 JUN 2018

[Signature]
 13/6/2018.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) **6500**Days Of Repair: **7**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL:

300
10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/MSG18002940/Aqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PA 2675U	Veh. Inspected	SLB 8126R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date		Inspection Date	13/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 06 Jun 2018

Preliminary Advice

Insured Vehicle No	: PA2675U	Accident Date	: 13/02/2018
TP Vehicle No	: SLB8126R	Assignment Date	: 28/02/2018
Make	: MAZDA 2	Est. Duration of Repair	: 7.00
Date of Inspection	: 13/02/2018		
Inspection At	: NEW HOCK TECK MOTOR WORKSHOP (HQ) BLK 1, KAKI BUKIT AVENUE 6 #01-43, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,406.20
Revised Amount	:S\$	7,518.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,518.16
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 23 February 2018 8:49 AM
To: Irene Tan; Hasrianah Binte Hassan
Cc: Christopher Chionh; KKLau; SUR; Accounts (LKKAUTO)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - , NEW HOCK TECK MOTOR WORKSHOP, DOA: 13/02/2018 , SLB 8126R (TP VEHICLE), PA 2675U (OI VEHICLE)
Attachments: SLB8126R GIA.pdf

Dear Irene and Hasrianah,

Please be informed that we had inspected the vehicle SLB 8126R at M/s: NEW HOCK TECK MOTOR WORKSHOP, BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0036J

Vehicle Details

Vehicle No.:	SLB8126R
Vehicle to be Exported:	No
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	P520335997
Chassis No.:	MM6DL2SAAGW185142
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,662.00
Original Registration Date:	22 Apr 2016
First Registration Date:	22 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$9,662.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Apr 2026
PARF Rebate Amount:	\$7,246.00

Intended COE Rebate Details

COE Expiry Date:	21 Apr 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$47,510.00
COE Rebate Amount:	\$37,676.00
Total Rebate Amount:	\$44,922.00

The information contained herein is correct as at 13 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 17:59
Date Of Accident	13/02/2018 07:00
Exact Location Of Accident	KJE TWDS BRICK LAND RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB8126R
Insured/Policyholder	
Name Of Registered Owner	WU YONGHAN
NRIC No	S9490036J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98169069
Alternative Phone No	OFFICE-98169069

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA2 SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096444535
Cover Note Number	-

Driver

Name of Driver	WU YONGHAN
NRIC No	S9490036J
Date Of Birth	13/03/1994
Occupation	INDOOR
Date Of Driving Pass	02/10/2015
Driving Experience	2 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98169069
Fax Number	
Contact Number	OFFICE-98169069
Email Address	NOEMAIL

Address BLK 847 WOODLANDS ST 82 #08-273
 Postcode 730847
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA2675U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

A: SLE 0126R
B: PA2672A

KJE Towards To Brick land Rd Ext HTH
Chon Chu Kang Ext

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along KJE towards to brick land Rd Ext HTH
Chon Chu Kang Ext at middle lane of 3 lanes.
Vh in front of me suddenly jammed brake. I managed stopped in
time.
Suddenly, ven "B" collided into rear portion of my vehicle and
caused damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

W yfw

Policyholder's Signature
Date & Time:

W yfw

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Handwritten signature of Reporting Centre Personnel


Reporting Centre Personnel's Signature
Name:
NRIC/Fin No:


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

A: SLEB126R
B: PA2612A

KJE Towards to Brick land Rd extn after
Choa Chu Kang extn

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight along KJE towards to brick land Rd extn after
Choa Chu Kang extn at middle lane of 3 lanes.
Veh in front of me suddenly jammed brake, I managed stopped in
time.
Suddenly, ven "B" collided into rear portion of my vehicle and
caused damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

W Y L W
Policyholder's Signature
Date & Time:

W Y L W
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

26/02/2018

WU YONGHAN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS16
Xiao Chan

Accident date: 13/02/2018

Estimated repair cost for vehicle no: SLB8126R MAZDA 2 1.5 A '16

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Buckled</i>		\$984.80 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$128.00	\$256.00 x
3	1	Rear Boot Lid Emblem Logo <i>2</i>		\$35.40 ✓
4	1	Rear Boot Lid Mazda 2 Logo <i>new</i>		\$58.10 ✓
5	1	Rear Boot Lid Skyactiv Logo		\$68.30 ✓
6	2	Rear Boot Lid Side Reflector <i>new</i>	\$357.20	\$714.40 x
7	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$328.10 ✓
8	1	Rear Boot Lid Inner Rubber <i>new</i>		\$222.60 ✓
9	1	Rear Boot Lid Inner Trim Board <i>2 new</i>		\$465.10 x
10	8	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$52.00 x
11	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 x
12	2	Rear Tail Lamp <i>cracked</i>	\$456.60	\$913.20 ✓
13	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
14	2	Rear Tail Lamp Panel <i>Repair</i>	\$313.20	\$626.40 x
15	1	Rear Bumper <i>Dented</i>		\$1,090.00 ✓
16	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30
17	2	Rear Bumper Side Retainer <i>new</i>	\$48.70	\$97.40 ✓
18	2	Rear Bumper Side Reflector <i>new</i>	\$61.00	\$122.00 x
19	2	Rear Bumper Lower Side Cover <i>new</i>	\$152.90	\$305.80 x
20	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 2nd/su
21	1	Rear End Panel <i>Dented</i>		\$869.70 ✓
22	1	Rear End Panel Top Garnish <i>Dented</i>		\$164.80 ✓
23	1	Rear Spare Tyre Panel <i>Repair</i>		\$1,132.00 x
24	1	Rear Spare Tyre Panel Top Cover <i>Dented</i>		\$378.30 ✓
25	1	Rear Spare Tyre Panel Centre Sponge <i>new</i>		\$256.00 x
26	2	Rear Spare Tyre Panel Side Sponge <i>Dented</i>		\$166.00 ✓
27	1	Rear Spare Tyre Panel & End Panel Sealant <i>new</i>		\$450.00 x
28	1	Rear Spare Tyre Lock <i>new</i>		\$58.00 x

29	1	Rear Exhaust <i>Best</i>		\$1,084.00 ✓
30	1	Rear Centre Exhaust <i>Good</i>		\$1,496.20 x
31	2	Rear Exhaust Mounting <i>fair</i>	\$52.30	\$104.60 x

6522.70

S.N: 200

5218.16

Subtotal :- \$12,996.20

Labour charges

To remove & refit cushion

~~\$280.00~~ 80

To remove & refit rear & centre exhaust

~~\$380.00~~ 80

To remove & refit reverse sensor

~~\$100.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$1,800.00~~ 80

Spray painting

~~\$1,600.00~~ 80

Subtotal :- \$4,410.00

Total:- \$17,406.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 7318.16
w/s 65K (10%)
07 days

65K 07 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18002940/AQBN2
Date: 14/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28699581TMV
Claimant: SLB8126R Insured Vehicle No: PA2675U
Vehicle No: SLB8126R Nature of Claim: TP Claim No: 549812
Date of Loss: 13/02/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB8126R Engine No: P520335997
Make & Model: MAZDA 2, 1.5 SEDAN L SP.6EAT (A) Chassis No: MM6DL2SAAGW185142
Reg. Date: 22/04/2016 (Man. Year: 2016) Odometer: 13853 km
Colour: Red
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,996.20	5,418.16	7,578.04	58.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	1,900.00	2,510.00	56.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,406.20	7,318.16	10,088.04	57.96
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	17,406.20	6,500.00	10,906.20	62.66
+ GST 7.00/7.00% (S\$)	1,218.43	455.00	763.43	62.66
Nett Amount (S\$)	18,624.63	6,955.00	11,669.63	62.66

INSPECTION

Date of Assignment: 28/02/2018
Date Inspected: 13/02/2018 Inspected At:

New Hock Teck Motor Workshop (HQ)
Blk 1, Kaki Bukit Avenue 6 #01-43,
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

Adjuster Report

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2018)
 Parts: 143 MAZDA 2 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLB8126R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	984.80 F	*984.80 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	256.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM LOGO	Necessary	35.40 F	*35.40 FL
4	1		*REAR BOOT LID MAZDA 2 LOGO	Necessary	58.10 F	*58.10 FL
5	1		*REAR BOOT LID SKYACTIV LOGO	Necessary	68.30 F	*68.30 FL
6	2		*REAR BOOT LID SIDE REFLECTOR	Not Necessary	714.40 F	*- FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	328.10 F	*328.10 FL
8	1		*REAR BOOT LID INNER RUBBER	Cut	222.60 F	*222.60 FL
9	1		*REAR BOOT LID INNER TRIM BOARD	Not Necessary	465.10 F	*- FL
10	8		*REAR BOOT LID INNER TRIM BOARD CLIP	Not Necessary	52.00 F	*- FL
11	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
12	2		*REAR TAIL LAMP	Cracked	913.20 F	*913.20 FL
13	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
14	2		*REAR TAIL LAMP PANEL	Repair	626.40 F	*- FL
15	1		*REAR BUMPER	Deformed	1,090.00 F	*1,090.00 FL
16	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	97.40 F	*97.40 FL
18	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	122.00 F	*- FL
19	2		*REAR BUMPER LOWER SIDE COVER	Not Necessary	305.80 F	*- FL
20	1		*REAR END PANEL	Dented	869.70 F	*869.70 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	164.80 F	*164.80 FL
22	1		*REAR SPARE TYRE PANEL	Repair	1,132.00 F	*- FL
23	1		*REAR SPARE TYRE PANEL TOP COVER	Deformed	378.30 F	*378.30 FL
24	1		*REAR SPARE TYRE PANEL CENTRE SPONGE	Not Necessary	256.00 F	*- FL
25	2		*REAR SPARE TYRE PANEL SIDE SPONGE	Deformed	166.00 F	*166.00 FL
26	1		*REAR SPARE TYRE PANEL & END PANEL SEALANT	Not Necessary	450.00 F	*- FL
27	1		*REAR SPARE TYRE LOCK	Not Necessary	58.00 F	*- FL
28	1		*REAR EXHAUST	Bent	1,084.00 F	*1,084.00 FL
29	1		*REAR CENTRE EXHAUST	Not Necessary	1,496.20 F	*- FL
30	2		*REAR EXHAUST MOUNTING	Not Necessary	104.60 F	*- FL
31	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,996.20 6,722.70

Report was unsubmitted during this print-out.

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	1,304.54
Total Parts (S\$)					12,996.20	5,418.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	280.00	80.00
2	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
3	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
4	TO CHECK WIRING	New	100.00	30.00
5	TUFF KOTE	New	150.00	60.00
6	PANEL BEATING	New	1,800.00	800.00
7	SPRAY PAINTING	New	1,600.00	800.00
Gross Labour Cost (\$\$)			4,410.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >