



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Xiao YunShan Lynn
Period of Insurance : 23 Dec 2017 To 22 Dec 2018
Engine No. : BWA268964
Chassis No. : TRUZZZ8J3A1008481

Vehicle No. : SJU7235P
Policy No. : 2100183492-08
Endorsement No. :
Issued Date : 21 Dec 2017

ABOUT THE COVER

Make/Model : AUDI TT 2.0 FSI
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2009
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Xiao YunShan Lynn - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63862323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE
AIGSGMOBILEAPP

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8612407F**

Name: **XIAO YUNSHAN LYNN**

Birth Date: **06 May 1986**

Issue Date: **30 May 2015**

002434089H

SG

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8612407F**

Name: **XIAO YUNSHAN LYNN**

蕭韻珊

Race: **CHINESE**

Date of Birth: **06-05-1986** Sex: **F**

Country of Birth: **SINGAPORE**

S8612407F

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

EFFECTIVE DATE

02 Feb 2007

Licence No: **S8612407F**

NP 428A

A0018472

S8612407F

NRIC No: **S8612407F**

Blood Group: **O+** Date of Issue: **09-05-2001**

120 SARACA ROAD
SINGAPORE 807414

NRIC No: **S8612407F** Date: **21/06/2008** No: **5928851**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0184/2018/CCS
Date	:	13-Feb-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Xiao YunShan Lynn
Address	:	120 Saraca Road

	:	Singapore 807414
Telephone	:	HP +65 91286232
Type of Claim	:	Own Damage Claims
Policy No.	:	2100183492-08
Vehicle No	:	SJU 7235 P
Model Code	:	Audi TTC 2.0T FSI
Model / Year	:	Dec-09
Engine No	:	BWA 268964
Chassis No	:	TRUZZZ8J3A1008481
Mileage	:	
Date In	:	5-Feb-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Feb-18
Place of Accident	:	Along Steven Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJU 7235 P.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 480.00 ✓	✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,400.00 ✓	✓
3	To dismantle front bumper, LHS front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, lhs front fender and bonnet. Cut out and reweld lhs front fender support. Re-organise front crash management components. Reinstall all parts removed.	\$ 7,200.00	4500 4500 5250
4	To respray paint on front bumper, bonnet, lhs front fender, lhs a-pillar, lhs fender support and rhs door.	\$ 3,200.00	3000 ✓
5	To carry out wheel alignment.	S/N \$ 280.00	X.
6	To carry out diagnostic checks.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 12,944.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 7235 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Discontinued</i>	\$ 1,455.00	✓ 1164
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 267.00	+
3	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 144.00	+
4	FRONT BUMPER GRILLE - LH <i>missing</i>	\$ 115.00	✓ 92
5	FRONT BUMPER GRILLE BACK COVER - LH <i>and</i>	\$ 96.00	✓ 76.48
6	FRONT BUMPER GUIDE - LH <i>and</i>	\$ 33.00	✓ 25.54
7	FRONT BUMPER FOAM - INNER <i>could</i>	\$ 90.00	✓ 71.92
8	FRONT BUMPER REINFORCEMENT BEAM <i>Bent</i>	\$ 765.00	✓ 611.60
9	FRONT BUMPER TOP COVER - LH/RH <i>Discontinued</i>	2 \$ 62.00	✓ X nvl
10	FRONT BUMPER RADIUS ROD <i>Bent</i>	\$ 93.00	74.40
11	HEADLIGHT WASHER CYLINDER - LH <i>and</i>	\$ 184.00	✓ 147.20
12	HEADLIGHT WASHER COVER - LH <i>missing</i>	\$ 52.00	✓ 41.20
13	FOG LAMP - LH <i>new</i>	\$ 342.00	X
14	RADIATOR GRILLE <i>could</i>	\$ 679.00	✓ 543.80
15	BONNET <i>Discontinued</i>	\$ 3,619.00	✓ 2895.20
16	BONNET ATTACHMENT PARTS <i>new</i>	\$ 289.00	? X
17	BONNET HINGE - LH/RH <i>new</i>	2 \$ 400.00	? X
18	BONNET DAMPER <i>new</i>	\$ 105.00	+
19	BONNET DAMPER BALL STUD <i>new</i>	\$ 36.00	? X
20	BONNET LOCK CATCH HOOK <i>Bent</i>	\$ 112.00	✓ 89.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,938.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 7235 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET LOCK <i>Not New</i>	\$ 180.00	✓ X
22	BONNET LOCK CABLE - FRONT <i>2 new</i>	\$ 74.00	+
23	BONNET LOCK CABLE COVER	\$ 16.00	+
24	BONNET STOP BUFFER <i>in</i>	\$ 18.00	✓ 14.40
25	BONNET SEAL - FRONT <i>in</i>	\$ 55.00	✓ 44
26	BONNET LOCK COVER - UPPER <i>Not New</i>	\$ 44.00	? X
27	FRONT FENDER - LH <i>Discolored</i>	\$ 930.00	✓ 744
28	FRONT FENDER BRACE - LH <i>Bent</i>	\$ 107.00	✓ 85.20
29	FRONT FENDER BRACKET - LH <i>Bent</i>	\$ 35.00	✓ 27.68
30	FRONT FENDER RETAINING PLATE - LH UPPER <i>in</i>	\$ 30.00	✓ 23.92
31	FRONT FENDER CLOSING ELEMENT - LH <i>in</i>	\$ 57.00	✓ 45.28
32	FRONT FENDER WHEEL HOUSING LINER - LH FRONT <i>cracked</i>	\$ 151.00	✓ 120.80
33	FRONT FENDER WHEEL HOUSING LINER - LH REAR <i>cracked</i>	\$ 97.00	✓ 77.36
34	FRONT WHEEL SPOILER - LH <i>in</i>	\$ 30.00	+
35	FRONT FENDER CONNECTING PLATE - LH LOWER <i>Discolored</i>	\$ 658.00	? X 526
36	FRONT FENDER CONNECTING PLATE - LH UPPER <i>Discolored</i>	\$ 126.00	? X 100.80
37	HEADLIGHT - LH <i>Smashed</i>	\$ 1,830.00	✓ 1725.60
38	HEADLIGHT CONTROL UNIT <i>Bent</i>	\$ 1,919.00	✓ 1535.20
39	HEADLIGHT CONNECTOR HOUSING <i>cracked</i>	\$ 28.00	✓ 21.76
40	GAS DISCHARGE BULB <i>Not New</i>	\$ 394.00	✓ 314.80
SUB-TOTAL SPARE PARTS CHARGES		\$ 6,779.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 7235 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT LOCK CARRIER <i>Cracked</i>	\$ 861.00	✓ 698.80
42	FRONTAL SUPPORT FRAME <i>Not New</i>	\$ 744.00	7 X
43	A/C CONDENSER <i>Bent</i>	\$ 505.00	✓ 403.60
44	RADIATOR <i>Bent</i>	\$ 998.00	✓ 786.40
45	COOLANT <i>New</i>	\$ 100.00	✓ 106.24 &
46	CHARGE AIR COOLER <i>Bent</i>	\$ 1,006.00	✓ 804.80
47	ACRYLIC SEALER <i>Not New</i>	S/N \$ 180.00	? X
48	CAVITY WAX <i>Not New</i>	S/N \$ 140.00	? X
49	FRONT NUMBER PLATE <i>New</i>	S/N \$ 25.00	✓ 25
50	SUNDRIES <i>New</i>	\$ 600.00	? 185.20
TOTAL SPARE PARTS CHARGES		\$ 20,876.00	
TOTAL LABOUR CHARGES		\$ 12,944.00	
GRAND TOTAL		\$ 33,820.00	35,755.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

3553732

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Lj
: 13/02/18
:
:
:
:
: Not Authorised, 12 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 21 June 2018 9:14 AM
To: 'Boo seng yak'; Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION SJU7235P - OD AIG - SURVEYED 13 FEB 18

Dear Mr Boo,

Confirm repair cost of \$25,674.76 before excess \$1400 @ 15 days of repairs

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Friday, 25 May 2018 4:38 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION SJU7235P - OD AIG - SURVEYED 13 FEB 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$25,674.76 @ 15 days of repairs exclude 2 Sundays.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0184/2018/CCS
Date : 13-Feb-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Xiao YunShan Lynn
Address : 120 Saraca Road

Telephone : Singapore 807414
Type of Claim : HP +65 91286232
Policy No. : Own Damage Claims
Vehicle No : 2100183492-08
Model Code : **SJU 7235 P**
Model / Year : Audi TTC 2.0T FSI
Engine No : Dec-09
Chassis No : BWA 268964
Mileage : TRUZZZ8J3A1008481
Date In :
Liability : 5-Feb-18
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Feb-18
Place of Accident : Along Steven Road

Hi Adrian

You recommended 12 days

We took 15 days exclude 2 Sundays

jb - 25 May 18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJU 7235 P.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,400.00	\$ 1,400.00
3	To dismantle front bumper, LHS front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, lhs front fender and bonnet. Cut out and reweld lhs front fender support. Re-organise front crash management components. Reinstall all parts removed. (Add \$750.00 for fender support) Item 35 & 36	\$ 7,200.00	\$ 5,250.00
4	To respray paint on front bumper, bonnet, lhs front fender, lhs a-pillar, lhs fender support and rhs door.	\$ 3,200.00	\$ 3,000.00
5	To carry out wheel alignment.	S/N \$ 280.00	nil
6	To carry out diagnostic checks.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 12,944.00	\$ 10,514.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SJU 7235 P.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,455.00	\$ 1,164.00
2	FRONT BUMPER FIXING PARTS	\$ 267.00	
3	FRONT BUMPER CLOSING ELEMENT	\$ 144.00	
4	FRONT BUMPER GRILLE - LH	\$ 115.00	\$ 92.00
5	FRONT BUMPER GRILLE BACK COVER - LH	\$ 96.00	\$ 76.48
6	FRONT BUMPER GUIDE - LH	\$ 33.00	\$ 25.84
7	FRONT BUMPER FOAM - INNER	\$ 90.00	\$ 71.92
8	FRONT BUMPER REINFORCEMENT BEAM	\$ 765.00	\$ 611.60
9	FRONT BUMPER TOP COVER - LH/RH	2 \$ 62.00	
10	FRONT BUMPER RADIUS ROD	\$ 93.00	\$ 74.40
11	HEADLIGHT WASHER CYLINDER - LH	\$ 184.00	\$ 147.20
12	HEADLIGHT WASHER COVER - LH	\$ 52.00	\$ 41.20
13	FOG LAMP - LH	\$ 342.00	
14	RADIATOR GRILLE	\$ 679.00	\$ 542.80
15	BONNET	\$ 3,619.00	\$ 2,895.20
16	BONNET ATTACHMENT PARTS	\$ 289.00	
17	BONNET HINGE - LH/RH	2 \$ 400.00	
18	BONNET DAMPER	\$ 105.00	
19	BONNET DAMPER BALL STUD	\$ 36.00	
20	BONNET LOCK CATCH HOOK	\$ 112.00	\$ 89.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 8,938.00	\$ 5,831.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 7235 P.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	5,831.84
21	BONNET LOCK	\$	180.00	
22	BONNET LOCK CABLE - FRONT	\$	74.00	
23	BONNET LOCK CABLE COVER	\$	16.00	
24	BONNET STOP BUFFER	\$	18.00	\$ 14.40
25	BONNET SEAL - FRONT	\$	55.00	\$ 44.00
26	BONNET LOCK COVER - UPPER	\$	44.00	
27	FRONT FENDER - LH	\$	930.00	\$ 744.00
28	FRONT FENDER BRACE - LH	\$	107.00	\$ 85.20
29	FRONT FENDER BRACKET - LH	\$	35.00	\$ 27.68
30	FRONT FENDER RETAINING PLATE - LH UPPER	\$	30.00	\$ 23.92
31	FRONT FENDER CLOSING ELEMENT - LH	\$	57.00	\$ 45.28
32	FRONT FENDER WHEEL HOUSING LINER - LH FRONT	\$	151.00	\$ 120.80
33	FRONT FENDER WHEEL HOUSING LINER - LH REAR	\$	97.00	\$ 77.36
34	FRONT WHEEL SPOILER - LH	\$	30.00	
35	FRONT FENDER CONNECTING PLATE - LH LOWER	\$	658.00	
36	FRONT FENDER CONNECTING PLATE - LH UPPER	\$	126.00	
37	HEADLIGHT - LH	\$	1,830.00	\$ 1,725.60
38	HEADLIGHT CONTROL UNIT	\$	1,919.00	\$ 1,535.20
39	HEADLIGHT CONNECTOR HOUSING	\$	28.00	\$ 21.76
40	GAS DISCHARGE BULB	\$	394.00	\$ 314.80
SUB-TOTAL SPARE PARTS CHARGES			\$ 6,779.00	\$ 10,611.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJU 7235 P.

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	10,611.84
41	FRONT LOCK CARRIER	\$	861.00	\$ 688.80
42	FRONTAL SUPPORT FRAME	\$	744.00	
43	A/C CONDENSER	\$	505.00	\$ 403.60
44	RADIATOR	\$	998.00	\$ 786.40
45	COOLANT	\$	100.00	\$ 106.24
46	CHARGE AIR COOLER	\$	1,006.00	\$ 804.80
47	ACRYLIC SEALER	S/N \$	180.00	
48	CAVITY WAX	S/N \$	140.00	
49	FRONT NUMBER PLATE	S/N \$	25.00	\$ 25.00
50	ADDED PARTS - SEE ATTACHED	\$	1,929.00	\$ 1,548.88
52	SUNDRIES	\$	600.00	\$ 185.20
TOTAL SPARE PARTS CHARGES			\$ 22,805.00	\$ 15,160.76
TOTAL LABOUR CHARGES			\$ 12,944.00	\$ 10,514.00
GRAND TOTAL			\$ 35,749.00	\$ 25,674.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0184/2018/CCS
1-Mar-18
CHANG
1 of 1
SJU 7235 P
Audi TTC 2.0T FSI

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT BUMPER TOP COVER - LH/RH <i>2 Dischld</i>	\$ 134.00	\$ 106.88
2	FRONT NOISE INSULATION <i>Dischld</i>	\$ 207.00	\$ 165.60
3	SIDE MEMBER CABLE GUIDE - LH FRONT <i>Dischld</i>	\$ 22.00	\$ 17.20
4	AIR FILTER AIR GUIDE - FRONT <i>Dischld</i>	\$ 34.00	\$ 26.96
5	INTAKE AIR DUCT <i>Dischld</i>	\$ 29.00	\$ 22.72
6	FRONT FENDER SUPPORT - LH <i>Dischld</i>	\$ 40.00	\$ 31.84
7	FRONT FENDER CONNECTING PLATE - LH LOWER (Check item) <i>Requird</i>	\$ 658.00	\$ 526.00
8	FRONT FENDER CONNECTING PLATE - LH UPPER (Check item) <i>Dischld</i>	\$ 126.00	\$ 100.80
9	FRONT FENDER CONNECTING PLATE - LH UPPER (Check item)	\$ 401.00	\$ 320.80
10	ALUMINIUM RIVET SET <i>in</i>	\$ 29.00	\$ 23.68
11	FRONT LOCK CARRIER AIR GUIDE - LH <i>Dischld</i>	\$ 165.00	\$ 137.60
12	WASHER HOSE <i>Dischld</i>	\$ 84.00	\$ 68.80
12	WASHER TANK BRACKET <i>Dischld</i>		
TOTAL PARTS :		\$ 1,929.00	\$ 1,548.88
GRAND TOTAL :		\$ 1,929.00	\$ 1,548.88

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

X

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SJU 7235 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0184/2018/TF
15 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

Make & Model	:	Audi TTC 2.0T FSI
Vehicle Chassis No.	:	TRUZZZ8J3A1008481
Vehicle Regn No.	:	SJU 7235 P
Vehicle Mileage	:	99755km
Vehicle Owner	:	Ms. Xiao YunShan Lynn
Certificate No	:	2100183492-08
Policy Excess	:	\$1,498.00 (inclusive 7% GST)
Accident Date	:	05/02/2018
Place	:	<u>Along Steven Road</u>
Repair Cost	:	\$ <u>25,973.99</u>
WIP No.	:	54849
Repairer's Name	:	Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : _____

Time : _____

Date : 15/11/16

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJU 7239 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0184/2018/MAS

28 June 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SJU 7235 P, Audi TTC 2.0T FSI

With reference to the above-mentioned vehicle, no. **SJU 7235 P**, claimant, **Ms. Xiao Yunshan Lynn**, please find the related document per attached.

1. A copy of the Original invoice no. 85012653 – S\$25,973.99
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJU 7235 P

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733
Page 2 10:43

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408679
Telephone 6388 2223
Telefax 6841 1483

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012653 Date : 26/06/2018 Order : SJU7235P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SJU7235P (V 11346) Regn Date: 23/12/2009 Mileage: 99755 WIP No.: 54849
Model: TTC 2.0T FSI 8J302X Chassis: TRUZZ28J3A1000481 Engine: BWA268964 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	FENDER AND BONNET CUT OUT AND REWELD LHS FRONT FENDER SUPPORT, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED M:	3000.00	1.00	3,000.00
S	BODYWORK	TO RESPRAY PAINT ON FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS A PILLAR, LHS FENDER SUPPORT AND RHS DOOR M:	384.00	1.00	384.00
X	A1K0145803CD	COOLER (A) Less 020%	1.00	1006.00	804.80
X	A8J0971615B	CONDUIT (G) (V) Less 020%	1.00	21.50	17.20
X	A1K0129618BM	AIR DUCT (A) Less 020%	1.00	33.70	26.96
X	AN 0154487	SPEED NUT (A) Less 020%	2.00	1.60	2.56
X	AN 90986802	BOLT (A) Less 020%	2.00	0.40	0.64
X	ABJ0005971A	AIR DUCT (A) Less 020%	1.00	28.40	22.72
X	ABJ0005537D	SUPPORT (A) Less 020%	1.00	39.80	31.84
X	A8J0005099E	PLATE (G) (V) Less 020%	1.00	657.50	526.00
X	A8J0005189F	PLATE (A) Less 020%	1.00	126.00	100.80
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Page 1 10:43

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer Service
Service Appointment
24 hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9628 1233

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85012653 Date : 26/06/2018 Order : SJU7235P Term : 30	Account: A0005 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No.: SJU7235P (V 11346) Model: TTC 2.0T FSI 8J302X V58 No.: You have been assisted by :- UB-Jiayee (33)		Regn Dates: 23/12/2009 Chassis: TRUZZ8J3A1008481		Mileage: 99755 Engine: BWA268964 WIP No.: 54849 Dept: U	
		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	1400.00	1.00	-1,400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	480.00	1.00	480.00
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT	5250.00	1.00	5,250.00
Sub-Total					
7% GST					
Grand Total					

Customer