



# Premium Automobiles Pte Ltd

**Audi Centre Singapore**  
 281 Alexandra Road  
 Singapore 159938  
 Main Telephone: 6836 2223  
 Main Telefax: 6471 3733  
 Page 3 10:43

**Alexandra Service Centre**  
 281 Alexandra Road  
 Singapore 159938  
 Telephone: 6388 2223  
 Telefax: 6475 1023

**Ubi Service Centre**  
 55 Ubi Road 1  
 Singapore 408629  
 Telephone: 6388 2223  
 Telefax: 6841 1183

**Customer Service**  
 Service Appointment  
 24-hour Breakdown Service  
 Email: customer.care@premiumauto.com.sg  
 6366 2323  
 9828 1233

**INSURANCE INVOICE**  
 Company No. 199902271W  
 GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 05012653 Date: 26/06/2010 Order: SJU7235P Term: 30	Account: A0005 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SJU7235P (V 11346) Regn Date: 23/12/2009 Mileage: 99755 WIP No.: 54849  
 Model: TTC 2.0T FSI 8J382X Chassis: TRUZZZ78J3A1008461 Engine: BWA268964 Dept: U  
 VSB No.:  
 You have been assisted by :- UB-Jiayee ( 33 )

		Details		Qty	Unit Price	Amount
X	A4A0971849B	BRACKET (B) (V)	Less 020%	2.00	43.00	68.80
X	AG A13A8JM1	COOLANT ADDITIVE	Less 020%	4.00	33.20	106.24
X	ABJ0853651 10P	GRILLE (A)	Less 020%	1.00	678.50	542.80
X	ABJ0941029AK	HEADLAMP	Less 020%	1.00	2157.00	1,725.60
X	ABJ0821103B	FENDER (A)	Less 020%	1.00	930.00	744.00
X	ABJ0821191H	WHEEL HOUS (A)	Less 020%	1.00	95.70	77.36
X	ABJ0821171B	WHEEL HOUS	Less 020%	1.00	151.00	120.80
X	A1K0820411AK	CONDENSER	Less 020%	1.00	504.50	403.60
X	A1K0121251EH	RADIATOR	Less 020%	1.00	983.00	786.40
X	ABJ0825237A	BAFFLE	Less 020%	1.00	207.00	165.60
X	ABJ0805594G	CARRIER (A)	Less 020%	1.00	861.00	688.80
X	ABJ0807694C	S-LINE ABSORBER (A)	Less 020%	1.00	89.90	71.92
X	ABJ0807109	BEAM (A)	Less 020%	1.00	764.50	611.60
X	ABJ0823029E	HOOD (A)	Less 020%	1.00	3519.00	2,895.20
X	ABJ0807105A GRU	BUMPER W/HW (A)	Less 020%	1.00	1455.00	1,164.80
X	AN 10139301	CLIP (0.10)	Less 020%	3.00	5.70	13.68
X	A3D0971838N	TIE WRAP	Less 020%	1.00	0.90	0.72
X	A1J0972741	SEAL	Less 020%	4.00	2.60	8.32
<b>Sub-Total</b>						
<b>7% GST</b>						
<b>Grand Total</b>						

Customer



# Premium Automobiles Pte Ltd

**Audi Centre Singapore**  
 281 Alexandra Road  
 Singapore 159938  
 Main Telephone 6836 2223  
 Main Telefax 6471 3733  
 Page 4 10:43

**Alexandra Service Centre**  
 281 Alexandra Road  
 Singapore 159938  
 Telephone 6388 2223  
 Telefax 6475 1023

**Ubi Service Centre**  
 55 Ubi Road 1  
 Singapore 408599  
 Telephone 6388 2223  
 Telefax 6841 1489

**Customer Service**  
 Service Appointment 6366 2323  
 24-hour Breakdown Service 9826 1233  
 Email customer.care@premiumauto.com.sg

INSURANCE INVOICE  
 Company No. N99902271W  
 GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-1E SINGAPORE 079120 079120	Invoice: 85012653 Date : 26/06/2018 Order : SJU7235P Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-1E SINGAPORE 079120
---	---	--

Regn No.: SJU7235P (V 11346) Regn Date: 23/12/2009 Mileage: 99755 WIP No.: 54849  
 Model: TTD 2.0T FSI 8J302X Chassis: TRUZZ26J3A1008481 Engine: BWA268964 Dept: U  
 VSB No.:  
 You have been assisted by :- UB-Jiayee ( 33 )

		Details		Qty	Unit Price	Amount
X	A8E0955873	PIECE	Less 020%	1.00	22.40	17.92
X	AN 10566103	GAS DISCHARGE BULB	Less 020%	1.00	393.50	314.80
X	A8J0807151	COVER (A)	Less 020%	1.00	95.60	76.48
X	A8J0805637	BRACKET	Less 020%	1.00	19.90	15.92
X	A8J0807753 GRU	CAP (A)	Less 020%	1.00	51.50	41.20
X	A8J0805638	BRACKET	Less 020%	1.00	19.90	15.92
X	A8J0807183B	GUIDE	Less 020%	1.00	32.30	25.84
X	A8J0807081B	COVER (A)	Less 020%	1.00	66.80	53.44
X	A8J0807082B	COVER (A)	Less 020%	1.00	66.80	53.44
X	A8J0821135F	SUPPORT (A)	Less 020%	1.00	106.50	85.20
X	A8J0806491	RADIUS ROD (A)	Less 020%	1.00	93.00	74.40
X	A8J0823480C	HOOK	Less 020%	1.00	111.50	89.20
X	A077133382B	CONN PIPE	Less 020%	1.00	10.00	8.00
X	A1K0805962C 9B9	AIR DUCT	Less 020%	1.00	13.20	10.56
X	A8J0821111A	PLATE (A)	Less 020%	1.00	56.60	45.28
X	A4E0260749A	WASHER	Less 020%	1.00	3.20	2.56
X	A3D0260749C	WASHER	Less 020%	1.00	3.80	3.04
X	A4B0823481	BUMPER	Less 020%	4.00	4.50	14.40
<b>Sub-Total</b>						
<b>7% GST</b>						
<b>Grand Total</b>						



# Premium Automobiles Pte Ltd

**Audi Centre Singapore**  
281 Alexandra Road  
Singapore 159938  
Main Telephone 6836 2223  
Main Telefax 6471 3733  
Page 5 10:43

**Alexandra Service Centre**  
281 Alexandra Road  
Singapore 159938  
Telephone 6388 2223  
Telefax 6475 1023

**Ubi Service Centre**  
55 Ubi Road 1  
Singapore 408699  
Telephone 6388 2223  
Telefax 6411 1823

**Customer Service**  
Service Appointment 6366 2323  
24-hour Breakdown Service 9828 1233  
Email customer.care@premiumauto.com.sg

**INVOICE**  
Company No. 199902271W  
GST Reg. No. 199902271W

RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 05012653 Date: 26/06/2018 Order: SJU7235P Term: 30	Account: A0006 (T 0) RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT RIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SJU7235P (V 11346)	Regn Date: 23/12/2005	Mileage: 99755	WIP No.: 54849
Model: TTC 2.0T FSI 8J302X	Chassis: TRUZZ78J3A1000401	Engine: BWA268964	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	ABJ00106598	PLATE (A)	1.00	23.90	23.92
X	ABJ0021151C	BRACKET (G) (V)	1.00	34.60	27.60
X	ABJ0007681 01C	GRILL (A)	1.00	115.00	92.00
X	ABJ0023731B	BASKET (G) (V)	1.00	55.00	44.00
X	ABJ0955101A	CYLINDER (A)	1.00	184.00	147.20
X	A000979141E	WIRE SET	2.00	20.20	32.32
X	A400971992	HOUSING	1.00	15.40	12.32
X	A1J0973737	HOUSING (A)	1.00	27.20	21.76
X	A0K0010520A	PLATE	1.00	11.60	9.28
X	A0P0010191B	STICKER (V)	1.00	15.20	12.16
X	ABJ0121283A	GUIDE (A)	1.00	29.60	23.68
X	ABJ0907391	BALLAST (A)	1.00	1915.00	1,535.20
X	A1J0953964F	HOSE	5.00	34.40	137.60
X	AN 10744001	RIVET NOYE	20.00	17.00	284.00
X	AN 10323901	RIVET NOYE	25.00	1.00	36.00
X	AN 90859402	NUT (G) (V)	2.00	1.00	1.60
X	AN 90656401	CLIP (A)	1.00	18.10	14.48
X	AN 90808201	SCREW (A)	4.00	1.00	3.20

Parts 15,135.76	Sub-Total	24,274.76
Labour 0.00	7% GST	1,699.23
Sublet 10,539.00	<b>Grand Total</b>	<b>25,973.99</b>
Menus 0.00		
Lubricant 0.00		



Received by \_\_\_\_\_ For & on behalf of Premium Automobiles Pte Ltd

Customer



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S8612407F**

Name: **XIAO YUNSHAN LYNN**

Birth Date: **06 May 1986**

Issue Date: **30 May 2015**

002434089H





**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S8612407F**



Name: **XIAO YUNSHAN LYNN**

蕭韻珊

Race

**CHINESE**

Date of Birth

**06-05-1986**

Sex

**F**

Country of Birth

**SINGAPORE**

S8612407F

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)**

	EFFECTIVE DATE
Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	02 Feb 2007


Licence No: S8612407F



NP 428A



A0018472



NRIC No: **S8612407F**

Blood Group

**O+**

Date of issue

**09-05-2001**

120 SARACA ROAD  
 SINGAPORE 807414

NRIC No: S8612407F

Date: 21/06/2008

No: 5928851



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : Xiao YunShan Lynn  
**Period of Insurance** : 23 Dec 2017 To 22 Dec 2018  
**Engine No.** : BWA268964  
**Chassis No.** : TRUZZZ8J3A1008481

**Vehicle No.** : SJU7235P  
**Policy No.** : 2100183492-08  
**Endorsement No.** :  
**Issued Date** : 21 Dec 2017

### ABOUT THE COVER

**Make/Model** : AUDI TT 2.0 FSI  
**Engine Capacity/Tonnage** : 1,984.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2009  
**Insuring with COE/PARF** : Yes

#### Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

**Section 1**  
Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

**Section 2**  
Property Damage - \$0

**Windscreen** : \$100

#### Named Driver and Excess (where applicable)

Xiao YunShan Lynn - \$1400 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

† Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP  
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938  
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	06 Feb 2018		13 Feb 2018 17:38 <a href="#">Edit Adj Rpt</a>	<b>S\$25,674.76</b> <a href="#">Edit Estimates</a>	<b>S\$25,674.76</b> <a href="#">View Rpt</a>	<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	XIAO YUNSHAN LYNN, ID: S8612407F, Tel: +6591286232, Email: NOEMAIL								
Vehicle Reg. No.:	SJU7235P	Date of Loss: 05/02/2018 09:00 - :59 [97 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type:	OD / 6866563133SG	Policy/Cover Note No.: (Comprehensive)							
		Excess: S\$1,400.00							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/02/2018]								
Driver/Custodian:	XIAO YUNSHAN LYNN (31 / Female), NRIC: S8612407F, Tel: +6591286232								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (19/02/2018): Alert - Adj Mandate Approved (S\$30004.00) - SJU7235P - Claim Handler: Loo, Tong ...</li> <li>AIG_SG (15/02/2018): SJU7235P / OD / 05/02/2018 / Coverage &amp; Excess update</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

\*SJU7235P (6866563133SG)  
 OD  
 Feb 5 2018 9:00AM  
 [XIAO YUNSHAN LYNN]  
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>		
										1 per page	<input checked="" type="checkbox"/>	
<b>Assessment Reports</b>										<b>Thumbnail</b>	<b>Print</b>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								<input checked="" type="checkbox"/>	Load HTM	
1	14/02/18 11:23	<b>Adjuster Immediate Advice</b>										
										3 per page	<input checked="" type="checkbox"/>	
<b>Photos/Images</b>										<b>Thumbnail</b>	<b>Print</b>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
1	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
2	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
3	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
4	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
5	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
6	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
7	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
8	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
9	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
10	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
11	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
12	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
13	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
14	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
15	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
16	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
17	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
18	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
19	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
20	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
21	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
22	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
23	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
24	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
25	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
26	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
27	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
28	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
29	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
30	14/02/18 09:09	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
31	14/02/18 09:10	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
32	14/02/18 09:10	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
33	14/02/18 09:10	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
34	14/02/18 09:10	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
35	14/02/18 09:10	<b>General View</b>								<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
37	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
38	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
39	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
40	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
41	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
42	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
43	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
44	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
45	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
46	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
47	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
48	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
49	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
50	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
51	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>
52	14/02/18 09:10	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 09:45	Singapore Accident Statement	Load PDF	
2	14/02/18 09:45	Certificate of Insurance	Load PDF	
3	14/02/18 09:46	Insured's Driving License	Load PDF	
4	14/02/18 09:46	ESTIMATE	Load PDF	
5	06/07/18 14:12	Workshop Invoice	Load PDF	
6	06/07/18 14:12	Discharge Voucher	Load PDF	

### Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page	<input checked="" type="checkbox"/>
1	06/02/18 09:17	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	06/02/18 08:55	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/02/18 08:52	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	06/02/18 08:52	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

### Documents Checklist

<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
<b>DOCUMENTS CHECKLIST</b> There are no document checklists configured.
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG18002941/AVBE2  
**Date:** 06/07/2018

#### REFERENCE

Insured/Claimant: XIAO YUNSHAN LYNN Policy No:  
Date of Loss: 05/02/2018 Nature of Claim: OD Claim No: 6866563133SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU7235P** Engine No: BWA268964  
Make & Model: AUDI TTC, 2.0 TFSI S-TRONIC (A) Chassis No: TRUZZZ8J3A1008481  
Reg. Date: 23/12/2009 (Man. Year: 2009) Odometer: 99755 km  
Colour: White  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$62,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 235/40 R17 Rear Tyre Size: 235/40 R17  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,588.32	15,160.76	7,427.56	32.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,944.00	10,514.00	2,430.00	18.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>35,532.32</b>	<b>25,674.76</b>	<b>9,857.56</b>	<b>27.74</b>
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	34,132.32	24,274.76	9,857.56	28.88
+ GST 7.00/7.00% (S\$)	2,389.26	1,699.23	690.03	28.88
<b>Nett Amount (S\$)</b>	<b>36,521.58</b>	<b>25,973.99</b>	<b>10,547.59</b>	<b>28.88</b>

#### INSPECTION

Date of Assignment: 13/02/2018  
Date Inspected: 13/02/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 15.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

# Adjuster Report

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,455.00 FS	*1,164.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	267.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	144.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LH	Missing	115.00 FS	*92.00 FS
5	1		*FRONT BUMPER GRILLE BACK COVER - LH	Damaged	96.00 FS	*76.48 FS
6	1		*FRONT BUMPER GUIDE - LH	Damaged	33.00 FS	*25.84 FS
7	1		*FRONT BUMPER FOAM - INNER	Cracked	90.00 FS	*71.92 FS
8	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	765.00 FS	*611.60 FS
9	2		*FRONT BUMPER TOP COVER - LH / RH	Not Necessary	62.00 FS	*- FS
10	1		*FRONT BUMPER RADIUS ROD	Bent	93.00 FS	*74.40 FS
11	1		*HEADLIGHT WASHER CYLINDER - LH	Damaged	184.00 FS	*147.20 FS
12	1		*HEADLIGHT WASHER COVER - LH	Missing	52.00 FS	*41.20 FS
13	1		*FOG LAMP - LH	Not Necessary	342.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	679.00 FS	*542.80 FS
15	1		*BONNET	Distorted	3,619.00 FS	*2,895.20 FS
16	1		*BONNET ATTACHMENT PARTS	Not Necessary	289.00 FS	*- FS
17	2		*BONNET HINGE - LH / RH	Not Necessary	400.00 FS	*- FS
18	1		*BONNET DAMPER	Not Necessary	105.00 FS	*- FS
19	1		*BONNET DAMPER BALL STUD	Not Necessary	36.00 FS	*- FS
20	1		*BONNET LOCK CATCH HOOK	Bent	112.00 FS	*89.20 FS
21	1		*BONNET LOCK	Not Necessary	180.00 FS	*- FS
22	1		*BONNET LOCK CABLE - FRONT	Not Necessary	74.00 FS	*- FS
23	1		*BONNET LOCK CABLE COVER	Not Necessary	16.00 FS	*- FS
24	1		*BONNET STOP BUFFER	Necessary	18.00 FS	*14.40 FS
25	1		*BONNET SEAL - FRONT	Necessary	55.00 FS	*44.00 FS
26	1		*BONNET LOCK COVER - UPPER	Not Necessary	44.00 FS	*- FS
27	1		*FRONT FENDER - LH	Distorted	930.00 FS	*744.00 FS
28	1		*FRONT FENDER BRACE - LH	Bent	107.00 FS	*85.20 FS
29	1		*FRONT FENDER BRACKET - LH	Bent	35.00 FS	*27.68 FS
30	1		*FRONT FENDER RETAINING PLATE - LH UPPER	Necessary	30.00 FS	*23.92 FS
31	1		*FRONT FENDER CLOSING ELEMENT - LH	Necessary	57.00 FS	*45.28 FS
32	1		*FRONT FENDER WHEEL HOUSING LINER - LH FRONT	Crumpled	151.00 FS	*120.80 FS
33	1		*FRONT FENDER WHEEL HOUSING LINER - LH REAR	Crumpled	97.00 FS	*77.36 FS
34	1		*FRONT WHEEL SPOILER - LH	Not Necessary	30.00 FS	*- FS
35	1		*FRONT FENDER CONNECTING PLATE - LH LOWER	Distorted	658.00 FS	*526.00 FS
36	1		*FRONT FENDER CONNECTING PLATE - LH UPPER	Distorted	126.00 FS	*100.80 FS
37	1		*HEADLIGHT - LH	Smashed	1,830.00 FS	*1,725.60 FS
38	1		*HEADLIGHT CONTROL UNIT	Dented	1,919.00 FS	*1,535.20 FS
39	1		*HEADLIGHT CONNECTOR HOUSING	Cracked	28.00 FS	*21.76 FS
40	1		*GAS DISCHARGE BULB	Damaged	394.00 FS	*314.80 FS
41	1		*FRONT LOCK CARRIER	Cracked	861.00 FS	*688.80 FS
42	1		*FRONTAL SUPPORT FRAME	Not Necessary	744.00 FS	*- FS
43	1		*A/C CONDENSER	Bent	505.00 FS	*403.60 FS
44	1		*RADIATOR	Bent	998.00 FS	*786.40 FS
45	1		*COOLANT	Necessary	106.24 FS	*106.24 FS
46	1		*CHARGE AIR COOLER	Bent	1,006.00 FS	*804.80 FS
47	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
48	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
49	1		*FRONT NUMBER PLATE	Necessary	25.00 FS	*25.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*SUNDRIES	Necessary	600.00 FS	*185.20 FS
51	2		*FRONT BUMPER TOP COVER - LH / RH	Distorted	106.88 FS	*106.88 FS
52	1		*FRONT NOISE INSULATION	Damaged	165.60 FS	*165.60 FS
53	1		*SIDE MEMBER CABLE GUIDE - LH FRONT	Damaged	17.20 FS	*17.20 FS
54	1		*AIR FILTER AIR GUIDE - FRONT	Damaged	26.96 FS	*26.96 FS
55	1		*INTAKE AIR DUCT	Damaged	22.72 FS	*22.72 FS
56	1		*FRONT FENDER SUPPORT - LH	Distorted	31.84 FS	*31.84 FS
57	1		*FRONT FENDER CONNECTING PLATE - LH LOWER	Repeated	658.00 FS	*- FS
58	1		*FRONT FENDER CONNECTING PLATE - LH UPPER	Repeated	126.00 FS	*- FS
59	1		*SET ALUMINIUM RIVET	Necessary	320.80 FS	*320.80 FS
60	1		*FRONT LOCK CARRIER AIR GUIDE - LH	Damaged	23.68 FS	*23.68 FS
61	1		*WASHER HOSE	Damaged	137.60 FS	*137.60 FS
62	1		*WASHER TANK BRACKET	Damaged	68.80 FS	*68.80 FS
<b>Total Parts (\$\$)</b>					<b>22,588.32</b>	<b>15,160.76</b>

F=Franchise part, S=SpcNett.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,400.00	1,400.00
3	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER AND BONNET. CUT OUT AND REWELD LHS FRONT FENDER SUPPORT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	5,250.00
4	TO RESPRAY PAINT ON FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS A-PILLAR, LHS FENDER SUPPORT AND RHS DOOR	New	3,200.00	3,000.00
5	TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,944.00</b>	<b>10,514.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >