

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 7340Y

MAKE :

MODEL : HYUNDAI i40

DATE 12/2/2018 13:53

Like

4/8am
CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Grille (LH)			\$ 40.30
	Front Bumper Centre Grille Top Garnish			\$ 80.00
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Retainer Mounting			\$ 9.20
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH)			\$ 1,388.00
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Front Fender Retainer X			\$ 9.20
	SUB TOTAL			\$ 4,636.00
	LESS 20%			\$ 927.20
	DISCOUNTED TOTAL			\$ 3,708.80
	Front Fender Advertisement Logo (LH)			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			400
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Remove/Refix Aircon & Refill Gas			\$ 150.00 X
	TOTAL LABOUR			\$ 1,500.00
	ESTIMATE TOTAL			\$ 5,308.80

Kalin LKK
12/2/18 1420h
2011
4/5
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
 Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.