

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/159/2018/GW
Date : 6-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. James Lufianto Santoso
Address : Blk 310 b Anchorvale Rd
#13-17
Singapore 542310
Telephone : HP +65 97945102
Type of Claim : Own Damage Claims
Policy No. : 2100284607-06
Vehicle No : **SKD 7425 K**
Model Code : Audi A6 C7 2.0 TFSI Mu
Model / Year : Dec-11
Engine No : CDN 235010
Chassis No : WAUZZZ4G2CN064991
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-18
Place of Accident : The Cathay Cineplex Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKD 7425 K

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKD 7425 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$ 2,205.00	✓
2	REAR BUMPER SPOILER <i>cut</i>	\$ 301.00	✓
3	REAR BUMPER SECURING STRIP <i>new</i>	\$ 148.00	+
4	REAR BUMPER CARRIER <i>Bent</i>	\$ 851.00	✓
5	REAR BUMPER IMPACT BAR GASKET-LH/RH	2 \$ 24.00	+
6	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 56.00	+
7	REAR BUMPER UPPER GUIDE-RH	\$ 49.00	+
8	REAR BUMPER GUIDE SECTION-CENTRE	\$ 91.00	+
9	REAR BUMPER SENSOR	\$ 421.00	+
10	REAR BUMPER WIRING SET	\$ 603.00	+
11	REAR BUMPER VENT TRIM	\$ 65.00	+
12	REAR SILENCER	\$ 1,157.00	+
13	REAR SILENCER BRACKET-RH	\$ 50.00	+
14	REAR SILENCER-DUAL CLIP	\$ 47.00	+
15	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 6,368.00	
TOTAL LABOUR CHARGES		\$ 2,502.00	
GRAND TOTAL		\$ 8,870.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling*
Surveyed Date : *13/02/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 03 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant