

# SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:11/02/18

Date:12/02/18

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

|                                                 |             |             |
|-------------------------------------------------|-------------|-------------|
| 1pce tail gate                                  | \$ 1,200.00 | RM /        |
| 1pce tail gate top lock                         | 129.40      | RM /        |
| 1pce tail gate lower lock                       | 30.70       | RM /        |
| 1pce tail gate lower lock cover end panel cover | 130.00      | DE /        |
| 1pce tail gate airwave plate                    | 35.10       | RM /        |
| 1pce tail gate emblem                           | 38.00       | RM /        |
| 2pcs tail gate reflectors@\$255.30              | 510.60      | SC /        |
| 1pce tail gate centre garnish cover             | 321.20      | CR /        |
| 1pce tail gate trim cover                       | 345.90      | CR /        |
| 1pce tail gate handed                           | 21.10       | RM /        |
| 2pcs tail gate dampers@\$198                    | 396.00      | X           |
| 2pcs rear fender trim cover@\$158.20 LH-cut /   | 316.40      | RH X        |
| 2pcs tail lamps@\$278                           | 556.00      | LH-X / RH-? |
| 1pce rear windscreen top rubber                 | 42.20       | RM /        |
| 1pce rear windscreen lower rubber               | 38.50       | RM /        |
| 2pcs rear windscreen side rubber@\$28.10        | 56.20       | RM /        |
| 1pce rear windscreen inner sealant              | 140.00      | 60 RM / S/N |
| 1pce rear windscreen sunx sticker               | 350.00      | X           |
| 1pce tail gate rubber                           | 178.40      | RM /        |
| 1pce rear bumper                                | 985.00      | RM /        |
| 1set rear bumper reverse sensors                | 450.00      | X           |
| 10pcs rear bumper inner clips@\$5               | 50.00       | RM /        |
| 4pcs rear bumper top side clips#@\$10           | 40.00       | RM /        |
| 2pcs rear bumper side holders@\$68              | 136.00      | RM /        |
| 1pce rear panel                                 | 485.00      | BT /        |
| 1pce rear spare tyer panel                      | 850.10      | page 1 RM / |

# SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:11/02/18

Date:12/02/18

Rene

Hp 90010068

10 days

4/5

12/02/18 @ 1010

Recy after repair

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

|                                                   |                    |            |
|---------------------------------------------------|--------------------|------------|
| 1set spare tyer panel paddling                    | \$ 285.20          | na /       |
| 1pce spare tyer top cover                         | 198.20             | X          |
|                                                   | \$ 8,315.20        |            |
|                                                   | 1,663.04           |            |
|                                                   | \$ 6,652.16        |            |
| 1pce rear number plate with cover                 | 100.00             | 35 M - S/A |
| To rustproof                                      | 150.00             | 100        |
| To check wiring                                   | 50.00              | 30         |
| To remove/refit rear windscreen                   | 140.00             | 120        |
| To dismantle/renew tail gate                      | 150.00             | 80         |
| To remove/refit rear interior to effect repair    | 100.00             | 60         |
| To remove/refit rear petrol tank to effect repair | 150.00             | X          |
| To dismantle/renew reverse sensors                | 100.00             | 60         |
| To remove/refit top spoiler                       | 100.00             | 60         |
| To dismantle/renew accident portion               | 1,800.00           | 1200       |
| To spray paint                                    | 1,500.00           | 1200       |
| <b>Total:</b>                                     | <b>\$10,992.16</b> |            |
| 1pc Tailgate water Lock                           | 215.10             | ?          |
| 2PCS Tail lamp inner panel                        | 430.40             | R          |
| 1pc rear reverse Camera                           | 3350.00            | X          |

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: