

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711

NAME :	Dr Yong Kian Hui
ADDRESS :	5 Rivervale Crescent #12-08 Singapore 545084

WIP: 31641

DATE: 12.02.2018

ATTN.:	MOTOR CLAIMS DEPT
FAX :	62244174

TEL : 02 23 68 60 00

VEH NO :	SGF2703C
----------	----------

DATE IN :		CONTACT PERSON :
-----------	--	------------------

RICK	63602445
FBI - CHICAGO	

CHASSIS NO :	WP1ZZZ95ZGLB05630
--------------	-------------------

MILEAGE :		TYPE OF CLAIM :
-----------	--	-----------------

TP AGAINST SHA4422P	

MODEL :	Porsche Macan PDK
---------	-------------------

DATE REG.:	03-11-15	POLICY NO.:
------------	----------	-------------

--	--

NATURE OF WORKS	
1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100

[illegible][illegible]

1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	1560/day.	\$ 3,900.00
2	TO SPRAY PAINT REAR BUMPER.	1300/bumper	\$ 1,500.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	NETT	\$ 250.00

4	TO REMOVE / REPLACE EXHAUST SYSTEM INCLUDE		\$ 2,340.00
	CHECK FOR LEAKAGE.		1560
5	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES	NETT	\$ 600.00
	AFTER ACCIDENT REPAIR.		
6	TO SUPPLY 1 PC NO PLATE \$70.00 EA	NETT	\$ 70.00
7	SUNDRIES.		\$ 100.00
			50
		TOTAL LABOUR	\$ 8,760.00
		TOTAL PARTS	\$ 6,941.61
		GRAND TOTAL	\$ 15,701.61

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

Sebastian.
21/2/18.

- Part by part repair.
- Question Mark Iron Photo.
- Photo Before Paint

90036121

sebastianyeang@lkkauto.com.

5 days.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: