

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHD 3985Y

DATE 12/2/2018

MAKE :

MODEL : HYUNDAI SONATA

Ang Asia - (LH) TS
 LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid X <i>140</i>			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate -			\$ 43.60
	Boot Lid Hyundai Plate -			\$ 24.20
	Boot Lid 'H' Emblem -			\$ 26.10
	Boot Lid CRDI Plate -			\$ 22.70
	Rear Bumper -			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip -			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (RH) -			\$ 38.00
	Tail Lamp (RH) X			\$ 344.00
	Rear Panel X			\$ 391.80
	Rear Panel Garnish X			\$ 95.80
	<i>Rear Fender (RH) x repair</i>			
	SUB TOTAL			\$ 4,015.90
	LESS 20%			\$ 803.18
	DISCOUNTED TOTAL			\$ 3,212.72
	Boot Lid Comfort Logo & Tel No. Sticker -			\$ 30.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Advertisement Logo -			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) -		\$ 100.00	\$ 200.00
				\$ 415.70
	Labour Charge			
	Panel Beating			\$ 400 <i>850.00</i>
	Spray Painting Charge			\$ 600.00 <i>540</i>
	Wiring Charge			\$ 50.00 <i>8X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,298.42

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.