

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

*ALG ASIA - C/P/P* TS

VEHICLE NO : SHD 7164Z

DATE 12/2/2018

MAKE :

*LKK - Kalvin*

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket, LH ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH) ✓			\$ 32.00
				<b>\$ 1,939.35</b>
				<b>\$ 387.87</b>
				<b>\$ 1,551.48</b>
				<b>\$ 50.00</b> Nett
				<b>\$ 50.00</b>
				<b>200</b>
	Labour Charge			\$ <del>380.00</del>
	Panel Beating			\$ <del>200.00</del>
	Spray Painting Charge			<b>180</b>
				<b>\$ 580.00</b>
				<b>\$ 2,181.48</b>

Rear Bumper i40 Plate ✓ (*modl*)

Labour Charge  
 Panel Beating  
 Spray Painting Charge

**TOTAL LABOUR**

**ESTIMATE TOTAL**

*Kalvin LKK*  
*12/2/18 1540h*  
*2 Days*  
*PIP*  
*Before Part photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.