

AZG

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8755S

DATE 12/2/2018 15:59

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x 1 pc</i>			\$ 603.60
	Rear Bumper Clips 10 pcs <i>x</i>			\$ 22.00
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Labour Charge			<i>100</i>
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 200.00
	TOTAL LABOUR			\$ 400.00
	ESTIMATE TOTAL			\$ 900.48
<p><i>Kehar (KK)</i></p> <p><i>11 12/2/18 1610L</i></p> <p><i>20-71</i></p> <p><i>P/P</i></p> <p><i>At the Repair p Ltd</i></p>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				