

INSURANCE

INS. CASE OWNER:

Rachah

CC 6 / AIG18002969 / A983

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

12/02/18

Date / Time:

12/02/18

Registered in Merimen:

13/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJY 6226B

Claim No.:

8730054522SG

Name of Insured:

CHAN KUM SENG

Policy No.:

2100507171

Insured Tel No.:

HP: 9669 8803

Make / Model:

KIA CERATO K3-1.6 (17)

Excess Sec II :\$5

D.O.A: 12/02/18

Place of Accident:

SLE - SKE - 11.6 KM LANE 23

Is driver the owner?

YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP: NHT
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5 13,000.00 (14 days) Reduction: (9.10 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 100

Repair Cost:

\$5 13,000.00

(SUEH C.L. OI 2MT)

Loss of Rental (LOR): (w/43)

\$5 1,177.00 (11 days) 100 + 11 days

Loss of Use (LOU):

\$5 - (5 x days)

Loss of Income (LOI):

\$5 - (5 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LO ☐ (Tick only one)

GIA/LTA Search

\$5 7.45

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/Independent)

Legal Cost:

\$5 -

Total:

\$5 14,177.00 Global Sum \$5: 14100.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

\$5 14,100.00

Name 1:

New Hock Tek Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

4370.00

Surveyor

REF:

ASSIGNMENT

From _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 14 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF4000T Yr Regn: 2016 Oct
 Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna cc 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 63/98 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: 11FAT3590k206618

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C
 R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A.		D.O.I. <u>12/02/18</u>	

Survey held at: NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

MV: 70K
 PV: 37.4K
 Nett: 32.6K

\$13,000/-

(rel \$30,040 / 69.7%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 - RS - \$

Phone

Other

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: _____

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18002969/Ays3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 6226B	Veh. Inspected	GBF 4000T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/02/2018	Inspection Date	12/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

NEWZONE SINGAPORE PTE LTD

12/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP A16

Jas

JTFAT35Y90K206618

Accident date: 12/02/2018

Estimated repair cost for vehicle no: GBF4000T TOYOTA DYNA 150 3.0 M '16

CHASSIS: JTFAT35Y90K206618

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Panel <i>Dented</i>		\$976.30 ✓
2	1	Front Panel Dyna Logo <i>new</i>		\$79.90 ✓
3	1	Front Grille <i>crushed</i>		\$372.70 ✓
4	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 <i>20</i>
5	1	Front Grille Emblem Logo <i>new</i>		\$61.10 ✓
6	2	Front Head Lamp <i>crushed</i>	\$573.90	\$1,147.80 ✓
7	2	Front Head Lamp Lower Rubber <i>short new</i>	\$38.00	\$76.00 ✓
8	1	Front Bumper <i>Bent</i>		\$356.20 ✓
9	1	Front Bumper Centre Member <i>Bent</i>		\$291.25 ✓
10	1	Front Bumper Number Plate <i>Bent</i>		\$50.00 <i>30(SN)</i>
11	1	Front Windscreen Rubber <i>new</i>		\$290.20 ✓
12	1	Front L/H Door <i>Repair</i>		\$1,712.10 ✓
13	1	Front L/H Step Panel <i>new</i>		\$374.10 ✓
14	1	Front Air-Con Coolant Coil & Blower Assy <i>crushed</i>		\$1,800.90 <i>1431.8</i>
15	1	Front Air-Con Coolant Coil Section Pipe <i>3 new</i>		\$398.90 ✓
16	1	Front Air-Con Coolant Coil Discharge Pipe <i>1 new</i>		\$386.60 ✓
17	1	Front Air-Con Air Duct & Blower Assy <i>crushed</i>		\$978.10 ✓
18	1	Front L/H Bumper Air-Con Condenser <i>Dented</i>		\$486.00 ✓
19	1	Front L/H Bumper Air-Con Condenser Fan Motor Assy <i>new</i>		\$798.00 ✓
20	1	Front L/H Bumper Condenser Section Pipe <i>3 new</i>		\$279.10 ✓
21	1	Front L/H Bumper Condenser Discharge Pipe <i>1 new</i>		\$269.60 ✓
22	1	Rear Tailgate <i>Dented</i>		\$1,714.40 <i>1349</i>
23	1	Rear Tailgate Toyota Sticker <i>3 new</i>		\$80.00 ✓
24	1	Rear Tailgate Dyna Sticker		\$40.00 ✓
25	2	Rear Tailgate Top Side Handle <i>new</i>	\$187.30	\$374.60 ✓
26	2	Rear Tailgate Lower Side Lock <i>Bent</i>	\$171.40	\$342.80 <i>24320</i>
27	2	Rear Tailgate Lower Side Hinge <i>Bent</i>	\$181.70	\$363.40 <i>11240</i>
28	2	Rear Tailgate Lower Side Bracket <i>Bent</i>	\$168.60	\$337.20 ✓

29	4	Rear Tailgate Lower Side Rubber Stopper	at 2 pieces	\$31.20	\$124.80	62.40
30	2	Rear Tail Lamp	smashed	\$327.50	\$655.00	522.60
31	2	Rear Tail Lamp Panel	distorted	\$374.45	\$748.90	373.20
32	1	Rear Number Plate	Best		\$50.00	30.50
33	1	Rear Number Plate Lamp	coil		\$131.35	
34	1	Rear Number Plate Panel	Best		\$127.30	
35	1	Rear Spare Tyre Lock	Done		\$283.00	
36	1	Rear Exhaust	Best		\$980.10	585.10
37	2	Rear Exhaust Mounting	for	\$61.10	\$122.20	61.10
38	1	Rear Centre Exhaust	Best		\$678.10	
39	1	Rear Floor Panel	Local Repair	Refuse	\$10,000.00	12000
				S.N. 1060	Subtotal:-	\$28,390.00

11522.50
8641.87

S/N	QTY	ITEMS / SPECIAL NETT	U/PRICE	AMOUNT
40	1	Front Bumper LED Light <i>Done</i>		\$380.00 <i>x 250</i>
41	1	Front L/H Door Sticker <i>new</i>		\$30.00 <i>x</i>
42	1	Rear Tailgate 70km/H Sticker <i>new</i>		\$30.00 <i>15</i>
43	1	Rear Tailgate 13pax Sticker <i>new</i>		\$30.00 <i>15</i>
44	1	Rear Tailgate Aluminium Cover <i>new</i>		\$450.00 <i>x</i>
45	100	Rear Tailgate & Floor Panel Aluminium Rivet <i>new</i>	\$3.50	\$350.00 <i>x</i>
46	1	Rear Step Panel Bracket <i>Best</i>		\$580.00 <i>280</i>
47	1	Rear Reverse Sensor <i>Done</i>		\$380.00 <i>200</i>
48	1	Rear Spare Tyre Lock Member <i>Best</i>		\$380.00 <i>✓</i>
49	1	Rear Floor Panel Aluminium Cover <i>new</i>		\$950.00 <i>x</i>
Subtotal:-				\$3,560.00

1140

Labour charges

To remove & refit front windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit windscreen camera	\$180.00 40
To remove & refit dashboard	\$380.00 220
To remove & refit air-con coolant coil & air duct blower pipe, L/H air-con condenser, fan motor & top up gas	\$750.00 280
To remove & refit front L/H door gear motor, trim board, glass & lock	\$180.00 X
To remove & refit rear & centre exhaust	\$380.00 160
To remove & refit reverse sensor	\$100.00 50
To remove & refit aluminium box	\$450.00 X
To remove & refit floor box & repair chassis frame	\$2,800.00 1000
To check wiring	\$100.00 60
Towing fee	\$150.00 50
Tuff kote	5410 \$150.00 80
Panel beating	\$2,500.00 1700
Spray painting	\$2,800.00 1600

Subtotal:- \$11,090.00

Total:- \$43,040.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged pan(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any item(s) must be resurveyed and approved from Insurance Company

total 16251.87

H/S 13K

14 Days

13K

14 Days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3452R

Vehicle Details

Vehicle No.:	GBF4000T
Vehicle to be Exported:	No
Intended De-registration Date:	12 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2626064
Chassis No.:	JTFAT35Y90K206618
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	11 Oct 2016
First Registration Date:	11 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,182.00
COE Rebate Amount:	\$37,396.00
Total Rebate Amount:	\$37,396.00

The information contained herein is correct as at 12 Feb 2018

OK

- COE Bidding – 1st Round of February 2018
- Photos of the week
- Kindly educate on opening car doors

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

BMW 7 Series 740i Sunroof



Direct Owner, Select colour, 1st
Market New & Multiple Road
Tax!
Direct Owner, Shared



Browse by Category

Sort by Date Posted

20 results/page

14 vehicles

Dyna

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Dyna	Any	Any	2016	Any	Any	Any	Available
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Well Maintained, See To Believe, Almost New. \$0 Drive Away, 100% Loan Available, High Trade In. Call Now For More Details.	\$67,888	\$8,590 /yr	08-Jan-2016	2,982 cc	33,547 km	Truck	Available
Posted: 08-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel Insurance Until March 2018. Direct Owner. Call To View, Auto Engine Wash And Well Maintained.	\$70,000	\$8,660 /yr	14-Mar-2016	2,982 cc	80,500 km	Truck	Available
Posted: 21-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel View To Offer, Price Negotiable. Come With Full Checker Plate And Canopy. Well Maintained, Excellent Condition! Minimum Down Payment With In House Loan Available. Call For More Enquiries!	\$66,800	\$8,260 /yr	15-Mar-2016	2,982 cc	-	Truck	Available
ABWIN (1994) Pte Ltd Posted: 06-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Best Selling Toyota Dyna 10 Feet Lorry Come With Canopy. 100% Loan Available, \$0 Drive Away, High Trade In. Act Fast, Don't Miss It, Call Now.	\$66,888	\$8,230 /yr	29-Mar-2016	2,982 cc	-	Truck	Available
Posted: 01-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
Car Buying	Car Selling	Car Aftermarket		Buying a pre-owned car, but unsure of its condition? Get STA Car Evaluation				
Car Ownership	On The Move	Lifestyle						
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Best Selling Toyota Dyna 10 Feet Lorry. Like New, Showroom Condition. 100% Loan Available, \$0 Drive Away. High Trade In. Act Fast, Don't Miss It, Call Now For More Details.	\$67,888	\$8,350 /yr	01-Apr-2016	2,982 cc	-	Truck	Available
Posted: 31-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Low Mileage, \$0 Drive Away, Almost New, Most Reliable Commercial Lorry. High Trade In. Don't Miss It. Call Now!	\$69,888	\$8,440 /yr	23-May-2016	2,982 cc	18,523 km	Truck	Available
Posted: 03-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel Auction Closing Time: 14th Feb 2018 at 11:00 PM This Vehicle Is GST Chargeable, Kindly Download The GST Chargeable Tender Form At This Link: http://goo.gl/ZvupBS	-	N.A	21-Jun-2016	2,982 cc	70,012 km	Truck	Available
Posted: 08-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota								
Toyota Dyna 150		\$71,500	\$8,470 /yr	22-Jul-2016	2,982 cc	54,900 km	Truck	Available

**Fuel Type:** Diesel

Think One Automobile & Trading

Posted: 18-Dec-2017 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$69,800****\$8,250 /yr****29-Jul-2016****2,982 cc****-****Truck****Available****Fuel Type:** Diesel

1 Owner, Vehicle Only Run At Terminal 4 Contract Project, Come And View The Smooth And Buttery Drive That Can Carry You With Your Daily Life! Low Mileage, All Trade In Are Welcome, 100% Loan Available...

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 12-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$78,000****\$9,200 /yr****05-Aug-2016****2,982 cc****21,000 km****Truck****Available****Fuel Type:** Diesel

1 Owner Only And Low Mileage! Like Brand New Condition. No Repairs Needed! Nice Number Plate! Low Depreciation! Most Importantly, Hassle Free Immediate Hand Over And Buy With Peace Of Mind Because Th...

SINGLE OWNER

Posted: 16-Dec-2017 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$70,800****\$8,300 /yr****24-Aug-2016****2,982 cc****-****Truck****Available****Fuel Type:** Diesel

1 Owner, Vehicle Only Run At Terminal 4 Contract Project, Good Condition, Low Mileage, Look Like New, All Trade In Are Welcome, 100% Loan Available, New Paint Work Done! No Gimmick! Please Call Now!

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 12-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$66,800****\$7,740 /yr****29-Sep-2016****2,982 cc****36,445 km****Truck****Available****Fuel Type:** Diesel

Almost New Toyota Dyna 150 Box With Powerful Euro 5 Diesel Turbo Engine! 6.5 Feet High Box, Engine And Gearbox In Tip Top Condition, Low Mileage Serviced By Agent And Accident Free. COE Of \$48k, High ...

PREMIUM AD

Posted: 22-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$75,800****\$8,630 /yr****23-Nov-2016****2,982 cc****-****Truck****Available****Fuel Type:** Diesel

Almost New! 100% Loan Available! Ready Stock! Color Silver, White And Blue! Any Trade In Welcome! Limited Stock Only! Call Now To Fix An Appointment!

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 12-Feb-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

**Toyota Dyna 150****\$66,800****\$7,580 /yr****06-Dec-2016****2,982 cc****4,000 km****Truck****Available****Fuel Type:** Diesel

3 Years/100,000km Warranty By Agent Borneo Motors. Up To 100% Loan With Lowest Interest Rate, Special Gift, High Trade-In! Please Call Now!

PREMIUM AD

ABWIN Bus Pte Ltd

Posted: 25-Jan-2018 Tags: 2016 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Dyna, Dyna Singapore, used Dyna Singapore, used Dyna, used vehicles Singapore or even buy used Dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

Poh Kin (LKKAUTO)

From: Admin nht <admin@nhtmotor.com>
Sent: Tuesday, 18 June 2019 2:19 PM
To: Poh Kin (LKKAUTO)
Cc: Olivia Lau (LKKAUTO); Chloe; Admin A
Subject: Re: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE.

Categories: clear

Without Prejudice

Hi Poh Kin

Thanks for your offer.

For amicable settlement, we accept your offer as \$14,100 for close case.

Please send us the discharge voucher for close case, thanks.

Best Regards,

Sukyi Chong

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276

<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------

On Tue, Jun 18, 2019 at 11:11 AM Poh Kin (LKKAUTO) <pohkin@lkkauto.com> wrote:

"Without Prejudice"

"Save As To Costs"

Our Ref: CC6/AIG18002969/Amb3

Your Ref: GBF 4000T

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 18 June 2019 11:11 AM
To: Admin nht
Cc: Olivia Lau (LKKAUTO); Chloe; Admin A
Subject: RE: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE.

Importance: High

"Without Prejudice"
"Save As To Costs"

Our Ref: CC6/AIG18002969/Amb3
Your Ref: GBF 4000T

Dear Sukyi,

We refer to the above matter.

Thank you for your patient waiting.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement at global sum of **\$ 14,100.00(all in)** on this matter.

Kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Print Received Message

This mail is associated with :

***GBF4000T (8730054522SG)
[SJY6226B]**

TP
NEWZONE SINGAPORE PTE LTD
Feb 12 2018 7:00AM
[Chan Kum Seng]
New Hock Teck Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 13/06/2019 11:13 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14100.00) - GBF4000T - Claim Handler: Foo, Chit Yan

Approved:14100.00:Subject to GIA/LTA search billing

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 30 April 2019 10:46 AM
To: Foo, Chityan
Cc: Admin A
Subject: RE: [AIG]: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE // LKK Ref: CC6/AIG18002969/Amb3

Importance: High

Our Ref: CC6/AIG18002969/Amb3
Your Ref: 8730054522SG

Dear Jimmy,

We refer to the above matter and below e-mail.

As requested, Surveyor justify damages on the following parts:

Parts	Comment/remarks	Photo
Front Panel	Dented	14-17, 131-132
Front Panel DYNA logo	Necessary	
Front Grille	Cracked	9-12, 94-97
Front Grille Clip	Necessary	
Front Grille Emblem Logo	Necessary	
Front Head Lamp	Cracked	12-13-98-102
Front Windscreen Rubber	Necessary	
Front Air-con Coolant Coil & Blower Assy	Cracked	68-70
Front Air-con Air Duct & Blower Assy	Cracked	71-72
Front Left Hand Bumper Air-con Condenser	Dented	76-81
Rear Tailgate Lower Side Lock	Bent	31-32, 122-124
Rear Tailgate Lower Side Bracket	Bent	31,40-41
Rear Tailgate Lower side bracket stopper	Cut	31,40-41
Rear Spare Tyre Lock	Damaged	59-61
Rear Centre Exhaust	Bent	29-30, 39, 53-55,85-92
Rear Floor Panel (Local Repair)	Necessary	103-106, 118-120
Front Bumper LED Light	Damaged	8
Rear Spare Tyre Lock Member	Bent	114-117

Hope above information clarify.

For your Instruction in Merimen please.

Poh Kin (LKKAUTO)

From: Foo, Chityan <Chityan.Foo@aig.com>
Sent: Monday, 29 April 2019 11:55 AM
To: Poh Kin (LKKAUTO)
Subject: RE: [AIG]: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE // LKK Ref: CC6/AIG18002969/Amb3

Hi Poh Kin,

We refer to your email dated 03.04.19.

We seek your clarification on the replacement parts as follow:

- Front Panel 14-17, 131-132
- Front Panel DYNA logo *new*
- Front Grille 9-12, 94-97
- Front Grille Clip *new*
- Front Grille Emblem Logo *new*
- Front Head Lamp 12-13, 98-102
- Front Windscreen Rubber *new*
- Front Air-con Coolant Coil & Blower Assy 68-70
- Front Air-con Air Duct & Blower Assy 71-72
- Front Left Hand Bumper Air-con Condenser 76-81
- Rear Tailgate Lower Side Lock 31-32, 122-124
- Rear Tailgate Lower Side Bracket 31, 40-41
- Rear Tailgate Lower side bracket stopper 31, 40-41
- Rear Spare Tyre Lock 59-61
- Rear Centre Exhaust 29-30, 39, 53-55, 85-92
- Rear Floor Panel (Local Repair) 103-106, 118-120
- Front Bumper LED Light 8
- Rear Spare Tyre Lock Member 114-117

Kindly let us hear from you soon before approval of mandate in merimen.

Kind regards,

Jimmy Foo
AIG
Complex Claims Examiner
AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1945 | Fax +(65) 6835 7416

Chityan.foo@aig.com | www.aig.sg

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Wednesday, April 3, 2019 10:00 AM
To: Foo, Chityan <Chityan.Foo@aig.com>
Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: [EXTERNAL] RE: [AIG]: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE // LKK
Ref: CC6/AIG18002969/Amb3
Importance: High

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Wednesday, 3 April 2019 10:00 AM
To: 'Foo, Chityan'
Cc: Olivia Lau (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: [AIG]: ACCIDENT ON 12.02.18 INVOLVING SJY6226B and GBF4000T ALONG SLE/BKE // LKK Ref: CC6/AIG18002969/Amb3

Importance: High

Our Ref: CC6/AIG18002969/Amb3
Your Ref: 8730054522SG

Dear Jimmy,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SJY 6226B (OI), GBF 4000T (TP) AND OTHERS ON 12/02/2018

We refer to the above matter and our tele conversation.

Liability: The said chain collision involved Three vehicles whereby TP was the second vehicle, our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer to Third Party repairer, "New Hock Teck Motor Pte Ltd" is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 43,040.00	\$13,000.00
2. Loss of Rental	\$ 1,765.50 (11 days x \$150.00)+7%gst	\$ 1,412.40 (11 days x \$120.00)+7%gst
3. LTA search fee	\$ 7.45	\$ 7.45
Total	\$ 44,812.95	\$14,419.85

Total amount of claim (Liability 100%)

\$14,419.85

***Recommended 14 repair days

All the relevant documents had been uploaded in Merimen for your perusal.

For your kind attention on this matter.

NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1803-0026/ GBF4000T
Your Ref : SJY6226B
Date : 27th March 2018

1 Kaki Bukit Avenue 6
Blk C #01-43 Autobay@KB
Singapore 417883

AIG ASIA Pacific Insurance Pte Ltd
78 Shenton Way,
AIG Building, #09-16
Singapore 079120

Dear Sirs,

RE: ACCIDENT INVOLVING GBF4000T & SJY6226B AT SLE(BKE) BEFORE EXIT 11 ON 12.02.2018, 07:12HRS

We are instructed by **NEWZONE SINGAPORE PTE LTD** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **GBF4000T** was damaged by vehicle **SJY6226B** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$ 13,000.00
2) Loss of Rental for 11 days	\$ 1,765.50
3) LTA Search Fees	\$ 7.45
	<u>\$ 14,772.95</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$14,772.95** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

A handwritten signature in black ink is written over a circular stamp. The stamp contains the text "NEW HOCK TECK MOTOR PTE LTD" around the perimeter and a star in the center.

NEW HOCK TECK MOTOR PTE LTD

Bevan Lim (LKK Auto)

From: Mohamedrasheed, Rashidah <Rashidah.Mohamedrasheed@aig.com>
Sent: Thursday, 24 May 2018 1:23 PM
To: Bevan Lim (LKK Auto)
Cc: Vic (LKKAuto); Admin A; Olivia Lau (LKKAuto)
Subject: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018
Attachments: Re: FW: GBF4000T CLAIMING SJY6226B DOA 12.02.18; VD.pdf

Dear Bevan,

Based on vehicle damaged report;

Towing	0.00	0.00	0.00
Calculated Gross Total (S\$)	43,040.00	16,828.00	26,212.00
Approved Total (Overridden) (S\$)		13,000.00	
Nett Amount (S\$)	43,040.00	13,000.00	30,040.00
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00	
+ Doc/Search Fee (S\$)		7.45	
Nett Liability (S\$)		14,184.45	

INSPECTION

Date of Assignment:

12/02/2018

Date Inspected:

12/02/2018 Inspected At:

New Hock Teck Motor Pte Ltd
 1 Kaki Bukit Ave 6, Blk C #01-
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair:

14.0 days

As per your email;

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 43,040.00	\$13,000.00
2. Loss of Rental (11days x \$150)(w/gst)	\$ 1,765.50	\$ 1,765.50 (11days x \$150.00)(w/gst)??
3. LTA/GIA search fee	\$ 7.45	\$ 7.45
TOTAL	\$ 44,812.95	\$14,772.95
Total amount of claim (Liability 100%)		\$14,772.95??

Why the report and email amount inconsistent?

By the way, our surveyor advice, COR \$6973.51 8DAYS

We agreed to the following;

Loss of Rental - \$140 * 11 days = \$1647.80

LTA - \$7.45

Please advice the COR gap \$6.9k and \$13k with photos.

Thank you

Rashidah Rasheed

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Bevan Lim (LKK Auto) [mailto:bevanlim@lkkauto.com]

Sent: Thursday, May 24, 2018 12:55 PM

To: Mohamedrasheed, Rashidah

Cc: Vic (LKKAuto); Admin A; Olivia Lau (LKKAuto)

Subject: RE: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/GBF 4000T (TP) /OTHERS ON 12/02/2018

Dear Sir/Madam,

We further to our email below.

We have offer TP a global sum of \$9,000.00 (all-in) and was rejected. Attached Email for your reference.

Kindly let us have your instruction for our necessary action.

Thank you.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Bevan Lim (LKK Auto)

Sent: Thursday, 24 May 2018 12:19 PM

To: 'Mohamedrasheed, Rashidah' <Rashidah.Mohamedrasheed@aig.com>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

Dear Sir/Madam,

We refer to your email below.

We will offer \$9000.00 (all-in) to TP repairer as per your instruction.

Thank you.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Mohamedrasheed, Rashidah [<mailto:Rashidah.Mohamedrasheed@aig.com>]

Sent: Thursday, 24 May 2018 12:14 PM

To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

Dear Bevan,

Enclosed our In-house surveyor advice.

Approved \$9000 (all in).

Thank you

Rashidah Rasheed

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Mohamedrasheed, Rashidah

Sent: Tuesday, May 22, 2018 4:31 PM

To: 'Bevan Lim (LKK Auto)'

Cc: Vic (LKKAuto); Admin A

Subject: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

Dear Bevan,

We are reviewing the claim.

Thank you

Rashidah Rasheed

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Bevan Lim (LKK Auto) [mailto:bevanlim@lkkauto.com]
Sent: Tuesday, May 22, 2018 3:58 PM
To: Mohamedrasheed, Rashidah
Cc: Vic (LKKAuto); Admin A
Subject: RE: Your Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018
Importance: High

Dear Sir/Madam,

We refer to our email dated 25/04/2018.

Kindly let us have mandate approval as TP repairer is chasing us for settlement.

Thank you.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Bevan Lim (LKK Auto)
Sent: Wednesday, 25 April 2018 11:25 AM
To: 'Mohamedrasheed, Rashidah' <Rashidah.Mohamedrasheed@aig.com>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Your Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

Your Ref: **TP / 8730054522SG**
Our Ref: **CC6/AIG18002969/Amb3q2**

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

We refer to the above matter.

This a 3 vehicle chain collision and insured was the last vehicle. Liability is down against our insured.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **New Hock Teck Motor Pte Ltd** is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 43,040.00	\$13,000.00
2. Loss of Rental (11 days x \$150)(w/gst)	\$ 1,765.50	\$ 1,765.50 (11 days x \$150.00)(w/gst)

3. LTA/GIA search fee		\$ 7.45	\$ 7.45
	TOTAL	\$ 44,812.95	\$14,772.95
Total amount of claim (Liability 100%)			\$14,7723.95

***Recommended 14 repair days

Market Value	: \$70,000.00(est)
LTA Rebate	: \$ 37,400.00(est)
Nett Value	: \$ 32,600.00 (est)

All the relevant documents had been uploaded in Merimen for your perusal.

For your approval in Merimen please.

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Bevan Lim (LKK Auto)

From: Mohamedrasheed, Rashidah <Rashidah.Mohamedrasheed@aig.com>
Sent: Thursday, 24 May 2018 12:14 PM
To: Bevan Lim (LKK Auto)
Cc: Vic (LKKAuto); Admin A
Subject: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018
Attachments: Re: FW: GBF4000T CLAIMING SJY6226B DOA 12.02.18; 20180523164918.pdf

Dear Bevan,

Enclosed our In-house surveyor advice.

Approved \$9000 (all in).

Thank you

Rashidah Rasheed
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1767 | Fax +(65) 6835 7416

Rashidah.Mohamedrasheed@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Mohamedrasheed, Rashidah
Sent: Tuesday, May 22, 2018 4:31 PM
To: 'Bevan Lim (LKK Auto)'
Cc: Vic (LKKAuto); Admin A
Subject: our Ref: TP / 8730054522SG Our Ref: CC6/AIG18002969/Amb3q2 ACCIDENT INVOLVING SJY 6226B(OI)/ GBF 4000T (TP) /OTHERS ON 12/02/2018

Dear Bevan,

We are reviewing the claim.

Print Received Message

This mail is associated with :

***GBF4000T (8730054522SG)**

[SJY6226B]

TP

NEWZONE SINGAPORE PTE LTD

Feb 12 2018 7:00AM

[Chan Kum Seng]

New Hock Teck Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/05/2018 12:13 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9000.00) - GBF4000T - Claim Handler: Mohd-Rasheed, Rashidah

Approved:9000.00.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18002969/Ams3

14 MARCH 2018

CHAN KUM SENG
688E WOODLANDS DRIVE 75
#11-68
SINGAPORE 735688

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 6226B AND GBF 4000T ON 12/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

New Hock Teck Motor Pte Ltd

Kaki Bukit Avenue 6

Blk 1 #01-43

Singapore 417883

Dear Sir,

Accident on 12/02/2018, 07:12
Involving Vehicles GBF4000T, SJY6226B.
Along SLE(BKE) Before EXH 11

I/We, the registered owner/driver of vehicle registration no: GBF 4000T.
have involved in the above accident.

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.


I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature
(Company's stamp if applicable)



Name: _____

NRIC No.: _____

Date: _____

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **New Hock Teck Motor Pte Ltd** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$14,100.00** (Global Sum) for vehicle no. **GBF 4000T** that was damaged pursuant to the accident which occurred on **12/02/2018** (date) along **SLE** (location) involving vehicle no/s **SJY 6226B**. This is pursuant to the inspection conducted on **12/02/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **NEWZONE SINGAPORE PTE LTD** ("the third party claimant") of vehicle no. **GBF 4000T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **GBF 4000T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of 06 (month) 2019 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)





新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TAX INVOICE

AIG ASIA Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building, #09-16

Singapore 079120

Client: NEWZONE SINGAPORE PTE LTD

Invoice No : NPL1803-0056

Date : 27-Mar-18

Date of Accident : 12-Feb-18

Vehicle No. : GBF4000T

Model Type : Toyota Dyna

Descriptions	Amount
Lump Sum Repair Cost	13,000.00
Total	13,000.00

SIN DOLLARS: THIRTEEN THOUSAND ONLY





長江企業(私人)有限公司

Chiang Kang Enterprises Co. (Pte.) Ltd.



1995 - 2003

TOTAL DEFENCE

TAX INVOICE

No. 4 Petain Road, Petain Court Singapore 208086 Tel: 6298 1936, 6294 0246 Fax: 6298 3864

RENTAL OF CARS, VANS, PICK-UPS & LORRIES

出租：汽車、廣告車、必甲與輕重型羅厘

GST Reg. No. 29-8304039-K

HIRER'S PARTICULARS

If Different From

Section 1

I/We

of

S

Tel:

hereinafter called "the Hirer" hereby confirm having agreed to hire this day from CHIANG KANG ENTERPRISES CO. (PTE.) LTD. hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

a) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$1500/- to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire or loss resulting from theft and destruction of the Vehicle.

b) COMPREHENSIVE MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2000/- for any damage caused to the hired Vehicle from any single accident or any loss resulting from third party damage claim, injury claim, theft or destruction of the Vehicle.

c) Only persons above 24 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the vehicle whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the terms and conditions of Hire, hereinafter mentioned and printed at the back hereof.

Vehicle Regn No. 車輛註冊號碼 GBF1857 GBF1587		Rental Agreement 合同號碼 No. A 90726	
Section 1 Hire's And/Or Driver's Particulars 租車者/駕駛員個人記錄		租出日期及時間 Date & Time OUT 12/2/18 @ 0945	
姓名 Mohan Senthikumar Name:		交車日期及時間 Date & Time IN 23/02/18 @ 10am	
地址 2 Kishun Ind St 1 #05-08 North Point Address:		Chargeable Rates Amount	
Bizhub		11	天 Days @ \$ 81650/-
居民證/護照號碼 I/C No./Passport No. 87948755X		駕駛執照號碼 Driving Licence No:	
居民證/護照種類 Type of I/C/Passport:		星期 Weeks @ \$	
出生日期 Date of Birth: 03/06/1983		月 Month @ \$	
發出地 Place of Issue:		ADD 7% GST 8115.50	
三號保險底金 \$1500/- a) Third Party Only Policy Excess \$1500/-		一號保險底金 \$2000/- b) Comprehensive Policy Excess \$2000/-	
送車/費 Delivery Fees		總計 Total Charge 81765.50	
車輛必須將還車主於 Vehicle Must Be Returned To Owner's Office By:		備註與付款記錄 Remarks & Payment Records	
按金 Security Deposit		總金額 Total Payable 81765.50	
來銀 Amount Paid		收車費用 Collection Fees/Misc.	
IMPORTANT! For Singapore Use only!		超過/小時 Extra Hours @ \$	
出車油箱 Fuel Tank OUT	出車油箱 Fuel Tank IN	租費不包括汽油 Rates Do Not Include Fuel	原油 Refuelling
車牌號碼 Vehicle No:	1)	起 From:	至 To:
車牌號碼 Vehicle No:	2)	起 From:	至 To:
工具 Tools	輪胎 Spare Tyre	裝飾品 Accessories	加額費用 Total Additional Charges
車輛發出人 Vehicle Issued By:	車輛接收人 Vehicle Collected By:	總計 Grand Total	
NOTE: 註 租車者或司機必須付所有停車及違反交通法例負起一切的責任。 HIRER AND/OR DRIVER IS LIABLE FOR ALL PARKING AND TRAFFIC VIOLATIONS.			

租車者不准載沙或石灰
HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

我/我們同意以上及後頁租車公司所列的條款與條件。

I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

日期
Date:

12/2/18

租車者簽名
Signature of Hirer:



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Feb 2018 / 09:28:13

Receipt Date/Time : 12 Feb 2018 / 09:28:13

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180212-000267

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	------------------------------------------------------------	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SJY6226B

As at 12 Feb 2018/07:12:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SJY6226B

Enquiry Fee

20180212092731546146

7.00 0.49 7.49

Sub-Total

7.00 0.49 7.49

Total Before Rounding

7.00 0.49 7.49

Rounding Difference

0.04

Total Amount Payable

7.45

Paid By

20180212092737664 Direct Debit: eNETS Debit
(Internet Banking) 7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[Print Receipt](#) [OK](#) [Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018 Edit Reg		12 Feb 2018 00:00 Edit Adj Rpt	\$S\$13,000.00 Edit Estimates	\$S\$13,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Chan Kum Seng, ID: S1746774C								
Main Claimant:	NEWZONE SINGAPORE PTE LTD. Co. Reg. No.: 201003452R								
Vehicle Reg. No.:	GBF4000T	Date of Loss:	12/02/2018 07:00 - :59 [16 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8730054522SG	Policy/Cover Note No.:	2100507171 (Comprehensive) Coverage: 19/04/2017 - 18/04/2018						
Vehicle Reg. No. (Insured):	SJY6226B	Policy No. (Claimant):	DMCPHQ17-005375						
		Excess:							
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (13/06/2019): Alert - Adj Mandate Approved (\$S\$14100.00) - GBF4000T - Claim Handler: Foo, Chit ... AIG_SG_EXPRESS (24/05/2018): Alert - Adj Mandate Approved (\$S\$9000.00) - GBF4000T - Claim Handler: Mohd-Rashee... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF4000T (8730054522SG)
[SJY6226B]
TP
NEWZONE SINGAPORE PTE LTD
Feb 12 2018 7:00AM
[Chan Kum Seng]
New Hock Teck Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1			Edit		
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail			Print		
1	14/02/18 09:12	Accident Statement From: OD – Reg. No: SJY6226B, Claimant: CHAN KUM SENG													1			Load HTM		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	08/03/18 11:49	General View													1			Load JPG		
2	08/03/18 11:49	General View													1			Load JPG		
3	08/03/18 11:49	Chassis Number													1			Load JPG		
4	08/03/18 11:49	General View													1			Load JPG		
5	08/03/18 11:49	General View													1			Load JPG		
6	08/03/18 11:49	General View													1			Load JPG		
7	08/03/18 11:49	General View													1			Load JPG		
8	08/03/18 11:49	General View													1			Load JPG		
9	08/03/18 11:49	General View													1			Load JPG		
10	08/03/18 11:49	General View													1			Load JPG		
11	08/03/18 11:49	General View													1			Load JPG		
12	08/03/18 11:49	General View													1			Load JPG		
13	08/03/18 11:49	General View													1			Load JPG		
14	08/03/18 11:49	General View													1			Load JPG		
15	08/03/18 11:49	General View													1			Load JPG		
16	08/03/18 11:49	General View													1			Load JPG		
17	08/03/18 11:49	General View													1			Load JPG		
18	08/03/18 11:49	General View													1			Load JPG		
19	08/03/18 11:49	General View													1			Load JPG		
20	08/03/18 11:49	General View													1			Load JPG		
21	08/03/18 11:49	General View													1			Load JPG		
22	08/03/18 11:49	General View													1			Load JPG		
23	08/03/18 11:49	General View													1			Load JPG		
24	08/03/18 11:49	General View													1			Load JPG		
25	08/03/18 11:49	General View													1			Load JPG		
26	08/03/18 11:49	General View													1			Load JPG		
27	08/03/18 11:49	General View													1			Load JPG		
28	08/03/18 11:49	General View													1			Load JPG		
29	08/03/18 11:49	General View													1			Load JPG		
30	08/03/18 11:49	General View													1			Load JPG		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
32	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
33	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
34	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
35	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
36	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
37	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
38	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
39	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
40	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
41	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
42	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
43	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
44	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
45	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
46	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
47	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
48	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
49	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
50	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
51	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
52	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
53	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
54	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
55	08/03/18 11:49	General View		<input checked="" type="checkbox"/>
56	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
57	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
58	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
59	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
60	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
61	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
62	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
63	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
64	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
65	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
66	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
67	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
68	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
69	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
70	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
71	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
72	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
73	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
74	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
75	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
76	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
77	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
78	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
79	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>
80	08/03/18 11:50	Reinspection Photo		<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	08/03/18 11:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 21:05	TP GIA REPORT	 Load PDF	
2	14/03/18 09:22	LETTER TO OI	 Load PDF	
3	23/04/18 15:18	RENTAL RECEIPT	 Load PDF	
4	23/04/18 15:18	LTA SEARCH	 Load PDF	
5	19/09/18 17:56	TP Estimate-Marked	 Load PDF	
6	03/04/19 10:01	seek mandate e-mail	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY6226B (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBF4000T (TP veh)		
Date of Accident:	12/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	:	\$		43,040.00
Final Repair Cost	:	\$		14,100.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		11 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		14,100.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	: \$	14,100.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

27 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18002969/AFB3Q2

Date: 27/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507171
Claimant Vehicle No : GBF4000T **Insured Vehicle No :** SJY6226B
 Date of Loss: 12/02/2018 Nature of Claim: TP Claim No: 8730054522SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4000T**
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2626064
 Reg. Date: 11/10/2016 (Man. Year: 2016) Chassis No: JTFAT35Y90K206618
 Colour: White Odometer: 63198 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,950.00	11,418.00	20,532.00	64.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,090.00	5,410.00	5,680.00	51.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,040.00	16,828.00	26,212.00	60.90
Approved Total (Overridden) (S\$)		13,000.00		
Nett Amount (S\$)	43,040.00	13,000.00	30,040.00	69.80
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		14,184.45		
Global Sum Settlement (S\$)		14,100.00		

INSPECTION

Date of Assignment: 12/02/2018
 Date Inspected: 12/02/2018 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43
 Autobay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	976.30 F	*976.30 FL
2	1		*FRONT PANEL DYNA LOGO	Necessary	79.90 F	*79.90 FL
3	1		*FRONT GRILLE	Cracked	372.70 F	*372.70 FL
4	8		*FRONT GRILLE CLIP	Necessary	52.00 F	*20.00 FL
5	1		*FRONT GRILLE EMBLEM LOGO	Necessary	61.10 F	*61.10 FL
6	2		*FRONT HEAD LAMP	Cracked	1,147.80 F	*1,147.80 FL
7	2		*FRONT HEAD LAMP LOWER RUBBER	Not Necessary	76.00 F	*- FL
8	1		*FRONT BUMPER	Bent	356.20 F	*356.20 FL
9	1		*FRONT BUMPER CENTRE MEMBER	Bent	291.25 F	*291.25 FL
10	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 FS	*30.00 FS
11	1		*FRONT WINDSCREEN RUBBER	Necessary	290.20 F	*290.20 FL
12	1		*FRONT L/H DOOR	Repair	1,712.10 F	*- FL
13	1		*FRONT L/H STEP PANEL	Not Necessary	374.10 F	*- FL
14	1		*FRONT AIR-CON COOLANT COIL & BLOWER ASSY	Cracked	1,800.90 F	*1,431.90 FL
15	1		*FRONT AIR-CON COOLANT COIL SECTION PIPE	Not Necessary	398.90 F	*- FL
16	1		*FRONT AIR-CON COOLANT COIL DISCHARGE PIPE	Not Necessary	386.60 F	*- FL
17	1		*FRONT AIR-CON AIR DUCT & BLOWER ASSY	Cracked	978.10 F	*978.10 FL
18	1		*FRONT L/H BUMPER AIR-CON CONDENSER	Dented	486.00 F	*486.00 FL
19	1		*FRONT L/H BUMPER AIR-CON CONDENSER FAN MOTOR ASSY	Not Necessary	798.00 F	*- FL
20	1		*FRONT L/H BUMPER CONDENSER SECTION PIPE	Not Necessary	279.10 F	*- FL
21	1		*FRONT L/H BUMPER CONDENSER DISCHARGE PIPE	Not Necessary	269.60 F	*- FL
22	1		*REAR TAILGATE	Dented	1,714.40 F	*1,349.00 FL
23	1		*REAR TAILGATE TOYOTA STICKER	Necessary	80.00 F	*80.00 FL
24	1		*REAR TAILGATE DUNA STICKER	Necessary	40.00 F	*40.00 FL
25	2		*REAR TAILGATE TOP SIDE HANDLE	Not Necessary	374.60 F	*- FL
26	2		*REAR TAILGATE LOWER SIDE LOCK	Bent	342.80 F	*240.20 FL
27	2		*REAR TAILGATE LOWER SIDE HINGE	Bent	363.40 F	*112.40 FL
28	2		*REAR TAILGATE LOWER SIDE BRACKET	Bent	337.20 F	*337.20 FL
29	4		*REAR TAILGATE LOWER SIDE RUBBER STOPPER	Cut (2 PCS ONLY)	124.80 F	*62.40 FL
30	2		*REAR TAIL LAMP	Smashed	655.00 F	*570.60 FL
31	2		*REAR TAIL LAMP PANEL	Distorted	748.90 F	*373.20 FL
32	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
33	1		*REAR NUMBER PLATE LAMP	Cracked	131.35 F	*131.35 FL
34	1		*REAR NUMBER PLATE PANEL	Bent	127.30 F	*127.30 FL
35	1		*REAR SPARE TYRE LOCK	Damaged	283.00 F	*283.00 FL
36	1		*REAR EXHAUST	Bent	980.10 F	*585.20 FL
37	2		*REAR EXHAUST MOUNTING	Torn	122.20 F	*61.10 FL
38	1		*REAR CENTRE EXHAUST	Bent	678.10 F	*678.10 FL
39	1		*REAR FLOOR PANEL (LOCAL REPAIR)	Necessary	10,000.00 FS	*1,000.00 FS
40	1		*FRONT BUMPER LED LIGHT	Damaged	380.00 FS	*250.00 FS
41	1		*FRONT L/H DOOR STICKER	Not Necessary	30.00 FS	*- FS
42	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*15.00 FS
43	1		*REAR TAILGATE 13PAX STICKER	Necessary	30.00 FS	*15.00 FS
44	1		*REAR TAILGATE ALUMINIUM COVER	Not Necessary	450.00 FS	*- FS
45	1		*REAR TAILGATE & FLOOR PANEL ALUMINIUM RIVET (100 PCS)	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR STEP PANEL BRACKET	Bent	580.00 FS	*280.00 FS
47	1		*REAR REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
48	1		*REAR SPARE TYRE LOCK MEMBER	Bent	380.00 FS	*380.00 FS
49	1		*REAR FLOOR PANEL ALUMINIUM COVER	Not Necessary	950.00 FS	*- FS
					Sub Total (\$\$)	31,950.00 13,722.50
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 2,304.50
					Total Parts (\$\$)	31,950.00 11,418.00

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT WINDSCREEN CAMERA	New	180.00	40.00
4	TO REMOVE & REFIT DASHBOARD	New	380.00	220.00
5	TO REMOVE & REFIT AIR-CON COOLANT COIL & AIR DUCT BLOWER PIPE,L/H AIR-CON CONDENSER ,FAN MOTOR & TOP UP GAS	New	750.00	280.00
6	TO REMOVE & REFIT FRONT L/H DOOR GEAR MOTOR ,TRIM BOARD ,GLASS & LOCK	New	180.00	0.00
7	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	160.00
8	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE & REFIT ALUMINIUM BOX	New	450.00	0.00
10	TO REMOVE & REFIT FLOOR BOX & REPAIR CHASSIS FRAME	New	2,800.00	1,000.00
11	TO CHECK WIRING	New	100.00	60.00
12	TOWING FEE	New	150.00	50.00
13	TUFF KOTE	New	150.00	80.00
14	PANEL BEATING	New	2,500.00	1,700.00
15	SPRAY PAINTING	New	2,800.00	1,600.00
Gross Labour Cost (S\$)			11,090.00	5,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >