

22/03/2002

ASS. REC. BY:

REF:

CS / AXA18002973 / 11/02/02

Special Instruction:

merimen 7-5

SUBJECT:

Maxus

ASSIGNMENT (Office)

From (Person):

Stacy Ng

of

AXA

Date/Time:

12022018 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 1344J

Insured:

SHB 9579H

at Workshop n/s

SME Motor

Tel:

6747 6106

of

Blk 1 Kaki Bukit Ave 6 #02-15

Policy No:

P1680520

Claim No:

C0470350

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08022012

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 1344J - x

SHB 9579H - NO / TP14005297/13

D.O.A. : 170514

Sent poli thru merimen

(08/11/13) wef

ASS. REC. BY: *MORCIS*

REF:

AXA

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SK213447*
at Workshop m/s *Sme*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *SK213447* Yr Regn: *6 16*
Type: *C* M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA /*
Make: *Toyota* *harrier* c.c. *1986*
Colour: *Black* A/C: Insured / Std / NI / NA
Sp. Reading: *33929* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *2SU600074113*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *In order* / Jammed / Leaked / Burnt or
Brake: *In order* / Jammed / Leaked / Burnt or
Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: *235/55R16*
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
DAC Accident Rpt: _____ Consistent? : Yes or No
CA / PR Seen: *9* Consistent? : Yes or No
Est. Repairs: *6* days Res.: Yes or No
Lum Sum: *1.81* % 3 Val.: Yes or No

Front Rear
R/Bal. *2* mm R/Bal. *2* mm
L/Bal. *2* mm L/Bal. *2* mm
D.O.A. _____ D.O.I. *13/2/18*
Survey held at _____

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: *0/S Rear 2* Frt / Rear / O/S / N/S / U/C / Rooftop or
The *U/C* Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
have video
21/3/18 confirm P. no 1. by 7802.58 with AHGing
Red: 82835.10, 26%

RECEIVED 10/3/2013

Date/Time: File Pass to? ☐ : Preli. Report
☒ : Final Report

Days Of Repair: *6*
Resurvey No. of Trip: *2*

1) *typist*
Date/Time: File Return to?

2) _____
Report Format: *TP*
Lump Sum / I.B.I: (\$ *7902.58*)

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: *250*
Transportation: _____
S + RS: _____
Photos _____
Others _____
TOTAL *250*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA18002973/Urb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-02-2018



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 9579H	Veh. Inspected	SKZ 1344J
Policy No.	P1680520	Coverage (\$)	0.00
Claim No.	C0470350	Excess (\$)	0.00
Assign From	MERIMEN (STACEY NG)	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/02/2018	Inspection Date	13/02/2018
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		12 Feb 2018 22:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD		
Main Claimant:	MOHANDAS S/O SITALDAS NANDWANI		
Vehicle Reg. No.:	SKZ1344J	Date of Loss:	08/02/2018 20:00 - :59
Claim Type:	TP / C0470350	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9579H	Policy No. (Claimant):	
	Excess:	S\$5,000.00	
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/02/2018]		
Driver/Custodian (Insured):	CHAN YUE WAH (67 / Male), NRIC: S0189872H, Tel: +6591909120		
Adj Asg. Remarks:	Please survey only		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Stacey Ng

Date: 21 Feb 2018

Preliminary Advice

Insured Vehicle No	: SHB9579H	Accident Date	: 08/02/2018
TP Vehicle No	: SKZ1344J	Assignment Date	: 12/02/2018
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 5.00
Date of Inspection	: 13/02/2018		
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	7,182.18
Revised Amount	:S\$	2,484.58
Check Items (Estimated)	:S\$	2,913.75
Total	:S\$	5,398.33

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorize repair.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 15:51
Date Of Accident	08/02/2018 20:50
Exact Location Of Accident	PIE (BEFORE EXIT AFTER PAYA LEBAR)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ1344J
Insured/Policyholder	
Name Of Registered Owner	MOHANDAS S/O SITALDAS NANDWANI
NRIC No	S1558357F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96501344
Alternative Phone No	OFFICE-96501344

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 PREMIUM (A)
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5081567861-01
Cover Note Number	

Driver

Name of Driver	MOHANDAS S/O SITALDAS NANDWANI
NRIC No	S1558357F
Date Of Birth	18/12/1962
Occupation	INDOOR
Date Of Driving Pass	30/12/2005
Driving Experience	12 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96501344
Fax Number	
Contact Number	OFFICE-96501344
EMail Address	NOEMAIL


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8357F

Vehicle Details

Vehicle No.: SKZ1344J

Vehicle to be Exported: No

Intended De-registration
Date: 14 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: HARRIER PREMIUM 2.0 A

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: 3ZRB744634

Chassis No.: ZSU600074113

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$31,418.00

Original Registration Date: 24 Jun 2016

First Registration Date: 24 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$30,986.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 23 Jun 2026

PARF Rebate Amount: \$23,239.00

Intended COE Rebate Details

COE Expiry Date: 23 Jun 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$49,000.00

COE Rebate Amount: \$40,955.00

Total Rebate Amount: \$64,194.00

The information contained herein is correct as at 14 Feb 2018

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

Not Authorized
LWK
To be signed before
13/2/18
Bdy.

M/S : AXA INSURANCE PTE LTD
8 Shenton Way #24-01
AXA Tower
Singapore 068811
TEL: 68804741 FAX: 68804838
ATTN: Motor Claim Department
Your Ref No: 18/AXA/TP-035 (02)
Claim Type: Third Party
Accident Date: 08/02/2018
TP Veh Reg No: SHB9579H

Estimate No: EST0003966
Date: 12 Feb 2018
Policy No: 5081567861-01
Veh Reg No: SKZ1344J
Make/Model: TOYOTA HARRIER
Chassis No: ZSU600074113
Engine No: 3ZRB744634
Reg. Date: 24/06/2016

Estimate Repair Cost to Vehicle No :SKZ1344J

Description	Quantity	List Price S\$	Amount S\$
List Price			
1 REAR BUMPER <i>top Dis</i>	1 PC	1,415.10	—
2 REAR BUMPER SIDE RETAINER RH <i>3rd</i>	1 PC	85.00	—
3 REAR BUMPER CLIP <i>2nd</i>	10 PC	15.00	—
4 REAR SHOCK ABSORBER RH <i>1st/2nd</i>	1 PC	291.00	—
5 REAR LOWER ARM RH <i>2nd/3rd</i>	1 PC	643.00	—
6 REAR KNUCKLE ARM RH <i>2nd/3rd</i>	1 PC	535.00	—
7 REAR KNUCKLE ARM BEARING RH <i>2nd</i>	1 PC	845.00	—
8 REAR STEERING CROSSMEMBER <i>2nd/3rd</i>	1 PC	1,336.00	—
9 REAR TAIL LAMP RH <i>1st</i>	1 PC	465.00	—
10 REAR UPPER ARM RH <i>2nd</i>	1 PC	331.00	—
11 REAR LOWER ARM BALL JOINT RH <i>2nd</i>	1 PC	195.00	—
12 REAR EXHAUST BOX <i>2nd</i>	1 PC	1,296.80	—
13 REAR EXHAUST BOX RUBBER HOLDER <i>1st</i>	2 PC	110.00	—
		7,562.90	5,672.18
	Less 25%	1,890.73	
Labour			
14 WIRE CHECKING	1 UNIT	20.00	—
15 REMOVE & REFIX REAR UNDERCARRIAGE (CROSSMEMBER)	1 UNIT	250.00	—
16 WHEEL ALIGNMENT	1 UNIT	60.00	—
17 REMOVE & REFIX EXHAUST	1 UNIT	180.00	—
18 LABOUR CHARGE	1 UNIT	500.00	—
19 SPRAY PAINTING	1 UNIT	500.00	—
		1,510.00	1,510.00

Total S\$ 7,182.18
Add GST @ 7% 502.75
Total Amount Payable S\$ 7,684.93

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED EIGHTY FOUR AND CENTS NINETY THREE ONLY

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

7902-58

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S: MOHANDAS S/O SITALDAS NANDWANI
16B JALAN RUMAU

SINGAPORE 418738

ATTN:

Your Ref No: 18/AXA/TP-035 (02)

Claim Type: Third Party

Accident Date: 08/02/2018

TP Veh Reg No: SHB9579H

Estimate No: EST0003966

Date: 02 Mar 2018

Policy No: 5081567861-01

Veh Reg No: SKZ1344J

Make/Model: TOYOTA HARRIER

Chasis No: ZSU600074113

Engine No: 3ZRB744634

Reg. Date: 24/06/2016

Estimate Repair Cost to Vehicle No :SKZ1344J

Description	Quantity	List Price	Amount
		S\$	S\$
Supplementary Parts to Repair			
List Price			
1 REAR RH SPORT RIM	1 PC	2,655.00	10005.~
2 REAR RH TRAILING ARM	1 PC	240.00	
3 REAR RH ADJUSTMENT ROD	1 PC	255.00	
4 REAR RH FENDER INNER COWLING	1 PC	254.00	
5 INNER COWLING CLIPS	10 PC	55.00	
6 REAR BUMPER (LOWER)	1 PC	455.00	
		3,914.00	
	Less 25%	978.50	2,935.50
Labour			
7 REPAIR REAR EXHAUST BOX	1 UNIT	120.00	60
8 REPAIR REAR RH FENDER	1 UNIT	300.00	✓
9 SPRAY REAR END PANEL	1 UNIT	200.00	✓
		560	620.00
Total			S\$ 3,555.50
GST Amount			S\$ 248.89
Total Amount Payable			S\$ 3,804.39

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

07/03/2018

P-6950-1
5212.58

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2018		12 Feb 2018 22:41 Edit Adj Rpt	S\$7,902.57 Edit Estimates	S\$7,902.57 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	MOHANDAS S/O SITALDAS NANDWANI		
Vehicle Reg. No.:	SKZ1344J	Date of Loss:	08/02/2018 20:00 - :59
Claim Type:	TP / C0470350	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB9579H	Policy No. (Claimant):	
		Excess:	S\$5,000.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/02/2018]		
Driver/Custodian (Insured):	CHAN YUE WAH (67 / Male), NRIC: S0189872H, Tel: +6591909120		
Adj Asg. Remarks:	Please survey only		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKZ1344J (C0470350)**
[SHB9579H]
TP
MOHANDAS S/O SITALDAS NANDWANI
Feb 8 2018 8:00PM
[TRANS-CAB SERVICES PTE LTD]
SME Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/18 11:35	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/18 11:47	SKZ 1344J INSPECTION	1	Load PDF	
2	21/03/18 16:31	SKZ 1344J RE-INSPECTION 2	1	Load PDF	
3	21/03/18 16:31	SKZ 1344J RE-INSPECTION	1	Load PDF	
Documentation				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	12/02/18 10:40	ESTIMATE & SKZ1344J TP GIA_ABS	1	Load PDF	
2	12/02/18 10:40	SHB9579H INS GIA_ABS	1	Load PDF	
3	12/02/18 10:40	EMAIL_ABS	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/02/18 11:48	SKZ 1344J ESTIMATE	1	Load PDF	
2	21/03/18 15:56	SKZ 1344J SUPPLEMENTARY	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 500px; margin: 5px 0;"></div> <div style="text-align: right; margin-right: 10px;"> <input type="button" value="^"/> <input type="button" value="v"/> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AXA18002973/URBE2

Date: 23/03/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SKZ1344J

Insured Vehicle No :

SHB9579H

Date of Loss: 08/02/2018

Nature of Claim:

TP

Claim No: C0470350

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ1344J**

Make & Model: TOYOTA HARRIER, 2.0 Premium (A)

Engine No: 3ZRB744634

Reg. Date: 24/06/2016 (Man. Year: 2016)

Chassis No: ZSU600074113

Colour: Black

Odometer: 33929 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side: Bridgestone 8 mm

Rear Left Side:

Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side:

Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,607.67	6,212.57	2,395.10	27.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,690.00	440.00	20.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,737.67	7,902.57	2,835.10	26.40
+ GST 7.00/7.00% (S\$)	751.64	553.18	198.46	26.40
Nett Amount (S\$)	11,489.31	8,455.75	3,033.56	26.40

INSPECTION

Date of Assignment: 12/02/2018

Date Inspected: 13/02/2018 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @

Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2018)
Parts: M1-SUV TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ1344J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP (CONSISTENT)	Distorted	1,415.10 FL	*1,415.10 FL
2	1		*REAR BUMPER SIDE RETAINER RH (CONSISTENT)	Bent	85.00 FL	*85.00 FL
3	10		*REAR BUMPER CLIP (CONSISTENT)	Necessary	15.00 FL	*15.00 FL
4	1		*REAR SHOCK ABSORBER RH (CONSISTENT)	Cracked / Twisted	291.00 FL	*291.00 FL
5	1		*REAR LOWER ARM RH (CONSISTENT)	Bent / Twisted	643.00 FL	*643.00 FL
6	1		*REAR KNUCKLE ARM RH (CONSISTENT)	Bent / Twisted	535.00 FL	*535.00 FL
7	1		*REAR KNUCKLE ARM BEARING RH (CONSISTENT)	Necessary	845.00 FL	*845.00 FL
8	1		*REAR STEERING CROSSMEMBER (CONSISTENT)	Twisted / Cracked	1,336.00 FL	*1,336.00 FL
9	1		*REAR TAIL LAMP RH (CONSISTENT)	Not Necessary	465.00 FL	*- FL
10	1		*REAR UPPER ARM RH (CONSISTENT)	Bent	331.00 FL	*331.00 FL
11	1		*REAR LOWER ARM BALL JOINT RH (CONSISTENT)	Bent	195.00 FL	*195.00 FL
12	1		*REAR EXHAUST BOX (CONSISTENT)	Repair	1,296.80 FL	*- FL
13	2		*REAR EXHAUST BOX RUBBER HOLDER (CONSISTENT)	Not Necessary	110.00 FL	*- FL
14	1		*REAR RH SPORT RIM (CONSISTENT)	Dented / Cracked	1,991.25 FS	*1,000.00 FS
15	1		*REAR RH TRAILING ARM (CONSISTENT)	Bent / Twisted	240.00 FL	*240.00 FL
16	1		*REAR RH ADJUSTMENT ROD (CONSISTENT)	Twisted	255.00 FL	*255.00 FL
17	1		*REAR RH FENDER INNER COWLING (CONSISTENT)	Torn	254.00 FL	*254.00 FL
18	10		*INNER COWLING CLIPS (CONSISTENT)	Necessary	55.00 FL	*55.00 FL
19	1		*REAR BUMPER (LOWER) (CONSISTENT)	Grazed	455.00 FL	*455.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,813.15	7,950.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,205.48	1,737.53
Total Parts (\$\$)	8,607.67	6,212.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	20.00	20.00
2	REMOVE & REFIX REAR UNDERCARRIAGE (CROSSMEMBER)	New	250.00	250.00
3	WHEEL ALIGNMENT	New	60.00	60.00
4	REMOVE & REFIX EXHAUST	New	180.00	0.00
5	LABOUR CHARGE	New	500.00	400.00
6	SPRAY PAINTING	New	500.00	400.00
7	REPAIR REAR EXHAUST BOX	New	120.00	60.00
8	REPAIR REAR RH FENDER	New	300.00	300.00
9	SPRAY REAR END PANEL	New	200.00	200.00
Gross Labour Cost (S\$)			2,130.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >