

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

**AIG ASIA PACIFIC INSURANCE PTE LTD**

Charts Building  
 78 Shenton Way #07-16  
 Singapore 079120  
 Tel : 6419 - 3000  
 Fax : 6835 - 7416

**Quotation**  
 DATE : 02.03.2018  
 VEH NO : SKJ354X  
 MODEL : Lexus IS250  
 D O A : 06.02.2018  
 YR REF : SGC3403C

*Asher*

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SKJ354X (LEXUS IS250)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amnt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Bumper <i>Repair</i>	1	806.10 *
2	Front Bumper Clips <i>new</i>	1 set	30.00 *
3	Front Bumper Side Holder - RH <i>new</i>	1	99.50 *
4	Front Fender - RH <i>Dented</i>	1	731.40 ✓
			<hr/> 1,667.00
	Less 10%		(166.70)
			<hr/> \$ 1,500.30
	<b>Total Parts</b>		<hr/> <b>\$ 1,500.30</b>

**LABOUR CHARGE**

1	To knocking & pull out front portion & renew above parts	\$	<del>400.00</del> 200
2	To putty & spray up paint works	\$	<del>600.00</del> 400
3	To check wiring	\$	<del>50.00</del> 30
	<b>Total Labour</b>	\$	<hr/> 1,050.00

**Grand Total**

**\$ 2,550.30**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price to be reflected in the final bills
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

**NOTE**

**PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN**  
 Acknowledged by Repairer  
 Signature:  
 Date:

*total: 1288.26*  
*4/31/18*  
*03 Pys.*

RE : ESTIMATE FOR ACCIDENT REPAIR SKJ354X (LEXUS IS250)

THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY  
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE  
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.