

ESTIMATE

Invoice Name & Address				Owner Name & Vehicle Info			
Paamee Go				Cust No/Name /Paamee Go			
B1k718A Upper Changi Road East				Reg No/Reg Date SKU4830D / 30/07/2015			
#01-05 Changi Green				Date In/Mileage / 0			
Singapore 486850				Chassis No VF73A9HC8FJ651615			
				Engine No 10JBEX3056680			
Contact No Mobile: 91067570				Make/Model CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG			
				Colour/Trim 9PM / BK			

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	12/02/2018/ 20:03	TLC	442 / CocoLu	13240

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000				2400 4800.00
TO RENEW FRT DOOR LH, SIDE SILL LH, REPAIR REAR DOOR LH	600			1260 1680.00
E PNT98000				120 280.00
TO SPRAY PAINT FOR FRT DOOR LH, REAR DOOR LH, SIDE SILL LH	420			
E PNT88000				80.00
TO REMOVE & INSTALL FRT DOOR TRIMS AND GLASS TO FACILITATE REPAIR				
M SUNDRY				50.00
TO APPLY SEALANT FOR ACCIDENT AFFECTED AREA				
A 54900099				300.00
TO CHECK WIRING & ELECTRICAL SYSTEM				
A 54900099				20.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				
M SUNDRY				1234.00
Sundry	1.00	1234.00	0.00	bt 1234.00
M FRONT DOOR LH ASS	1.00	73.00	0.00	73.00
M DOOR HINGE LH INF	1.00	73.00	0.00	73.00
M DOOR HINGE LH SUP	1.00	86.00	0.00	86.00
M DOOR STOP	1.00	67.00	0.00	nei 67.00
M DR WEATHERSTRIP LH AV	1.00	75.00	0.00	nei 75.00
M DR WEATHERSTRIP LH INF	1.00	119.00	0.00	nei 119.00
M DR WEATHERSTRIP LH SUP	1.00	177.00	0.00	nei 177.00
M SEALING PANEL LH	1.00	72.00	0.00	nei 72.00
M MOULDING LH	1.00	44.00	0.00	nei 44.00
M TRIM LH	1.00	219.00	0.00	nei 219.00
M DOOR FIXINGS	1.00	183.00	0.00	3 183.00
M WINDOW CHANNEL LH	1.00	523.00	0.00	523.00
M WINDOW LIFTER LH	1.00	847.00	0.00	bt 847.00
M UNDER-BODY LH				

SURVEYOR NAME: Tanpin 97445749

SURVEYOR SIGNATURE: [Signature]

DATE: 14/2/18 @ 10:20

REMARKS: WP Resurvey before paint
sur @ 14/2/18
8 days

Confirm & accepted by Customer

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation

Authorized high priority survey on "Without Prejudice" basis

No illegal modification(s) is allowed

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are including GST. We would warrant that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must acknowledge the amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature: _____ Date: _____

Parts	3,792.00
Labour	7,110.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	100.00
Total(w/o GST)	11,002.00