

INS CASE OWNER:

CC6 / III1800 2978, A 3 e 9

LKK:
IDAC:

Surveyor:

ADRIAN / XLR

ASSIGNMENT
DOI: 12/1/2018

Date / Time:

12/1/2018

Registered in Merimen:

14/1/18

Pre-assign / CCU / FTE

SHD 4141J



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : SS

D.O.A: 7/1/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lee Ah Hong

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SKX 5873H



INSRS:

WSP: Ho Hong

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/2
17/1

SKX 5873H, X ; SHD 4141J, X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

11.12.19

CHECK WITH WSP NO EVIDENCE.

Documentation Check List: Handler Typist

11.12.19

SEEK MANDATE FOR LIABILITY.

Notification ltr (if non-pickup)

After call ltr to OI:

11.12.19

IN MAINTAIN AS CID ADVISED NO CONTACT.

Authorisation To Act:

Release Voucher:

26.12.20

INFORM TM WOULD LIKE TO CLOSE (SE THE CASE DUE TO NO DEVELOPMENTS.

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WSP

Repair Cost: S\$ 1,300

(3 days)

Reduction:

73 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 50

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

CONFIRMING YES/NO.

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$ x

days)

Loss of Income (LOI):

S\$

(\$ x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP/WP

3) Survey fee:

4250.

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

GK31112596 01 JAN 2018

TP 111

Thin Thin

Accident date: 07th JAN 2018

Estimated repair cost for vehicle no: SKX5873H HONDA FIT 1.3A '15

S/n	Qty	Items	U/price	Amount
1	1	Rear tail lamp-LH <i>could</i>		\$420.20 387.70
2	1	Rear tail lamp panel-LH <i>Rp</i>		\$128.40 X
3	2	Rear tail lamp clips <i>new</i>	\$6.50	\$13.00 ✓
4	1	Rear Bumper <i>del</i>		\$853.00 495
5	2	Rear Bumper Side Bracket <i>re</i>	\$68.70	\$137.40 24
6	8	Rear bumper clips <i>re</i>	\$5.00	\$40.00 30
7	1	Rear Bumper reverse sensor <i>not re</i>		\$350.00 ✓
8	1	Rear Bumper towing cover <i>not re</i>		\$58.10 X
9	2	Rear bumper LH inner cover <i>del</i>		\$118.00 ✓
10	1	Rear End Panel <i>Reps</i>		\$492.90 X
11	1	Rear End Panel Top Garnish <i>del re</i>		\$168.00 X

1068.70
854.96

Subtotal :- \$2,779.00

Labour charges

To remove & re-fix cushion

\$120.00 X

To remove & re-fix reverse sensor

~~\$100.00~~ 50

To Check Wiring System

~~\$60.00~~ 30

Tuff Kote

\$120.00 X

Panel beating

~~\$800.00~~ 200

Spray painting

~~\$800.00~~ 400

Subtotal :- \$2,000.00

Total:- \$4,779.00

total 1634.96
L/s 13K
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1348H

Vehicle Details

Vehicle No.: SKX5873H

Vehicle to be Exported: Yes

Intended De-registration Date: 16 Jan 2018

Vehicle Make: HONDA

Vehicle Model: FIT 1.3G F PACKAGE A

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: L13B1213002

Chassis No.: GK31112996

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$12,764.00

Original Registration Date: 18 Dec 2015

First Registration Date: 18 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$7,764.00

Intehded PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Dec 2025

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 21 February 2020 11:30 AM
To: Zuhaidah Samsuri
Subject: MCT18011010 // ACCIDENT INVOLVING SHD 4141J AND SKX 5873H ON 07/01/2018

Hi Aida,

We refer to the above matter.

ACCIDENT INVOLVING SHD 4141J AND SKX 5873H ON 07/01/2018

There is no development on the case, third party did not submit any evidence to us till date.

In view on above we would like to submit our w/p report and close off the matter.

...CLA

Claim Audit	Activity Log
Seek Mandate from Insurer	Edit Adjuster Rpt >>

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt
ain	19 Feb 2018 Edit Reg		14 Feb 2018 00:00 Edit Adj Rpt	

Main	Reference
------	-----------

CLAIM SUBFOLDER DETAILS

red:	
Claimant:	ZHOU LITING CLARIS, ID: S8441348H
icle Reg. No.:	SKX5873H
m Type:	TP / MCT18011010
icle Reg. No. (Insured):	SHD4141J
airer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100
dling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Sam
mant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888
ster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final I

ASSOCIATED MAIL RECEIVED

II_SG (11/12/2019): Alert - Adj Mandate Maintained - SKX5873H - Claim Handler: Zuhaidah Bte Samsuri
II_SG (12/04/2018): Request for TP video footage

Shall reopen for further action if third party return.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2018 Edit Reg		12 Jan 2018 00:00 Edit Adj Rpt	S\$1,300.00 Edit Estimates	S\$1,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	ZHOU LITING CLARIS , ID: S8441348H								
Vehicle Reg. No.:	SKX5873H	Date of Loss:	07/01/2018 00:00 - :59 [24 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18011010	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4141J	Policy No. (Claimant):	D28660457QMY						
	Excess:								
Repairer:	Ho Beng Trading (HQ) Blk 3020A #01-33, Ubi Road 1, 408714 Ubi - Tel: 81862100								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (11/12/2019): Alert - Adj Mandate Maintained - SKX5873H - Claim Handler: Zuhaidah Bte Samsuri - III_SG (12/04/2018): Request for TP video footage									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKX5873H (MCT18011010)
[SHD4141J]
TP
ZHOU LITING CLARIS
Jan 7 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Ho Beng Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 19:01	General View	 Load JPG	☒
2	17/07/18 19:01	General View	 Load JPG	☒
3	17/07/18 19:01	General View	 Load JPG	☒
4	17/07/18 19:01	General View	 Load JPG	☒
5	17/07/18 19:01	General View	 Load JPG	☒
6	17/07/18 19:01	General View	 Load JPG	☒
7	17/07/18 19:01	General View	 Load JPG	☒
8	17/07/18 19:01	General View	 Load JPG	☒
9	17/07/18 19:01	General View	 Load JPG	☒
10	17/07/18 19:01	General View	 Load JPG	☒
11	17/07/18 19:01	General View	 Load JPG	☒
12	17/07/18 19:01	General View	 Load JPG	☒
13	17/07/18 19:01	General View	 Load JPG	☒
14	17/07/18 19:01	General View	 Load JPG	☒
15	17/07/18 19:01	General View	 Load JPG	☒
16	17/07/18 19:01	General View	 Load JPG	☒
17	17/07/18 19:01	General View	 Load JPG	☒
18	17/07/18 19:01	General View	 Load JPG	☒
19	17/07/18 19:01	General View	 Load JPG	☒
20	17/07/18 19:01	General View	 Load JPG	☒
21	17/07/18 19:01	General View	 Load JPG	☒
22	17/07/18 19:01	General View	 Load JPG	☒
23	17/07/18 19:01	General View	 Load JPG	☒
24	17/07/18 19:01	General View	 Load JPG	☒
25	17/07/18 19:01	General View	 Load JPG	☒
26	17/07/18 19:01	General View	 Load JPG	☒
27	17/07/18 19:01	General View	 Load JPG	☒
28	17/07/18 19:01	General View	 Load JPG	☒
29	17/07/18 19:01	General View	 Load JPG	☒
30	17/07/18 19:01	General View	 Load JPG	☒
31	17/07/18 19:01	General View	 Load JPG	☒
32	17/07/18 19:01	General View	 Load JPG	☒
33	17/07/18 19:01	General View	 Load JPG	☒
34	17/07/18 19:01	General View	 Load JPG	☒
35	17/07/18 19:01	General View	 Load JPG	☒
36	17/07/18 19:01	General View	 Load JPG	☒
37	17/07/18 19:01	General View	 Load JPG	☒
38	17/07/18 19:01	General View	 Load JPG	☒
39	17/07/18 19:01	General View	 Load JPG	☒
40	17/07/18 19:01	General View	 Load JPG	☒
41	17/07/18 19:01	General View	 Load JPG	☒
42	17/07/18 19:01	General View	 Load JPG	☒
43	17/07/18 19:01	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 21:13	TP GIA REPORT		Load PDF
2	13/09/18 16:10	Email from TP		Load PDF
3	21/02/20 11:36	EMAIL TO III DD 210220		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/04/18 14:41	INSURED GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18002978/AEA3Q2

Date: 26/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SKX5873H Insured Vehicle No: SHD4141J
 Vehicle No: SKX5873H
 Date of Loss: 07/01/2018 Nature of Claim: TP Claim No: MCT18011010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX5873H
 Make & Model: HONDA FIT, 1.3 G F-Package (A) Engine No: L13B1213002
 Reg. Date: 18/12/2015 (Man. Year: 2015) Chassis No: GK31112996
 Colour: Red Odometer: 42771 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,779.00	854.96	1,924.04	69.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	780.00	1,220.00	61.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,779.00	1,634.96	3,144.04	65.79
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	4,779.00	1,300.00	3,479.00	72.80
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/01/2018
 Date Inspected: 12/01/2018 Inspected At: Ho Beng Trading (HQ)
 Blk 3020A #01-33, Ubi Road 1
 Singapore 408714
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2020)
Parts:	144	HONDA FIT 1.3 G F-Package (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5873H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP-LH	Cracked	420.20 F	*388.70 FL
2	1		*REAR TAIL LAMP PANEL -LH	Repair	128.40 F	*- FL
3	2		*REAR TAIL LAMP CLIPS	Necessary	13.00 F	*13.00 FL
4	1		*REAR BUMPER	Deformed	853.00 F	*495.00 FL
5	2		*REAR BUMPER SIDE BRACKET	Necessary	137.40 F	*24.00 FL
6	8		*REAR BUMPER CLIPS	Necessary	40.00 F	*30.00 FL
7	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	350.00 F	*- FL
8	1		*REAR BUMPER TOWING COVER	Not Necessary	58.10 F	*- FL
9	2		*REAR BUMPER LH INNER COVER	Deformed	118.00 F	*118.00 FL
10	1		*REAR END PANEL	Repair	492.90 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	168.00 F	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	2,779.00	1,068.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	213.74
Total Parts (\$\$)	2,779.00	854.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX CUSHION	New	120.00	0.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
3	TO CHECK WIRING SYSTEM	New	60.00	30.00
4	TUFF KOTE	New	120.00	0.00
5	PANEL BEATING	New	800.00	300.00
6	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (S\$)			2,000.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >