

ASS. REC. BY:

REF:

TP /

CS/TP18002987/Krbn2

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SITC 5344P

Yr Regn:

09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude c.c. 1995

Colour

m. white / R

A/C: Insured / Std / NI / NA

Sp. Reading

437569

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABLISAUC 279353

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

R/Bal.

4

mm

Rear

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

9/12/18

D.O.I.

13/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/2

File pass to Corheim

SITC 5344P - NA / INCI8000006/hu

Submit L/S \$3150 @ 2 days  
Red: \$28,012-20, 90%

RECEIVED 26 OCT 2018

Date/Time, File Pass to:

1) typist

Date/Time, File Return to:

2)



Prell. Report



Final Report

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

21x15, 315

170+315

50

11

80

626

Report Format:

TP - (dependent

Lump Sum / L.B.1: (\$

3150.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18002987/Krb	
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 14-02-2018	
		Code : TP378	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	Veh. Inspected		SHC 5344P
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		13/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	c.c		0
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/02/2018	Inspection Date	13/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/02/2018 16:13
Date Of Accident	09/02/2018 12:40
Exact Location Of Accident	VIVO CITY LEVEL 1 PICK UP POINT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5344P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TONG CHEE HIONG
NRIC No	S1263990B
Date Of Birth	24/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	23/08/1979
Driving Experience	38 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96693067
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 165 HOUGANG AVE 1 #05-1608
Postcode	530165
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHAN JENNIE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On the 09.02.2018 at about 1240hours, i was arriving at Vivo City Level 1 Pick Up Point to alight my passenger(Chan Jennie). Before i could stop the taxi at the taxi stand, my passenger had already open my taxi's rear left side door without checking for oncoming vehicles and causing Vehicle B(SLS9298G) to collided onto the open door. i wish stated that my passenger agreed to compensate for the damages. Passenger Details : Name: Chan Jennie Address: Block 69 Leng Kok Bahru #08-551

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	CHAN JENNIE
Phone Number	
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS9298G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	ANG BENG HAI
NRIC/Passport Number	

Contact Number

98004573

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

A - SHC 5440

B - SLS 92986

Vivo city level 1

Taxi stand

Drop off point

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to G117 report -

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3878K
<b>Vehicle Details</b>	
Vehicle No.:	SHC5344P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001992
Chassis No.:	VF1ABL15AUC279353
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$9,373.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$24,876.00
<b>Total Rebate Amount:</b>	<b>\$34,249.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Oct 2018

OK

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5344P
Vehicle to be Exported:	Yes
Intended De-registration Date:	11 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001992
Chassis No.:	VF1ABL15AUC279353
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Sep 2014
First Registration Date:	30 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	29 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$29,366.00
<b>Total Rebate Amount:</b>	<b>\$38,739.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Feb 2018

OK

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5344P -**

AAD1802-112

*Not Authored*  
*1/1/2018 @ 3150L*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC5344P - JHOW**

VF1ABL15AUC279353

RENAULT

LATITUDE

09.02.2018

**PART****LIST**

1	1	BUMPER COVER REAR	\$	Sn 1,108.46	}	X
2	1	BUMPER LOWER REAR	\$	Sn 768.84		
3	1	BUMPER BRACKET CTR REAR	\$	Sn 113.47		
4	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn 135.97		
5	1	BUMEPR RETAINER LH REAR	\$	Sn 44.99		
6	1	BUMPER REFLECTOR LH	\$	Sn 43.61		
7	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn 135.97		
8	1	BUMEPR RETAINER LH REAR	\$	Sn 44.99		
9	1	ROCKER PANEL OUTER LH	\$	R 987.49	}	
10	1	FENDER PANEL REAR LH	\$	R 3,299.13		
11	1	WHEELARCH REAR LH	\$	Sn 543.47		
12	1	TAILLAMP LH	\$	Sn 552.55		
13	1	TAILLAMP PANEL LH	\$	R 986.70	}	
14	1	DOOR PANEL REAR LH	\$	R 2,844.66		
15	1	DOOR GUIDE REAR LH	\$	Sn 176.82	}	X
16	1	DOOR HINGE UPPER LH	\$	R 274.50		
17	1	DOOR HINGE LOWER LH	\$	R 300.55	}	X
18	1	DOOR CHECK REAR LH	\$	Sn 203.06		
19	1	DOOR LOCK REAR LH	\$	no 908.75	}	
20	1	DOOR GRAB HANDLE REAR LH	\$	Sn 210.96		
21	1	DOOR HANDLE OUTER REAR LH	\$	Sn 126.49	}	X
22	1	DOOR HANDLE CAP REAR LH	\$	Sn 35.52		
23	1	DOOR HANDLE SEAL REAR LH	\$	Sn 7.89		
24	1	DOOR HANDLE COVER REAR LH	\$	Sn 13.22		
25	1	DOOR HANDLE MODULE REAR LH	\$	Sn 133.60		
26	1	DOOR REGULATOR REAR LH	\$	R 1,135.10		
27	1	DOOR REGUALTOR MOTOR REAR LH	\$	Sn R 893.75		
28	1	DOOR FINISHER REAR LH	\$	Sn 423.10		
29	1	DOOR WHEATHESTRIIP REAR LH	\$	Sn 410.66		
30	1	DOOR SEAL REAR LH	\$	Sn 162.02		
31	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn 334.69		
32	1	DOOR MOULDING REAR LH	\$	Sn 176.82		
33	1	DOOR PANEL FRT LH	\$	R 2,844.66		

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1802-112

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5344P -

TOTAL	\$	20,382.46
10%	\$	2,038.25
	\$	18,344.22

**Special Nett**

1	1SET	PARKING AID	\$	Sn	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	
5	1SET	BUMEPR RETAINER LH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
9	1	TAILLAMP CLIP LH	\$	nn	5.00	
10	1SET	WHEELARCH CLIP RR LH	\$	nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
12	1	WINDSCREEN MOULDING	\$	Sn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14	1	CAP HUB LH RR	\$	Sn	35.00	
15	1	RIM LH RR	\$	Sn	385.00	
16	1	TYRE LH RR	\$	Sn	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
18	1	DOOR STICKER "Classic"	\$	nn	30.00	
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	

TOTAL	\$	2,208.00
TOTAL PARTS	\$	20,552.22

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 2200

To reinstall rear bumper parking sensor.

\$ nn 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 300

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,200.00 2000

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To repair and realign rear exhaust pipe.

\$ nn 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-112**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHC5344P -**

Towing Fees	\$	<i>nn</i> 120.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>

<b>TOTAL</b>	<b>\$</b>	<b>10,610.00</b>
<b>Over All Total</b>	<b>\$</b>	<b>31,162.22</b>

**(PARTS BY PARTS)****Repair Days***15 Days*  
*2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18002987/Krbn2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 01-11-2018		
		Code : TP378		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	Veh. Inspected		SHC 5344P	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		13/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279353	Colour	METALLIC WHITE / RED	
Odometer	437569	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	4 mm	
L/H Front Tyre	215/60 R16	GITI	4 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S DOOR.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/02/2018	Inspection Date	13/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5344P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	SERVICEABLE	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	DENTED	908.75	908.75
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	SERVICEABLE	893.75	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-

Report Ref No. CS/TP18002987/Krbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,038.25	-375.34
			18,344.21	3,378.07
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER LH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR LH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			2,208.00	60.00
	<b><u>LABOUR</u></b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER LH,FENDER PANEL REAR LH,TAILLAMP PANEL LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER LH,DOOR REGULATOR REAR LH AND DOOR PANEL FRT LH.		4,200.00	200.00

Report Ref No. CS/TP18002987/Krbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			10,610.00	510.00
	<b>GRAND TOTAL</b>		<b>31,162.21</b>	<b>3,948.07</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,150.00</b>

Report Ref No. CS/TP18002987/Krbn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.