



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LIM SEOK CHENG

09/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 08/02/2018

Estimated repair cost for vehicle no: SKJ6555T SUBARU FORESTER 2.0 XT A '17

CHASSIS: JF1SJGK85HG087117

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bonnet <i>Dented</i>		\$980.00
2	2	Front Bonnet Hinge <i>2 new</i>	\$48.00	\$96.00
3	2	Front Bonnet Shock Absorber	\$116.30	\$232.60
4	1	Front Bonnet Top Lock <i>Dmg</i>		\$60.00
5	1	Front Bonnet Insulator Centre <i>2 new</i>		\$115.00
6	2	Front Bonnet Insulator Side <i>1 new</i>	\$79.50	\$159.00
7	30	Front Bonnet Insulator Clip <i>new</i>	\$6.50	\$195.00 30
8	1	Front Bonnet Air Duct <i>new</i>		\$156.00
9	1	Front Bonnet Top Chrome <i>cracked</i>		\$180.30
10	1	Front Bonnet Emblem Logo <i>new</i>		\$64.50
11	1	Front Bonnet Grille <i>cracked</i>		\$280.00
12	2	Front Bonnet Grille & Side Chrome Assy <i>1st cracked</i>	\$95.00	\$190.00 95
13	2	Front Head Lamp Assy <i>cracked</i>	\$2,480.80	\$4,961.60
14	1	Front Grille <i>cracked</i>		\$360.80
15	6	Front Grille Clip <i>new</i>	\$6.90	\$41.40
16	1	Front Grille Chrome <i>cracked</i>		\$180.00
17	1	Front Grille Top Bracket <i>Best</i>		\$61.20
18	1	Front Side Mirror Assy <i>Dmg</i>		\$844.30
19	1	Front Bumper <i>Distorted</i>		\$694.50
20	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 20
21	2	Front Bumper Side Retainer <i>new</i>	\$26.30	\$52.60
22	1	Front Bumper Number Plate <i>Best</i>		\$50.00
23	1	Front Bumper Towing Cover <i>Best</i>		\$24.90
24	2	Front Bumper Fog Lamp <i>cracked</i>	\$360.40	\$720.80
25	2	Front Bumper Fog Lamp Cover <i>1st missing</i>	\$48.30	\$96.60 98.30
26	2	Front Bumper Fog Lamp Side Cover <i>missing</i>	\$40.10	\$80.20
27	2	Front Bumper Wiper Nozzle Cover <i>1st missing</i>	\$52.10	\$104.20 52.10
28	2	Front Bumper Wiper Nozzle & Bracket Assy	\$82.10	\$164.20

all cracked

82.10

Reinforcement

29	1	Front Bumper Inner Sponge <i>Cover Distorted</i>		\$140.20	✓
30	1	Front Bumper Reinforcement <i>Best</i>		\$320.30	✓
31	2	Front Fender <i>Ry's</i>	\$380.00	\$760.00	+
32	2	Front Fender Cowling <i>3 new 14 torn</i>	\$125.00	\$250.00 +125	
33	20	Front Fender Cowling Clip <i>n</i>	\$6.50	\$130.00 +30	
34	1	Front Support Panel <i>Distorted</i>		\$570.80	✓
35	1	Front Support Panel Top Cover <i>cracked</i>		\$140.10	✓
36	10	Front Support Panel Top Cover Clip <i>n</i>	\$6.50	\$65.00 +20	
37	1	Front Support Panel Air Cleaner Air Duct <i>new</i>		\$136.00	+
38	1	Front Air Cleaner Box Assy <i>new</i>		\$650.10	+
39	1	Front Air-Con Condenser <i>Best</i>		\$680.00	✓
40	1	Front Air-Con Fan Motor Assy <i>cracked</i>		\$599.10	✓
41	1	Front Air-Con Suction Pipe <i>Best</i>		\$280.30	✓
42	1	Front Air-Con Discharge Pipe <i>new</i>		\$280.30	+
43	1	Front Air-Con Liquid Pipe <i>new</i>		\$291.80	+
44	1	Front Air-Con Compressor <i>new</i>		\$1,500.30	+
45	1	Front Radiator <i>Dented</i>		\$909.00	✓
46	1	Front Radiator Fan Motor Cowling Assy <i>new</i>		\$581.30	+
47	1	Front Radiator Top Hose <i>new</i>		\$44.60	+
48	1	Front Radiator Lower Hose <i>new</i>		\$32.00	+
49	1	Front Radiator Spare Tank <i>new</i>		\$72.00	+
50	1	Front Engine Lower Cover <i>Distorted</i>		\$310.00	✓
51	1	Front Engine Top Cover (Subaru Boxer) <i>cracked</i>		\$408.70	✓
52	1	Front Water Pump <i>new</i>		\$312.40	+
53	1	Front Fan Belt <i>new</i>		\$78.10	+
54	1	Front Intercoolant Housing <i>new</i>		\$1,040.60	+

Subtotal:- \$21,780.70

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To remove & refit air cleaner box, fan belt, water pump, top & lower cover	\$350.00 ?
To reset computer	\$450.00 x
To check wiring	\$100.00 30
Towing fee	\$220.00 120
Panel beating	\$1,200.00 800
Spray painting	\$1,200.00 700
Subtotal:-	<u>\$3,900.00</u>
Total:-	<u>\$25,680.70</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
H/s 20/02/18 08 Days

Not Authorised

Excess \$1750