

ASS. REC. BY:

REF:

CS/CTI18003002 / Avd3

Special Instruction:

Surveyor
Merimen
From (Person):

Adrian

ASSIGNMENT (Office)

Joel Goh

of

CTI

Date/Time: 13/2/2018 @ 4:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 6555 T

Insured:

at Workshop m/s

New Hock Teck

Tel:

67479241

of

I kaki Bkt Ave 6, Blk C #01-13 Autobay

Policy No:

DMPCSN1728371700

Claim No:

SNM18D00829C01/5

Sum Insured:

Excess:

\$1,750.00 (No waiver)

Make of Veh:

(Client's Record)

D.O.A. 8/2/18

CA / REV

REP. / REV 24 HRS

Date/Time:

9:14am @ 14/2/18

Person Contacted:

Mr. Henry

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Wksp closed from 14/2/18 - 20/2/18. call back on 20/2/18 after 3pm

SKJ 6555 T - X

21/2/18

sent preli thm merimen

21/2/18

Rere approved up to \$20,725.90 from A/Pred by merimen

22/2/18

Informed Sukyi c/A ex \$1750 by email

28/2/18

Revert by merimen (with supplementary)

1/3/18

@ 1034am Eddie call up to check on the Alternator

Signature

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKJ655ST Yr Regn: 2017 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forester c.c. 1998Colour: Gray A/C: Insured / Std / NI / NASp. Reading: 13267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFISJ6K85H6087H7Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/55R18R: 225/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 20/02/18Survey held at NHTDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ChiruMV: 120kPV: 56.7kNett: 63.3k

RECEIVED 1 APR 2018

17/4/18 Adrian confirmed LS \$ 17,500 (Red 27, 258.40, 619)

RECEIVED 1 APR 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 14

1)

☐

Final Report

Resurvey No. of Trip: 3Survey Fee: 220

Date/Time, File Return to?

2) 18/4 - typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend \$

Report Format: merimenLump Sum / L.B.I: (\$ 17,500)

TOTAL

Survey Department Check List (Case Handler)

Reference No.: CS/CTI18003002/Avd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

18/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18003002/Avd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 14-02-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKJ 6555T
Policy No.	DMPCSN1728371700	Coverage (\$)	0.00
Claim No.	SNM18D00839C01/5	Excess (\$)	1,750.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	14/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/02/2018	Inspection Date	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE MARKET VALUE IS S\$———(EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Recd	Adj Submitted	Est Auth'd	Status
Main	12 Feb 2018		13 Feb 2018 16:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	LIM SEOK CHENG, ID: S7102347H	[Created by insurer]	
Vehicle Reg. No.:	SKJ6555T	Date of Loss:	08/02/2018 14:00 - :59
Claim Type:	OD / SNM18D00839C01/5	Policy/Cover Note No.:	DMPCSN1728371700 (Comprehensive)
		Excess:	S\$1,750.00
Repairer:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/02/2018]		
Driver/Custodian:	TOH KOK SIONG FELIX (49 / Male), NRIC: S6900787B, Tel: +6591683678		
Adj Asg. Remarks:	OD SURVEY AND REVERT. EXCESS: \$1,750.00 NO WAIVER		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Assigned By	Completed On	Created On	Done?
No results.								

View All

Search Tasks

Create New Task

Complete

View Received Message

This mail is associated with :

***SKJ6555T (SNM18D00839C01/5)**

OD

Feb 8 2018 2:00PM

[LIM SEOK CHENG]

New Hock Teck Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **01/03/2018 11:30 AM**.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$31036.00) - SKJ6555T - Claim Handler: Joel Goh

Approved:31036.00:Please proceed to authorize repairs UP TO \$20,725.90 BEFORE Excess of \$1,750.00. RE-INSPECTION OF VEHICLE required.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joel Goh	Date: 28 Feb 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKJ6555T	Accident Date	: 08/02/2018
Make	: SUBARU FORESTER	Policy No.	: DMPCSN1728371700
Assignment Date	: 13/02/2018	Excess	: S\$1,750.00
Date of Inspection	: 20/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: NEW HOCK TECK MOTOR PTE LTD (HQ) 1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,758.40	(incl.supplementary \$19,077.70)
Revised Amount	:S\$	23,795.00	(incl.supplementary \$19,077.70)
Check Items (Estimated)	:S\$	7,241.00	
Total	:S\$	31,036.00	
Lump Sum Repair	:S\$		
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	120,000.00	
COE / PARF Rebate	:S\$	56,648.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	63,352.00	

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 6/6 mm
Tyre Condition (Rear)	: 6/6 mm

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

()	Other comments :
-----	------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 22 February 2018 9:53 AM
To: 'Admin nht'; SUR
Cc: Reena; Olivia Lau (LKKAuto)
Subject: RE: OD CLAIM - SKJ6555T DOA:08.02.18

Dear Sukyi,

As instructed by our client , please proceed to repair the insured vehicle **SKJ 6555T (Excess \$1,750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin nht [mailto:admin@nhtmotor.com]
Sent: Wednesday, 21 February 2018 5:32 PM
To: SUR <sur@lkkauto.com>
Cc: Reena <reena@nhtmotor.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: OD CLAIM - SKJ6555T DOA:08.02.18

Hi all,

Please advice us the status of the authorization as client chase at our end,thanks.

Best Regards,

Sukyi

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6 Bldg C #01-43 Autobay@Kaki Bukit S(417883)

Tel: 6747 9241 Fax: 6741 7276

x

x

View Received Message

This mail is associated with :

***SKJ6555T (SNM18D00839C01/5)**

OD

Feb 8 2018 2:00PM

[LIM SEOK CHENG]

New Hock Teck Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 21/02/2018 17:05 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$20725.90) - SKJ6555T - Claim Handler: Joel Goh

Approved:20725.90:Please proceed to authorize repairs UP TO \$20,725.90 BEFORE Excess of \$1,750.00. RE-INSPECTION OF VEHICLE required.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joel Goh

Date: 20 Feb 2018

Preliminary Advice

Vehicle No	: SKJ6555T	Accident Date	: 08/02/2018
Make	: SUBARU FORESTER	Policy No.	: DMPCSN1728371700
Assignment Date	: 13/02/2018	Excess	: S\$1,750.00
Date of Inspection	: 20/02/2018	Est. Duration of Repair	: 8.00
Inspection At	: NEW HOCK TECK MOTOR PTE LTD (HQ) 1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,680.70
Revised Amount	:S\$	7,667.80
Check Items (Estimated)	:S\$	13,058.10
Total	:S\$	20,725.90

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	56,648.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,352.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2347H
Vehicle Details	
Vehicle No.:	SKJ6555T
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	FA20B959785
Chassis No.:	JF15JGK85HG087117
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,931.00
Original Registration Date:	11 Apr 2017
First Registration Date:	11 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$17,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Apr 2027
PARF Rebate Amount:	\$13,448.00
Intended COE Rebate Details	
COE Expiry Date:	10 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$43,200.00
Total Rebate Amount:	\$56,648.00

The information contained herein is correct as at 20 Feb 2018

OK

**YOUR ONLY PLACE FOR
CERTIFIED PRE-OWNED BMW.**
PERFORMANCE PREMIUM SELECTION

[View available cars](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Toyota Corolla Altis 1.6A Elegance at only \$85.8k.



Totally Like Brand New - 1
Owner. Road Tax till May 18.
Bidded Car Number
Lake View Credit Granted


[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

4 vehicles

Forester

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Forester	Any	Any	2017	Any	Any	Any	Available
	Subaru Forester 2.0XT	\$130,000	\$13,560 /yr	03-Jan-2017	1,998 cc	16,000 km	SUV	Available
1 Owner, Panoramic Sunroof, Harman Kardon Sound System With Android Touch Screen, Bluetooth, Reverse Camera And Etc, Consignment Unit, Accident Free, Showroom Condition. Free Paint Protection Coating....								
Posted: 06-Feb-2018 Tags: 2017 Subaru Forester, Subaru Forester, Subaru, Forester, Used Subaru								
	Subaru Forester 2.0XT	\$125,900	\$12,850 /yr	08-Mar-2017	1,998 cc	20,000 km	SUV	Available
Rare Evergreen All Models Of Subaru Forester Catalog Signature Blue! Full Motor Image Service Records From Day 1 Meaning Still Qualified For 5 Years Warranty! Furthermore, No Modifications! Totally St...								
Posted: 13-Feb-2018 Tags: 2017 Subaru Forester, Subaru Forester, Subaru, Forester, Used Subaru								
	Subaru Forester 2.0XT	\$127,800	\$13,040 /yr	31-Mar-2017	1,998 cc	8,400 km	SUV	Available
One Owner, Better Value Than A New Car. Very Low Mileage Done, Perfect Condition, Call/SMS Now To Make An Arrangement For This Hot Selling Car! Consignment Unit, Viewing By Appointment, High Loan And ...								
Prem Roy Motoring								
Posted: 22-Dec-2017 Tags: 2017 Subaru Forester, Subaru Forester, Subaru, Forester, Used Subaru								
	Subaru Forester 2.0XT	\$133,000	\$12,710 /yr	22-Nov-2017	1,998 cc	7,200 km	SUV	Available
Under Agent Warranty 5yrs/100k Km. 10k Km Free Servicing. Sheltered Carpark. Powerful Car With Off Road Capability, VDC Sys Prevent Understeer Or Oversteer, Deliver Power When Needed. Very Good Safety...								
Posted: 30-Jan-2018 Tags: 2017 Subaru Forester, Subaru Forester, Subaru, Forester, Used Subaru								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Forester, Forester Singapore, used Forester Singapore, used Forester, used vehicles Singapore or even buy used Forester Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool &

- About Us
- Careers
- Contact Us
- Sitemap

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2347H
Vehicle Details	
Vehicle No.:	SKJ6555T
Vehicle to be Exported:	No
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	FA20B959785
Chassis No.:	JF1SJK85HG087117
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$17,931.00
Original Registration Date:	11 Apr 2017
First Registration Date:	11 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$17,931.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Apr 2027
PARF Rebate Amount:	\$13,448.00
Intended COE Rebate Details	
COE Expiry Date:	10 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,000.00
COE Rebate Amount:	\$49,359.00
Total Rebate Amount:	\$62,807.00

The information contained herein is correct as at 20 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 16:31
Date Of Accident	08/02/2018 14:30
Exact Location Of Accident	WEST COAST PARK LP NO 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ6555T
Insured/Policyholder	
Name Of Registered Owner	LIM SEOK CHENG
NRIC No	S7102347H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91783678
Alternative Phone No	OFFICE-91783678

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT AWD CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1728371700
Cover Note Number	

Driver

Name of Driver	TOH KOK SIONG FELIX
NRIC No	S6900787B
Date Of Birth	06/01/1969
Occupation	INDOOR
Date Of Driving Pass	12/12/1995
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91683678
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 27B WEST COAST PARK #12-09 S(127722)

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CLEMENTI N.P.C

Police Station Address ROAD: 20 CLEMENTI AVE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180209/2024

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No: T/20180209/2024

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/02/2018 09:19	Vide Report No.: D/20180208/0065	Station Diary No.: 21
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: TOH KOK SIONG FELIX			Address: 27B WEST COAST PARK #12-09 SINGAPORE 127722		
ID Type / ID No.: NRIC NO / S6900787B			Contact No.: Home/Office: 96665781 Mobile: 91683678		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 06/01/1969	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Retail/Shop sales manager			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Government Property	Drink Drive: No	Date/Time of Accident: 08/02/2018 14:30	Type of Location: Bend
Location: Along Road 1 WEST COAST PARK				
Lamp Post Number: 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Lamp Post			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKJ6555T	Car	SUBARU	FORESTER	Brown	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA				



**SINGAPORE
POLICE FORCE**



T/20180209/2024

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 3

Report No. T/20180209/2024

CONTINUATION OF REPORT

Driver			
Name	TOH KOK SIONG FELIX		ID No. S6900787B
Related Vehicle	SKJ6555T (Car)		Contact No. 91683678
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

Brief Details.

On 08/02/2018 at about 1430hrs, I was driving along West Coast Park heading towards Botannia Condominium. As I was negotiating the bend, my car mount the kerb and subsequently hit onto a lamp post and also a OFO Bike which was parked at the said lamp post.

I then called for Police assistance vide D/20180208/0065 and Traffic Police came to my location. I was then advised to lodge a Police report.

I do not suffer any injury.



**SINGAPORE
POLICE FORCE**



T/20180209/2024

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No: T/20180209/2024

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 MUHAMMAD SYAHMI BIN SENIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI KASMAWATI BTE SAMIAN

Contact No.: 65476179

Signature Of Informant:

Date/Time:

09/02/2018 09:19

Classification Of Case:

Authentication Stamp



SINGAPORE
POLICE FORCE

SN 37

SIGNATURE



新福德車廠私

NEW HOCK TECK I

1 Kaki Bukit Ave 6, Blk C #01-43 Austr

Email: admin@nhtmotor.com

Tel: 6747 9241

UEN: 20

China OD - LXX
- 117 8 31 111111

0.0

- 980.00

- 50.00

- 30.00

02/2018

LIM SEOK CHENG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 08/02/2018

Estimated repair cost for vehicle no: SKJ6555T

'17

CHASSIS: JF1SJGK85HG087117

S/N	QTY	ITEMS	AMOUNT
1	1	Front Bonnet <i>Dented</i>	\$980.00
2	2	Front Bonnet Hinge <i>2 pcs</i>	\$96.00
3	2	Front Bonnet Shock Absorber	\$232.60
4	1	Front Bonnet Top Lock <i>2 pcs</i>	\$60.00
5	1	Front Bonnet Insulator Centre <i>2 pcs</i>	\$115.00
6	2	Front Bonnet Insulator Side <i>2 pcs</i>	\$159.00
7	30	Front Bonnet Insulator Clip <i>30</i>	\$195.00
8	1	Front Bonnet Air Duct <i>new</i>	\$156.00
9	1	Front Bonnet Top Chrome <i>cont</i>	\$180.30
10	1	Front Bonnet Emblem Logo <i>new</i>	\$64.50
11	1	Front Bonnet Grille <i>cont</i>	\$280.00
12	2	Front Bonnet Grille & Side Chrom	\$190.00
13	2	Front Head Lamp Assy <i>?</i>	\$4,961.60
14	1	Front Grille <i>cont</i>	\$360.80
15	6	Front Grille Clip <i>new</i>	\$41.40
16	1	Front Grille Chrome <i>cont</i>	\$180.00
17	1	Front Grille Top Bracket <i>Best</i>	\$61.20
18	1	Front Side Mirror Assy <i>?</i>	\$844.30
19	1	Front Bumper <i>Distorted</i>	\$694.50
20	8	Front Bumper Clip <i>new</i>	\$52.00
21	2	Front Bumper Side Retainer	\$52.60
22	1	Front Bumper Number Plate <i>new</i>	\$50.00
23	1	Front Bumper Towing Cover <i>2nd</i>	\$24.90
24	2	Front Bumper Fog Lamp <i>?</i>	\$360.40
25	2	Front Bumper Fog Lamp Cover <i>1st missing</i>	\$48.30
26	2	Front Bumper Fog Lamp Side Cover <i>missing</i>	\$40.10
27	2	Front Bumper Wiper Nozzle Cover <i>1st missing</i>	\$52.10
28	2	Front Bumper Wiper Nozzle & Bracket Assy	\$82.10

HT covered

82.10

29	1	Front Bumper Inner Sponge ?		\$140.20	✓
30	1	Front Bumper Reinforcement Bent		\$320.30	✓
31	2	Front Fender Pyro	\$380.00	\$760.00	+
32	2	Front Fender Cowling Green	\$125.00	\$250.00	+
33	20	Front Fender Cowling Clip	\$6.50	\$130.00	+
34	1	Front Support Panel Distorted		\$570.80	✓
35	1	Front Support Panel Top Cover Cured		\$140.10	✓
36	10	Front Support Panel Top Cover Clip n	\$6.50	\$65.00	20
37	1	Front Support Panel Air Cleaner Air Duct ?		\$136.00	✓
38	1	Front Air Cleaner Box Assy n		\$650.10	+
39	1	Front Air-Con Condenser Bent		\$680.00	✓
40	1	Front Air-Con Fan Motor Assy ?		\$599.10	✓
41	1	Front Air-Con Suction Pipe ?		\$280.30	✓
42	1	Front Air-Con Discharge Pipe ?		\$280.30	✓
43	1	Front Air-Con Liquid Pipe ?		\$291.80	✓
44	1	Front Air-Con Compressor ?		\$1,500.30	✓
45	1	Front Radiator ?		\$909.00	✓
46	1	Front Radiator Fan Motor Cowling Assy ?		\$581.30	✓
47	1	Front Radiator Top Hose n		\$44.60	✓
48	1	Front Radiator Lower Hose ?		\$32.00	✓
49	1	Front Radiator Spare Tank n		\$72.00	+
50	1	Front Engine Lower Cover Distorted		\$310.00	✓
51	1	Front Engine Top Cover (Subaru Boxer) Cured		\$408.70	✓
52	1	Front Water Pump ?		\$312.40	✓
53	1	Front Fan Belt ?		\$78.10	✓
54	1	Front Intercoolant Housing ?		\$1,040.60	✓

Subtotal:- \$21,780.70

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To remove & refit air cleaner box, fan belt, water pump, top & lower cover	\$350.00 ?
To reset computer	\$450.00 x
To check wiring	\$100.00 30
Towing fee	\$220.00 120
Panel beating	\$1,200.00 800
Spray painting	\$1,200.00 700
Subtotal:-	<u>\$3,900.00</u>
Total:-	<u>\$25,680.70</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Ling
t/s 20/02/18 08 Days
x/of Authorised
Excess \$1750



China OD - LTA
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LIM SEOK CHENG

09/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 08/02/2018

Estimated repair cost for vehicle no: SKJ6555T SUBARU FORESTER 2.0 XT A '17

CHASSIS: JF1SJGK85HG087117

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bonnet <i>Dented</i>		\$980.00 ✓
2	2	Front Bonnet Hinge <i>2 new</i>	\$48.00	\$96.00 +
3	2	Front Bonnet Shock Absorber	\$116.30	\$232.60 +
4	1	Front Bonnet Top Lock <i>2 new</i>		\$60.00 ✓
5	1	Front Bonnet Insulator Centre <i>2 new</i>		\$115.00 +
6	2	Front Bonnet Insulator Side <i>1 new</i>	\$79.50	\$159.00 ✓
7	30	Front Bonnet Insulator Clip <i>rec</i>	\$6.50	\$195.00 20 ✓
8	1	Front Bonnet Air Duct <i>rec</i>		\$156.00 +
9	1	Front Bonnet Top Chrome <i>cut</i>		\$180.30 ✓
10	1	Front Bonnet Emblem Logo <i>rec</i>		\$64.50 ✓
11	1	Front Bonnet Grille <i>cut</i>		\$280.00 ✓
12	2	Front Bonnet Grille & Side Chrome Assy <i>1st cut</i>	\$95.00	\$190.00 95 ✓
13	2	Front Head Lamp Assy <i>cut</i>	\$2,480.80	\$4,961.60 ✓
14	1	Front Grille <i>cut</i>		\$360.80 ✓
15	6	Front Grille Clip <i>rec</i>	\$6.90	\$41.40 ✓
16	1	Front Grille Chrome <i>cut</i>		\$180.00 ✓
17	1	Front Grille Top Bracket <i>best</i>		\$61.20 ✓
18	1	Front Side Mirror Assy <i>2 new</i>		\$844.30 ✓
19	1	Front Bumper <i>Dented</i>		\$694.50 ✓
20	8	Front Bumper Clip <i>rec</i>	\$6.50	\$52.00 20 ✓
21	2	Front Bumper Side Retainer <i>rec</i>	\$26.30	\$52.60 ✓
22	1	Front Bumper Number Plate <i>best</i>		\$50.00 ✓
23	1	Front Bumper Towing Cover <i>cut</i>		\$24.90 ✓
24	2	Front Bumper Fog Lamp <i>cut</i>	\$360.40	\$720.80 ✓
25	2	Front Bumper Fog Lamp Cover <i>1st missing</i>	\$48.30	\$96.60 98.3 ✓
26	2	Front Bumper Fog Lamp Side Cover <i>missing</i>	\$40.10	\$80.20 ✓
27	2	Front Bumper Wiper Nozzle Cover <i>1st missing</i>	\$52.10	\$104.20 52.10 ✓
28	2	Front Bumper Wiper Nozzle & Bracket Assy	\$82.10	\$164.20 ✓

ht covered

82.10

Reinforcement

29	1	Front Bumper Inner Sponge	Cover Distorted	\$140.20	2
30	1	Front Bumper Reinforcement	Belt	\$320.30	✓
31	2	Front Fender	Pyis	\$380.00	\$760.00 +
32	2	Front Fender Cowling	3 years Lt torn	\$125.00	\$250.00 + 125
33	20	Front Fender Cowling Clip	m	\$6.50	\$130.00 + 30
34	1	Front Support Panel	Distorted	\$570.80	✓
35	1	Front Support Panel Top Cover	Cracked	\$140.10	✓
36	10	Front Support Panel Top Cover Clip	m	\$6.50	\$65.00 + 20
37	1	Front Support Panel Air Cleaner Air Duct	New	\$136.00	+
38	1	Front Air Cleaner Box Assy	New	\$650.10	+
39	1	Front Air-Con Condenser	Belt	\$680.00	✓
40	1	Front Air-Con Fan Motor Assy	Cracked	\$599.10	✓
41	1	Front Air-Con Suction Pipe	Belt	\$280.30	✓
42	1	Front Air-Con Discharge Pipe	New	\$280.30	+
43	1	Front Air-Con Liquid Pipe	New	\$291.80	+
44	1	Front Air-Con Compressor	New	\$1,500.30	+
45	1	Front Radiator	Distorted	\$909.00	✓
46	1	Front Radiator Fan Motor Cowling Assy	New	\$581.30	+
47	1	Front Radiator Top Hose	New	\$44.60	+
48	1	Front Radiator Lower Hose	New	\$32.00	+
49	1	Front Radiator Spare Tank	New	\$72.00	+
50	1	Front Engine Lower Cover	Distorted	\$310.00	✓
51	1	Front Engine Top Cover (Subaru Boxer)	Cracked	\$408.70	✓
52	1	Front Water Pump	New	\$812.40	+
53	1	Front Fan Belt	New	\$78.10	+
54	1	Front Intercoolant Housing	New	\$1,040.60	+

Subtotal:- \$21,780.70

14379.40

11503.52

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 120
To remove & refit air cleaner box, fan belt, water pump, top & lower cover	\$350.00 ? X
To reset computer	\$450.00 X
To check wiring	\$100.00 30
Towing fee	\$220.00 120
Panel beating	\$1,200.00 000
Spray painting	\$1,200.00 900

2070

Subtotal:- \$3,900.00

Total:- \$25,680.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
t/s 20/02/18 08 Days

Not Authorised

Excess \$1750

Supplied by 892568

total 21989.20
t/s 17.5K

17.5K

14 days



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LIM SEOK CHENG

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Supplementary 24/02/2018

Accident date: 08/02/2018

Supplementary cost for vehicle no: SKJ6555T SUBARU FORESTER 2.0 XT A '17

CHASSIS: JF1SJGK85HG087117

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	2	Front Head Lamp Lower Bracket <i>Good</i>	\$65.30	\$130.60 ✓
2	1	Front L/H Engine Lower Side Member <i>3 Bent</i>		\$320.00 ✓
3	1	Front R/H Engine Lower Side Member <i>1 Bent</i>		\$320.00 ✓
4	1	Front Engine Lower Member Centre Bracket <i>Bent</i>		\$280.00 ✓
5	1	Front Engine Member Bracket Inner Cover <i>Refined</i>		\$28.00 ✓
6	2	Front Engine Member Bracket Inner Cover Clip <i>New</i>	\$8.00	\$16.00 ✓
7	1	Front Steering Crossmember <i>Bent</i>		\$972.60 ✓
8	1	Front Steering Rack <i>New</i>		\$2,520.80 ✓
9	1	Front Anti Roll Bar <i>New</i>		\$198.20 ✓
10	1	Front L/H Tyre (Special Nett) <i>New</i>		\$550.00 ✓
11	1	Front L/H Rim (Special Nett) <i>Lot</i>		\$780.00 <i>400/500</i>
12	1	Front L/H Lower Arm <i>Bent</i>		\$493.20 ✓
13	1	Front L/H Knuckle Arm <i>Bent</i>		\$264.90 ✓
14	1	Front L/H Knuckle Arm Bearing <i>New</i>		\$261.00 ✓
15	1	Front L/H Shock Absorber <i>Bent</i>		\$340.00 ✓
16	1	Front L/H Stabilizer Bar <i>New</i>		\$60.90 ✗
17	1	Front Wiper Tank <i>New</i>		\$114.30 ✓
18	1	Front Oil Coolant Turbo Tank Oil Clutch <i>New</i>		\$326.20 ✓
19	1	Front Exhaust Pipe Converter <i>rated 1100/1200</i>		\$2,240.20 <i>250</i>
20	1	Front Alternator <i>Replaced New</i>		\$1,520.00 ✓

Turbo Charger

Replaced - 4370.20

Subtotal:-

\$11,736.90

Support panel / oil member - 130.60 ✓

2 Front Chassis Member Bracket

Bent

(9) *255*

SIO ✓

8707.10
6965.68

S.N. 400

Labour charges

To remove & refit oil coolant oil clutch, exhaust pipe converter & alternator		\$750.00 280
To remove & refit steering rack, crossmember & centre member		\$650.00 380
To remove & refit front L/H undercarriage		\$380.00 220
To check wheel alignment		\$150.00 80
To reset computer system	1060	\$380.00 100

Subtotal:- \$2,310.00

Total:- -\$14,046.90

19,071.70

Adrian Lj
t/s 26/02/18.
Shaf

Supplementary 8425.68

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		13 Feb 2018 16:43 Edit Adj Rpt	S\$17,500.00 Edit Estimates	S\$17,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: LIM SEOK CHENG , ID: S7102347H									
Vehicle Reg. No.: SKJ6555T		Date of Loss: 08/02/2018 14:00 - :59 [9 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D00839C01/5		Policy/Cover Note No.: DMPCSN1728371700 (Comprehensive)							
		Excess: S\$1,750.00							
Repairer: New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/02/2018]									
Driver/Custodian: TOH KOK SIONG FELIX (49 / Male), NRIC: S6900787B, Tel: +6591683678									
Adj Asg. Remarks: OD SURVEY AND REVERT. EXCESS: \$1,750.00 NO WAIVER									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (01/03/2018): Alert - Adj Mandate Approved (S\$31036.00) - SKJ6555T - Claim Handler: Joel Goh - CHINA_TAIPING (21/02/2018): Alert - Adj Mandate Approved (S\$20725.90) - SKJ6555T - Claim Handler: Joel Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKJ6555T (SNM18D00839C01/5)

OD

Feb 8 2018 2:00PM

[LIM SEOK CHENG]

New Hock Teck Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print	
1	09/02/18 17:26	Accident Statement	Load HTM	☐	
2	12/02/18 11:04	Addendum Sheet	Load TIF	☐	
3	12/02/18 11:05	Accident Statement Addm. #1	Load HTM	☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/02/18 12:19	Adjuster Immediate Advice	Load HTM	☐	
2	28/02/18 16:09	Adjuster Immediate Advice	Load HTM	☐	
Photos/Images				3 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print	
1	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
2	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
3	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
4	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
5	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
6	09/02/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	27/02/18 10:23	SURVEY PHOTOS	Load PDF	☐	
2	17/04/18 18:40	General View	Load JPG	☒	
3	17/04/18 18:40	General View	Load JPG	☒	
4	17/04/18 18:40	General View	Load JPG	☒	
5	17/04/18 18:40	General View	Load JPG	☒	
6	17/04/18 18:40	General View	Load JPG	☒	
7	17/04/18 18:40	General View	Load JPG	☒	
8	17/04/18 18:40	General View	Load JPG	☒	
9	17/04/18 18:40	General View	Load JPG	☒	
10	17/04/18 18:40	General View	Load JPG	☒	
11	17/04/18 18:40	General View	Load JPG	☒	
12	17/04/18 18:40	General View	Load JPG	☒	
13	17/04/18 18:40	General View	Load JPG	☒	
14	17/04/18 18:40	General View	Load JPG	☒	
15	17/04/18 18:40	General View	Load JPG	☒	
16	17/04/18 18:40	General View	Load JPG	☒	
17	17/04/18 18:40	General View	Load JPG	☒	
18	17/04/18 18:40	General View	Load JPG	☒	
19	17/04/18 18:40	General View	Load JPG	☒	
20	17/04/18 18:40	General View	Load JPG	☒	
21	17/04/18 18:40	General View	Load JPG	☒	
22	17/04/18 18:40	General View	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
23	17/04/18 18:40	General View	 Load JPG	☒
24	17/04/18 18:40	General View	 Load JPG	☒
25	17/04/18 18:40	General View	 Load JPG	☒
26	17/04/18 18:40	General View	 Load JPG	☒
27	17/04/18 18:40	General View	 Load JPG	☒
28	17/04/18 18:40	General View	 Load JPG	☒
29	17/04/18 18:40	General View	 Load JPG	☒
30	17/04/18 18:40	General View	 Load JPG	☒
31	17/04/18 18:40	General View	 Load JPG	☒
32	17/04/18 18:40	General View	 Load JPG	☒
33	17/04/18 18:40	General View	 Load JPG	☒
34	17/04/18 18:40	General View	 Load JPG	☒
35	17/04/18 18:40	General View	 Load JPG	☒
36	17/04/18 18:40	General View	 Load JPG	☒
37	17/04/18 18:40	General View	 Load JPG	☒
38	17/04/18 18:40	General View	 Load JPG	☒
39	17/04/18 18:40	General View	 Load JPG	☒
40	17/04/18 18:40	General View	 Load JPG	☒
41	17/04/18 18:40	General View	 Load JPG	☒
42	17/04/18 18:40	General View	 Load JPG	☒
43	17/04/18 18:40	General View	 Load JPG	☒
44	17/04/18 18:40	General View	 Load JPG	☒
45	17/04/18 18:40	General View	 Load JPG	☒
46	17/04/18 18:40	General View	 Load JPG	☒
47	17/04/18 18:40	General View	 Load JPG	☒
48	17/04/18 18:40	General View	 Load JPG	☒
49	17/04/18 18:40	General View	 Load JPG	☒
50	17/04/18 18:40	General View	 Load JPG	☒
51	17/04/18 18:40	General View	 Load JPG	☒
52	17/04/18 18:40	General View	 Load JPG	☒
53	17/04/18 18:40	General View	 Load JPG	☒
54	17/04/18 18:40	General View	 Load JPG	☒
55	17/04/18 18:40	General View	 Load JPG	☒
56	17/04/18 18:40	General View	 Load JPG	☒
57	17/04/18 18:40	General View	 Load JPG	☒
58	17/04/18 18:40	General View	 Load JPG	☒
59	17/04/18 18:40	General View	 Load JPG	☒
60	17/04/18 18:40	General View	 Load JPG	☒
61	17/04/18 18:40	General View	 Load JPG	☒
62	17/04/18 18:40	General View	 Load JPG	☒
63	17/04/18 18:40	General View	 Load JPG	☒
64	17/04/18 18:40	General View	 Load JPG	☒
65	17/04/18 18:40	General View	 Load JPG	☒
66	17/04/18 18:40	General View	 Load JPG	☒
67	17/04/18 18:40	General View	 Load JPG	☒
68	17/04/18 18:40	General View	 Load JPG	☒
69	17/04/18 18:40	General View	 Load JPG	☒
70	17/04/18 18:40	General View	 Load JPG	☒
71	17/04/18 18:40	General View	 Load JPG	☒
72	17/04/18 18:40	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
73	17/04/18 18:40	General View	 Load JPG	☒
74	17/04/18 18:40	General View	 Load JPG	☒
75	17/04/18 18:40	General View	 Load JPG	☒
76	17/04/18 18:40	General View	 Load JPG	☒
77	17/04/18 18:40	General View	 Load JPG	☒
78	17/04/18 18:41	General View	 Load JPG	☒
79	17/04/18 18:41	General View	 Load JPG	☒
80	17/04/18 18:41	General View	 Load JPG	☒
81	17/04/18 18:41	General View	 Load JPG	☒
82	17/04/18 18:41	General View	 Load JPG	☒
83	17/04/18 18:41	General View	 Load JPG	☒
84	17/04/18 18:41	General View	 Load JPG	☒
85	17/04/18 18:41	General View	 Load JPG	☒
86	17/04/18 18:41	General View	 Load JPG	☒
87	17/04/18 18:41	General View	 Load JPG	☒
88	17/04/18 18:41	General View	 Load JPG	☒
89	17/04/18 18:41	General View	 Load JPG	☒
90	17/04/18 18:41	General View	 Load JPG	☒
91	17/04/18 18:41	General View	 Load JPG	☒
92	17/04/18 18:41	General View	 Load JPG	☒
93	17/04/18 18:41	General View	 Load JPG	☒
94	17/04/18 18:41	General View	 Load JPG	☒
95	17/04/18 18:41	General View	 Load JPG	☒
96	17/04/18 18:41	General View	 Load JPG	☒
97	17/04/18 18:41	General View	 Load JPG	☒
98	17/04/18 18:41	General View	 Load JPG	☒
99	17/04/18 18:41	General View	 Load JPG	☒
100	17/04/18 18:41	General View	 Load JPG	☒
101	17/04/18 18:41	General View	 Load JPG	☒
102	17/04/18 18:41	General View	 Load JPG	☒
103	17/04/18 18:41	General View	 Load JPG	☒
104	17/04/18 18:41	General View	 Load JPG	☒
105	17/04/18 18:41	General View	 Load JPG	☒
106	17/04/18 18:41	General View	 Load JPG	☒
107	17/04/18 18:41	General View	 Load JPG	☒
108	17/04/18 18:41	General View	 Load JPG	☒
109	17/04/18 18:41	General View	 Load JPG	☒
110	17/04/18 18:41	General View	 Load JPG	☒
111	17/04/18 18:41	General View	 Load JPG	☒
112	17/04/18 18:41	General View	 Load JPG	☒
113	17/04/18 18:41	General View	 Load JPG	☒
114	17/04/18 18:41	General View	 Load JPG	☒
115	17/04/18 18:41	General View	 Load JPG	☒
116	17/04/18 18:41	General View	 Load JPG	☒
117	17/04/18 18:41	General View	 Load JPG	☒
118	17/04/18 18:41	General View	 Load JPG	☒
119	17/04/18 18:41	General View	 Load JPG	☒
120	17/04/18 18:41	General View	 Load JPG	☒
121	17/04/18 18:41	General View	 Load JPG	☒
122	17/04/18 18:41	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
123	17/04/18 18:41	General View	 Load JPG	☒
124	17/04/18 18:41	General View	 Load JPG	☒
125	17/04/18 18:41	General View	 Load JPG	☒
126	17/04/18 18:41	General View	 Load JPG	☒
127	17/04/18 18:41	General View	 Load JPG	☒
128	17/04/18 18:41	General View	 Load JPG	☒
129	17/04/18 18:41	General View	 Load JPG	☒
130	17/04/18 18:41	General View	 Load JPG	☒
131	17/04/18 18:41	General View	 Load JPG	☒
132	17/04/18 18:41	General View	 Load JPG	☒
133	17/04/18 18:41	General View	 Load JPG	☒
134	17/04/18 18:41	General View	 Load JPG	☒
135	17/04/18 18:41	General View	 Load JPG	☒
136	17/04/18 18:41	General View	 Load JPG	☒
137	17/04/18 18:41	General View	 Load JPG	☒
138	17/04/18 18:41	General View	 Load JPG	☒
139	17/04/18 18:41	General View	 Load JPG	☒
140	17/04/18 18:41	General View	 Load JPG	☒
141	17/04/18 18:41	General View	 Load JPG	☒
142	17/04/18 18:41	General View	 Load JPG	☒
143	17/04/18 18:41	General View	 Load JPG	☒
144	17/04/18 18:41	General View	 Load JPG	☒
145	17/04/18 18:41	General View	 Load JPG	☒
146	17/04/18 18:41	General View	 Load JPG	☒
147	17/04/18 18:41	General View	 Load JPG	☒
148	17/04/18 18:41	General View	 Load JPG	☒
149	17/04/18 18:41	General View	 Load JPG	☒
150	17/04/18 18:41	General View	 Load JPG	☒
151	17/04/18 18:41	General View	 Load JPG	☒
152	17/04/18 18:41	General View	 Load JPG	☒
153	17/04/18 18:41	General View	 Load JPG	☒
154	17/04/18 18:41	General View	 Load JPG	☒
155	17/04/18 18:41	General View	 Load JPG	☒
156	17/04/18 18:41	General View	 Load JPG	☒
157	17/04/18 18:41	General View	 Load JPG	☒
158	17/04/18 18:41	General View	 Load JPG	☒
159	17/04/18 18:41	General View	 Load JPG	☒
160	17/04/18 18:41	General View	 Load JPG	☒
161	17/04/18 18:41	General View	 Load JPG	☒
162	17/04/18 18:41	General View	 Load JPG	☒
163	17/04/18 18:41	General View	 Load JPG	☒
164	17/04/18 18:41	General View	 Load JPG	☒
165	17/04/18 18:41	General View	 Load JPG	☒
166	17/04/18 18:41	General View	 Load JPG	☒
167	17/04/18 18:41	General View	 Load JPG	☒
168	17/04/18 18:41	General View	 Load JPG	☒
169	17/04/18 18:41	General View	 Load JPG	☒
170	17/04/18 18:41	General View	 Load JPG	☒
171	17/04/18 18:41	General View	 Load JPG	☒
172	17/04/18 18:41	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
173	17/04/18 18:41	General View	 Load JPG	☒
174	17/04/18 18:41	General View	 Load JPG	☒
175	17/04/18 18:41	General View	 Load JPG	☒
176	17/04/18 18:41	General View	 Load JPG	☒
177	17/04/18 18:41	General View	 Load JPG	☒
178	17/04/18 18:41	General View	 Load JPG	☒
179	17/04/18 18:41	General View	 Load JPG	☒
180	17/04/18 18:41	General View	 Load JPG	☒
181	17/04/18 18:41	General View	 Load JPG	☒
182	17/04/18 18:41	General View	 Load JPG	☒
183	17/04/18 18:41	General View	 Load JPG	☒
184	17/04/18 18:41	General View	 Load JPG	☒
185	17/04/18 18:41	General View	 Load JPG	☒
186	17/04/18 18:41	General View	 Load JPG	☒
187	17/04/18 18:41	General View	 Load JPG	☒
188	17/04/18 18:41	General View	 Load JPG	☒
189	17/04/18 18:41	General View	 Load JPG	☒
190	17/04/18 18:41	General View	 Load JPG	☒
191	17/04/18 18:41	General View	 Load JPG	☒
192	17/04/18 18:41	General View	 Load JPG	☒
193	17/04/18 18:41	General View	 Load JPG	☒
194	17/04/18 18:41	General View	 Load JPG	☒
195	17/04/18 18:41	General View	 Load JPG	☒
196	17/04/18 18:41	General View	 Load JPG	☒
197	17/04/18 18:41	General View	 Load JPG	☒
198	17/04/18 18:41	General View	 Load JPG	☒
199	17/04/18 18:41	General View	 Load JPG	☒
200	17/04/18 18:41	General View	 Load JPG	☒
201	17/04/18 18:41	General View	 Load JPG	☒
202	17/04/18 18:41	General View	 Load JPG	☒
203	17/04/18 18:41	General View	 Load JPG	☒
204	17/04/18 18:41	General View	 Load JPG	☒
205	17/04/18 18:41	General View	 Load JPG	☒
206	17/04/18 18:41	General View	 Load JPG	☒
207	17/04/18 18:41	General View	 Load JPG	☒
208	17/04/18 18:41	General View	 Load JPG	☒
209	17/04/18 18:41	General View	 Load JPG	☒
210	17/04/18 18:41	General View	 Load JPG	☒
211	17/04/18 18:41	General View	 Load JPG	☒
212	17/04/18 18:41	General View	 Load JPG	☒
213	17/04/18 18:41	General View	 Load JPG	☒
214	17/04/18 18:41	General View	 Load JPG	☒
215	17/04/18 18:41	General View	 Load JPG	☒
216	17/04/18 18:41	General View	 Load JPG	☒
217	17/04/18 18:41	General View	 Load JPG	☒
218	17/04/18 18:41	General View	 Load JPG	☒
219	17/04/18 18:41	General View	 Load JPG	☒
220	17/04/18 18:41	General View	 Load JPG	☒
221	17/04/18 18:41	General View	 Load JPG	☒
222	17/04/18 18:41	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
223	17/04/18 18:41	General View	Load JPG	☒
224	17/04/18 18:41	General View	Load JPG	☒
225	17/04/18 18:41	General View	Load JPG	☒
226	17/04/18 18:41	General View	Load JPG	☒
227	17/04/18 18:41	General View	Load JPG	☒
228	17/04/18 18:41	General View	Load JPG	☒
229	17/04/18 18:41	General View	Load JPG	☒
230	17/04/18 18:41	General View	Load JPG	☒
231	17/04/18 18:41	General View	Load JPG	☒
232	17/04/18 18:41	General View	Load JPG	☒
233	18/04/18 10:30	Reinspection Photo (1)	Load PDF	
234	18/04/18 10:30	Reinspection Photo (2)	Load PDF	
235	18/04/18 10:30	Reinspection Photo (3)	Load PDF	
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/02/18 16:43	OD ESTIMATES	Load PDF	
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 17:24	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	09/02/18 17:24	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	09/02/18 17:25	DL [Linked Accident Report Documents]	Load TIF	
4	09/02/18 17:25	IC [Linked Accident Report Documents]	Load TIF	
5	09/02/18 17:25	INS CERT [Linked Accident Report Documents]	Load TIF	
6	09/02/18 17:25	POLICE REPORT [Linked Accident Report Documents]	Load JPG	☒
7	09/02/18 17:25	POLICE REPORT [Linked Accident Report Documents]	Load JPG	☒
8	09/02/18 17:25	POLICE REPORT [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/18 12:30	SKJ 6555T ESTIMATE	Load PDF	
2	28/02/18 16:11	Supplementary	Load PDF	
3	28/02/18 16:13	MARK ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 17:26	Accident Statement	Load HTM	
2	12/02/18 11:04	Addendum Sheet	Load TIF	
3	12/02/18 11:05	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 17:25	Accident Photo	Load JPG	☒
2	09/02/18 17:25	Accident Photo	Load JPG	☒
3	09/02/18 17:25	Accident Photo	Load JPG	☒
4	09/02/18 17:25	Accident Photo	Load JPG	☒
5	09/02/18 17:25	Accident Photo	Load JPG	☒
6	09/02/18 17:25	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	09/02/18 17:24	Sketch Plan	 Load TIF	
2	09/02/18 17:24	Sketch Plan #2	 Load TIF	
3	09/02/18 17:25	DL	 Load TIF	
4	09/02/18 17:25	IC	 Load TIF	
5	09/02/18 17:25	INS CERT	 Load TIF	
6	09/02/18 17:25	POLICE REPORT	 Load JPG	☒
7	09/02/18 17:25	POLICE REPORT	 Load JPG	☒
8	09/02/18 17:25	POLICE REPORT	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18003002/AVD3Q2

Date: 24/04/2018

REFERENCE

Insured/Claimant: LIM SEOK CHENG Policy No: DMPCSN1728371700

Date of Loss: 08/02/2018 Nature of Claim: OD Claim No: SNM18D00839C01/5

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKJ6555T

Make & Model: SUBARU FORESTER, 2.0 XT AWD CVT (A)

Engine No: FA20B959785

Reg. Date: 11/04/2017 (Man. Year: 2017)

Chassis No: JF1SJGK85HG087117

Colour: Grey

Odometer: 13267 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,548.40	18,869.20	19,679.20	51.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	3,130.00	3,080.00	49.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,758.40	21,999.20	22,759.20	50.85
Approved Total (Overridden) (S\$)		17,500.00		
- Excess (S\$)	1,750.00	1,750.00	0.00	0.00
Nett Amount (S\$)	43,008.40	15,750.00	27,258.40	63.38

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 20/02/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKJ6555T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	980.00 F	*980.00 FL
2	2		*FRONT BONNET HINGE	Not Necessary	96.00 F	*- FL
3	2		*FRONT BONNET SHOCK ABSORBER	Not Necessary	232.60 F	*- FL
4	1		*FRONT BONNET TOP LOCK	Damaged	60.00 F	*60.00 FL
5	1		*FRONT BONNET INSULATOR CENTRE	Not fitted	115.00 F	*- FL
6	2		*FRONT BONNET INSULATOR SIDE	Not Necessary	159.00 F	*- FL
7	1		*FRONT BONNET INSULATOR CLIP (30 PCS)	Necessary	195.00 F	*30.00 FL
8	1		*FRONT BONNET AIR DUCT	Not Necessary	156.00 F	*- FL
9	1		*FRONT BONNET TOP CHROME	Cracked	180.30 F	*180.30 FL
10	1		*FRONT BONNET EMBLEM LOGO	Necessary	64.50 F	*64.50 FL
11	1		*FRONT BONNET GRILLE	Cracked	280.00 F	*280.00 FL
12	1		*FRONT BONNET GRILLE & SIDE CHROME ASSY	N/S Cracked	190.00 F	*95.00 FL
13	2		*FRONT HEAD LAMP ASSY	Cracked	4,961.60 F	*4,961.60 FL
14	1		*FRONT GRILLE	Cracked	360.80 F	*360.80 FL
15	6		*FRONT GRILLE CLIP	Necessary	41.40 F	*41.40 FL
16	1		*FRONT GRILLE CHROME	Cracked	180.00 F	*180.00 FL
17	1		*FRONT GRILLE TOP BRACKET	Bent	61.20 F	*61.20 FL
18	1		*FRONT SIDE MIRROR ASSY	Damaged	844.30 F	*844.30 FL
19	1		*FRONT BUMPER	Distorted	694.50 F	*694.50 FL
20	8		*FRONT BUMPER CLIP	Necessary	52.00 F	*30.00 FL
21	2		*FRONT BUMPER SIDE RETAINER	Necessary	52.60 F	*52.60 FL
22	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
23	1		*FRONT BUMPER TOWING COVER	Deformed	24.90 F	*24.90 FL
24	2		*FRONT BUMPER FOG LAMP	Cracked	720.80 F	*720.80 FL
25	1		*FRONT BUMPER FOG LAMP COVER	N/S Missing	96.60 F	*48.30 FL
26	2		*FRONT BUMPER FOG LAMP SIDE COVER	Missing	80.20 F	*80.20 FL
27	1		*FRONT BUMPER WIPER NOZZLE COVER	N/S Missing	104.20 F	*52.10 FL
28	1		*FRONT BUMPER WIPER NOZZLE & BRACKET ASSY	N/S Cracked	164.20 F	*82.10 FL
29	1		*FRONT BUMPER INNER REINFORCEMENT COVER	Distorted	140.20 F	*140.20 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	320.30 F	*320.30 FL
31	2		*FRONT FENDER	Repair	760.00 F	*- FL
32	1		*FRONT FENDER COWLING	N/S Torn	250.00 F	*125.00 FL
33	20		*FRONT FENDER COWLING CLIP	Necessary	130.00 F	*30.00 FL
34	1		*FRONT SUPPORT PANEL	Distorted	570.80 F	*570.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*FRONT SUPPORT PANEL TOP COVER	Cracked	140.10 F	*140.10 FL
36	10		*FRONT SUPPORT PANEL TOP COVER CLIP	Necessary	65.00 F	*20.00 FL
37	1		*FRONT SUPPORT PANEL AIR CLEANER AIR DUCT	Not Necessary	136.00 F	*- FL
38	1		*FRONT AIR CLEANER BOX ASSY	Not Necessary	650.10 F	*- FL
39	1		*FRONT AIR-CON CONDENSER	Bent	680.00 F	*680.00 FL
40	1		*FRONT AIR-CON FAN MOTOR ASSY	Cracked	599.10 F	*599.10 FL
41	1		*FRONT AIR-CON SUCTION PIPE	Bent	280.30 F	*280.30 FL
42	1		*FRONT AIR-CON DISCHARGE PIPE	Not Necessary	280.30 F	*- FL
43	1		*FRONT AIR-CON LIQUID PIPE	Not Necessary	291.80 F	*- FL
44	1		*FRONT AIR-CON COMPRESSOR	Not Necessary	1,500.30 F	*- FL
45	1		*FRONT RADIATOR	Dented	909.00 F	*909.00 FL
46	1		*FRONT RADIATOR FAN MOTOR COWLING ASSY	Not Necessary	581.30 F	*- FL
47	1		*FRONT RADIATOR TOP HOSE	Not Necessary	44.60 F	*- FL
48	1		*FRONT RADIATOR LOWER HOSE	Not Necessary	32.00 F	*- FL
49	1		*FRONT RADIATOR SPARE TANK	Not Necessary	72.00 F	*- FL
50	1		*FRONT ENGINE LOWER COVER	Distorted	310.00 F	*310.00 FL
51	1		*FRONT ENGINE TOP COVER (SUBARU BOXER)	Cracked	408.70 F	*280.00 FL
52	1		*FRONT WATER PUMP	Not Necessary	312.40 F	*- FL
53	1		*FRONT FAN BELT	Not Necessary	78.10 F	*- FL
54	1		*FRONT INTERCOOLANT HOUSING	Not Necessary	1,040.60 F	*- FL
55	2		*FRONT HEAD LAMP LOWER BRACKET	Cracked	130.60 F	*130.60 FL
56	1		*FRONT L/H ENGINE LOWER SIDE MEMBER	Bent	320.00 F	*320.00 FL
57	1		*FRONT R/H ENGINE LOWER SIDE MEMBER	Bent	320.00 F	*320.00 FL
58	1		*FRONT ENGINE LOWER MEMBER CENTRE BRACKET	Bent	280.00 F	*280.00 FL
59	1		*FRONT ENGINE MEMBER BRACKET INNER COVER	Deformed	28.00 F	*28.00 FL
60	2		*FRONT ENGINE MEMBER BRACKET INNER COVER CLIP	Necessary	16.00 F	*16.00 FL
61	1		*FRONT STEERING CROSSMEMBER	Bent	972.60 F	*972.60 FL
62	1		*FRONT STEERING RACK	Not Necessary	2,520.80 F	*- FL
63	1		*FRONT ANTI ROLL BAR	Not Necessary	198.20 F	*- FL
64	1		*FRONT L/H TYRE	Not Necessary	550.00 FS	*- FS
65	1		*FRONT L/H RIM	Cut	780.00 FS	*400.00 FS
66	1		*FRONT L/H LOWER ARM	Bent	493.20 F	*493.20 FL
67	1		*FRONT L/H KNUCKLE ARM	Bent	264.90 F	*264.90 FL
68	1		*FRONT L/H KNUCKLE ARM BEARING	Necessary	261.00 F	*261.00 FL
69	1		*FRONT L/H SHOCK ABSORBER	Bent	340.00 F	*340.00 FL
70	1		*FRONT L/H STABILIZER BAR	Not Necessary	60.90 F	*- FL
71	1		*FRONT WIPER TANK	Not Necessary	114.30 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
72	1		*FRONT OIL COOLANT TURBO TANK OIL CLUTCH	Not Necessary	326.20 F	*- FL
73	1		*FRONT EXHAUST PIPE CONVERTER	Dented	2,240.20 F	*250.00 FL
74	1		*FRONT ALTERNATOR	Not Necessary	1,520.00 F	*- FL
75	1		*TURBO CHARGES	Damaged	4,370.20 F	*4,370.20 FL
76	1		*SUPPORT PANEL LOWER MEMBER	Distorted	150.60 F	*150.60 FL
77	2		*FRONT CHASSIS MEMBER BRACKET	Bent	510.00 F	*510.00 FL
					Sub Total (\$\$)	38,548.40 23,486.50
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 4,617.30
					Total Parts (\$\$)	38,548.40 18,869.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	380.00	120.00
2	TO REMOVE & REFIT AIR CLEANER BOX ,FAN BELT ,WATER PUMP ,TOP & LOWER COVER	New	350.00	0.00
3	TO RESET COMPUTER	New	450.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TOWING FEE	New	220.00	120.00
6	PANEL BEATING	New	1,200.00	900.00
7	SPRAY PAINTING	New	1,200.00	900.00
8	TO REMOVE & REFIT OIL COOLANT OIL CLUTCH ,EXHAUST PIPE CONVERTER & ALTERNATOR	New	750.00	280.00
9	TO REMOVE & REFIT STEERING RACK ,CROSSMEMBER & CENTRE MEMBER	New	650.00	380.00
10	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE	New	380.00	220.00
11	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
12	TO RESET COMPUTER SYSTEM	New	380.00	100.00
Gross Labour Cost (S\$)			6,210.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >