

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1030 R

1 pc	Rear bumper	✓	\$	696.00
1 pc	Rear bumper lower cover	X	\$	206.00
			\$	902.00
			\$	90.20
			\$	811.80

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	Reverse sensor	✓	\$	280.00
1 pc	Rear bumper top protector	X	\$	80.00

Sundry	\$	50.00	X
To dismantle / replace/ test reverse sensor to new bumper and reset to the same	\$	120.00	20
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	450.00	200
To putty and spray painting on rear bumper	\$	200.00	180
To apply rustproofing on the repaired and replaced panels.	\$	200.00	X
	\$	2,239.80	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin (6666)

13/2/18 1610hr.
2 Days.
PIP

Before Paint photo

UDK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: